

PLEASE ARRANGE TO SURVEY
VEHICLE AT 22 TAMPINES ST 92 (S
528876)

Jimmy Goh K1
CLAIM DEPARTMENT
DID : 66547618
FAX :

Like: J.A 1e

Date : 09/10/2019
To : LONPAC INSURANCE BHD.

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd
: SOMPO INSURANCE SINGAPORE PTE. LTD.
Certificate No : D17MTHCVE000063 Accident Date : 09/09/2019
Vehicle No : GBH-9248-C Make & Model : TOYOTA HIACE 3.0 TURBO VAN G (M) EURO

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
-----	-------------	-------------------	---------------

List Item

1	BONNET	R 983.40	X
1	BONNET LOGO	68.80	
1	CORNEL PANEL LH	50.40	
1	FRONT HEADLAMP LH	SCR 843.40	
1	FRONT DOOR LH	R 1,925.60	X
1	FRONT DOOR HINGE LH(UPPER)	17 121.20	X
1	FRONT DOOR HINGE LH(LOWER)	17 121.20	X
1	FRONT DOOR CHECKER LH	17 190.60	X
1	SIDE MIRROR LH	1053.10	

not Alund

h/s 2250

10/10/19

Whip Ahn

P-2258.50

252

P-1692.37

S.N-340.00

L-800.00

2832.77

207

2265.

Date : 09/10/2019
To : LONPAC INSURANCE BHD.

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd
: SOMPO INSURANCE SINGAPORE PTE. LTD.
Certificate No : D17MTHCVE000063 Accident Date : 09/09/2019
Vehicle No : GBH-9248-C Make & Model : TOYOTA HIACE 3.0 TURBO VAN G (M) EURO

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	SIDE MIRROR GLASS LH	17 214.20	X
	Sub Total	6046.70	
	Discount 25% On Parts	(1511.67)	
	<u>Special Nett Item</u>		
1	BONNET ADVERTISMENT STICKER <i>6 door sticker</i>	ner 320.00	✓
1	FRONT DOOR LH ADVERTISMENT STICKER	ner 20.00	✓
	Sub Total	340.00	
	<u>Labour & Misc</u>		
	LABOUR TO FACILIATE REPAIR	550.00	300
	LABOUR TO SPRAY PAINT AFFECTED AREAS	750.00	480

Date : 09/10/2019
To : LONPAC INSURANCE BHD.

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd
SOMPO INSURANCE SINGAPORE PTE. LTD.
Certificate No : D17MTHCVE000063 Accident Date : 09/09/2019
Vehicle No : GBH-9248-C Make & Model : TOYOTA HIACE 3.0 TURBO VAN G (M) EURO

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	30.00	20
	TO REMOVE & REFIT FRONT DOOR COMPONENT	11 80.00	X
	Sub Total	1410.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts quoted are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No legal implication(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

6,285.02

Acknowledged by Repairer

Signature:

Date:

SUB TOTAL

GST 7.0 % 439.95

TOTAL 6,724.98

Remarks:

Surveyor's name: _____

Principal's name: ETHOZ Group Ltd

Survey Date & Time: _____