



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

08/10/2019

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP111

Xiao Tong

Accident date: 08/10/2019

Estimated repair cost for vehicle no: SKB6637H MERCEDES GLA180 1.6 A '18

CHASSIS: WDC1569422J444870

S/n	Qty	Items	U/price	Amount	
1	1	Front Bumper <i>torn</i>		\$1,610.00	✓
2	10	Front Bumper Clip <i>new</i>	\$8.00	\$80.00 30	
3	1	Front R/H Bumper Side Retainer <i>new</i>		\$38.00	✓
4	1	Front R/H Bumper Sensor <i>new</i>		\$236.00	+
5	1	Front R/H Headlamp <i>lt</i>		\$2,635.00	✓
6	1	Front R/H Headlamp Lower Bracket <i>new</i>		\$84.00	+
7	1	Front R/H Fender <i>dent</i>		\$875.00	✓
8	1	Front R/H Fender Cowling <i>torn</i>		\$209.00	✓
9	8	Front R/H Fender Cowling Clip <i>new</i>	\$8.00	\$64.00	✓
10	1	Front R/H Fender Protector <i>lt</i>		\$286.00	✓
11	8	Front R/H Fender Protector Clip <i>new</i>	\$8.00	\$64.00 20	
12	1	Front R/H Rim <i>lt</i>		\$1,060.00	✓
13	1	Front R/H Tyre <i>not new</i>		\$380.00	+
14	1	Front R/H Side Mirror Assembly <i>Damaged</i>		\$1,682.00	✓
15	1	Front R/H Door <i>Repair</i>		\$1,825.00	+
16	2	Front R/H Door Hinge	\$109.00	\$218.00	+
17	1	Front R/H Door Lock		\$480.00	+
18	1	Front R/H Door Weather Strip		\$375.00	+
19	1	Front R/H Door Inner Trim Board		\$1,135.00	+
20	1	Front R/H Door Power Window Motor		\$660.00	+
21	1	Front R/H Door Window Regulator		\$705.00	+
22	1	Rear R/H Door <i>Repair</i>		\$2,010.00	+
23	2	Rear R/H Door Hinge	\$109.00	\$218.00	+
24	1	Rear R/H Door Lock		\$475.00	+
25	1	Rear R/H Door Weather Strip		\$375.00	+
26	1	Rear R/H Door Inner Trim Board		\$1,135.00	+
27	1	Rear R/H Door Power Window Motor		\$660.00	+
28	1	Rear R/H Door Window Regulator		\$705.00	+

29	1	R/H Rocker Panel	New	\$1,495.00	X
30	1	R/H Rocker Panel Side Skirt	New	\$592.00	X
31	12	R/H Rocker Panel Side Skirt Clip	New	\$8.00	\$96.00 X

8509

765810

Subtotal :- \$22,462.00

Labour charges

To remove & refit cushion & trim board	\$380.00	X
To remove & refit front R/H door, lock, rubber, glass, regulator window motor & trim board	\$280.00	X
To remove & refit rear R/H door, lock, rubber, glass, regulator window motor & trim board	\$280.00	X
To remove & refit ^{front} reverse sensor	\$100.00	X
To reset computer	\$380.00	X
To check wiring	\$100.00	³⁰
Tuff kote	\$150.00	X
Panel beating	\$1,600.00	⁶⁰⁰
Spray painting	\$1,600.00	¹⁰⁰⁰

Subtotal :- \$4,870.00

Total:- \$27,332.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total 840810

1/8: 7.5K.

06 Days.

7.5K.

66 Days.