

VOLKSWAGEN CENTRE SINGAPORE

17 Tuas Avenue
Singapore 639176
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page 1/2

Company
INDIA INTERNATIONAL INSURANCE
64 CECIL STREET
#04-05 IOB BUILDING
Singapore 049711

Customer Details:
Mr
KEMP
ADRIAN DANIEL
7K TONG WATT ROAD
Singapore 238021

Document no.
Document date
Customer no.
Customer GST-ID
Dealer
Job order number
Job order date
Service Advisor

08-10-2019
5211000972
198703792K
39999
2019002274/ 1
08-10-2019
EDMUND, HUI HUANG
GOH

License plate	Model code	First registration	VIN	Model	Mileage
SKZ5653R	AM14HZ	27-01-2016	WVWZZZAUZGW560083	Sportsvan 1.4HLBMT 92 TSI D7F	46,723

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
	Diagnostic and Programming	1	pcs.	480.00	#1	480.00	513.60
	Check Short Circuit / Harness Repair	1	pcs.	280.00	#1	280.00	299.60
510807417M GRU	Cover For Bumper Primed	1	pcs.	1,090.69	#1	1,090.69	1,167.04
5G6807568D 9B9	Rear Diffusor Satin Black	1	pcs.	277.23	#1	277.23	296.64
5G9807305E	Bumper	1	pcs.	572.31	#1	572.31	612.37
510807863A	Attachment Strip	1	pcs.	58.98	#1	58.98	63.11
510807393A	Guide Piece (BUMPER GUIDE LH)	1	pcs.	34.51	#1	34.51	36.93
510807394A	Guide Piece (BUMPER GUIDE RH)	1	pcs.	34.51	#1	34.51	36.93
510807393C	Guide Piece (BUMPER BRACKET LH)	1	pcs.	34.51	#1	34.51	36.93
510807394C	Guide Piece (BUMPER BRACKET RH)	1	pcs.	34.51	#1	34.51	36.93
510919397	Sensor Bracket	1	pcs.	13.79	#1	13.79	14.76
510919491	Sensor Bracket	1	pcs.	12.15	#1	12.15	13.00
510919491A	Sensor Bracket	1	pcs.	12.15	#1	12.15	13.00
510919492A	Sensor Bracket	1	pcs.	12.15	#1	12.15	13.00
510919492	Sensor Bracket	1	pcs.	12.15	#1	12.15	13.00
510919398	Sensor Bracket	1	pcs.	13.79	#1	13.79	14.76
D 822150A1	Bonding Agent For Plastic	1	pcs.	56.90	#1	56.90	60.88
D 180KU2A1	2k-Plastic Adhesive	1	pcs.	74.29	#1	74.29	79.49
5Q0919133 704	Seal Ring Grey	4	pcs.	1.63	#1	6.52	6.98
5Q0919275B GRU	Sensor Primed	4	pcs.	164.62	#1	658.48	704.57
	LABOUR	3	pcs.	840.00	#1	2,520.00	2,696.40
	Spray Painting	3	pcs.	800.00	#1	2,400.00	2,568.00

Quotation valid till 15-10-2019

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	760.00	7,929.62	7%	608.27	8,689.62	9,297.89
Total	760.00	7,929.62		608.27	8,689.62	9,297.89

Customer

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Tanpin 97495249
WP 11/10/19C100m
Service Advisor
Resurvey before paint
03 days
Tanpin 97495249