

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5863H**AAD1910-065***Not Withheld
11 Sep \$2400h*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

09 OCT 2019

SHC 5863H

VF1ABL15AUC281486

RENAULT

LATITUDE

7.10.19

III

16/3/2015

PART

1	BUMPER COVER FRT
1	BUMPER SPOILER FRT
1	BUMPER ABSORBER FRT
1	BUMPER RETAINER FRT RH
1	BUMPER SUPPORT FRT
1	BUMPER UNDERTRAY FRT
1	BUMPER GRILLE LOWER FRT
1	BUMPER FOG LAMP GRILLE RH
1	BUMPER BEAM FRT
1	HEADLAMP RH
1	HEADLAMP PANEL FRT RH
1	FENDER PANEL FRT RH
1	WHEELARCH FRT RH
1	FENDER BRACKET LOWER RH
1	FENDER INSULATOR RH
1	TOW COVER FRT
1	FRONT BRACE PANEL
1	RADIATOR GRILLE
1	RADIATOR GRILLE BADGE 'RENAULT'
1	RADIATOR GRILLE FRAME
1	FRAME FULL SUPPORT PANEL
1	FRAME FULL SUPPORT BRACKET
1	BONNET
1	BONNET INSULATOR
1	BONNET STRUT RH
1	BONNET HINGE RH
1	BONNET LOCK

LIST

\$	Bu	747.20	✓
\$	SL	344.70	X
\$	SL	394.68	X
\$	0.18	101.40	✓
\$	SL	10.70	X
\$	SL	292.50	X
\$	SL	147.00	X
\$	SL	207.21	X
\$	R	663.70	X
\$	msm	743.60	✓
\$	R	128.30	X
\$	B	437.10	✓
\$	Tn SL	191.40	✓
\$	SL	11.80	} X
\$	SL	66.30	
\$	SL	60.90	
\$	R	177.22	
\$	SL	969.90	
\$	SL	225.36	
\$	SL	686.00	
\$	SL	592.70	
\$	SL	41.60	
\$	R	1,312.70	
\$	SL	294.30	
\$	SL	53.30	
\$	R	237.40	
\$	R	152.80	

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5863H**AAD1910-065**

1	BONNET CABLE	\$	P _L	55.20	} X
1	BONNET CABLE COVER	\$	P _L	80.60	
1	BONNET SEAL OUTER	\$	P _L	83.20	
1	BONNET SEAL INNER	\$	P _L	70.10	
1	LOWER ARM RH L70Y	\$	P _L	192.70	
1	KNUCKLE ARM RH L70Y	\$	P _L	481.50	
1	ABSORBER FRT RH L70Y	\$	P _L	203.50	
1	DRIVESHAFT RH	\$	N	1,355.70	
1	STABILIZER BAR FRT	\$	P _L	427.90	
1	WIPER RESERVOIR MOTOR	\$	P _L	82.60	
1	WIPER RESERVOIR	\$	P _L	179.60	
1	WIPER RESERVOIR NECK	\$	P _L	29.30	
1	DOOR PANEL FRT RH	\$	N	2,844.66	
1	DOOR MIRROR ASSY RH	\$	P _L	1,483.40	
TOTAL		\$		16,861.73	
10%		\$		1,686.17	
		\$		15,175.56	

Special Nett

1	BUMPER CLIP FRT	\$	Ni	66.00	✓
1	BUMPER BRACKET CLIP FRT RH	\$	Nn	12.00	X
1	BUMPER SUPPORT CLIP FRT RH	\$	Nn	10.50	X
1	BUMPER GRILLE LOWER CLIP	\$	Nn	69.00	X
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	Nn	70.00	X
2	FRAME FULL SUPPORT PANEL NUT	\$	Nn	20.00	X
2	FRAME FULL SUPPORT PANEL STUD	\$	Nn	30.00	X
1	WHEELARCH CLIP FRT RH	\$	Nti	30.50	} X
1	FRONT RIGHT TYRE	\$	Ph	300.00	
1	FRONT RIGHT TYRE RIM	\$	Ph	380.00	
1	FRONT WHEEL RIM COVER	\$	Sh	50.00	
1SET	Front licence plate with holder	\$	Sh	80.00	
1SET	RADIATOR GRILLE SCREW	\$	Sh	16.00	
1SET	RADIATOR GRILLE FRAME CLIP	\$	Nn	52.00	
1	WINDSCREEN SEALANT	\$	Nn	109.20	
1	FRONT WINDSCREEN MOULDING	\$	Nn	120.00	
1	FRONT WINDSCREEN INNER SPONGE SEAL	\$	Nn	100.00	

Trans-cab Auto Services Pte Ltd**AAD1910-065**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5863H

6	BONNET INSULATOR CLIP L70Y	\$	7.30	✓
2	BONNET CABLE COVER SCREW L70Y	\$	10.85	✓
1	FRONT DOOR STICKER 'Trans-Cab'	\$	80.00	✓
1	FRONT DOOR STICKER 'Classic'	\$	80.00	✓
TOTAL		\$	1,693.36	

TOTAL PARTS	\$	16,868.91
--------------------	-----------	------------------

LABOUR

Putty and spray painting of the affected portion.	\$	6,000.00	4401
To Check Electrical Lighting Concerned.	\$	170.00	201
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	6,000.00	4001
To rust-proofing of the affected areas.	\$	170.00	301
To transfer of front windscreen glass to facilitate bodywork repair.	\$	170.00	✓
To transfer of front fender fittings, attachment and perform water seepage test.	\$	380.00	✓
To transfer of bonnet fittings, attachment and perform water seepage test.	\$	380.00	✓
To check steering geometry and computer wheel alignment	\$	220.00	✓
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	380.00	✓

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5863H**AAD1910-065**

To transfer of front bumper fittings, attachment
and perform water seepage test. \$ *nn* 380.00 X

To transfer of tire, rim and on wheel balancing. \$ *nn* 170.00 X

To remove and refit interior fittings, trimings,
garnish, fittings and other, to enable repair. \$ *nn* 380.00 X

Labour charge to mount and dismount vehicle on
jig bench, to facilitate repair. \$ *nn* 380.00 X

To transfer of front door fittings, attachment and
perform water seepage test. \$ *nn* 380.00 X

TOTAL \$ 15,560.00

Over All Total \$ 32,428.91

LUMP SUM (REPAIR DAY)**20 DAYS***2 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: