PRIYA

CC4/III19017828/Dpa3

EKK:

••	, ,		~		_	•	~	-	~	_
	A	c	c	16	3	N	N	(F	NI	,
	-/-		72	*,	4	-	1.8		4.5.4	-

Surveyor:

BRYAN

DOI: 09/10/19 18:45

Date / Time: 09/10/2019

Registered in Merimen: 09/10/2019

Pre-assi	ign.	CCU	/ FTE

-	Insured Vehicle No.	SHD 4085N		Claim No.		(^
	Name of Insured	COMFORT TRANSPORTATION PTE LTD			HYUNDAI SONATA	
	Insured Tel No. Excess Sec II :S\$ Is driver the owner?	(YES / NO)	D.O.A : 06/10/2019 04:00 Nature of Accident :	Place of Accident :	OTESVEVE	AU AVE NORTH TWDS NEWTON CIRC
	If NO, Driver Name / Driver Tel No.	Age: CHUA YONG	A STATE OF THE PARTY OF THE PAR	Ol GIA REPORT: Insured Liability:	YES / NO : 7	TP GIA REPORT: YES / NO Final ? Yes / No
	SHD 6718H INSRS: WSP: CHUNNI Tel Liability:	INSR WSP Tel: Liabii	ity :	INSRS: WSP; Tel: Liability:		INSRS: WSP: Tel: Liability:

3.00		
Dute/Time		
	SHD 6718H - CS/FCI19007263/Kqd3n2; DOA: 19	
	 CS/FCI18006914/Avbn2; DOA; 26/. 	2/18 Non-Reporting ltr (1st):
	- CS/FCI17024620/Avd3e2; DOA: 2	
	SHD 4085M - NS/INC19014637/K1sf3s2; DOA: 19	9/8/19 Non-Reporting by (Final):
	 CS3/III19011709/Gvd3e2-1; DOA: 2 	8/6/19 Notification for (if non-pickup):
		Call Of:
2444-	- Pls fer News	After call lir to OL
(V)		Documentation Check List: Handler Typist
74144_	files : By a + Prac.	Notification Itr (if non-pickup)
	,	After call ltr to OI
		Autherisation To Act:
07111/2029	Thursday 110 Ctool- vit- 8 day	Release Voucher:
2111/201	Junepul 4/5 6700/- vit- 8 day	Final Repair Bill
		Car Rental Invoice:
12/11/16	File -) Su li to sure W.	Towing Invoice
		LTA (CIA)
10/12/10-	File pass to USP to close	Modical Bill:
(8 15 1. L	FILE PASS OF CALL TO CANA	PBE >
		Mand of Reject Instruction:
		LOD
		Payment Breakdown Form:
RELIMINARY ADVICE	Date/Time: Sent By:	Post-Repair Photos:
		Others:
NALIZATION	Date/Time: Confirm with:	Confirm by:
epair Cost:	SS (days) Reduction: 9	Email Call
NAL SETTLEMENT	Date/Time: VIV Confirm with William	Email Call
nal Liability:	14 [U (Agreed / A Coyled) BOLA S/N No. 1	If NO or B 28, Ass. Liu:
rpair CostU61	ss 7169.W	
oss of Rental (LOR):	ss 996.03 (9 days) X # 1(0.67	CORN RENT
ss of Use (LOU):	SS — (S — x — days)	TOUR A POLY
ss of Income (LOI):	88360. W(840 x 9 days)	(S) (2) (1) (1)
R only LOU only	LOR + LOU LOR + LOT [Tick only one]	- 11
A/LTA Search	55	X
edical:	ss —	1) Claim status: Kormal/Reject/Private Settle
sbursement:	SS - (e.g. Tow/ Independent)	2) Report Format: 1
gal Cost	ss -	3) Survey fee \$600-00
otal:	SS 85) 5. UZ Global Sum S\$: 85W-42	
NAL PAYMENT	Date/Time: Confirm with:	Email Call
ryee 1:	SS 85W,W Name 1: Chunni Mot	for work Pte Utd
ryec 2: (Strike if N.A.)	SS Name 2:	AT A MARKET MANAGEMENT
avec 3: (Strike if N.A.)	SS Name 3:	

		ASSIGNMENT		COE 30)	15 mm
	Was control of the co	3	RIFA CHE	H YI Ragn JOIS	
rom:	Date:			Lorry Taxi / Prime Mover	
stimated Cost.			Trailer or		
DITPIWS/TPRES/ODRE	S / EVA / INV / MV	107.5517	Huundai.	140 Smb. 50 11	18-
Mispect Vehicle No.			-	A/C: Insured / Std	
t Workshop m/s		Colour	Dive 731100	T/Radio: Insured / Str	
1		Sp.Reading	734205		II MII NA.
nured:		Eng/No:		4377406	1700
folicy No.		C/No:		B414 MF40	6470
Staims No.		>	Fair / Poor / Bu		
um Insured:	Excess:	/	dor / Jammed / Leak	100.00	
(Client's Record)		3	der / Jammed / Leak		
Aske of Veh:		Modi: (Nil)	/ S/Rim / STD A/Rim		
	/	Tyre Size:	F: C	205 60 R 16	
(Policy Condition)	(2		R:		
temark: The veh had commen	iced its	N/S O/S BS/DUN/E	XNOVA/GY/FS/LI	ZA / MIC / OHTSU / PIR / SU	JMI /
repair at the time of It	inspection.	TOYO / YO	KO or -	Hankook	
Sal. or Market Value.		Front		Rear	
DAC Accident Room:	Consistent?: Yes or I	No R/Bal.	S, mm	R/Bal.	mm
SIA / PR Seen:	Consistent? : Yes or I	No L/Bal	S mm	UBal. S	1000
Est. Repairs: 8 6 d	days Res.: Yes or	No D.O.A. 06	5/10/2019	0.0,1 09 10	219
Lum Sum: 20 1	% 3 Val.: Yes or	No Survey held	et Chur	in AMK	
04 DEU DED 041	une	Des. of Dam	ages : Frt / Rear / C	D/S / N/S / U/C / Rooftep	of
CA / REV / REP. / 24 h	HRS Vei	hicle: IN / OUT	From HIS	3	
Date: Person t	Contacted:	The U/C	/ Chassis frame / E	Body Structure affected due	to collision
	3HD 4085M				1.5
Date / Time Action / Instr	S POT 1 1 / (-1/1/90) - 1/1				
Date / Time Action / Instr	7115 4005 MI			P 7	
Diste / Time Action / Instr		1001- vitu 8 d	1	8411,46/7	37/1
711/200 Jina			(Red \$1	85U1.98/7	37/1
711/2ma Jina	yn 2/5 67		(Red \$ 1	8541,94 7	37/1
7)11/2000 File Fand Inc	: Prell, Report	Days Of Re	(Red \$ 1		37/1
Till 2004 Time File Fana Int	: Prell, Report	Days Of Re Resurvey M	(Red \$ 1	Survey Fee:	37/1
7)11/2000 Jina	: Prell, Report	Days Of Re Resurvey h	Peel \$ (Survey Fee:	37/1
Till 2004 Time File Fana Int	: Prell, Report	Days Of Re Resurvey M Add Fee: Site	pair:	Survey Fee: Transportation: J_S+RS_SI	37/1
Till 2004 Jina Designation File Fana in 7	: Prell, Report	Days Of Re Resurvey M Add Fee: Site	pair: lo. of Trip:	Survey Feet Transportation J. S.+RS. St. Frinklit	37/1

CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD 6718H

MAKE :

DATE: 7.10.2019

TEL: 6542 5119

HIVINDAT M FAY - 6542 6039 INDIA

DEL	: HYUNDAI i40	_	: 6542 6039	INDIA	
Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Bonnet 15+			\$ 2,265.90	_
	Bonnet Hinge (LH/RH) NA		\$ 41.00	\$ 82.00	×
	Bonnet Moulding Had MF			\$ 126.25	X
	Bonnet Lock MAI			\$ 36.90	X
	Bonnet Absorber NLI		S 58.10	\$ 116.20	×
	Bonnet Insulator NA			\$ 196.50	×
	Bonnet Insulator Clips N4			\$ 8.40	X
	Radiator Grille mand CANC			S 251.00	
	Radiator Grille H Emblem Nec			S 27.50	_
	Front Bumper Cover 1914			S 544.50	_
	Front Bumper Sponge 184			\$ 99.20	_
	Front Bumper Reinforcement 14+			5 402.10	
	Front Bumper Grille (LH) by ten Jasladged			\$ 41.60	-
	Front Bumper Centre Grille Clack de Tonel			\$ 178.60	
	Front Bumper Centre Grille Top Garnish,LH (\$ 80.00	_
	Front Bumper Bracket Top (LH) rul			The state of the s	X
	Front Bumper Bracket (LH) hybku		}	\$ 24.60	سا
	Headlamp Support Top Cover 141			\$ 222.60	×
	Headlamp Support Panel Assy bakes 1		0	S 907.40	
	Headlamp (LH/RH) N/3 broker 0 5 NN		\$ (1,388.00	S 2,776.00	4
	Front Fender (LH) Dendth			\$ 566.30	
	Front Fender Apron Panel (LH) Dendik			\$ 637.00	
	Front Fender Shield (LH) Tork			\$ 174.90	
	Air Cleaner Assy Glade NA			The second secon	-
	Air Cleaner Bottom Assy Hal			\$ 325.00	×
	Front Wheel Rim (LH) NA			\$ 325.30	×
	Front Wheel Hub Cap (LH) Nat			S 107.10	×
	Front Wheel Bearing HA			\$ 540.50	×
	Front Shock Absorber (Assy) (LH)			\$ 342.20	
	Front Shock Absorber Mounting (LH)			\$ 108.80	
	Front Drive Shaft (LH) NAM			\$ 1,030.80	
	Rack & Pinion Assy NA		9.8	\$ 969.60	1
	STG Tic End NW	PhAO	teken	S 62.60	J
	Front Suspension Lower Arm (LH) Nat	to	chede.	\$ 529.30	Ĵ
	Knuckle Arm (LH) N4	4	chede photo show notest on	\$ 552.00	5
	Engine Under Cover Net	Scere	SNOW SALL	\$ 334.60	5
	Engine Crossmember Nu	20.00	notest on	5 2,094,40	5
	Inter Cooler has	Y 10 1	i cim.	S 1,032.50	Ì
	Inter Cooler November (2 BCS)	whee	~	S 1,032.50	S
	Inter Cooler Mounting (2 PCS) AU ABS Sensor, LH Nu		7588.60		7
			1500 00	75.000	15
	Wiring-Engine Nowing broken from		7588.60 6870.88	\$ 3,326.00	7
	Electric Power Steering		0.0	\$ 3,641.00	X
	SUB TOTAL			\$ 25,488.05	
	LESS 20%			\$ 5,097.61	
	DISCOUNTED TOTAL			\$ 20,390.44	

SHD 6718H

		SHD 6718H		
Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Number Plate No.			\$ 25.00 \$ 30.00
	Front Fender Advertisement Logo (LH)			\$ 100.00
	Front Tyre (LH) NN		600.00	\$ 216.00
				\$ 371.00
	Labour Charge			
	Panel Beating			\$ -1,500.00
	Spray Painting Charge			\$ 1,000:00
	Wiring Charge			\$ _50.00
	Tuff Kote			\$ 100.00
	Towing Charge			\$ 50.00
	Remove/Refix Undercarriage (FRT)			\$ 200.00
	FRT Wheel Alignment		12	\$ 120.00
	Remove/Refix Aircon & Refill Gas		1750.00	S 150.00
	Remove/Refix Dashboard		35%	\$ 450.00 \$ 180.00
	Remove/Refix Fuse Box			\$ 180.00 \$ 200.00
	Re-set Frt ABS System			S 480.00
	Diagnostic & Resetting To Erase Fault Code			3 480.00
	TOTAL LABOUR			\$ 4,480.00
	ESTIMATE TOTAL			\$ 25,241.44
	09/10/2019 C 1330m		8420.88	
	MA Autur		LIS 6700 -	
	= + Smu & Suys			
	- 15mm & Buys			
	2KK Ando			
	017 1000	LIO	Auto Consultants her	ce notify
	3	the + To	Repairer of the follows esurvey before/after spray	eg: painting
		* To	display damaged part(a) du ets prices are subject to con	ing resurvey
		*Th	aid party survey is on a "Wit	out Prejudice" basis
	/	* No	Regal modification(s) is all	wed
		* Si	oplementary item(s) must be subject to final approval from	resurveyed and Insurance Company
			nowledged by Repairer	200
			Nume:	
		Date		

be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

ADDRESS

Home Tel.:

VIN:

Registration: SHD 6718 H

Technician:

Mileage:

734205

Time Printed 9.10.19 2:01 PM

HYUNDAI 140

Front : Left

Actual	BEFORE	Specified Range
-0°36°		-3°00' 3°00'
3°46'		-0°19' 5°41'
2"36"		-1°30' 1°30'
17°08'		
16°32'		

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Actual	BEFORE	Specified Range
-0°06°		-3°00, 3°00,
4"17"		-0°19' 5°41'
-0°10'		-1°30' 1°30'
14°50'		
14°43'		

Front: Right

Front

Cross Camber Cross Caster Cross SAI Total Toe Cross Turn Diff.

Actual	BEFORE	Specified Range
-0°29'	1	-3°00' 3°00'
-0°30°		-3°00' 3°00'
2°18'		-3°00' 3°00'
2"26"		-3°00, 3°00,

Rear: Left

Actual BEFORE Specified Range
-1°01' -3°30' 2°30'
-0°12' -1°30' 1°30'

Camber Toe

Rear: Right						
Actual	BEFORE	Specified Range				
-0"47"		-3°30' 2°30'				
-0°01"		-1°30' 1°30'				

Rear

Cross Camber Total Toe Thrust Angle

Actual	BEFORE	Specified Range
-0°14'		-3°00, 3°00,
-0"12"		-3°00, 3°00,
-0°05°		-3°00' 3°00'

Nivitha (LKK Auto)

17828/6

From:

Motor Claim - III < motorclaim@iii.com.sg>

Sent:

Wednesday, 9 October 2019 11:16 AM

To:

Admin-D (LKKAuto) Gabriel Wee: Sherini Pillai

Subject:

RE: Accident involving veh no: SHD 6718H & SHD 4085M on 06.10.19

Attachments:

07102019165408.pdf

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SHD6718H and let us have your report urgently.

This claim will be handled by Ms Priya.

p: Lynn

*Kindly upload this survey request email to merimen.

T: 11.37a.m

Thank You.

V:14

EV

Best Regards, Gabriel Wee



64 Cecil Street; #05 - IOB Building

Singapore 049711

Tel: 6347 6100, Ext - 248

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]

Sent: 09 October, 2019 10:48 AM

To: Motor Claim - III < motorclaim@iii.com.sg>

Cc: Gabriel Wee <Gabriel@iii.com.sg>; Sherini Pillai <sherini@iii.com.sg>

Subject: RE: Accident involving veh no: SHD 6718H & SHD 4085M on 06.10.19

Dear Sir/Mdm,

Kindly assist on below matter.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: <u>assignments@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933) From: Chunni Motor [mailto:chunnimotor@gmail.com]

Sent: Wednesday, 9 October 2019 10:41 AM

To: assignments@lkkauto.com

Cc: Bryan Ang (LKKAuto) <bryanang@lkkauto.com>

Subject: Fwd: Accident involving veh no: SHD 6718H & SHD 4085M on 06.10.19

----- Forwarded message -----

From: Motor Claim - III <motorclaim@iii.com.sg>

Date: Tue, Oct 8, 2019 at 10:53 AM

Subject: RE: Accident involving veh no: SHD 6718H & SHD 4085M on 06.10.19

To: Chunni Motor < chunnimotor@gmail.com >

Dear Sir / Mdm,

We acknowledge receipt of your email.

We proprose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,

Gabriel Wee



64 Cecil Street; #05 - IOB Building

Singapore 049711

Sent: 08 October, 2019 10:45 AM
To: Motor Claim - III < motorclaim@iii.com.sg>
Subject: Re: Accident involving veh no: SHD 6718H & SHD 4085M on 06.10.19
Dear Sir,
Dear on,
We appoint LKK Auto Consultants.
Thank you
Regards,
regards,
Chunni Motor Work P/L
On The Oct 8 2019 at 10:36 AM Motor Claim. III (materials)
On Tue, Oct 8, 2019 at 10:36 AM Motor Claim - III < motorclaim@iii.com.sg > wrote:
Dear Sir / Mdm,
We acknowledge receipt of your email.
The deline receipt of your entail.
We proprose using one of the following motor surveyors:
LKK Auto Consultants Pte Ltd Vicom Assessment Centre Pte Ltd
Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,

Gabriel Wee



64 Cecil Street; #05 - IOB Building

Singapore 049711

Tel: 6347 6100, Ext - 248

From: Chunni Motor [mailto:chunnimotor@gmail.com]

Sent: 08 October, 2019 9:59 AM

To: Motor Claim - III < motorclaim@iii.com.sg>

Subject: Fwd: Accident involving veh no: SHD 6718H & SHD 4085M on 06.10.19

----- Forwarded message -----

From: Chunni Motor < chunnimotor@gmail.com >

Date: Mon, Oct 7, 2019 at 5:05 PM

Subject: Accident involving veh no: SHD 6718H & SHD 4085M on 06.10.19

To: Motor Claim - III <motorclaim@iii.com.sg>

Dear Sir/Mdm.

We refer the above mentioned matter.

We enclosed herewith the relevant documents for your necessary action.

In line with the new protocol, kindly provide us with the list of surveyors on your panel for assessment of the damaged accident taxi involved.

Kindly survey at AMK Autopoint, Soon Hock Motor,#01-05/06.

Should you have any queries, please do not hesitate to contact Ms Lynn or Ms Irene at 65425119 or 6542 7162

Thank you for your kind assistance.

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.


Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission

or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K



This email has been checked for viruses by AVG antivirus software. www.avg.com

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment. India International Insurance Pte Ltd.

Registration No. 198703792-K

Claim Audit

- 4	AUDIT TRAIL			
λo,	0.6	Audit	Remarks	[A]
1	09 Oct 2019 15:54	Clm Dtl Modified	Claimant's Name: -> COMFORT TRANSPORTATION PTE LTD. Claimant's ID: -> 19930382 1R.	
2	09 Oct 2019 15:54	Clm Veh Model Changed	(205325) HYUNDAI 140 1.7 L CRDI AT ABS AIRBAG 4DR (A).	(A) HOW MEI KWA
3	09 Oct 2019 15:54	Clm Created	Reg No: SHD6718H, Acct Date: 2019/10/06. Claim Type: TP. Insurer: India International Insurance Pte Ltd (HQ), TP Insurer: MS First Capital Insurance Ltd (HQ), Workshop: Chu nni Motor Work Pte Ltd (HQ)	HOV MEI KWA
4	09 Oct 2019 15:54	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] HOV MEI KWA
5	09 Oct 2019 15:54	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/10/18	HOV ME: KWA
5	09 Oct 2019 15:54	Adj Mandate Set	Approved: 0.00.Reinsp: Adj decides.	HOV ME KWA
7	09 Oct 2019 15:54	Label Added	(30653):Direct Settlement.	ME KWA
8	09 Oct 2019 15:54	Adj Adjuster Assigned	[None] -> BRYAN TANI	HOV ME KWA
9	26 Oct 2019 08:47	Adj Mandate Request	Cur.Req:0.00:PODS Liability: 100% Remark: Insured driver made U-turn and collided with third party.	CHE HSIA TON
10	29 Oct 2019 11:58	Adj Next Rpt Changed	Next Rpt:Final Rpt,Due Date:2019/10/18	[I] Priv
11	29 Oct 2019 11:58	Adj Mandate Set	Approved:0.00,	[I] Priy

■ Date To ■ Audit Type None ₹ Go Date From

ACTIVITY

No record

ferimen Billing for this case - Transaction History									
		BH Type:	ACC TYPE	WENE TO SERVE					
2308045	10 Oct 2019 08:30:55	TP Case (Insurer)	Motor	LKK Auto Consultants Pte Ltd	India International Insurance Pte Ltd (HQ)	SHD6718H	SHD4085M	11.77	

Hsiao Tong (LKKAuto)

From:

Hsiao Tong (LKKAuto)

Sent:

Friday, 29 November 2019 5:36 PM

To:

Manivel Priyadarshini

Subject:

Your Ref: MCT19100154// LKK REF: CC4/III19017828/Dpa3 [ACCIDENT INVOLVING

SHD 4085M(III) AND SHD 6718H ON 06/10/2019]

Attachments:

SHD6718H vs SHD4085M-TP VIDEO.mp4

Hi Priya,

Attached is a copy of video from third party for your easy reference.

We have seek mandate thru Merimen.

Kindly let us have your approval in Merimen.

Best Regards,

Hsiao Tong, Chew (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Claim Audit

1	AUDIT TRAIL			
(0.	On	Audit	Remarks	Ву
			97.5000	[A]
1	09 Oct 2019	Clm Dtl Modified	Claimant's Name: -> COMFORT TRANSPORTATION PTE LTD, Claimant's ID: -> 1993038	HO
	15:54		21R.	KWA
				[A]
	09 Oct 2019	AND THE PROPERTY OF THE PARTY O		HOV
2.	15:54	Clm Veh Model Changed	(205325) HYUNDAI 140 1.7 L CRDI AT ABS AIRBAG 4DR (A),	ME
				KWA
			Reg No: SHD6718H. Acct Date: 2019/10/06. Claim Type: TP. Insurer: India Internation	[A]
3	09 Oct 2019	Clm Created	al Insurance Pte Ltd (HQ). TP Insurer: MS First Capital Insurance Ltd (HQ). Workshop:	HOV
_	15:54		Chunni Motor Work Pte Ltd (HQ)	KWA
			PUREST TRANSPORT ASSESSMENT NEEDS	[A]
	09 Oct 2019		2 1 1522	HOV
4	15:54	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	ME
	410-510-11			KWA
				[A]
5	09 Oct 2019	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/10/18	HOV
	15:54			KWA
				[A]
	09 Oct 2019			HOV
6	15:54	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	ME
	-213.1			KWA
				[A]
7	09 Oct 2019	Label Added	(30653): Direct Settlement.	HOV
-	15:54	Label Added	(30033): Direct Settlement.	ME
				KWA
	02020202021			[A]
8	09 Oct 2019	Adj Adjuster Assigned	[None] -> BRYAN TANI	ME
	15:54			KWA
				(A)
01	26 Oct 2019		Cur.Reg:0.00:PODS Liability: 100% Remark: Insured driver made U-turn and collided w	CHE
9	08:47	Adj Mandate Request	ith third party.	HSIA
				TON
10	29 Oct 2019	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/10/18	[1]
	11:58	Auj Heat Apt changes	THESE TYPEST THOSE TO SEE THE SECOND STATE OF	Priy
ü	29 Oct 2019	Adj Mandate Set	Approved: 0.00.	[11]
	11:58			Priy
				JOAN
2	20 Nov 2019	Adj Rpt Initiated		LEE
	12:46	and whe summer		KHAN
				MIN
				[A]
	20 Nov 2019			JOAN
3	20 Nov 2019 12:46	Clm Dtl Modified	Insured Name: -> -, Insured ID: -> -:	LEE
	PARTIES.			KHAN
				[A]
	TIME PROTES			JOAN
4	20 Nov 2019	Clm Dtl Modified	JP3 Reg. Date: -> 2015/04/09.	LEE
	12:46	beautiful to the state of the s	THE PROPERTY OF STREET AND THE PROPERTY OF THE	KHAN
				MIN
				[A]
	20 Nov 2019			JOAN
5	12:46	Clm Details Notified		LEE
				MIN
			Cur.Req:8525.03:PODS Liability: 190% *Quantum: (a)CORw/GST: \$7,169.00 + (b)LOR	[A]
	29 Nov 2019		(9days x \$110.67):\$996.03 + (c)LOI(9days x \$40.00):\$360.00 = Total: \$8,525.03 *Ve	CHE
16	17:34	Adj Mandate Request	hicle Model: Hyundai I40 (1685cc) *8 recommendation repair days +15unday = 9days	HS1A
			*For	TON
-			► Date To	

_			_	_			-
Α.	c	т	ľ	v	т	•	v
_	•		*	•	•		

No record

Bill-ReCNo	Bill:Dirte	BILLLAND	-Acc Type	Acc Name	Co Name (Stanch)	Ref. t	Ref 2	Betterung
2308045	10 Oct 2019 08:30:55	TP Case (Insurer)	Motor	LKK Auto Consultants Pte Ltd	India International Insurance Pte Ltd (HQ)	SHD6718H	SHD4085M	11.77
2351198	20 Nov 2019	OD/TP Case	Mator	LKK Auto	LKK Auto	SHD6718H	SHD4085M	11,77

Print Received Message

This mail is associated with:

*SHD6718H (MCT19100154) [SHD4085M] TP

COMFORT TRANSPORTATION PTE LTD Oct 6 2019 4:00AM

[-] Chunni Motor Work Pte Ltd

From	India International Insurance Pte Ltd (HQ) (III_SG), sent on 03/12/2019 15:04 PM.
To	LKK_HQ
Subject	Alert - Adj Mandate Approved (S\$8525.03) - SHD6718H - Claim Handler: Priya

Approved:8525.03.

Hsiao Tong (LKKAuto)

From: Chunni motor Work <chunnimw@yahoo.com.sg>

Sent: Wednesday, 11 December 2019 11:06 AM

To: Hsiao Tong (LKKAuto)

Subject: Re: Your Ref: SHD 6718H //Our Ref: CC4/III19017828/Dpa3 [ACCIDENT INVOLVING

SHD 4085M(III) AND SHD 6718H ON 06/10/2019]

Your Ref : CC4/III19017828/Dpa3 Our Ref : SHD 6718 H (061019)

WITHOUT PREJUDICE

Hi Hsiao Tong,

Your email of 11-12-2019 refers.

Strictly on a without prejudice basis and without any admission of liability, we confirm settlement for our client's property damage claim (Cost of repair, GIA search fee and the Loss of rental & income during the period of repair) at a global sum of \$8,500.00.

Please note that the settlement reached is strictly for the aforesaid property damage only and is without prejudice to the relief driver of SHD 5718 H, Selambram S/O Pariannan's injury claim and other losses against your principal, M/s India International Insurance Pte Ltd and /or their insured his own solicitor.

Kindly forward us your Discharge Voucher for our client's execution as soon as possible.

Thank you and have a nice day ahead!

Best Regards William Claims Department

Chunni Motor Work Pte Ltd 10 Ang Mo Kio Industrial Park 2A #03-19 AMK AutoPoint Singapore 568047

Tel: 6483-6016 (Claims)

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.



Save the trees - Do you really need to print this e-mail?

On Wednesday, 11 December 2019, 9:35:29 am SGT, Hsiao Tong (LKKAuto) <chewht@lkkauto.com> wrote:

Your Ref: SHD 6718H Without Prejudice

Our Ref: CC4/III19017828/Dpa3
Dear Sirs/Mdm,
ACCIDENT INVOLVING SHD 4085M(III) AND SHD 6718H ON 06/10/2019
We refer to the above matter.
We propose settlement at a global sum of \$8,500.00(all-in).
Please confirm acceptance.
"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.
In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."
"Best Wishes for Merry Christmas, and Happy New Year 2020"
Best Regards,
Hsiao Tong, Chew (Ms) Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6742-3197 email: chewht@lkkauto.com fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 S(408933)

CHUNNI MOTOR WORK PTE LTD

Our Ref : SHD 6718 H (061019) Your Ref : CC4/III19017828/Dpa3 Date : 12 BEC 2019

M/s LKK Auto Consultants Pte Ltd Blk 51 Paya Ubi Industrial Park #02-25 Ubi Avenue 1 Singapore 408933

WITHOUT PREJUDICE

Dear Hsiao Tong Case Handler

ACCIDENT INVOLVING SHD 6718 H & SHD 4085 M ALONG CLEMECEAU AVENUE NORTH TOWARDS NEWTON CIRCUS ON 06-10-2019

Your email of 12-12-2019 refers.

Strictly on a without prejudice basis and without any admission of liability, we confirm settlement for our client's property damage claim (Cost of repair and the loss of rental & income during the period of repair) at a global sum of \$8,500.00.

Please note that the settlement reached is strictly for the aforesaid property damage claim only and is without prejudice to the relief driver of SHD 6718 H, Selambram S/O Pariannan's injury claim and other losses against your principals, M/s India International Insurance Pte Ltd and /or their insured through his own solicitor.

As requested, we return the attached Discharge Voucher duly executed together with the original Letter of Demand & enclosures for your onward transmission.

Kindly expedite payment and forward us your cheque for the sum of \$8,500.00 made in favour of M/s Chunni Motor Work Pte Ltd as soon as possible.

Thank you.

Yours faithfully,

For CHUNNI MOTOR WORK PTE LTD

Claims Department

Enc

...CLAIM SUBFOLDER...(Pending for Survey Report) Direct Settlement

LAIM SUB	FOLDER TRA	CKING								
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt		Adj Submitted	Ins Auth'ed	Status		
Main	09 Oct 2019 Edit Reg		09 Oct 2019 00:00 Edit Adj Rpt	5\$6,700 Edit Esti	And the second second	\$\$6,700.00 View Rpt		Report Cancel (for Survey	
	Main	1	Reference) c	aim Det	aits	Document		Snow All	
CLAIM SU	BFOLDER DE	ETAILS				[Create	d by adjuster]			
Insured:	COMFORT	TRANSPORTAT	TION PTE LTD, Co.	Reg. No.: 1	9930382	1R				
Main Claimant:	COMFOR	TRANSPORTAT	TION PTE LTD, Co	Reg. No.:	1993038	21R				
Vehicle Reg No.:	SHD671	вн			Date of I	.055: [53 Mont	019 04:00 - ;59 ths and 27 Days Fro	om LTA Reg D	ate (Man Yr))	
Claim Type	TP / MC	T19100154			Palicy/Co Note No.		MCOM0015			
Vehicle Reg. No. (Insured): SHD4085M Policy No. (Claimant): D-18088936MFSH										
					Excess:					
Repairer:	Chunni M 7162	latar Work Pte L	Ltd (HQ) Blk 10 Ang	Mo Kio Indu	strial Par	k 2A, #03-19 A	MK Autopoint, 5680	347 Ang Mo Ki	o - Tel: 6542	
Handling Insurer:	India Int	ernational Insu	rance Pte Ltd (HQ)	- Tei: 6347	6100	Handled by Pri	ya]			
Claimant's Insurer:	MS First		ce Ltd (HQ) - Tel: 6							
Adjuster:	LKK Auto	Consultants Pt	e Ltd (HQ) - Tel: 62	256-3561	[Handled	by BRYAN TA	NI] [Final Rpt	due 18/10	/2019]	
ASSOCIA	TED MAIL RE	CEIVED					Vi	ew All Cor	mpose Case Mai	
			date Approved (S\$ date Approved (S\$							
ALL ASS	OCIATED TA	sks=				View All	Search Tasks	Create New Ta	sk Complet	
Due Dat		Type Tas	k Group Subje	ct Handi	er A	ssigned By	Completed On	Create	d On Done	

Claim Documents

*SHD6718H (MCT19100154) [SHD4085M] TP

COMFORT TRANSPORTATION PTE LTD Oct 6 2019 4:00AM [COMFORT TRANSPORTATION PTE LTD] Chunni Motor Work Pte Ltd

Vid	eo		1 per	page V	W
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Prin
1	29/11/19 17:39	Video - Accident -TP	0	Load MP4	
	10001110000000		5.000	page 🔽	
-	tos/Images	Low A. A. Considerate Discussion (MD)	3 per	Thumbnail	-
No.	Relabel/Reorder 02/11/19 12:55	LKK Auto Consultants Pte Ltd (HQ) Front View Right	0	Load JPG	Ø
2	02/11/19 12:55	Front View Left	0	Load 3PG	Ø
3	02/11/19 12:58	General View	0	Load JPG	B
4.	02/11/19 12:58	General View	0	Load JPG	V
5	02/11/19 12:58	General View	0	Load JPG	8
6	02/11/19 12:58	General View	0	Load JPG	V
7	02/11/19 12:58	General View	0	Load JPG	V
8	02/11/19 12:58	General View	0	Load JPG	82
9	02/11/19 12:58	General View	0	Load JPG	Z
10	02/11/19 12:58	General View	0	Load JPG	W
11	02/11/19 12:58	General View	0	Load JPG	EZ.
12	02/11/19 12:58	General View	0	Load JPG	V
13	02/11/19 12:58	General View	0	Load JPG	82
14	02/11/19 12:58	General View	0	Load JPG	2
15	02/11/19 12:58	General View	0	Load JPG	V
16	02/11/19 12:58	General View	0	Load JPG	R
-	02/11/19 12:58	General View	0	Load JPG	R
17		General View	0	Load JPG	R
	02/11/19 12:58	General View	0	Load JPG	V
19	02/11/19 12:58	General View	0	Load JPG	E E
20	02/11/19 12:58	General View	0	Load JPG	V
21	02/11/19 12:58	200000000000000000000000000000000000000	0	Load JPG	2
22	02/11/19 12:58	General View	0	Load JPG	2
23	02/11/19 12:58	General View	0	Load JPG	12
24	02/11/19 12:58		0	Load JPG	V
25	02/11/19 12:58	General View	0	Load JPG	R
26	02/11/19 12:58	General View	0	Load JPG	2
27	02/11/19 12:58	General View	8	Load JPG	2
28	02/11/19 12:58	General View	8		12
29	02/11/19 12:58	General View			-
30	02/11/19 12:58	General View	6	Load JPG	12
31	02/11/19 12:58	General View	0		2
32	02/11/19 12:58	General View	6	Load JPG	- N
33	02/11/19 12:58	General View	0	Load JPG	- Britishee
34	02/11/19 12:58	General View	8	Load 3PG	8
35	02/11/19 12:58	General View	6	Load JPG	N N
36	02/11/19 12:58	General View	0	Load JPG	-
37	02/11/19 12:58	General View	0	Load JPG	2
38	02/11/19 12:58	General View	0	Load JPG	2
39	02/11/19 12:58	General View	0	Load JPG	12

	10		1 per page	V	2
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thum	iliand	
					2
1	02/11/19 12:58	General View	€ Load	-	82
2	02/11/19 12:58	General View	6 Load	JPG	2
3	02/11/19 12:58	General View	E Load	JPG	82
14	02/11/19 12:58	General View	6 Load	JPG	82
15	02/11/19 12:58	General View	€ Load	JPG	V
16	02/11/19 12:58	General View	■ Load	JPG	2
17	02/11/19 12:58	General View	■ Load	JPG	2
18	02/11/19 12:58	General View	■ Load	JPG:	2
19	02/11/19 12:58	General View	■ Load	JPG	V
50	02/11/19 12:58	General View	O Load	JPG	82
51	02/11/19 12:58	General View	O Load	JPG	V
52	02/11/19 12:58	General View	■ Load	JPG.	V
53	02/11/19 12:58	General View	€ Load	3PG	82
		General View	O Load		82
54	02/11/19 12:58		O Load		Z
55	02/11/19 12:58	General View	O Load		2
56	02/11/19 12:58	General View		100000	N.
57	02/11/19 12:58	General View	6 Load		4
58	02/11/19 12:58	General View	O Load	111111111111111111111111111111111111111	2
59	02/11/19 12:58	General View	6 Load	-	8
50	02/11/19 12:58	General View	O Load		2
51	02/11/19 12:58	General View	€ Load	JPG.	8
62	02/11/19 12:58	General View	E Load	JPG	2
63	02/11/19 12:58	General View	1 Load	JPG	1
54	02/11/19 12:58	General View	1.oad	JPG	E
65	02/11/19 12:58	General View	■ Load	JPG	8
66	02/11/19 12:58	General View	Load	3PG	₽
67	02/11/19 12:58	General View	1 Load	JPG	₽
68	02/11/19 12:58	General View	1 Load	JPG	82
69	02/11/19 12:58	General View	1 Load	JPG	82
70	02/11/19 12:58	General View	O Load	3PG	V
71	02/11/19 12:58	General View	O Load	3PG	2
72	02/11/19 12:58	General View	€ Load	JPG	R
73	02/11/19 12:58	General View	€ Load	JPG.	R
74	a and the state of	General View	1 Load		R
W	02/11/19 12:58	PASSIFICATE MADA		JPG.	R
75	02/11/19 12:58	General View		JPG	2
76	02/11/19 12:58	General View	F201 0000	The late	2
77	02/11/19 12:58	General View		JPG	+
70	02/11/19 12:58	General View	1,	JPG	2
79	02/11/19 12:58	General View		JPG	82
80	02/11/19 12:58	General View		JPG	2
81	02/11/19 12:58	Odometer Reading		JPG.	8
82	02/11/19 12:58	Chassis Number		JPG	2
83	02/11/19 12:59	Reinspection Photo		JPG.	12
84	02/11/19 12:59	Reinspection Photo	6 Load	JPG	8
85	02/11/19 12:59	Reinspection Photo	O Load	JPG.	2
86	02/11/19 12:59	Reinspection Photo	■ Load	JPG.	8
87	02/11/19 12:59	Reinspection Photo	■ Load	JPG	8
88	02/11/19 12:59	Reinspection Photo	1 Load	3PG	2
89	02/11/19 12:59	Reinspection Photo		JPG	1
90	02/11/19 12:59	Reinspection Photo		3PG	1
91	02/11/19 12:59	Reinspection Photo		JPG	1 5
	100000000000000000000000000000000000000	Reinspection Photo		JPG	5
92	02/11/19 12:59	10000000000000000000000000000000000000	-	JPG	5
93	02/11/19 12:59	Reinspection Photo		-	-
94	02/11/19 12:59	Reinspection Photo	1 Load	JPG	1 2

Page 3 of 3

Vide	10		1 per ;	sage 🗸	2
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print
96	02/11/19 12:59	Reinspection Photo	0	Load JPG	V
97	02/11/19 12:59	Reinspection Photo	0	Load JPG	2
98	02/11/19 12:59	Reinspection Photo	0	Load JPG	2
99	02/11/19 12:59	Reinspection Photo	0	Load JPG	
100	02/11/19 12:59	Reinspection Photo	0	Load JPG	Ø
101	02/11/19 12:59	Reinspection Photo	0	Load JPG	V
102	02/11/19 12:59	Reinspection Photo	0	Load JPG	V
103	02/11/19 12:59	Reinspection Photo	0	Load JPG	2
104	02/11/19 12:59	Reinspection Photo	0	Load JPG	2
105	02/11/19 13:00	After Repair Photo	0	Load 3PG	8
106	02/11/19 13:00	After Repair Photo	0	Load JPG	80
107	02/11/19 13:00	After Repair Photo	0	Load 3PG	Ø
			0	Load JPG	Ø
108	02/11/19 13:00	After Repair Photo	0	Load JPG	2
109	02/11/19 13:00	After Repair Photo	0	Load JPG	<u>E</u>
110	02/11/19 13:00	After Repair Photo			₩.
111	02/11/19 13:00	After Repair Photo	0	Load JPG	
112	02/11/19 13:00	After Repair Photo	0	Load JPG	M
113	02/11/19 13:00	After Repair Photo	0	Load JPG	Ø
114	02/11/19 13:00	After Repair Photo	0	Load JPG	82
115	02/11/19 13:00	After Repair Photo	0	Load JPG	N
116	02/11/19 13:00	After Repair Photo	0	Load JPG	N
117	02/11/19 13:00	After Repair Photo	0	Load JPG	
118	02/11/19 13:00	After Repair Photo	0	Load 3PG	Ø
119	02/11/19 13:00	After Repair Photo	0	Load JPG	12
120	02/11/19 13:00	After Repair Photo	0	Load JPG	N
121	02/11/19 13:00	After Repair Photo	0	Load JPG	M
-	02/11/19 13:00	After Repair Photo	0	Load JPG	Ø
	344,444,444,444,444	THIS A MICHINICAL STREET			
Doc	umentation		1 per	page 💟	V
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnall	Print
1	09/10/19 15:54	ACKNOWLEDGEMENT EMAIL TO III DD 09.10.19	0	Load PDF	
2	09/10/19 15:54	TP ESTIMATE + TP GIA REPORT	0	Load PDF	
3	15/10/19 16:22	WHEEL ALIGNMENT	0	Load POF	
4	15/10/19 16:22	TP ESTIMATE - MARKED	0	Load PDF	
5	29/11/19 17:42	LOD	0	Load PDF	
6	29/11/19 17:42	Workshop Invoice	0	Load PDF	
7	29/11/19 17:42	Rental Rate & Mileage	0	Load PDF	-
8	27/12/19 14:45	AUTHORISATION TO ACT FORM	0	Load PDF	-
9	27/12/19 14:45	DISCHARGE VOUCHER	0	Load PDF	-
No	Finalized On	India International Insurance Pte Ltd (HQ)	-	Thumbnail	Print
1	10/10/19 08:30	Singapore Accident Statement	6	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
			0
			~
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg. No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19017828/DPA3Q2

Date: 27/12/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

MCOM0015

Claimant Vehicle No:

SHD6718H

Insured Vehicle No: SHD4085M

Date of Loss:

06/10/2019

Nature of Claim:

TP

Claim No: MCT19100154

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SHD6718H

HYUNDAI 140, 1.7 L CRDI AT ABS AIRBAG 4DR

09/04/2015 (Man. Year: 2015)

Engine No:

D4FDDU377406

734205 km

Reg. Date:

Make & Model:

Chassis No:

Odometer:

KMHLB41UMFU067981

Colour: Engine Capacity: Blue

1685 cc

Market Value/New Car Price:

N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes Engine Modification:

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:

205/60 R16

Rear Tyre Size:

205/60 R16

Front Left Side:

Hankook 5 mm Hankook 5 mm Rear Left Side: Rear Right Side: Hankook 5 mm Hankook 5 mm

Front Right Side: The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,761.44	6,670.88	14,090.56	67.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,480.00	1,750.00	2,730.00	60.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	25,241.44	8,420.88	16,820.56	66.64
Approved Total (Overridden) (S\$)		6,700.00		
(S\$)	25,241.44	6,700.00	18,541.44	73.46
+ GST 7.00/7.00% (S\$)	1,766.90	469.00	1,297.90	73.46
Nett Amount (S\$)	27,008.34	7,169.00	19,839.34	73.46
+ Loss of Use (9.0 x S\$4	40.00/day) (S\$)	360.00		
+ Car Rental (9.0 x S\$1	10.67/day) (S\$)	996.03		
Ne	tt Liability (S\$)	8,525.03		
Global Sum S	ettlement (S\$)	8,500.00		

INSPECTION

Date of Assignment:

09/10/2019

09/10/2019 Inspected At: Date Inspected:

Chunni Motor Work Pte Ltd (HQ) Blk 10 Ang Mo Kio Industrial Park 2A, #03-19 AMK Autopoint Singapore 568047

Adjuster Report Page 2 of 5

Estimated Period of Repair: 8.0 days

Adjuster: BRYAN TANI Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 5

REPAIR DETAILS

Referen	ce		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Nov 2019)	
Parts:	143	HYUNDAI I40 1.7 L CRDI AT ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)	
Labour:	Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitte	d, no print-code for SHD6718H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page		
Further Info		not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Bent	2,265.90 FL	*2,265.90 FL
2	2		*BONNET HINGE (LH/RH)	Not Necessary	82.00 FL	*-FL
3	1		*BONNET MOULDING	Not fitted	126.25 FL	*-FL
4	1		*BONNET LOCK	Not Necessary	36.90 FL	*-FL
5	2		*BONNET ABSORBER	Not Necessary	116.20 FL	*-FL
6	1		*BONNET INSULATOR	Not Necessary	196.50 FL	*-FL
7	1		*BONNET INSULATOR CLIPS	Not Necessary	8.40 FL	*- FL
8	1		*RADIATOR GRILLE	Mtg Cracked	251.00 FL	*251.00 FL
9	1		*RADIATOR GRILLE H EMBLEM	Necessary	27.50 FL	*27.50 FL
10	1		*FRONT BUMPER COVER	Torn	544.50 FL	*544.50 FL
11	1		*FRONT BUMPER SPONGE	Torn	99.20 FL	*99.20 FL
12	1		*FRONT BUMPER REINFORCEMENT	Bent	402.10 FL	*402.10 FL
13	1		*FRONT BUMPER GRILLE (LH)	Broken / Dislodged	41.60 FL	*41.60 FL
14	1		*FRONT BUMPER CENTRE GRILLE	Cracked / Deformed	178.60 FL	*178.60 FL
15	1		*FRONT BUMPER CENTRE GRILLE TOP GARNISH LH	Cut	80.00 FL	*80.00 FL
16	1		*FRONT BUMPER BRACKET TOP (LH)	Not Necessary	22.40 FL	*-FL
17	1		*FRONT BUMPER BRACKET (LH)	Broken	24.60 FL	*24.60 FL
18	1		*HEADLAMP SUPPORT TOP COVER	Not Necessary	222.60 FL	*-FL
19	1		*HEADLAMP SUPPORT PANEL ASSY	Broken / Bent	907.40 FL	*907.40 FL
20	1		*HEADLAMP (LH/RH)	N/S Broken / O/S Not Necessary	2,776.00 FL	*1,388.00 FL
21	1		*FRONT FENDER (LH)	Dented	566.30 FL	*566.30 FL
22	1		*FRONT FENDER APRON PANEL (LH)	Dented	637.00 FL	*637.00 FL
23	1		*FRONT FENDER SHIELD (LH)	Torn	174.90 FL	*174.90 FL
24	1		*AIR CLEANER ASSY	Not Necessary	118.60 FL	*-FL
25	1		*AIR CLEANER BOTTOM ASSY	Not Necessary	325.00 FL	*-FL
26	1		*FRONT WHEEL RIM (LH)	Not Necessary	325.30 FL	*-FL
27	1		*FRONT WHEEL HUB CAP (LH)	Not Necessary	107.10 FL	*-FI
28	1		*FRONT WHEEL BEARING	Not Necessary	540.50 FL	*-FI
29	1		*FRONT SHOCK ABSORBER (ASSY) (LH)	Not Necessary	342.20 FL	*-FI
30	1		*FRONT SHOCK ABSORBER MOUNTING (LH)	Not Necessary	108.80 FL	
31	1		*FRONT DRIVE SHAFT (LH)	Not Necessary	1,030.80 FL	*-FI
32	1		*RACK & PINION ASSY	Not Necessary	969.60 FL	*-FI
33	1		*STG TIE END	Not Necessary	62.60 FL	*-FI
34	1		*FRONT SUSPENSION LOWER ARM (LH)	Not Necessary	529.30 FL	*-FI
35	1		*KNUCKLE ARM (LH)	Not Necessary	552.00 FL	*-FI
36	1		*ENGINE UNDER COVER	Not Necessary	334.60 FL	*-FI
37	1		*ENGINE CROSSMEMBER	Not Necessary	2,094.40 FL	*-FI
38	1		*INTER COOLER	Not Necessary	1,032.50 FL	*-FI
39	2		*INTER COOLER MOUNTING	Not Necessary	25.90 FL	
40	1		*ABS SENSOR LH	Not Necessary	234.00 FL	
10	-		Report was unsubmitted d			

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
41	1		*WIRING -ENGINE (LOCAL REPAIR)	Housing Broken	2,660.80 FS	*500.00FS
42	1		*ELECTRIC POWER STEERING	Not Necessary	3,641.00 FL	*-FL
43	1		*FRONT NUMBER PLATE	Not Necessary	25.00 FS	*-FS
44	1		*FRONT NO PLATE TRIM COVER	Not Necessary	30.00 FS	*-FS
45	1		*FRONT FENDER ADVERTISEMENT LOGO (LH)	Necessary	100.00 FS	*100.00 FS
46	1		*FRONT TYRE (LH)	Not Necessary	216.00 FS	*-FS
F=Fra	inchise	part. S=	SpcNett. L=ListttemDisc List Item Discount on	Sub Total (S\$) L Items 20.00/20.00% (S\$)		8,188.60 1,517.72
				Total Parts (S\$)	20,761.44	6,670.88
			Report was unsubmitted du	ring this print-out.		

Adjuster Report Page 5 of 5

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

ATING INTING CHARGE HARGE E	New New New	1,500.00 1,000.00 50.00	800.00 600.00
INTING CHARGE HARGE	New	1,000.00	600.00
HARGE		1.* E.W.E.S.D.D.	
	New	50.00	
E			30.00
	New	100.00	40.00
HARGE	New	50.00	0.00
REFIX UNDERCARRIAGE (FRT)	New	200.00	0.00
L ALIGNMENT	New	120.00	0.00
REFIX AIRCON & REFILL GAS	New	150.00	80.00
REFIX DASHBOARD	New	450.00	150.00
REFIX FUSE BOX	New	180.00	50.00
RT ABS SYSTEM	New	200.00	0.00
TIC & RESETTING TO ERASE FAULT CODE	New	480.00	0.00
Gross Labo	our Cost (S\$)	4,480.00	1,750.00
RT.	ABS SYSTEM & RESETTING TO ERASE FAULT CODE Gross Labo	ABS SYSTEM New	ABS SYSTEM

< END OF ESTIMATES >