

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Bonnet <i>kt</i>			\$ 2,265.90
	Bonnet Hinge (LH/RH) <i>NN</i>		\$ 41.00	\$ 82.00
	Bonnet Moulding <i>NF</i>			\$ 126.25
	Bonnet Lock <i>NN</i>			\$ 36.90
	Bonnet Absorber <i>NN</i>		\$ 58.10	\$ 116.20
	Bonnet Insulator <i>NN</i>			\$ 196.50
	Bonnet Insulator Clips <i>NN</i>			\$ 8.40
	Radiator Grille <i>washy crack</i>			\$ 251.00
	Radiator Grille H Emblem <i>Nee</i>			\$ 27.50
	Front Bumper Cover <i>torn</i>			\$ 544.50
	Front Bumper Sponge <i>torn</i>			\$ 99.20
	Front Bumper Reinforcement <i>kt</i>			\$ 402.10
	Front Bumper Grille (LH) <i>broken phylodged</i>			\$ 41.60
	Front Bumper Centre Grille <i>crack 1 oiled</i>			\$ 178.60
	Front Bumper Centre Grille Top Garnish, LH <i>Cnt</i>			\$ 80.00
	Front Bumper Bracket Top (LH) <i>NN</i>			\$ 22.40
	Front Bumper Bracket (LH) <i>broken</i>			\$ 24.60
	Headlamp Support Top Cover <i>NN</i>			\$ 222.60
	Headlamp Support Panel Assy <i>broken kt</i>			\$ 907.40
	Headlamp (LH/RH) <i>n/s broken o/s NN</i>		\$ 1,388.00	\$ 2,776.00
	Front Fender (LH) <i>Dental</i>			\$ 566.30
	Front Fender Apron Panel (LH) <i>Dental</i>			\$ 637.00
	Front Fender Shield (LH) <i>torn</i>			\$ 174.90
	Air Cleaner Assy <i>crack</i>			\$ 118.60
	Air Cleaner Bottom Assy <i>NN</i>			\$ 325.00
	Front Wheel Rim (LH) <i>NN</i>			\$ 325.30
	Front Wheel Hub Cap (LH) <i>NN</i>			\$ 107.10
	Front Wheel Bearing <i>NN</i>			\$ 540.50
	Front Shock Absorber (Assy) (LH) <i>NN</i>			\$ 342.20
	Front Shock Absorber Mounting (LH) <i>NN</i>			\$ 108.80
	Front Drive Shaft (LH) <i>NN</i>			\$ 1,030.80
	Rack & Pinion Assy <i>NN</i>			\$ 969.60
	STG Tie End <i>NN</i>			\$ 62.60
	Front Suspension Lower Arm (LH) <i>NN</i>			\$ 529.30
	Knuckle Arm (LH) <i>NN</i>			\$ 552.00
	Engine Under Cover <i>NN</i>			\$ 334.60
	Engine Crossmember <i>NN</i>			\$ 2,094.40
	Inter Cooler <i>NN</i>			\$ 1,032.50
	Inter Cooler Mounting (2 PCS) <i>NN</i>			\$ 25.90
	ABS Sensor, LH <i>NN</i>			\$ 234.00
	Wiring-Engine <i>wiring broken</i>			\$ 3,326.00
	Electric Power Steering <i>NN</i>			\$ 3,641.00
	SUB TOTAL			\$ 25,488.05
	LESS 20%			\$ 5,097.61
	DISCOUNTED TOTAL			\$ 20,390.44

SHD 6718H

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Front Number Plate NN			\$ 25.00	Nett X
	Front No Plate Trim Cover NN			\$ 30.00	Nett X
	Front Fender Advertisement Logo (LH) NCC			\$ 100.00	Nett ✓
	Front Tyre (LH) NN			\$ 216.00	Nett X
				\$ 371.00	
	Labour Charge				
	Panel Beating			\$ 1,500.00	800/-
	Spray Painting Charge			\$ 1,000.00	600/-
	Wiring Charge			\$ 50.00	30/-
	Tuff Kote			\$ 100.00	40/-
	Towing Charge			\$ 50.00	NN
	Remove/Refix Undercarriage (FRT)			\$ 200.00	NN
	FRT Wheel Alignment			\$ 120.00	NN
	Remove/Refix Aircon & Refill Gas			\$ 150.00	80/-
	Remove/Refix Dashboard			\$ 450.00	150 150/-
	Remove/Refix Fuse Box			\$ 180.00	50/-
	Rc-sct Frt ABS System			\$ 200.00	NN
	Diagnostic & Resetting To Erase Fault Code			\$ 480.00	NN
	TOTAL LABOUR			\$ 4,480.00	
	ESTIMATE TOTAL			\$ 25,241.44	
09/10/2019 @ 1330hr N/A Accident 2/Sum 6 days <u>ryan</u> LKK Auto 					
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:					
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					