



新福德車廠私人有限公司

Adrian LKK  
AKH

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

08/10/2019

Blk 1 Kaki Bukit Ave 6

# 01-43

Singapore 417883

TPALG.

Vic

Accident date: 07/10/2019

Estimated repair cost for vehicle no: GBE2010H NISSAN CABSTAR 3.0 M '15

CHASSIS: JN1SC2F24Z0857584

S/N	QTY	Items / Nett	U/PRICE	AMOUNT
1	1	Rear Tail Gate <i>Dented</i>		\$1,399.70 ✓
2	2	Rear Tailgate Top Side Handle <i>HE m</i>	\$185.10	\$370.20 ✓
3	2	Rear Tailgate Lower Side Lock <i>RH Danged</i>	\$48.20	<del>\$96.40</del> + 48.20
4	4	Rear Tailgate Lower Side Hinges <i>1 piece bent</i>	\$147.30	<del>\$589.20</del> 53
5	2	Rear Tailgate Lower Side Bracket <i>RH Distorted</i>	\$125.50	<del>\$251.00</del> 125.50
6	4	Rear Tailgate Lower Side Bracket Stopper Rubber <i>RH cut</i>	\$12.10	<del>\$48.40</del> 12.10
7	1	Rear Tailgate Lower Member <i>Dented</i>		\$418.80 ✓
8	2	Rear Tail Lamp <i>RH can't</i>	\$248.60	<del>\$497.20</del> 248.60
9	2	Rear Tail Lamp Bracket <i>RH Bent</i>	\$111.20	<del>\$222.40</del> 111.20
10	1	Rear Number Plate Lamp <i>?</i>		\$67.50 ✓
11	1	Rear Number Plate Bracket <i>AP</i>		\$175.50 ✓
12	1	Rear Spare Tyre Lock <i>AP</i>		\$238.30 ✓
13	2	Rear Exhaust Mounting	\$33.50	\$67.00 +
14	1	Rear Floor Panel <i>Repair</i>		\$8,000.00 +
			2417.10	
			2175.39	
			<b>Subtotal:-</b>	<b>\$12,441.60</b>

S/N	QTY	Items / Special Nett	U/PRICE	AMOUNT
15	1	Rear Tailgate 70 Km/h Sticker <i>HE m</i>		<del>\$30.00</del> 10.
16	1	Rear Tailgate Advertisement Sticker <i>HE m</i>		<del>\$450.00</del> 150
17	1	Rear Tailgate Aluminium Cover <i>HE m</i>		\$450.00 +
18	1	Rear Floor Panel Aluminium Cover <i>HE m</i>		\$950.00 +
19	100	Aluminium Cover Rivet <i>HE m</i>	\$2.00	<del>\$200.00</del> 50.
20	1	Rear Reverse Sensor <i>Danged</i>		<del>\$350.00</del> 200.
21	1	Rear Number Plate <i>HE m</i>		\$50.00 +
22	1	Rear Exhaust <i>3 HE</i>		\$545.50 +
23	1	Rear Center Exhaust <i>1 HE</i>		\$683.40 +
24	1	Rear Chassis Center Member <i>Repair</i>		\$680.00 +

410

Subtotal:- \$4,388.90

**Labour charges**

To remove & refit rear reverse sensor	\$100.00 <del>50</del>
To remove & refit rear & center exhaust	\$380.00 <del>X</del>
To remove & refit rear body & repair chassis member	\$1,200.00 <del>X</del>
To remove & refit rear aluminium fittings	\$1,000.00 <del>180</del>
To check wiring	\$100.00 <del>30</del>
Tuff kote	\$150.00 <del>80</del>
Towing fee	1790 \$100.00 <del>X</del>
Panel beating	\$2,000.00 <del>800</del>
Spray painting	\$1,600.00 <del>650</del>

Subtotal:- \$6,630.00

Total:- \$23,460.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total 4375.39

L/S: 3.5K.

04 Days

3.5K