	ASS. REC. BY: REF: CS CTII9	017830/Uvd3n2 Special Instruction:
* 2		MENT (Office)
100	From (Person); Chong Buon Sen of	CTI Date/Time: 9/10/19@ 10.29000
7	Estimated Cost:	Bill to:
	OD TP WS/TP RES/OD RES/EVA/INV/MY	
	To Inspect Vehicle No: 9L	J 4478J Insured: XB 83767
	at Workshop m/s Cun S	Success Tel: 9828 9277
	of 1 kalei Bulei	+ Ave 6 -# 02-03
	Policy No: 5086783927-02	Claim No: 3 NM 19 D 20 4732
	Sum Insured:	Excess:
	Make of Veh: (Client's Record)	D.O.A. 8/10/19
	CA / REV / REP. / REV 24 HRS Date/Time: 11: 15 myallolla Person Contact	ed: H.O.D. Endorsement:
	Date/Time Action/Instruction Volume (
	SLJ 44787-X	
	×B83767-CC6/ETI/901	3823 Ka3 - 249'-
	•	
(8)	The American Control of the Control	

ASS. REC. BY: MC/CLS	C11/		
ASS. REC. BY: 1744	ASSIGNMENT		
From: Date:	Veh No: SZJ Type: M.Car / M.Cycle /	442£J Yr Regn: 12 Bus / Van / Lorry / Taxi / Prime Move	er I
OD THE WS TH REST OD REST EVA INVINV	Truck / Traller or	CA/	1496
To Inspect Vehicle No: SLJ4478	J Make: Tryo	fa corolla Axio c.c Axio Axio Insured / S	td / NI / NA
at Workshop m/s Euro Sters	Colour J&	T/Radio: Insured / S	td / NI / NA
of	Sp.Reading /-9	5000 T/Radio: Insured / S	MAT HIT INC.
Insured:	Eng/No:	0 - 112-121 110	· · · · ·
Policy No.		RE16100196 48	
Claims No.	Gen. Cond. Good Fal		
Sum Insured: Excess:		nmed / Leaked / Burnt or	
(Client's Record)	70	nmed / Leaked / Burnt or	
Make of Veh:	Modi: Nil S	STD A/Rim or	
	Tyre Size: F:	175/65 no	3
(Policy Condition)	R:		6000 77
Remark: The veh had commenced its	S OS BS / DUN / EXNOVA	GY / FS / LIZA / MIC / OHTSU / PIR /	SUMI/
repair at the time of inspection.	TOYO I YOKO or	Karsen	THE R. P. LEWIS CO., LANSING, MICH.
Bal, or Market Value: SG k.	Front	Rear	5
IDAC Accident Rport: Consistent? : Yes or No	R/Bal.	mm R/Bal.	mm
GIAL PR Seen: Consistent? : Yes or No	/	, mm L/Bal. 6) mm
GIA PT Seen.		R D.O.L 9/	10/5
ESt. Repairs.	and the second s		
Lum Sum: 20 % 3 Val.: Yes or N	- 11	rt Rear O/S N/S U/C Roof	top or
CA I REV I REP. I 24 HRS	cle: IN/OUT	15 50 14	
Date: Person Contacted:	The U/C / Chas	sis frame / Body Structure affected	due to collision.
THE PARTY OF THE P			
16/10/8 conful 4/5 \$ 5	so with Anh	mf. (Rad 18, 324	33, 4810
9-17-			
	RECEIVED 15 00	T 2019,	
11 (2011) (C. 12)			-
A CARLES CHESTAN	production to the state of		
8		Alternative and the second second	0.1828802
	44 1		
		/	
Date/Time, File Pass to? : Preli. Report	Days Of Repair:	Trip: Survey Fee:	
; Final Report	Resurvey No. of	Transportation:	
Date/Time, File Return to?	Add Fee: : Site Insp		
2) 16/10 -typist	: Interview		
Report Format: Merimen	: Tech. Inv		
	: Weekend		220
Lump Sum / I.B.I: (\$ 5050 2	Weeken	TOTAL	

...CLAIM SUBFOLDER...(New Assignment)

Case	Notified	Est Submitted	Ad) Assigned	Adj Rpt	Adj Sub	mitted	Ins Auth'ed	Status	
Main	09 Oct 2019		09 Oct 2019 11:42 Assign					New Assignm Cancel Case	ent
	Main	Re	eference		Claim Details		Docume	nts	Show All
CLAIM S	JBFOLDER DI	ETAILS	ners and the service sur-		THE PERSON NAMED IN COLUMN	[Create	ed by insurer]	SHIP SHIP SHIP SHIP	HOLD STREET
Insured:									
Main Claimant:	AMV PTE	LTD., Co. Reg.	No.: 201505825	iz .		M-00			
Vehicle Re No.:	g. SLJ447	SLJ4478J			Date of Loss:	08/10/2	08/10/2019 08:00 - :59		
Claim Type	E: TP / SNI	TP / SNM19D204732C02			Policy/Cover Note No.:	DMCVSN18055419011			
Vehicle Re No. (Insured):	XB8376T				Policy No. (Claimant):				
					Excess:	S\$0.00			
Repairer:	Euro Suc	cess Services Pt	e Ltd (HQ) 1 KA	KI BUKIT AVE	ENUE 6 #02-03	AUTOBAY	, 417883 Kaki Bul	cit - Tel:	
Handling Insurer:	China Tai	iping Insurance	(Singapore) Pto	e. Ltd. (HQ)	- Tel: 6389 611	1 [Han	dled by Chong B	oon Sen]	
Claimant's Insurer:	NTUC Inc	come Insurance	Co-operative Lt	d (HQ) - Tel	:				
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel:	6256-3561 .	[Final Rpt	due 18/	10/2019]		
ASSOCIA	TED MAIL RE	CEIVED						View All Comp	se Case Ma
There are	no mail for this	case.							
ALL ASS	OCIATED TAS	sks⊡				View A	II Search Tasks	Create New Task	Complet
Photo Pho	to material	Your York	Figure Fire	and Head					
Due Da		Type Task	Group Sub	ject Hand	ller Assign	ned By	Completed O	n Created O	n
No results									

Nivitha (LKK Auto)

From:

Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Sent:

Wednesday, 9 October 2019 10:29 AM

To:

ruby@htapartners.com.sq

Cc:

assignments

Subject:

RE: OUR REF: SNM129D204732-XB8376T-TKL- REQUEST FOR PRE-REPAIR SURVEY

PROTOCOL FOR SLJ 4478J [OUR REF. TCL.GCN.RO.50632.19.ESS]

WITHOUT PREJUDICE

Dear Sir

We will be assigning M/s LKK AUTO CONSULTANTS to survey your client's vehicle.

Aside to LKK AUTO CONSULTANTS,

Please proceed to survey the third party vehicle on WP basis. Please merimen.

Thank you.

Chong Boon Sen

Claims Executive Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909 DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平狮城 Taiping SG 3 Anson

Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Claims Dept of CTI

Sent: Wednesday, October 9, 2019 9:22 AM

To: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>; Chong Boon Sen
boonsen.chong@sg.cntaiping.com>; ruby@htapartners.com.sg

Subject: OUR REF: SNM129D204732-XB8376T-TKL- REQUEST FOR PRE-REPAIR SURVEY

PROTOCOL FOR SLJ 4478J [OUR REF. TCL.GCN.RO.50632.19.ESS]

Importance: High

Dear boon Sen.

Please assist to conduct PRS for XB8376T.

Note: officer in charge – Kah Leong 63896193.

Regards,

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

T: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平狮城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Ruby Ong [mailto:ruby@htapartners.com.sg]

Sent: Tuesday, 8 October, 2019 2:43 PM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Subject: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR SLJ 4478J [OUR REF.

TCL.GCN.RO.50632.19.ESS]

Importance: High

Your ref:

XB 8376T

WITHOUT PREJUDICE

Our ref:

TCL.GCN.ro.50632.19.ess

8 October 2019

China Taiping Insurance Co (Singapore) Pte Ltd

By Email Only

Motor Claims Department 3 Anson Road #16-00 Springleaf Tower Singapore 079909

VERY URGENT

Dear Sirs

CLAIMANT: AMV PTE LTD

NOTICE OF ACCIDENT & PRE-REPAIR SURVEY: ACCIDENT INVOLVING <u>SLJ 4478J</u> & XB 8376T ALONG HOUGANG AVENUE 2 ON 8 OCTOBER 2019 @ 0800HRS

We are instructed by AMV Pte Ltd to notify you of a road traffic accident on 8 October 2019 at about 0800hrs along Hougang Avenue 2 involving our clients' vehicle registration number **SLJ 4478J** and vehicle registration number XB 8376T driven by your authorised driver at the material time.

As a result of the accident, our clients' vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, our client proposes to appoint <u>Marcus Chua of LKK Auto Consultants Pte Ltd</u> as the single joint expert to carry out the pre-repair survey for <u>SLJ 4478J</u>.

Kindly contact the person-in-charge to make the necessary arrangements for the pre-repair survey of our clients' vehicle. Please be informed that our clients' vehicle is at:

Venue

EURO SUCCESS SERVICES PTE LTD

1 Kaki Bukit Avenue 6 #02-03 Autobay Singapore 417883

Contact Person:

Ah Huat (Tel. 9828 9277 / 6742 6231)

In the event that the pre-repair survey was not conducted during the prescribed time or already conducted at your end previously, we reserve our clients' right to claim for compensation for loss of use for your current request for re-survey.

Best regards, Ruby Ong Secretary M/s Hin Tat Augustine & Partners 20 Upper Circular Road #02-10/12 The Riverwalk Singapore 058416

Tel: 6533 0212 ext 278 Fax: 6338 3536 / 6533 0313

www.htapartners.com.sg

Privileged/Confidential information is contained in this message. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email.

This email has been scanned by the Symantec Email Security.cloud service. For more information please visit http://www.symanteccloud.com

SGCARMART.COM

Login Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

Post an Advertisement Sell it yourself! Advertise it at just \$58 until it's SOLD! 2012 BMW 520I At \$57,500k



1 Owner With Good Condition Direct Owner StarAd

YONG LEE SENG MOTOR PTE LTD





Available

2 Years Warrantyl Full Loan Monthly \$900 Plus, We Are spCarMart Premium Dealer! Buy With No Womies! No Hidden Costs! Car In Origi...

Posted: 08-Oct-2019 Tags: 2016 Toyota Corolla, 2016 toyota corolla, Toyota Corolla, Toyota corolla, Toyota Corolla, Corolla, Corolla, Used Toyota

Toyota Corolla Axio 1.5A X \$51,800 \$7,190 /yr 13-May-2016 1,496 cc 30,000 km Sedan

Well Maintained By Previous Owner. 1 Owner Only, Very Low Mileage Of 30k Km Only! Low Interest Rate Just At 1,98%! Condition Very...

Posted: 05-Oct-2019 Tags: 2016 Toyota Corolla, 2016 toyota corolla, Toyota Corolla, toyota corolla, Toyota Corolla, Coro

SECTION STATES

CHEROMOTER STOR

Available



High-Performance Precision Braking Control

Hel Brake Line (Stainless Steel braided hose -Front + Rear) Improve your braking performances for safety and control More info about this product



Toyota Corolla Axio 1.5A G

\$55,000

\$7,930 /ут 1 Owner, High Spec G Model, Keyless Entry, High Loan Available, Smooth And Quiet Engine. Trade-In Welcome.One Of The Best Fuel C...

Available

Ka-Hup Vehicles Trading

(OPC)

Posted: 05-Oct-2019 Tags: 2016 Toyota Corolla, 2016 toyota corolla, Toyota Cor



Toyota Corolla Axio 1.5A X (OPC)

\$45,800

\$6,220 /yr

31-Aug-2016

1,496 cc 30,900 km

Available

Beautifully Maintained By 1 Owner! Low Mileage And Under Usage Due To OPC! Conversion To Normal Plate At \$58800 Available! Guara...

Posted: 05-Oct-2019 Tegs: 2016 Toyota Corolla, 2016 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, Corolla, Used Toyota



Toyota Corolla Axio 1.5A X Elegant White Axio 1.5A With New Car Feel/Smell! Bidded 2 Digits Number Plate Going Along! Non Private Hire/Leasing Car, 1 Retiree O...

\$54,800

\$7,380 /yr

28-Jun-2016

1,496 cc

Available PREMIN IS

STREET, ST.

Lake View Credit Pte Ltd Posted: 05-Oct-2019 Tags: 2016 Toyota Corolla, 2016 toyota corolla, toyota cor

Toyota Corolla Axio 1.5A X

\$46,800 \$6,220 /yr 07-Oct-2016

1,496 cc 23,000 km

Available Sedan

Compare

Attractive Loan Packages, Enquirer To Know Morel 1 Owner Only Rare OPC Axio! Very Low Mileage Done! Prestige Showroom Condition!...

SECTION STATES

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	825Z
Vehicle Details	
Vehicle No.:	SLJ4478J
Vehicle to be Exported:	No
ntended Deregistration Date:	09 Oct 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA AXIO 1.5X A
Primary Colour:	Beige
Manufacturing Year:	2016
Engine No.:	2NR8647046
Chassis No.:	NRE1610019648
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$16,462.00
Original Registration Date:	12 Dec 2016
First Registration Date:	12 Dec 2016
Transfer Count:	0
Actual ARF Paid:	\$6,462.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Dec 2026
PARF Rebate Amount:	\$4,846.00
Intended COE Rebate Details	
COE Expiry Date:	11 Dec 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$48,000.00
COE Rebate Amount:	\$34,425.00
Total Rebate Amount:	\$39,271.00

The information contained herein is correct as at 09 Oct 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

	ACCIDENT STATEMENT	
Date Of Report	09/10/2019 09:33	G.
Date Of Accident	08/10/2019 08:00	
Exact Location Of Accident	HOUGANG AVE 2	
Country/State of Loss	SINGAPORE	

DETAILS OF OWN VEHICLE

SLJ4478J Vehicle Registration Number

Insured/Policyholder

AMV PTE, LTD. Name Of Registered Owner 201505825Z Co Reg No NOEMAIL Email Address

Mobile Phone No

OFFICE-98583956 Alternative Phone No.

Vehicle Particulars

TOYOTA Manufacturer

COROLLA AXIO 1.5X A Model

Exact Purpose for which vehicle was being used at

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

THIRD PARTY If No, Please state action to be taken Vehicle Category

PRIVATE HIRE

Insurance Company

Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD

Type Of Coverage

COMPREHENSIVE

Fleet Policy

YES

Policy Number

5086783927-02

Cover Note Number

Driver

SATHIANESAN SAJAI PRABHU Name of Driver

G8446996W Passport No/FIN Date Of Birth 18/06/1981 OUTDOOR Occupation Date Of Driving Pass 08/08/2019

0 YEAR AND 2 MONTH Driving Experience

MALE Gender

(LOCAL) +65-83219275 Mobile Number

Fax Number

Contact Number

SAJAIPRABHU@GMAIL.COM EMail Address

Address

BLK 10 GLUOCESTER ROAD #09-47 FARRER PARK

Postcode

210010

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

SIDE SWIPE

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

Number of vehicles (including own vehicle) involved in the accident

2

Was any body injured in the Accident?

YES

Was any injured conveyed to hospital by

NO

ambulance?

Was any other material or property damaged?

YES

I have been approached by unknown person(s)

NO

soliciting/offering accident claims assistance. Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

YES

If Yes, Please state which Police Station

Police Station Name

TRAFFIC POLICE DIVISION HQ

Police Station Address

ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY:

SINGAPORE

Police Station Contact

TEL NO: 65470000 - FAX NO:

Was notice of Intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

AS PER POLICE REPORT No.T/2019008/7016;

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

XB8376T

Vehicle Make/Model/Colour

VOLVO / FMX370 64R SLEEPER CAB

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

5 ()		
	DETAILS OF INJURED PERSON 1	
Name	SATHIANESAN SAJAI PRABHU	or ecolonium
Approximate Age	38	
Injuries Sustain		
Injured person in which vehicle?	SLJ4478J	
Were seat belts worn?	YES	
Was this injured conveyed to hospital by ambulance?		
Address	BLK 10 GLUOCESTER ROAD #09-47 FARRER PARK	
Postcode	210010	

Common Statement

SKETCH PLAN

IMPORTANT NOTICE

- 2) Please import correctly the determinance account to usered up the claims process
- This form the completed by the Policyholder and/or the Authorised Driver
- Information provides must be at truthful and accurate as possible. Any within managementation or within engle truthful and accurate as possible. Any within managementation or within engle truthful and accurate as possible.
- The independence of this First by indicates considered in the admission of policy and the analysis of the analysis of the analysis.

Any false reporting may be referred to the Police for investigation

- 6. The report will be forwalded to the insulars of the GARG contributing more development by the Sarakan insular or Association of Singapore (GAR) or at the fig. of that could not the report well to letter the made are wolved application to instructive parties.
- 1. By the independ of this append, the masses souther by a medity the or being of this report at the victor open of the eight programme assessment and a formula.
- 6. Coment under the Personal Data Protection Act (PDPA)

where these acknowledge agreement or over their

- Macroscope to Authority and the Contraction of the Authority of ting-point (AAA) into the performance of the contraction of ting-point (AAA) into the performance of the contraction of the contraction of the period of the contraction of the period of the contraction of the contra
 - proteining mandling and/or dealing with my nation in our rights sufficient in ordinal area and any national analysis exerting to the claims.
 - the coestigating the an identification by claims
 - in Learnying out und/or dealing with my instructions in responding to any expudies by mo-
 - (iv) adirentations the flams (including the atlating of correspondence, statements, enough, reports or notices to me which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or
 - (v) complying with applicable awar administrating processing manding and or dealing with my claims scoler (self-the) the "Purposes";
- (b) all injuriets who have invoiced versions to include in this are designed to insure takey includes a responsible to the interest of the above Parameter for the order or more of the above Parameter.
- my Persons in formation may/ser be disclosed by any or the figuress and or the figures and party service provides or agents recluding their leavestallaw format, which may be sted outside of languages. For one or more of the ebove Policy re-
- (iii) the Personal Information will also be unlike ted and used to surveille stains history to the parcels of black drivings investigation and management in prevent and as Neture steems.
- in the information or collected under all above was be that or this used
 - (i) to all natures and/or any other third parties that event in evaluating investigating controlling or managing have registers. New enforcement and government agencies as rewardably required for the purposes stated or
 - is for complying with requirements under any regulations. Less or court orders.

3

Full Water & Trans

Dissert Standard

Driver's Signature of driver's not the palicyhologic Date & Fine IDAC KAKI BUKIT (VAC)


Some Singapore 415933 WEST TRANSFORM TO THE TOTAL STREET TO THE T

Email: vackb@singnet.com.sg

SKETCH PLAN

A SL744787

B * XB 83 76 T



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Dvi	the	Above	5464	rd de	the con	1	time	. I	terdita. G	, f.l	tering	сит	Eveny	
House	ung l	44 13	to	Homour	ng Ave	2	ľΑ	the	weigh	k veh	cle	2 to Fred	50	
that	1	(in	tilter	ewt	Succession	4	Se :	Ī	Eltered	041	si inq	1 2	ک باشی د	en
× _	((1)	et has	લ લવ	·~y	ueh,de	6,36	5	stut	enery	When	Sur	denty	vehicle	
Ь	(e) i d	al en	t _o	me. Pw	ring th	e	aud	ont_	tine	traffis	1-16	s. very	heliv	
and	the	rt W	45 a	jan	Sq	7	£.14	er	041	us the	that	help	of the	
yelle	w	box 1	ane F	i land	When	Swi	deny	ve	hicle	i) (1	Hided	on to	mg.	
Puri	n	the a	ccid ent	I	howe	9,	Lvi	Bares	55					

3

errors foregoing particular on true in every insent.

Policy of Time

Driver's Signature (if driver is not the policyholde) Date & Time IDAC KAKI BUKIT (VAC)
23 Kaki Bukit Ave 4
5ingapore 415933
Email vackb@singnet.com.sg





100401

/20191008/7016

Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No 65470000 1 of 3 Report No. T/20191008/7016

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 08/10/2019 14.45			Vide Report No.: Station Diary No.				
Informa	nt's Partic	ulars					
	Informant NESAN SA	JAI PRABHU	Address: APT BLK 10 GLOUCESTER GARDENS SINGAPORE 210	ROAD #09-47 FARRER PARK			
ID Type / ID No.: FIN NO / G8446996W			Contact No.: Home/Office: Mobile 83219275				
National INDIAN	ty:		Email sajaiprabhu@gmail.com				
Sex Age Date of Birth Male 38 18/06/1981			Type of Informant: Driver				
Race			Language English	Institution / School Name			
Occupation: Chauffeur			Driving Licence Information: Class: 2B,3C Date of Expiry				

Type of Accident:	Injury Others	Drink Drive No.	Date/Time of Accident. 08/10/2019 08:00	Type of Location Straight Road
Location: HOUGANG A	VENUE 2	Road Surface:		Road Speed Limit
Clare		Dry		60 Km/h
Clear Traffic Flow: One Way		Traffic Control Not Controlled		Fraffic Volume Heavy

Details of Vehicle Involved							
Vehicle No.	Туре	Make	Model	Color	Condition	No of Passenger	
SLJ4478J	Car					0	
XB8376T	Lorry		VOLVO			0	

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA





Police Station Of Origin Traffic Police 10 Ubi Avenue 3 SINGAPORE 498865 Tel No: 65470000

2 of 3 Report No. 1/20191008/7016

CONTINUATION OF REPORT

Driver		211/2		100			
Name	SATHIANESAN SAJAI PRABHU			ID No.		G8446996W	
Related Vehicle	StJ4478J (Car)			Contact N		83219275	
Hospital/Clinic	NIL			Class Drivin Licent Expire	g	Class. 2B,3C Date of Expiry. NIL	
Date Treatment	NIL		Date Disc	harge	08/10	0/2019	
No. of Days granted Medical Leave 05			Degree of Injury Serio		ius		

Bnef Details

ON THE ABOVE STATED DATE AND TIME. I WAS FILTERING OUT FROM HOUGANG AVE 10 TO HOUGANG AVE 2 HOUGANG AVE 2.
ALL THE VEHICLE STOPPED SO THAT I CAN FILTER OUT SUCCESSFULLY SO I FILTERED OUT AND I WAS ON THE CENTER LANE AND MY VEHICLE WAS STATIONARY WHEN SUDDENLY VEHICLE B COLLIDED ON TO ME.
I WAS IN THE YELLOW BOX WHEN THE ACCIDENT HAPPEN AND THE LORRY DRIVER JUST WENT STRAIGHT AND COLLIDED ON TO ME.
AT THE POINT OF HE ACCIDENT MY VEHICLE WAS STATIONARY AFTER THE ACCIDENT I PROCEEDED TO CONSULT A DOCTOR AT ANG MO KIO 24HR INTEMEDICAL CLINIC AND RECEIVE 5 DAYS MC FROM 08/10/2019 TO 12/10/2019.
I AM MAKING THIS REPORT FOR RECORD AND MEDICAL PURPOSES





Police Station Of Origin Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000

3 of 3 Report No. T/20191008/7016

CONTINUATION OF REPORT

Sketch Plan

NP168

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant The identity of the person making this report has been authenticated by SingPass. No signature is required
Signature Of Interpreter Not applicable	Date/Time: 08/10/2019 14 45
Officer in Charge Of Case: TP / TPHQ / YEO GEAK ENG CECILIA Contact No.: 65476404	Classification Of Case:
Authentication Stamp	

EURO SUCCESS SERV PTE. LTD Blk 1 Kaki Bukit 6, #02-03 Singapore 417883

TEL: 67426231

FAX: 67411019

H/P: 98289277 (AH HUAT)

Vehicle No: SLJ4478J

Model: TOYOTA AXIO

NOT ANDORA LIN 1/5 #5050 Boty. 9/10/18 10/18 10/18

		Zaha Welle
QTY	<u>List Items</u>	Price \$
1	FRONT BUMPER	1265.80 A
1	FRONT R/H HEAD LAMP	17 699.60 A
1	REAR R/H DOOR	3045 m 1085.65
1	REAR R/H DOOR INNER LOWER RUBBER	nec 88.60
1	REAR R/H DOOR INNER BOARD	322.65
1	FRONT R/H DOOR WINDOW MOTOR	450.90
2	REAR R/H DOOR HINGE @85.5	171.00 X
1	REAR R/H DOOR WEATHER STRIP 2/1.30	ML 360.60
1	REAR R/H DOOR OUTER HANDLE	11, 147.60
1	REAR R/H DOOR INNER LOCK	17 296.50
1	REAR R/H DOOR GLASS OUTER CHROME	17 122.30
1	REAR R/H DOOR GLASS RUN CHANNEL	17 145.60 X
1	REAR R/H DOOR GLASS	11 336.50 €
1	REAR R/H DOOR GLASS OUTER MOULDING	11 132.30
1	REAR R/H DOOR GLASS RUN CHANNEL	11 195.65 X
1	REAR R/H DOOR 1/4 GLASS RUBBER	119.10 X
1	REAR R/H DOOR 1/4 GLASS CORNER GARNISH	A 89.00 ★
1	REAR R/H DOOR CENTRE LOCK MOTOR	47 589.20 X
1	REAR R/H ROCKER PANEL	17 890.30 X
1	REAR R/H KNUCKLE ARM	11 587.60 X
1	REAR R/H KNUCKLE WHEEL BEARING	17 487.60 X
1	REAR R/H SHOCK ABSORBER	11 245.60 X
1	REAR R/H WHEEL BEARING	11 376.30 乂
1	REAR R/H LOWER ARM	∕ 17 320.20 ★
1	REAR R/H DOOR INNER BOARD	, 11 486.50 X
1	FRONT R/H DOOR	1285.65
1	FRONT R/H DOOR MIRROR	Shell 550.60
1	FRONT R/H DOOR WEATHER STRIP 244-10	Nex 380.60
1	FRONT R/H DOOR OUTER HANDLER	Tul 157.60
1	FRONT R/H DOOR OUTER HANDLER STOPPER	7~1 68.50
1	FRONT R/H DOOR GLASS	1 7 336.50 >
1	FRONT R/H DOOR GLASS OUTER MOULDING	132.30
1	FRONT R/H DOOR GLASS RUN CHANNEL	175.65 X
1	FRONT R/H DOOR INNER BOARD	a/1m 462.55
1	FRONT R/H DOOR INNER LOWER RUBBER	, N. 88.60
1	FRONT R/H DOOR INNER LOCK MOTOR 399.10	shuh 532.60
1	FRONT R/H DOOR POWER WINDOW MOTOR	W/m 656.65
1	FRONT R/H DOOR CHECKER	17 120.50 X
2	FRONT R/H DOOR HINGE @85.80	171.60
1	FRONT R/H DOOR POWER WINDOW SWITCH	1 1 395.80 A
1	FRONT R/H DOOR POWER MIRROR SWITCH	11 310.30 X
1	centre door pillar ett 899.10.	00/But 1066.00

1	R/H CENTRE DOOR PILLER INNER BOARD		11	236.35 🗶
1	R/H ROCKER PANEL		Rend	988.35
1	R/H ROCKER PANEL LOWER BOARD		17	182.25
1	FRONT R/H KNUCKLE ARM		11	587.60 X
1	FRONT R/H KNUCKLE WHEEL BEARING		11	487.60 🗶
1	FRONT R/H SHOCK ABSORBER		11	245.60 X
1	FRONT R/H WHEEL BEARING		17	376.30 X
1	FRONT R/H LOWER ARM		11	320.20 🗴
	T01	ΓAL	\$20),328.90
	LES	S 25%	\$5	,082.23
	T01	ΓAL	\$15	5,246.68
	Special Nett Items			
10	FRONT BUMPER CLIPS @4.5		11	45.000
1	REAR R/H TYRE		11	300.002
1	REAR R/H TYRE RIM		11	500.00a
1	REAR R/H HUPCASE		11	200.00
1	REAR R/H DOOR MECHANISM		N	200.00
1	FRONT R/H TYRE		11	300.00
1	FRONT R/H TYRE RIM		17	500.00
1	FRONT R/H HUPCASE		11	200.00 🗴
1	FRONT L/H DOOR MECHANISM		NS	200.00 X
1	DRIVER SEAT BELT		nn	632.65 X
	то	TAL	\$	3,077.65
	Labour Charges		12 327	~
	TO RESET AND REPROGRAME SYSTEM		11	500.00
	TO CHECK WHEEL ALIGNMENT		11	200.00 🗶
	TO CHECK FRONT AND REAR DOOR ELECTRICAL WIRING			150.00
	TO REMOVE, REFIX REAR INTERIOR TRIMS TO ASS	SIST		200.00 80
	REPAIR			· · · · · · · · · · · · · · · · · · ·
	TO REMOVE, REFIX FRONT AND REAR		11	250.00 X
	UNDERCARRIAGE			250.00 60
	TO RESPRAY UNDERCOATING			
	TO RESPRAY PAINTING AND ETC			1500.00 foo
	PANEL BEATING, CUT, WELD REMOVE AND			2000.00 600
	REPLACING ABOVE PARTS			

LKK Auto Consultants hence notify the Repairer of the following:

ESTIMATE PARTS AND LABOUR GRAND TOTAL

- No.11 _ inheditation(s) is allowed.
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

\$5,050.00

\$23,374.33

P- 6331.30 267 4748.47 1570.00 -63(8.47) 6054.77

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/CTI19017830/UVD3N2

Date:

17/10/2019

REFERENCE

Handling Insurer:

China Taiping Insurance

(Singapore) Pte. Ltd.

Policy No:

DMCVSN18055419011

Claimant Vehicle No:

SLJ4478J

Insured Vehicle No:

XB8376T

Date of Loss:

08/10/2019

Nature of Claim:

TP

Claim No:

SNM19D204732C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SLJ4478J

Make & Model:

TOYOTA COROLLA AXIO, 1.5 (A) 12/12/2016 (Man. Year: 2016)

Engine No: Chassis No:

Odometer:

2NR8647046 NRE1610019648

196000 km

Reg. Date: Colour:

Beige

Engine Capacity: Market Value/New Car 1496 cc

Price:

N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable): Yes Engine Modification:

Yes Footbrake (Serviceable): Pre-accident Condition:

Yes

Handbrake (Serviceable): **CONDITION OF TYRES**

Front Tyre Size:

175/65R15

Rear Tyre Size:

175/65R15

Front Left Side:

KAPSEN 6 mm

Rear Left Side:

KAPSEN 6 mm

Front Right Side:

KAPSEN 6 mm

Rear Right Side:

KAPSEN 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS Parts	Repairer's 18,324.32	Adjuster's 4,748.47	Difference 13,575.85	Diff % 74.09
Miscellaneous Items	0.00	0.00	0.00	
Labour Paintwork Labour	5,050.00 0.00	1,570.00 0.00	3,480.00 0.00	68.91
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$) Approved Total (Overridden) (S\$)	23,374.32	6,318.47 5,050.00	17,055.85	72.97
Nett Amount (S\$)	23,374.32	5,050.00	18,324.32	78.40

INSPECTION

Date of Assignment:

09/10/2019

Date Inspected:

09/10/2019 Inspected At:

Euro Success Services Pte Ltd (HQ) 1 KAKI BUKIT AVENUE 6 #02-03

AUTOBAY

Singapore 417883

Estimated Period of Repair:

6.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 17 Oct 2019)

Parts: 143 TOYOTA COROLLA AXIO 1.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLJ4478J)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Repair	1,265.80 FL	
2	1	*FRONT R/H HEAD LAMP	Not Necessary	699.60 FL	*-FL
3	1	*REAR R/H DOOR	Badly Dented		*1,085.65 FL
4	1	*REAR R/H DOOR INNER LOWER RUBBER	Necessary	88.60 FL	
5	1	*REAR R/H DOOR INNER BOARD	Not Necessary	322.65 FL	
6	1	*FRONT R/H DOOR WINDOW MOTOR	Not Necessary	450.90 FL	
7	2	*REAR R/H DOOR HINGE	Not Necessary	171.00 FL	
8	1	*REAR R/H DOOR WEATHERSTRIP	Necessary	360.60 FL	
9	1	*REAR R/H DOOR OUTER HANDLE	Not Necessary	147.60 FL	*-FL
10	1	*REAR R/H DOOR INNER LOCK	Not Necessary	296.50 FL	
11	1	*REAR R/H DOOR GLASS OUTER CHROME	Not Necessary	122.30 FL	
12	1	*REAR R/H DOOR GLASS RUN CHANNEL	Not Necessary	145.60 FL	
13	1	*REAR R/H DOOR GLASS	Not Necessary	336.50 FL	
14	1	*REAR R/H DOOR GLASS OUTER MOULDING	Not Necessary	132.30 FL	
15	1	*REAR R/H DOOR GLASS RUN CHANNEL	Not Necessary	195.65 FL	
16	1	*REAR R/H DOOR 1/4 GLASS RUBBER	Not Necessary	119.10 FL	
17	1	*REAR R/H DOOR 1/4 GLASS CORNER GARNISH	기계 하는 시계에서 할 때 수가를 하는데 하는데 있다면 해.	89.00 FL	
18	1	*REAR R/H DOOR CENTRE LOCK MOTOR	Not Necessary	589.20 FL	
19	1	*REAR R/H ROCKER PANEL	Not Necessary	890.30 FL	
20	1	*REAR R/H KNUCKLE ARM	Not Necessary	587.60 FL	
21	1	*REAR R/H KNUCKLE WHEEL BEARING	Not Necessary	487.60 FL	
22	1	*REAR R/H SHOCK ABSORBER	Not Necessary	245.60 FL	
23	1	*REAR R/H WHEEL BEARING	Not Necessary	376.30 FL	
24	1	*REAR R/H LOWER ARM	Not Necessary	320.20 FL	
25	1	*REAR R/H DOOR INNER BOARD	Not Necessary	486.50 FL	
26	1	*FRONT R/H DOOR	Badly Dented		*1,285.65 FL
27	1	*FRONT R/H DOOR MIRROR	Shorted	550.60 FL	
28	1	*FRONT R/H DOOR WEATHER STRIP	Necessary	380.60 FL	
29	1	*FRONT R/H DOOR OUTER HANDLER	Twisted	157.60 FL	
30	1	*FRONT R/H DOOR OUTER HANDLER STOPPER		68.50 FL	
31	1	*FRONT R/H DOOR GLASS	Not Necessary Bent	336.50 FL 132.30 FL	
32	1	*FRONT R/H DOOR GLASS OUTER MOULDING	(hitigry) played i decommendation of the	175.65 FL	
33	1	*FRONT R/H DOOR GLASS RUN CHANNEL *FRONT R/H DOOR INNER BOARD	Not Necessary Deformed/Twisted		
34	1			88.60 FL	
35	1	*FRONT R/H DOOR INNER LOWER RUBBER	Necessary Shorted	532.60 FL	
36	1	*FRONT R/H DOOR INNER LOCK	Bent/Jammed	656.65 FL	
37	1	*FRONT R/H DOOR POWER WINDOW MOTOR		120.50 FL	
38	1	*FRONT R/H DOOR CHECKER	Not Necessary		
39	2	*FRONT R/H DOOR HINGE	Not Necessary	171.60 FL 395.80 FL	
40	1	*FRONT R/H DOOR POWER WINDOW SWITCH	Not Necessary		
41	1	*FRONT R/H DOOR POWER MIRROR SWITCH *CENTRE DOOR PILLAR RH	Not Necessary Dented/Bent	310.30 FL 1,066.00 FL	
42	1		Not Necessary	236.35 FL	
43 44	1	*R/H CENTRE DOOR PILLAR INNER BOARD *R/H ROCKER PANEL	Repeated	988.35 FL	

					N- COMPANDO
15	1	*R/H ROCKER PANEL LOWER BOARD	Not Necessary	182.25 FL	*-FL
23) J	1	*FRONT R/H KNUCKLE ARM	Not Necessary	587.60 FL	*-FL
47	1	*FRONT R/H KNUCKLE WHEEL BEARING	Not Necessary	487.60 FL	*-FL
48	1	*FRONT R/H SHOCK ABSORBER	Not Necessary	245.60 FL	*- FL
49	1	*FRONT R/H WHEEL BEARING	Not Necessary	376.30 FL	*-FL
50	1	*FRONT R/H LOWER ARM	Not Necessary	320.20 FL	*-FL
	10	*FRONT BUMPER CLIPS	Not Necessary	45.00 FS	*-FS
52	1	*REAR R/H TYRE	Not Necessary	300.00 FS	*- FS
53	1	*REAR R/H TYRE RIM	Not Necessary	500.00 FS	*-FS
54	1	*REAR R/H HUPCASE	Not Necessary	200.00 FS	*- FS
55	1	*REAR R/H DOOR MECHANISM	No such part	200.00 FS	*- FS
56	1	*FRONT R/H TYRE	Not Necessary	300.00 FS	*- FS
57	1	*FRONT R/H TYRE RIM	Not Necessary	500.00 FS	*-FS
	1	*FRONT R/H HUPCASE	Not Necessary	200.00 FS	*- FS
	1	*FRONT L/H DOOR MECHANISM	No such part	200.00 FS	*- FS
60	1	*DRIVER SEAT BELT	Not Necessary	632.65 FS	*- FS
F=Fran	chise	part. S=SpcNett. L=ListItemDisc.			
			Sub Total (S\$)	23.406.55	6,331.30
		- List Item Discount on L Iten			1,582.83
			Total Parts (S\$)	18,324.32	4,748.47

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

Particulars	Lab.Type	Repairer's	Amount
ur Items			
TO RESET AND REPROGRAME SYSTEM	New	500.00	0.00
TO CHECK WHEEL ALIGNMENT	New	200.00	0.00
TO CHECK FRONT AND REAR DOOR ELECTRICAL WIRING	New	150.00	30.00
TO REMOVE, REFIX REAR INTERIOR TRIMS TO ASSIST REPAIR	New	200.00	80.00
TO REMOVE, REFIX FRONT AND REAR UNDERCARRIAGE	New	250.00	0.00
TO RESPRAY UNDERCOATING	New	250.00	60.00
TO RESPRAY PAINTING AND ETC	New	1,500.00	800.00
PANEL BEATING, CUT, WELD, REMOVE AND REPLACING ABOVE PARTS	New	2,000.00	600.00
Gross Labou	r Cost (S\$)	5,050.00	1,570.00
	TO RESET AND REPROGRAME SYSTEM TO CHECK WHEEL ALIGNMENT TO CHECK FRONT AND REAR DOOR ELECTRICAL WIRING TO REMOVE, REFIX REAR INTERIOR TRIMS TO ASSIST REPAIR TO REMOVE, REFIX FRONT AND REAR UNDERCARRIAGE TO RESPRAY UNDERCOATING TO RESPRAY PAINTING AND ETC PANEL BEATING, CUT, WELD, REMOVE AND REPLACING ABOVE PARTS	TO RESET AND REPROGRAME SYSTEM TO CHECK WHEEL ALIGNMENT TO CHECK FRONT AND REAR DOOR ELECTRICAL WIRING TO REMOVE, REFIX REAR INTERIOR TRIMS TO ASSIST REPAIR TO REMOVE, REFIX FRONT AND REAR UNDERCARRIAGE TO RESPRAY UNDERCOATING TO RESPRAY PAINTING AND ETC PANEL BEATING, CUT, WELD, REMOVE AND REPLACING New	TO RESET AND REPROGRAME SYSTEM TO CHECK WHEEL ALIGNMENT TO CHECK FRONT AND REAR DOOR ELECTRICAL WIRING TO REMOVE, REFIX REAR INTERIOR TRIMS TO ASSIST TO REMOVE, REFIX FRONT AND REAR UNDERCARRIAGE TO RESPRAY UNDERCOATING TO RESPRAY PAINTING AND ETC PANEL BEATING, CUT, WELD, REMOVE AND REPLACING ABOVE PARTS New 500.00 New 200.00 New 250.00 New 1,500.00 ABOVE PARTS

< END OF ESTIMATES >