

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 5876R**

AAD1910-040

*NOT Authored  
Return by paint  
82814.01*

Vehicle No.:  
Chassis No.:  
Vehicle Make:  
Vehicle Model: *24 MAR 2020*  
Date of Accident :  
Third Party Insurer :  
Date of Registration :

**SHD 5876R**  
JTDKB3FU803079270  
TOYOTA  
PRIUS  
6.10.19  
*Alled*  
17/1/2019

PART	
1	1 MOULDING ASSY, BODY ROCKER PANEL, RH
2	1 REAR FENDER RH
3	1 REAR FENDER LINER
4	1 REAR BUMPER
5	1 REAR BUMPER RE-INFORCEMENT
6	1 REAR BUMPER TOWING COVER
7	1 REAR BUMPER UNDER COVER (BLACK)
8	1 REAR BUMPER SIDE RETAINER RH
9	1 TAILLAMP LOWER RH
10	1 TAILLAMP UPPER RH
11	1 REAR BUMPER SIDE RH
12	1 REAR TAILGATE
13	1 PANEL SUB-ASSY, REAR DOOR, RH
14	1 LOCK ASSY, REAR DOOR W/MOTOR, RH

LIST	
\$	<i>Sm</i> 594.80 X
\$	<i>R</i> 854.80 ✓
\$	<i>Sm</i> 139.80
\$	<i>R</i> 442.60
\$	<i>R</i> 332.70
\$	<i>Sm</i> 15.40
\$	<i>Sm</i> 576.30
\$	<i>Sm</i> 117.70 } X
\$	<i>Sm</i> 502.00
\$	<i>Sm</i> 451.80
\$	<i>Sm</i> 123.70
\$	<i>R</i> 1,147.80
\$	<i>R</i> 1,281.70
\$	<i>Sm</i> 561.90
<b>TOTAL \$</b>	<b>7,143.00</b>
<b>25% \$</b>	<b>1,785.75</b>
<b>\$</b>	<b>5,357.25</b>

**Special Nett**

1	1 REAR DOOR STICKER '6555-3333'	\$	<i>na</i> 80.00 X
2	1 REAR RIGHT WHEEL RIM <i>→ 258</i>	\$	<i>na</i> 1,570.55 ✓
3	1 REAR RIGHT WHEEL RIM COVER	\$	<i>Sm</i> 175.80 X
4	1SET PARKING AID	\$	<i>Sm</i> 700.00 X
5	1SET REAR BUMPER CLIP	\$	<i>na</i> 66.00 X
6	1 REAR BUMPER PROTECTOR	\$	<i>Sm</i> 100.00 X
7	2 REAR WINDSCREEN SEALANT	\$	<i>na</i> 80.00 <i>30sm</i>
8	1 WINDSCREEN MOULDING	\$	<i>na</i> 100.00 X

**Trans-cab Auto Services Pte Ltd**

AAD1910-040

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 5876R**

9	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>na</i>	100.00	X
10	1	REAR TAILGATE TOYOTA LOGO	\$	<i>na</i>	47.00	X
11	1	REAR TAILGATE WORDING 'PRIUS'	\$	<i>na</i>	52.90	X
12	1	REAR TAILGATE WORDING 'HYBRID'	\$	<i>na</i>	53.50	X
13	1	REAR TAILGATE STICKER 'TRANS-CAB'	\$	<i>na</i>	80.00	X
14	1	REAR TAILGATE STICKER '6555-3333'	\$	<i>na</i>	80.00	X
<b>TOTAL</b>			<b>\$</b>		<b>3,285.75</b>	
<b>TOTAL PARTS</b>			<b>\$</b>		<b>8,643.00</b>	

**LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	4,500.00	<i>2201</i>
To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	<i>na</i> 170.00	X
To transfer of tire, rim and on wheel balancing.	\$	170.00	<i>201</i>
To check steering geometry and computer wheel alignment	\$	220.00	X
To transfer of Rear Bumper fittings, attachments and perform water seepage test.	\$	170.00	X
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	170.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,500.00	<i>6001</i>
To transfer of Rear Fender fittings, attachments and perform water seepage test.	\$	170.00	<i>* 801</i>
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>na</i> 380.00	X

**Trans-cab Auto Services Pte Ltd**

**AAD1910-040**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 5876R**

To Check Electrical Lighting Concerned.	\$	170.00	15/
To reinstall rear bumper parking sensor.	\$	<i>nn</i> 170.00	X
To Rust-Proofing Of The Affected Areas.	\$	170.00	3d
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i> 380.00	X
<b>TOTAL</b>	<b>\$</b>	<b>11,340.00</b>	
<b>Over All Total</b>	<b>\$</b>	<b>19,983.00</b>	

**(PART-BY-PART) Repair Days**

~~15~~ DAYS

4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:  
Signature:  
Date: