

ASS. REC. BY:

REF: es/CTH/19017844/02 d3n2 Special Instruction:Surveyor: Marcus

ASSIGNMENT (Office)

From (Person): Chong Buon Senof ctfDate/Time: 4/10/19 @ 5.54pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

XD 7806R

Insured:

GIBB 6324S

at Workshop m/s

Mah Lion Motor

Tel:

6282 3336

of

No. 38 Deth Lane 9

Policy No:

BMCVSN 30609818000

Claim No:

SNM 19D202404 COR

Sum Insured:

Excess:

Make of Veh:

D.O.A.

26/05/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 9.54am @ 9/10/19

Person Contacted:

Wan Roe

Vehicle IN/OUT

Date/Time	Action/Instruction	Signature
	<u>XD 7806R - NA / INC 15013228/d2</u>	<u>AVA: 1/8/2015</u>
	<u>GIBB 6324S - CCG / AG 13024110 / Uh 2m37.2</u>	<u>AVA: 15/12/2013</u>

ASS. REC. BY:

morus

Ref:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: XD 7806at Workshop m/s: noh lionof: 3.30

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 90

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or NoCA / REV / REP. / 24 HRS L1A 29161

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: XD 7806R Yr Regn: 10/13

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

☒ Truck / Trailer orMake: m.t Fuso FUS1 c.c. 12882Colour: white A/C: Insured / Std / NI / NASp. Reading: 389551 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: FV51JA10181

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ☒ Jammed / Leaked / Burnt orBrake: ☒ Jammed / Leaked / Burnt orModi: ☒ N/S/Rim / STD A/Rim orTyre Size: F: 235/80 R22.5

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Fin max

Front: _____ Rear: _____

R/Bal. 6 mm R/Bal. 0/6 0/6 mmL/Bal. 6 mm L/Bal. 0/6 0/6 mmD.O.A. 26/5/19 D.O.I. 29/10/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

o/s fnd.

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Dep 206. 444.5 m.8/11/19 confirmed L/S # 4100 with S. hai (Red # 495.56, 51.5)

RECEIVED 18 NOV 2019

Date/Time, File Pass to?

☐

Preli. Report

1) 18/4 turnish☐

Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 4Resurvey No. of Trip: 2

Survey Fee:

Transportation:

3 x RS. \$

Photos

Others

Total

220

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Inve (\$)☐ Wash and

Report Format:

MER-TP

Lump Sum / RPT:

4100

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Friday, 4 October 2019 5:54 PM
To: ct-admin@visionlawllc.com
Cc: assignments
Subject: RE: OUR REF: SNM19D202404-GBB6324S-CBS - RE: Scan Image

WITHOUT PREJUDICE

Dear Sir

We will be assigning M/s LKK AUTO CONSULTANTS to survey your client's vehicle.

Aside to LKK AUTO CONSULTANTS,

Please proceed to survey the third party vehicle on WP basis. Please merimen.

Thank you.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Claims Dept of CTI

Sent: Friday, October 4, 2019 5:28 PM

To: ct-admin@visionlawllc.com; Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>

Subject: OUR REF: SNM19D202404-GBB6324S-CBS - RE: Scan Image

Dear Boon Sen,

Please conduct PRS for XD7806R.

Note : officer in charge – Boon Sen 63896171.

Regards,

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909
T: (65) 63896116 | F: (65) 62247175

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: ct-admin@visionlawllc.com [<mailto:ct-admin@visionlawllc.com>]

Sent: Friday, October 04, 2019 3:13 PM

To: Claims Dept of CTI

Subject: Scan Image

VISION LAW LLC

Advocates & Solicitors - Notary Public - Commissioner for Oaths
Agents for Trade Marks
(Incorporated with limited liability)

ERIC NG CHING BOON
WONG KENG LEONG RAYNE
AUDREY WONG SU-HSIEN
PAUL YAP TAI SAN
ANJALLI DIO MUNIANDY
ANG KIM NOI DIANE
RAVENDRA KRISHNASAMY
TAN YINGXIAN, SELWYN
CHEONG YUNHUI, CLARISSA
SONIA LIM WEI LEE

Unique Entity Number :200721148H
✓ **HEAD OFFICE:** 133 New Bridge Road
#18-01/02 Chinatown Point
Singapore 059413

Branch: 490 Toa Payoh Lorong 6
#03-11 HDB Hub
Singapore 310490

✓ HEAD OFFICE

TEL : (65) 65342811 (Hunting)
FAX ✓ : (65) 65356802 (General)
: (65) 65355905 (Litigation)
E-mail : jactan@visionlawllc.com

BRANCH

TEL : 65 63580703
FAX : 65 63580448 (Conveyancing)

WHEN REPLYING PLEASE QUOTE OUR REFERENCE- KINDLY REPLY TO **HEAD OFFICE** FOR THIS MATTER

Our Ref: AM.jt.Ins.M46.111755.19 (sj)
Your Ref: **SNM19D202404-GBB 6324 S**

07 October 2019

CHINA TAIPING INSURANCE (S'PORE) PTE LTD
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909
Attention: Motor Claims Department

BY FAX: 6224 7175

email: claimsdept@sg.cntaiping.com
email: boonsen.chong@sg.cntaiping.com

Dear Sirs,

ACCIDENT INVOLVING XD 7806 R & GBB 6324 S ON 26 MAY 2019 ALONG CHINESE CEMETERY PATH 21 & CHINESE CEMETERY PATH 34 AT ABOUT 1200 HOURS (NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES)

We refer to your email 07 October 2019 of even date informing that you wish to conduct a pre-repair survey and your List of Surveyors.

Our client confirmed appointment LKK Auto Consultants Pte Ltd as the Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at:

Venue: Mah Lian Motor Vehicle Repairer
No.38 Defu Lane 9
Singapore 539278
Contact Person: Mr Goh / Ms Si Hui (6282 3336)

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully

ANJALLI M
(HEAD OFFICE)

cc: **XD 7806 R** – By fax: 6289-3336 only

FOR SURVEYOR

Please initial here after completion of pre-repair inspection.
Thank you.

1st Survey on _____
Appointed surveyor :
(Name & Signature)

2nd Survey on _____
Appointed surveyor
(Name & Signature)

3rd Survey on _____
Appointed Surveyor
(Name & signature)

NB.: Any settlement of offer is on the express condition that this settlement is in respect of our client's claim for property-related damages only and shall not preclude our client from claiming injury-related damages arising from this accident.

CONFIDENTIALITY

THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	537K

Vehicle Details

Vehicle No.:	XD7806R
Vehicle to be Exported:	No
Intended Deregistration Date:	30 Oct 2019
Vehicle Make:	MITSUBISHI
Vehicle Model:	FV51JJD4RDEA
Primary Colour:	Yellow
Manufacturing Year:	2013
Engine No.:	6M70457796
Chassis No.:	FV51JJA10181
Maximum Power Output:	-
Open Market Value:	\$89,858.00
Original Registration Date:	10 Oct 2013
First Registration Date:	10 Oct 2013
Transfer Count:	1
Actual ARF Paid:	\$4,493.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	09 Oct 2023
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$73,999.00
COE Rebate Amount:	\$29,161.00
Total Rebate Amount:	\$29,161.00

The information contained herein is correct as at 30 Oct 2019

OK

MAH LIAN MOTOR VEHICLE REPAIRER

No.38 Defu Lane 9 Singapore 539278
 TEL: 62823336 FAX: 62893336 Email: mahlian@singnet.com.sg
 GST:M90362564P RCB NO:201327339E

M/S : China Taiping Insurance (Singapore) Pte Ltd

TEL: - FAX: -
 ATTN: Motor Claim Department

Your Ref No: GG WASTE MNGMENT PL
 Claim Type: Own Damage/Third Party
 Accident Date: 26/05/2019
 TP Veh Reg No: GBB6324S

Estimate No: ES1700582
 Date: 05 Nov 2019
 Policy No: GA314636
 Veh Reg No: XD7806R
 Make/Model: MITSUBISHI
 FV51JJD4RDEA
 Chassis No: FV51JJA10181
 Engine No: 6M70457796
 Reg. Date: 10/10/2013

Not Authorized
 LKK
 29/10/19
 2/5 4100
 4 day!

Estimate Repair Cost to Vehicle No :XD7806R

Description	U/Price	Quantity	List Price	Amount
			SS	SS
List Price				
1 Front Fender - RH	1,212.84	1 PC	1,212.84	
2 Front Wheel Inner Shield - RH	397.17	1 PC	397.17	
3 Front Fender Garnish - RH	387.77	1 PC	387.77	
4 Front Fender Step Garnish - RH	68.00	1 PC	68.00	X
5 Front Fender Wheel Housing - RH	548.64	1 PC	548.64	
6 Front Mudguard - RH	522.18	1 PC	522.18	
7 Front Mudguard Bracket - RH	400.22	1 PC	400.22	
8 Step Panel - RH	457.24	1 PC	457.24	X
			3,994.06	
	Less 25%		998.52	2,995.56
Net Price				
9 Side Guard Assy - RH	1,800.00	1 PC	1,800.00	1,800.00
			1,800.00	1,800.00
Labour				
10 Labour to renew all above parts & knock & weld on affected area .	1,800.00	1 JOB	1,800.00	800
11 To spray & painting on affected area .	1,200.00	1 JOB	1,200.00	550
12 To rust proofing affected area .	500.00	1 JOB	500.00	X
			3,500.00	3,500.00
Total				SS 8,295.56 4
Add GST @ 7%				580.69
Total Amount Payable				SS 8,876.25

TOTAL: SINGAPORE DOLLAR EIGHT THOUSAND EIGHT HUNDRED SEVENTY SIX AND CENTS TWENTY FIVE ONLY

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No alteration/modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For MAH LIAN MOTOR VEHICLE
 REPAIRER

AUTHORISED SIGNATURE

346882
 257
 2601.61
 515161
 20%
 412

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19017844/UQD3N2

Date: 19/11/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN30609818000	
Claimant Vehicle No :	XD7806R	Insured Vehicle No :	GBB6324S	
Date of Loss:	26/05/2019	Nature of Claim:	TP	Claim No: SNM19D202404C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	XD7806R	Engine No:	6M70457796
Make & Model:	MITSUBISHI FV51JJD4RDEA, 12.9 D (M)	Chassis No:	FV51JJA10181
Reg. Date:	10/10/2013 (Man. Year: 2013)	Odometer:	389555 km
Colour:	White		
Engine Capacity:	12882 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	295/80 R22.5	Rear Tyre Size:	295/80 R22.5(D/D)
Front Left Side:	Firemax 6 mm	Rear Left Side:	Firemax 6/66/6 mm
Front Right Side:	Firemax 6 mm	Rear Right Side:	Firemax 6/66/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	4,795.54	3,801.61	993.93	20.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,500.00	1,350.00	2,150.00	61.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	8,295.54	5,151.61	3,143.93	37.90
Approved Total (Overridden) (\$\$)		4,100.00		
(\$\$)	8,295.54	4,100.00	4,195.54	50.58
+ GST 7.00/7.00% (\$\$)	580.69	287.00	293.69	50.58
Nett Amount (\$\$)	8,876.23	4,387.00	4,489.23	50.58

INSPECTION

Date of Assignment:	18/11/2019	
Date Inspected:	29/10/2019	Inspected At: Mah Lian Motor Vehicle Repairer (HQ) NO. 38 DEFU LANE 9 Singapore 539278
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 19 Nov 2019)	
Parts:	N/A	mitsubishi FV51JJD4RDEA 12.9 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for XD7806R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER-RH	Distorted	1,212.84 FL	*1,212.84 FL
2	1		*FRONT WHEEL INNER SHIELD-RH	Torn	397.17 FL	*397.17 FL
3	1		*FRONT FENDER GARNISH-RH	Torn	387.77 FL	*387.77 FL
4	1		*FRONT FENDER STEP GARNISH-RH	Not Necessary	68.00 FL	*- FL
5	1		*FRONT FENDER WHEEL HOUSING-RH	Distorted	548.64 FL	*548.64 FL
6	1		*FRONT MUDGUARD-RH	Distorted	522.18 FL	*522.18 FL
7	1		*FRONT MUDGUARD BRACKET-RH	Bent	400.22 FL	*400.22 FL
8	1		*STEP PANEL-RH	Not Necessary	457.24 FL	*- FL
9	1		*SIDE GUARD ASSY-RH	Bent	1,800.00 FS	*1,200.00 FS
					Sub Total (\$\$)	5,794.06 4,668.82
					- List Item Discount on L Items 25.00/25.00% (\$\$)	998.52 867.21
					Total Parts (\$\$)	4,795.54 3,801.61

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO RENEW ALL ABOVE PARTS & KNOCK & WELD ON AFFECTED AREA	New	1,800.00	800.00
2	TO SPRAY & PAINTING ON AFFECTED AREA	New	1,200.00	550.00
3	TO RUST PROOFING AFFECTED AREA	New	500.00	0.00
Gross Labour Cost (\$\$)			3,500.00	1,350.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >