

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Final Report

Estimate No. : **b1 52995**
Date Estimated : **08/10/2019**
Prepared By : **Gary Poh Chai Hoon**

- ESTIMATE REPAIR FOR -

Aizan Bin Asmaon
Blk 229 Yishun Street 21
#05-560

Singapore 760229

- ACCOUNT - 121

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLZ2540R	WBA1V72000V94546	27/04/2018	116d	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace front bumper and attachments, front left fender including to remove and install body parts in order to carry out painting job.	1,700.00		1,700.00 ✓
To respray front bumper and front left fender.	1,731.00		1,731.00 ✓
To replace left LED technology headlight.	408.00		408.00 ✓
To carry out body cavity preservation.	100.00		100.00 ✓
To check electrical wiring systems at the front section for proper function.	150.00		150.00 ✓
Sundries.	80.00		80.00 ✓

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# CLAMP	3.35	10.00		33.50 ✓
FRT LH FENDER	597.25	1.00		597.25 ✓
# FRT BUMPER LH INSERT	25.70	1.00		25.70 ✓
FRT BUMPER LH INSERT	60.45	1.00		60.45 ✓
# FRT BUMPER RH INSERT	60.45	1.00		60.45 ✓
FRT BUMPER PANEL PRIMED	829.65	1.00		829.65 ✓
# SET PDC HOLDER FRONT	25.75	1.00		25.75 ✓
# RIVET	0.50	6.00		3.00 ✓
LH HEADLIGHT LED TECHNOLOGY	2,145.20	1.00		2,145.20 ✓
# (DG/SL) ADHESIVE SET K6	53.05	1.00		53.05 ✓

SUPPLEMENTARY ITEMS

Total Labour :	4,169.00
Total Parts :	3,834.00
Total Labour & Parts :	8,003.00 ✓
GST @7%:	560.21
Grand Total :	8,563.21

LOSS OF USE = \$80 X 4 DAYS
LTA SEARCH FEE - \$2.00

Performance Motors Limited

A member of the Sims Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



Supplementary

Estimate No. : **b1 52995**
Date Estimated : **08/10/2019**
Prepared By : **Gary Poh Chai Hoon**

- ESTIMATE REPAIR FOR -

Aizan Bin Asmaon
Blk 229 Yishun Street 21
#05-560

Singapore 760229

- ACCOUNT - 121

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLZ2540R	WBA1V72000V94546	27/04/2018	116d	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# CLAMP / <i>MC BR</i>	3.35	10.00		33.50
# FRT BUMPER LH INSERT / <i>MC BR</i>	25.70	1.00		25.70
# FRT BUMPER RH INSERT / <i>MC BR</i>	60.45	1.00		60.45
# SET PDC HOLDER FRONT / <i>MC</i>	25.75	1.00		25.75
# RIVET / <i>MC</i>	0.50	6.00		3.00
# (DG/SL) ADHESIVE SET K6 / <i>MC</i>	53.05	1.00		53.05

SUPPLEMENTARY ITEMS

Total Labour :	
Total Parts :	201.45
Total Labour & Parts :	201.45

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559M GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

101, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

09 OCT 2019

Estimate No. : b1 52995 Page No. : 1 of 5
Date Estimated : 08/10/2019
Prepared By : Gary Poh Chai Hoon

- ESTIMATE REPAIR FOR -
Aizan Bin Asmaon
Blk 229 Yishun Street 21
#05-560

Singapore 760229

- ACCOUNT - 40000
Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLZ2540R	WBA1V72000V945462	27/04/2018	116d	0

DESCRIPTION	VALUE
To replace front bumper, left front fender and attachment include knocking cause by the accident.	1700 2,125.00
Painting front bumper, left front fender.	1731 1,923.00
To replace left headlight.	408 481.00
To carry out body cavity preservation. (Per panel).	100 118.00
To check electrical wiring systems at the front section for proper function including adjustments of headlights.	150 177.00
Sundries.	80.00

Total Labour 1: 4,904.00

DESCRIPTION	QTY	PRIC	VALUE
FRT LH FENDER / 00 ? X NN	1	597.25	597.25
SIDE PANEL BRACKET FRT LH 3	1	34.95	34.95
LH CLOSED GRID (BASIS) I X NN ? / OR	1	88.00	88.00
FRT BUMPER LH INSERT	1	60.1545	60.1545
FRT BUMPER PANEL PRIMED / CRU	1	829.65	829.65
LH HEADLIGHT LED TECHNOLOGY / DR	1	2,263.60 2145.20	2,263.60 2145.20
Total Parts :			3,873.60

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559M GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

101, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

115, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 52995
Date Estimated : 08/10/2019
Prepared By : Gary Poh Chai Hoon

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLZ2540R	WBA1V72000V945462	27/04/2018	116d	0

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No _____ Claim No _____
Date & Time 9/12/19, 10.30am Excess S\$ _____
Surveyor's Name Steve (LKK) Sign _____
Surveyor's Tel 8322 8817 Authorised Yes / No _____
Authorised Date _____ Time _____
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No _____
Surveyor's E-mail _____
No. of Working Days Recommend _____

WHL Paid
5 days
P/P
By Beh sy

Labour 1	:	4,904.00
Parts	:	3,873.80
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	614.43
Grand Total	:	9,392.03

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **