

Date: 09/10/2019
Vehicle No: SLP7148K
Model: TOYOTA HARRIER ELEGANCE 2.0 CVT
Chassis: ZSU600092173 - 2016
Reg.Year: 2017

Third Party Insurer: EQ INSURANCE
Third Party Veh No: YM9373A
Date of Accident: 08/10/2019

*Not Withheld
Recovery B4 pain 5 days*

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE	1		<i>Re</i> \$2,126.40 ✓
2	REAR TAILGATE "HARRIER" EMBLEM	1		<i>Re</i> \$73.70 ✓
3	REAR TAILGATE INNER TRIM	1		\$568.50 ✓
4	REAR TAILGATE INNER TRIM CLIPS	8	\$6.80	\$54.40 ✓
5	REAR TAILGATE REVERSE LAMP RH	1		<i>CM</i> \$560.30 ✓
6	REAR TAILGATE INNER LOCK	1		<i>Re</i> \$565.30 ✓
7	REAR TAILGATE RUBBER	1		<i>Dis / Re</i> \$441.30 ✓
8	REAR BUMPER	1		<i>CM</i> \$1,422.50 ✓
9	REAR BUMPER SIDE BRACKET LH	1		\$85.30 ✓
10	REAR BUMPER SIDE BRACKET RH	1		\$85.30 ✓
11	REAR BUMPER LOWER LIP COVER	1		<i>Re</i> \$409.50 ✓
12	REAR WINDSCREEN SIDE MOULDING	2	\$38.60	<i>Re</i> \$77.20 ✓
13	REAR WINDSCREEN LOWER MOULDING	1		<i>Re</i> \$51.50 ✓
14	REAR BUMPER CLIPS	10	\$5.50	<i>Re</i> \$55.00 ✓
15	REAR QUARTER PANEL LH	1		REPAIR
16	REAR QUARTER PANEL RH	1		REPAIR
17	REAR END PANEL	1		REPAIR
SUB TOTAL				\$6,576.20
LESS 25%				-\$1,644.05
PARTS TOTAL				\$4,932.15

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER REVERSE SENSOR SET	1		<i>Short</i> \$350.00 ✓
2	REAR WINDSCREEN SEALANT	1		<i>Re</i> \$60.00 ✓
S/N TOTAL				\$410.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1011

Branch

551 Upper Thomson Road Singapore 574415
Tel: (+65) 6452 6868 | Fax: (+65) 6452 9223



Date: 09/10/2019
 Vehicle No: SLP7148K
 Model: TOYOTA HARRIER ELEGANCE 2.0 CVT
 Chassis: ZSU600092173 - 2016
 Reg.Year: 2017

Third Party Insurer: EQ INSURANCE
 Third Party Veh No: YM9373A
 Date of Accident: 08/10/2019

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPAIR, READJUST, REPLACE REAR ACCIDENT AREAS & ETC.	\$800.00	500
LABOUR CHARGES TO REMOVE, REFIX REAR WINDSCREEN GLASS, REAR WINDSCREEN SEALANT, REAR WINDSCREEN MOULDING & ETC.	\$150.00	120
LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC. BACK TO ORIGINAL CONDITIONS.	\$120.00	80
LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR TAILGATE, REAR BUMPER, REAR QUARTER PANEL LH, REAR QUARTER PANEL RH & ETC.	\$1,200.00	660
LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC.	\$80.00	50
TO TUFF KOTE & UNDERSEAL MATERIALS.	\$150.00	30
TO DIAGNOSIS FAULTY CODE & RESET MEMORY.	\$120.00	2
LABOUR TOTAL	\$2,620.00	

ONG	TOTAL	\$7,962.15
-----	--------------	-------------------