

15/02/00

INS. CASE OWNER

CC 4/AIG1901 7876, A

LKK:
IDAC:

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

If NO, Driver Name / Age:

Driver Tel No.:

HP:

D.O.A:

Nature of Accident:

(V/L) YES / NO

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO

Insured Liability: %

TP GIA REPORT: YES / NO

Final ? Yes / No

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time	STAGE	DATE / PIC
	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	
	After call ltr to OI:	
	Authorisation To Act:	
	Release Voucher:	
	Final Repair Bill:	
	Car Rental Invoice:	
	Towing Invoice:	
	LTA / GIA:	
	Medical Bill:	
	PIR:	
	Mandate/Reject Instruction:	
	LOD	
	Payment Breakdown Form:	
	Post-Repair Photos:	
	Others:	

PRELIMINARY ADVICE	Date/Time:	Sent By:
FINALIZATION	Date/Time:	Confirm with:
Repair Cost:	SS	(days) Reduction: %
FINAL SETTLEMENT	Date/Time: 28/02/2020	Confirm with: Kae King
Final Liability:	% 100	(Agreed / Assessed) BOLA S/N No. : 10
Repair Cost:	SS 1460.00	
Loss of Rental (LOR):	SS -	(days)
Loss of Use (LOU):	SS 400.00	is 80 x 5 days
Loss of Income (LOI):	SS -	(\$ x days)
LOR only ☐ LOU only ☐	☒ LOR + LOU ☐ LOR + LOI ☐	[Tick only one]
GIA/LTA Search	SS 36.45	
Medical:	SS -	
Disbursement:	SS -	(e.g. Tow/ Independent)
Legal Cost	SS -	
Total:	SS 15036.45	Global Sum SS:
FINAL PAYMENT	Date/Time:	Confirm with:
Payee 1:	SS 15036.45	Name 1: Auto Both Body & Paint Pte Ltd
Payee 2: (Strike if N.A.)	SS	Name 2:
Payee 3: (Strike if N.A.)	SS	Name 3:

COPY SENT
2/3/2020

ASS. REC. BY:

REF:

A1G

ASSIGNMENT

From: _____ Date: 10.10.2019

Estimated Cost: _____

OD TP / VS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SKF 6897Cat Workshop m/s: Auto Bolt Body & Paintof 8 Kabi Bukit Avenue 4 #03-01

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

mp

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKF6897C Yr Regn: 2011, Oct.Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi A8 c.c. 2995Colour: Black A/C: Insured / Std / NI / NASp. Reading: 61834 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAU2ZZ4H 6BN 027028Gen. Cond: Good / Fair / Poor / BurntSteering: Ign / Jammed / Leaked / Burnt orBrake: Ign / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 255/45R19.

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 10/10/19.

Survey held at

Auto Bolt.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or +.

Front N/S.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP A1G.

45- \$14600 (Red \$ 8998.84 / 38%)

MV: 88/c

PV: 646/c

NCH: 23.4/c

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ Site Insp (\$☐ Interview (\$☐ Tech. Invs (\$☐ Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Rep. Form:

Lump Sum / I.D. is:

AUTO BOLT BODY AND PAINT PTE LTD

8 Kaki Bukit Avenue 4 #03-01 Premier @ Kaki Bukit Singapore 415875

Email: autoboltsvc@singnet.com.sg

Tel: 6384 1066 Fax: 6384 1067

- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and acknowledged by Repairer

TPAIG

9 October 2019

Reg No.: **SKF 6897.C**

Model: **AUDI A8**
Acknowledged by Repairer

Jia Le

QTY	DESCRIPTION	AMT \$
-----	-------------	--------

List Items

1	Front headlamp -L/H <i>lit</i>	\$ 2,764.80 ✓
1	Front bumper <i>Delint</i>	\$ 2,264.40 ✓
1	Front bumper clip (1 set) <i>new</i>	\$ 80.00 <i>30</i>
1	Front bumper inner sponge <i>new</i>	\$ 105.60 ✓
1	Front bumper reinforcement <i>new</i>	\$ 755.00 ✓
1	Front bumper side grille <i>new</i>	\$ 352.00 ✓
1	Front bumper side retainer <i>new</i>	\$ 44.00 ✓
1	Front bumper top seal <i>new</i>	\$ 135.00 ✓
1	Front bumper undercover <i>new</i>	\$ 215.60 ✓
2	Front bumper PDC sensors	\$ 431.20 ✓
1	Front fender -L/H <i>Delint</i>	\$ 1,548.80 ✓
1	Front fender inner shield <i>torn</i>	\$ 448.80 ✓
1	Front fender inner shield clip (1 set) <i>new</i>	\$ 80.00 <i>30</i>
1	Front wheel hub <i>new</i>	\$ 215.00 ✓
1	Front wheel bearing <i>new</i>	\$ 105.00 ✓
1	Front shock absorber <i>new</i>	\$ 960.00 ✓
1	Front knuckle arm <i>best</i>	\$ 760.00 ✓
1	Front lower arm <i>best</i>	\$ 419.00 ✓
2	Front top arms <i>best</i>	\$ 950.00 ✓
1	Front control arm <i>best</i>	\$ 425.00 ✓
1	Power steering rack <i>best</i>	\$ 6,308.00 ✓
		\$ 18,967.20
	Less 5%	\$ 948.36
		\$ 18,018.84

Special Nett Items

1	Front tyre <i>new</i>	\$ 550.00 ✓
1	Front wheel rim -L/H <i>lit</i>	\$ 1,200.00 <i>100</i>
		\$ 1,750.00

S/N Labour Charges

1	To check wiring and reset headlamps focusing.	\$ 80.00 <i>30</i>
2	To remove and refit front sensor.	\$ 150.00 <i>80</i>
3	To remove and refit front undercarriage.	\$ 450.00 <i>280</i>
4	To conduct wheel alignment.	\$ 150.00 <i>80</i>
5	To apply undercoating.	\$ 100.00 ✓
6	Panel beating.	\$ 1,400.00 <i>700</i>
7	To respray painting on the affected areas.	\$ 1,200.00 <i>50</i>
8	To diagnose erase fault memory after repair.	\$ 300.00 <i>120</i>
		\$ 3,830.00

Grand Total: \$ 23,598.84

Total: 18,345.71

L.S.: 14.6K

PRE-REPAIR INSPECTION REQUEST – SKF6897C vs SKQ947Z (OI) on D.O.A.: 09/10/2019

From: Hor, Yinrul
 To: 'assignmema@lkkauto.com', Admin A (admin-a@lkkauto.com)
 Cc: Fong, Andy-SY, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Parthiban, Theerthan, Subramaniam, Divy
 Sent: Thursday, 10 October, 2019 1:20:27 PM

Hi,

Please refer to the enclosed request from Auto Bolt Body & Paint Pte Ltd.

Claim no : 25988029875G003
 Case Owner : Bernard Lee Ji Qian

If you have any queries/concerns, please let us know.
 Kindly assist to assign Adrian Ling as Single Joint Expert as requested.

Thanks & Regards,

Hor Yin Rul (Viviane)
 AIG
 FNOL Adjuster I
 Singapore FNOL | Claims Operations – Auto

Tel: 8001200000 | Ext: 1002208
 Email: Yinrul.Hor@aig.com | www.aig.sg

P: Kai Ling

T: 1-31p.m

V: 1h

E: ✓

From: Autobolt Body & Paint Pte Ltd [mailto:autoboltp@gmail.com]

Sent: Thursday, October 10, 2019 11:44 AM

To: Hor, Yinrul

Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Parthiban, Theerthan; Subramaniam, Divyashni

Subject: [EXTERNAL] RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKQ947Z AND SKF6897C ON 09/10/2019

This message is from an external sender; be cautious with links and attachments.

Hi Yinrul,

Please send Mr Adrian Ling from LKK Auto Consultants Pte Ltd.

Thanks & Regards,

Kai Ling
 Auto Bolt Body & Paint Pte Ltd
 8 Kaki Bukit Avenue 4 #03-01 Singapore 415875
 Tel: 9061 2555
 9068 7204
 9851 1300

Email: autoboltp@gmail.com

Like us on our Facebook page @ Auto Bolt Body & Paint Pte Ltd

From: Hor, Yinrul <Yinrul.Hor@aig.com>

Sent: Thursday, 10 October, 2019 11:42 AM

To: autoboltp@gmail.com

Cc: Fong, Andy-SY <Andy-SY.Fong@aig.com>; Chin, Lee-Ying <Lee-Ying.Chin@aig.com>; Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>; Azlan, Syazairdina <Syazairdina.Azlan@aig.com>; Chan, Yoke Shi <yokeshi.chan@aig.com>; Lim, Sheng Yang <ShengYang.Lim@aig.com>; Mithoosingh, Aashweenjeetkaur <Aashweenjeetkaur.Mithoosingh@aig.com>; Parthiban, Theerthan <Theerthan.Parthiban@aig.com>; Subramaniam, Divyashni <Divyashni.Subramaniam@aig.com>

Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKQ947Z AND SKF6897C ON 09/10/2019



This is a secure, encrypted message. To read it, open the attachment.

这是安全加密信息。如需阅读此信息，请开启附件。

გამოწმებულია, რომ ეს არის უსაფრთხო, დაშიფვნილი საკომუნიკაციო.

이것은 안전한 암호화된 메시지입니다. 그것을 읽으려면 첨부파일을 엽니다.

Ini adalah pesan, aman terenkripsi. Untuk membacanya, membuka attachment.

[Click here](#) by 2019-10-17 11:41 +08 to read your message.
 After that, open the attachment.

[More info](#)

Disclaimer: This email and its content are confidential and intended solely for the use of the addressee. Please notify the sender if you have received this email in error or simply delete it.

Secured by Proofpoint Encryption, Copyright © 2009-2017 Proofpoint, Inc. All rights reserved.



Virus-free: www.aig.com

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: Yinnul Hor@aig.com
 To: autoboltp@gmail.com
 Cc: Andy SY Fong@aig.com; Lee-Ying Ching@aig.com; NoorManessa.AbuKassim@aig.com; Syazairdina Azlan@aig.com; yokeeshi.chan@aig.com; ShengYang.Lim@aig.com; Aashweenjeetkaur.Mithosingh@aig.com; Theerthan Parthiban
 Subject: aigenrypt PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKQ947Z AND SKF6897C ON 09/10/2019
 Date: Thu, 10 Oct 2019 03:41:32 +0000

Without Prejudice

Your Reference : SKF6897C
 Our Reference : 2598802987SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufik	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasol	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Hor Yinn Rul (Viviane)
 AIG
 FNOL Adjuster I
 Singapore FNOL / Claims Operations - Auto

Tel: 8001206886 | Ext: 10022068
Yinnul.Hor@aig.com | www.aig.sg

From: Autobolt Body & Paint Pte Ltd [mailto:autoboltp@gmail.com]
 Sent: Thursday, October 10, 2019 10:53 AM
 To: ClaimsDocManagement
 Cc: alvinong@singnet.com.sg
 Subject: [EXTERNAL] Accident involving SKF6897C and SKQ947Z on 09/10/2019 - Arrange for 2 day Pre-inspection for Direct Settlement

This message is from an external sender; be cautious with links and attachments.

Dear Claim Department,

Please kindly arrange for a pre-repair survey for SKF6897C.

Details as per below:

Our Client: SKF6897C
 Your Insured: SKQ947Z
 Date of Accident: 9 Oct 2019

Workshop Address:
 Auto Bolt Body & Paint Pte Ltd
 8 Kaki Bukit Avenue 4 #03-01 Singapore 415875

Thanks & Regards,

Kai Ling

Auto Bolt Body & Paint Pte Ltd

8 Kaki Bukit Avenue 4 #03-01 Singapore 415875

Tel: 9061 2555

9068 7204

9851 1300

Email: autoboltbd@gmail.com

Like us on our Facebook page @ Auto Bolt Body & Paint Pte Ltd

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner Information	
Owner ID Type:	Singapore NRIC
Owner ID:	737E
Vehicle Information	
Vehicle No.:	SKF6897C
Vehicle to be Exported:	Yes
Intended Deregistration Date:	11 Oct 2019
Vehicle Make:	AUDI
Vehicle Model:	A8L 3.0 TFSI QU (SR+HID)
Primary Colour:	Black
Manufacturing Year:	2011
Engine No.:	CGW013088
Chassis No.:	WAUZZZ4H6BN027028
Maximum Power Output:	213.0 kW (285 bhp)
Open Market Value:	\$81,914.00
Original Registration Date:	24 Oct 2011
First Registration Date:	24 Oct 2011
Transfer Count:	1
Actual ARF Paid:	\$81,914.00
PARF Eligibility	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Oct 2021
PARF Rebate Amount:	\$49,148.00
COE Information	
COE Expiry Date:	23 Oct 2021
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$75,889.00
COE Rebate Amount:	\$15,422.00
Total Rebate Amount:	\$64,570.00

The information contained herein is correct as at 11 Oct 2019

OK

Jia Le (LKK Auto)

From: Ler, Bernard-JQ <Bernard-JQ.Ler@aig.com>
Sent: Monday, 17 February 2020 1:51 PM
To: Jia Le (LKK Auto)
Subject: RE: <MANDATE REQUEST>Your ref: 2598802987SG [ACCIDENT INVOLVING VEHICLES SKQ947Z AND SKF6897C ON 09/10/2019]

Hi Jia Le,

Please let us have the replacement photos of the undercarriage parts in Merimen.

Thanks.

Best Regards,

Bernard Ler
AIG
Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore(079120)

Tel +(65) 6419 1946

Bernard-JQ.Ler@aig.com | www.aig.com.sg

From: Jia Le (LKK Auto) [mailto:JiaLe@lkkauto.com]
Sent: 03 February 2020 11:43
To: Ler, Bernard-JQ <Bernard-JQ.Ler@aig.com>
Subject: [EXTERNAL] <MANDATE REQUEST>Your ref: 2598802987SG [ACCIDENT INVOLVING VEHICLES SKQ947Z AND SKF6897C ON 09/10/2019]

This message is from an external sender; be cautious with links and attachments.

AIG Ref: **2598802987SG**

LKK Ref: CC4/AIG19017876/Adb3

Dear Sirs/Madam,

ACCIDENT INVOLVING SKQ 947Z(OI) AND SKF 6897C(TP) ON 09/10/2019

We refer to the above matter.

View Received Message

This mail is associated with :

***SKF6897C (2598802987SG)**
[SKQ947Z]
TP
LAI HUEN POH
Oct 9 2019 12:00AM
[TAN BEE HONG JUDY]
Auto Bolt Body & Paint Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 18/02/2020 16:14 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$15036.45) - SKF6897C - Claim Handler: Ler, Bernard-JQ

Approved:15036.45:Cost of Repair : \$14,600.00 Loss of Use : \$400.00 5 days @ S\$ 80/day LTA/ GIA Search Fee : \$36.45 Total : \$15,036.45

DOCUMENTS SUMMARY

There are no documents.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Oct 2019 Edit Reg		10 Oct 2019 00:00 Edit Adj Rpt	S\$14,600.00 Edit Estimates	S\$14,600.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	TAN BEE HONG JUDY, ID: S1851572E, Tel: +6596388463								
Main Claimant:	LAI HUEN POH, ID: S2503737E								
Vehicle Reg. No.:	SKF6897C	Date of Loss:	09/10/2019 00:00 - :59 [95 Months and 15 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 2598802987SG	Policy/Cover Note No.:	(Comprehensive)						
Vehicle Reg. No. (Insured):	SKQ947Z	Policy No. (Claimant):	S119V03449VPC/R06						
		Excess:							
Repairer:	Auto Bolt Body & Paint Pte Ltd (HQ) 8 Kaki Bukit Ave 4, #03-01 Premier @ Kaki Bukit, 415875 Kaki Bukit - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ler, Bernard-JQ] BernardJiQian.Ler@aig.com								
Claimant's Insurer:	Liberty Insurance Pte Ltd (HQ) - Tel: (65) 6221 8611								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 21/10/2019]								
Driver/Custodian (Insured):	TAN BEE HONG JUDY () . NRIC: S1851572E, Tel: +6596388463 Email:								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG_EXPRESS (18/02/2020): Alert - Adj Mandate Approved (S\$15036.45) - SKF6897C - Claim Handler: Ler, Berna... - AIG_SG_EXPRESS (14/02/2020): Alert - Adj Mandate Maintained - SKF6897C - Claim Handler: Ler, Bernard-JQ - AIG_SG (11/10/2019): TP GIA REPORT									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKF6897C (25988029875G)
[SKQ947Z]
TP
LAI HUEN POH
Oct 9 2019 12:00AM
[TAN BEE HONG JUDY]
Auto Bolt Body & Paint Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Letters/Correspondences															1 per page		☒			
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print			
1	(Draft)		Third Party Express Settlement – Payment Breakdown														Edit			
Photos/Images															3 per page		☒			
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print			
1	06/01/20 18:50		General View														Load JPG ☒			
2	06/01/20 18:50		General View														Load JPG ☒			
3	06/01/20 18:50		General View														Load JPG ☒			
4	06/01/20 18:50		General View														Load JPG ☒			
5	06/01/20 18:50		General View														Load JPG ☒			
6	06/01/20 18:50		General View														Load JPG ☒			
7	06/01/20 18:50		General View														Load JPG ☒			
8	06/01/20 18:50		General View														Load JPG ☒			
9	06/01/20 18:50		General View														Load JPG ☒			
10	06/01/20 18:50		General View														Load JPG ☒			
11	06/01/20 18:50		General View														Load JPG ☒			
12	06/01/20 18:50		General View														Load JPG ☒			
13	06/01/20 18:50		General View														Load JPG ☒			
14	06/01/20 18:50		General View														Load JPG ☒			
15	06/01/20 18:50		General View														Load JPG ☒			
16	06/01/20 18:50		General View														Load JPG ☒			
17	06/01/20 18:50		General View														Load JPG ☒			
18	06/01/20 18:50		General View														Load JPG ☒			
19	06/01/20 18:50		General View														Load JPG ☒			
20	06/01/20 18:50		General View														Load JPG ☒			
21	06/01/20 18:50		General View														Load JPG ☒			
22	06/01/20 18:51		Reinspection Photo														Load JPG ☒			
23	06/01/20 18:51		Reinspection Photo														Load JPG ☒			
24	06/01/20 18:51		Reinspection Photo														Load JPG ☒			
25	06/01/20 18:51		Reinspection Photo														Load JPG ☒			
26	06/01/20 18:51		Reinspection Photo														Load JPG ☒			
27	06/01/20 18:51		Reinspection Photo														Load JPG ☒			
28	06/01/20 18:51		Reinspection Photo														Load JPG ☒			
29	06/01/20 18:51		Reinspection Photo														Load JPG ☒			
30	06/01/20 18:51		Reinspection Photo														Load JPG ☒			
31	06/01/20 18:51		Reinspection Photo														Load JPG ☒			
32	06/01/20 18:51		Reinspection Photo														Load JPG ☒			
33	06/01/20 18:51		Reinspection Photo														Load JPG ☒			
34	06/01/20 18:51		Reinspection Photo														Load JPG ☒			
35	06/01/20 18:51		Reinspection Photo														Load JPG ☒			
36	06/01/20 18:51		Reinspection Photo														Load JPG ☒			
37	06/01/20 18:51		Reinspection Photo														Load JPG ☒			
38	06/01/20 18:51		Reinspection Photo														Load JPG ☒			
39	06/01/20 18:51		Reinspection Photo														Load JPG ☒			
40	06/01/20 18:51		Reinspection Photo														Load JPG ☒			

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				☒
41	06/01/20 18:51	Reinspection Photo	Load JPG	☒
42	06/01/20 18:51	Reinspection Photo	Load JPG	☒
43	06/01/20 18:51	Reinspection Photo	Load JPG	☒
44	06/01/20 18:51	Reinspection Photo	Load JPG	☒
45	06/01/20 18:51	Reinspection Photo	Load JPG	☒
46	06/01/20 18:51	Reinspection Photo	Load JPG	☒
47	06/01/20 18:51	Reinspection Photo	Load JPG	☒
48	06/01/20 18:51	Reinspection Photo	Load JPG	☒
49	06/01/20 18:51	Reinspection Photo	Load JPG	☒
50	06/01/20 18:51	Reinspection Photo	Load JPG	☒
51	06/01/20 18:51	Reinspection Photo	Load JPG	☒
52	06/01/20 18:51	Reinspection Photo	Load JPG	☒
53	06/01/20 18:51	Reinspection Photo	Load JPG	☒
54	06/01/20 18:51	Reinspection Photo	Load JPG	☒
55	06/01/20 18:51	Reinspection Photo	Load JPG	☒
56	06/01/20 18:51	Reinspection Photo	Load JPG	☒
57	18/02/20 12:14	After Repair Photo	Load JPG	☒
58	18/02/20 12:14	After Repair Photo	Load JPG	☒
59	18/02/20 12:14	After Repair Photo	Load JPG	☒
60	18/02/20 12:14	After Repair Photo	Load JPG	☒
61	18/02/20 12:14	After Repair Photo	Load JPG	☒
62	18/02/20 12:14	After Repair Photo	Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	10/10/19 14:37	EMAIL FROM AIG DD 10102019	Load PDF	
2	11/10/19 15:25	TP GIA REPORT	Load PDF	
3	31/01/20 16:44	LTA SEARCH	Load PDF	
4	31/01/20 16:44	LOD	Load PDF	
5	31/01/20 16:44	GIA SEARCH	Load PDF	
6	31/01/20 16:44	LETTER TO OI	Load PDF	
7	14/02/20 15:18	wheel alignment report	Load PDF	
8	04/03/20 10:40	WORKSHOP INVOICE	Load PDF	
9	04/03/20 10:40	AUTHORISATION TO ACT FORM	Load PDF	
10	04/03/20 10:40	Release Voucher	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	11/10/19 14:58	OI GIA REPORT	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKQ947Z (Insd veh)	Model:	AUDI A8 L 3.0 TFSI QU (A)
	SKF6897C (TP veh)		
Date of Accident:	09/10/2019		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	23,598.84
Final Repair Cost	:	\$	14,600.00
Loss of Use	:	\$	400.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	36.45
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	15,036.45

5.00 days at \$80.00 per day
days

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ 100 _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Auto Bolt Body & Paint Pte Ltd	:	\$ 15,036.45
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

04 Mar
2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19017876/ADS3Q2

Date: 04/03/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant Vehicle No : SKF6897C

Insured Vehicle No : SKQ947Z

Date of Loss: 09/10/2019

Nature of Claim: TP

Claim No: 2598802987SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKF6897C

Make & Model: AUDI A8 L, 3.0 TFSI QU (A)

Engine No: CGW013088

Reg. Date: 24/10/2011 (Man. Year: 2011)

Chassis No: WAUZZZ4H6BN027028

Colour: Black

Odometer: 61834 km

Engine Capacity: 2995 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 255/45 R19

Rear Tyre Size:

255/45 R19

Front Left Side: Pirelli 6 mm

Rear Left Side:

Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side:

Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,768.84	16,497.16	3,271.68	16.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,830.00	1,840.00	1,990.00	51.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,598.84	18,337.16	5,261.68	22.30
Approved Total (Overridden) (S\$)		14,600.00		
Nett Amount (S\$)	23,598.84	14,600.00	8,998.84	38.13
+ Loss of Use (5.0 x S\$80.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		15,036.45		

INSPECTION

Date of Assignment: 10/10/2019

Date Inspected: 10/10/2019 Inspected At:

Auto Bolt Body & Paint Pte Ltd (HQ)
8 Kaki Bukit Ave 4, #03-01 Premier @
Kaki Bukit
Singapore 415875

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT HEADLAMP - L/H	Cut	2,764.80 FL	*2,764.80 FL
2	1		*FRONT BUMPER	Deformed	2,264.40 FL	*2,264.40 FL
3	1		*FRONT BUMPER CLIP (1 SET)	Necessary	80.00 FL	*30.00 FL
4	1		*FRONT BUMPER INNER SPONGE	Not Necessary	105.60 FL	*- FL
5	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	755.00 FL	*- FL
6	1		*FRONT BUMPER SIDE GRILLE	Not Necessary	352.00 FL	*- FL
7	1		*FRONT BUMPER SIDE RETAINER	Necessary	44.00 FL	*44.00 FL
8	1		*FRONT BUMPER TOP SEAL	Not Necessary	135.00 FL	*- FL
9	1		*FRONT BUMPER UNDERCOVER	Not Necessary	215.60 FL	*- FL
10	2		*FRONT BUMPER PDC SENSORS	Not Necessary	431.20 FL	*- FL
11	1		*FRONT FENDER - L/H	Dented	1,548.80 FL	*1,548.80 FL
12	1		*FRONT FENDER INNER SHIELD	Torn	448.80 FL	*448.80 FL
13	1		*FRONT FENDER INNER SHIELD CLIP (1 SET)	Necessary	80.00 FL	*30.00 FL
14	1		*FRONT WHEEL HUB	Damaged	215.00 FL	*215.00 FL
15	1		*FRONT WHEEL BEARING	Necessary	105.00 FL	*105.00 FL
16	1		*FRONT SHOCK ABSORBER	Not Necessary	560.00 FL	*- FL
17	1		*FRONT KNUCKLE ARM	Bent	760.00 FL	*760.00 FL
18	1		*FRONT LOWER ARM	Bent	419.00 FL	*419.00 FL
19	2		*FRONT TOP ARMS	Bent	950.00 FL	*950.00 FL
20	1		*FRONT CONTROL ARM	Bent	425.00 FL	*425.00 FL
21	1		*POWER STEERING RACK	Bent	6,308.00 FL	*6,308.00 FL
22	1		*FRONT TYRE	Not Necessary	550.00 FS	*- FS
23	1		*FRONT WHEEL RIM - L/H	Cut	1,200.00 FS	*1,000.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	20,717.20	17,312.80
- List Item Discount on L Items 5.00/5.00% (S\$)	948.36	815.64
Total Parts (S\$)	19,768.84	16,497.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING AND RESET HEADLAMPS FOCUSING.	New	80.00	30.00
2	TO REMOVE AND REFIT FRONT SENSOR.	New	150.00	80.00
3	TO REMOVE AND REFIT FRONT UNDERCARRIAGE.	New	450.00	280.00
4	TO CONDUCT WHEEL ALIGNMENT.	New	150.00	80.00
5	TO APPLY UNDERCOATING.	New	100.00	0.00
6	PANEL BEATING.	New	1,400.00	750.00
7	TO RESPRAY PAINTING ON THE AFFECTED AREAS.	New	1,200.00	500.00
8	TO DIAGNOSE ERASE FAULT MEMORY AFTER REPAIR.	New	300.00	120.00
Gross Labour Cost (S\$)			3,830.00	1,840.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >