

INS. CASE OWNER:

Loh Chee Heng

CC4/AIG19017882/Gda3

LKK:

IDAC:

Surveyor:

GUO QIANG

DOI: 10/10/2019

Date / Time: 10/10/2019

Registered in Merimen: 10/10/2019

Pre-assign / CCU / FTE



Insured Vehicle No.:

SMK 7158X

Claim No.:

8177161573SG

Name of Insured:

BIS MOTORING PTE LTD

Policy No.:

Insured Tel No.:

HP:

Make / Model:

RENAULT GRAND SCENIC IV 1.5

Excess Sec II :SS

D.O.A: 05/10/2019 18:35

MARINE PARADE ROAD INFRONT OF CHURCH OF SINGAPORE

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

QUAH ENG MENG

OI GIA REPORT: YES / NO ; TI GIA REPORT: YES / NO

Driver Tel No.:

+65-90626131 (V/L: YES / NO)

Insured Liability:

Final ? Yes / No

SFG 618K



INSRS:

WSP:

Tel:

Liability:

RMKS:

ABWIN
SERVICE

INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time	STAGE	DATE / PIC
	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup):	☐
	After call ltr to OI:	☒
	Authorisation To Act:	☒
	Release Voucher:	☒
	Final Repair Bill:	☒
	Car Rental Invoice:	☒
	Towing Invoice:	☐
	LTA / GIA:	☒
	Medical Bill:	☐
	PIR:	☐
	Mandate/Reject Instruction:	☐
	LOD:	☒
	Payment Breakdown Form:	☐
	Post-Repair Photos:	☐
	Others:	☐

PRELIMINARY ADVICE		Date/Time:	Sent By:
FINALIZATION		Date/Time:	Confirm with:
Repair Cost:	SS	(days) Reduction:	%
FINAL SETTLEMENT		Date/Time: 4/1/2020	Confirm with: Abby
Final Liability:	% 100	(Agreed / Assessed) BOLA S/N No.:	27
Repair Cost: (w/ln)	SS 4387.00		
Loss of Rental (LOR):	SS 980.00	(7 days) x \$140	
Loss of Use (LOU):	SS -	(5 x days)	
Loss of Income (LOI):	SS -	(5 x days)	
LOR only ☒ LOU only ☐	LOR + LOU ☐	LOR + LOI ☐	[Tick only one]
GIA/LTA Search	SS 7.45		
Medical:	SS -		
Disbursement:	SS -	(e.g. Tow/ Independent)	
Legal Cost	SS -		
Total:	SS 5374.45	Global Sum SS:	
FINAL PAYMENT		Date/Time:	Confirm with:
Payee 1:	SS 5374.45	Name 1:	Abwin Service Pte Ltd
Payee 2: (Strike if N.A.)	SS	Name 2:	
Payee 3: (Strike if N.A.)	SS	Name 3:	

COPY SENT
10/3/2020

1) Claim status: Normal/Reject/Private Settle

2) Report Format: TP

3) Survey fee: \$320

Surveyor

GRL.

REF:

A/G

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD ☒ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV ☐

To inspect Vehicle No: _____

at Workshop m/s Abwin

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No:

SFG 618K

Yr Regn:

09 Sep 2016

Type: ☒ M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Harrier c.c. 1986

Colour

white

A/C: Insured / Std / NI / NA

Sp. Reading

60859

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

854600074935

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD ☒ A/Rim or

Tyre Size:

F: 235/55 R18

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mmL/Bal. 6 mm

D.O.A. _____

Survey held at

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

Rear

R/Bal. 6 mmL/Bal. 6 mmD.O.I. 10-10-19

w/s 4pm

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

17/2 Finalized \$4100 with Abwin
(Red \$9931.87/717.)

Date/Time, File Pass to?



: Preli. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

) \$ + RS. \$ Si

) Photos

) Others

TOTAL

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

ABWIN SERVICE PTE LTD

8 KAKI BUKIT AVENUE 4 - GATE 2
 #07-48 PREMIER @ KAKI BUKIT SINGAPORE 415875
 Tel: 67139400 Fax: 67139415
 Email: servicecentre@abwinm9.com.sg Website: www.abwinm9.com
 Company Reg. No: 201318685G GST Reg. No: 201318685G



ESTIMATED COST: HQQ000124

TO : AIG ASIA PACIFIC INSURANCE PTE. LTD.
 ATTN : MOTOR CLAIM DEPARTMENT

DATE : 10-OCT-2019
 MAKE : TOYOTA
 MODEL : HARRIER PREMIUM 2.0 A
 CHASSIS NO : ZSU600074935
 ENGINE NO : 3ZRB755323
 SERVICE ADVISOR : ABBY LIM
 PAGE : 1 OF 2

SFG618K
 LEE TZE BOON (LI ZHIWEN)
 CONTACT NO : 96990958

QTY	DESCRIPTION	REPAIR AMOUNT (SGD)	SURVEYOR APP (SGD)
LIST ITEM			
1	REAR BUMPER / Re.	1,495.30	1349
1	REAR BUMPER BRACKET R/H 500 X NN	95.80	X
1	REAR BUMPER BRACKET L/H 500 X NN	95.80	X
1	REAR BUMPER SIDE RETAINER	65.70	/
1	REAR END PANEL R/buc Re.	801.30	597.1
1	REAR END PANEL TOP GARNISH R/ Re	387.90	/
1	REAR BUMPER SPONGE R/CRA	127.80	/
1	REAR BUMPER LOWER GARNISH - Cut.	396.10	/
1	REFLECTOR X NN	56.70	X
1	TAILGATE / Buc.	1,621.50	1228.8
1	TAILGATE LOCK X NN	991.40	X
1	TAILGATE LAMP R/H 500 X NN	422.80	X
1	TAILGATE LAMP L/H X NN	422.80	X
1	TAIL LAMP R/H 500 X	451.60	X
1	SPARE TYRE PANEL X R/CRA	896.30	X
1	WEATHER STRIP X NN	443.07	X
Sub Total		8,771.87	4142.4 0.00

SPECIAL NETT

2	REVERSE SENSOR / DM.	760.00	200
1	REVERSE CAMERA X NN	680.00	X
10	REAR BUMPER CLIPS / MCL.	50.00	30
1	REAR END PANEL SEALANT R/MCL.	50.00	20
1	TAILGATE SEALANT X NN	50.00	X
1	TOYOTA LOGO X	80.00	X
1	EMBLEM "HARRIER" / MCL.	80.00	50
1	NUMBER PLATE / SCR	50.00	40
1	NUMBER PLATE BRACKET X NN	50.00	X

240

ABWIN SERVICE PTE LTD

8 KAKI BUKIT AVENUE 4 - GATE 2
#07-48 PREMIER @ KAKI BUKIT SINGAPORE 415875
Tel: 67139400 Fax: 67139415
Email: servicecentre@abwinm9.com.sg Website: www.abwinm9.com
Company Reg. No: 201318685G GST Reg. No: 201318685G

**ESTIMATED COST: HQ000124**

TO : AIG ASIA PACIFIC INSURANCE PTE. LTD.
ATTN : MOTOR CLAIM DEPARTMENT

SFG618K
LEE TZE BOON (LI ZHIWEN)
CONTACT NO : 96990958

DATE : 10-OCT-2019
MAKE : TOYOTA
MODEL : HARRIER PREMIUM 2.0 A
CHASSIS NO : ZSU600074935
ENGINE NO : 3ZRB755323
SERVICE ADVISOR : ABBY LIM
PAGE : 2 OF 2

QTY	DESCRIPTION	REPAIR AMOUNT (SGD)	SURVEYOR APP (SGD)
	Sub Total	1,850.00	0.00

LABOUR

1	TO CONDUCT PANEL BEATING AND STRAIGHTEN PARTS ON DAMAGED AREAS	1,200.00	500 800	
1	TO SPRAY PAINT ON AFFECTED AREAS	1,200.00	600	
1	TO APPLY TUFF COAT ON AFFECTED AREAS	100.00	7 60	
1	TO DISMANTLE, REPLACE AND/OR REPAIR REVERSE SENSOR & TESTING	180.00	40.	
1	TO DISMANTLE, REPLACE AND/OR REPAIR CAMERA & TESTING	200.00	40	
1	TO CHECK WIRING	100.00	30	
1	TO DISMANTLE, REPLACE AND/OR REPAIR TAILGATE COMPONENTS	250.00	60	
1	TO DISMANTLE & REFIX INTERIOR UPHOLSTERY	180.00	60.	
	Sub Total	3,410.00	1690	0.00

4 Days (5)

Impsm repair.

After repair photos.

Quo Qiang - 82880282

10/10/19

5136.8
70%: 4100

SUB-TOTAL	14,031.87	0.00
GST - 7 %	982.23	0.00
TOTAL	15,014.10	0.00

ABWIN SERVICE PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Prepared By: _____
Reviewed by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	607I
Vehicle Details	
Vehicle No.:	SFG618K
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Oct 2019
Vehicle Make:	TOYOTA
Vehicle Model:	HARRIER PREMIUM 2.0 A
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	3ZRB755323
Chassis No.:	ZSU600074935
Maximum Power Output:	111.0 kW (148 bhp)
Open Market Value:	\$32,947.00
Original Registration Date:	09 Sep 2016
First Registration Date:	09 Sep 2016
Transfer Count:	0
Actual ARF Paid:	\$33,126.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	08 Sep 2026
PARF Rebate Amount:	\$24,844.00
Intended COE Rebate Details	
COE Expiry Date:	08 Sep 2026
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$56,002.00
COE Rebate Amount:	\$38,708.00
Total Rebate Amount:	\$63,552.00

The information contained herein is correct as at 10 Oct 2019

OK

PRE-REPAIR INSPECTION REQUEST – SFG618K vs SMK7158X (OI) on D.O.A.: 05/10/2019

From: Hor Yinnul
To: 'assignments@lkkauto.com', Admin A (admin-a@lkkauto.com)
Cc: Fong, Andy-SY, Chin, Lee-Ying, Abu Kassim, Noor Mariessa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Parthiban, Theerthan, Subramaniam, Divyashni
Sent: 10/10/2019 10:26:15 AM

Hi,

Please refer to the enclosed request from Abwin Service Pte Ltd.

Claim no : 8177161573SG003
Case Owner : Loh Chee Heng

If you have any queries/concerns, please let us know.

Thanks & Regards,

Hor Yin Rut (Viviane)
AIG
FNOL Adjuster I
Singapore FNOL | Claims Operations – Auto

Tel: 8001206506 | Ext: 1002208
Yinnul.Hor@aig.com | www.aig.sg

2.04pm @ 10/10/19
vehicle in
p: shanfeih

From: motorclaims@abwinm9.com [mailto:motorclaims@abwinm9.com]
Sent: Thursday, October 10, 2019 9:37 AM
To: Hor, Yinnul
Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SMK7158X AND SFG618K ON 05/10/2019

Hi Yinnul,

Please appoint LKK

From: Hor, Yinnul
Sent: Thu, 10 Oct 2019 01:31:12 +0000
To: motorclaims@abwinm9.com
Cc: Fong, Andy-SY, Chin, Lee-Ying, Abu Kassim, Noor Mariessa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Parthiban, Theerthan, Subramaniam, Divyashni
Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SMK7158X AND SFG618K ON 05/10/2019

Without Prejudice

Your Reference : SFG618K
Our Reference : 8177161573SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufik	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd

Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Hor Yin Rui (Viviane)
AIG
FNOL Adjuster I
Singapore FNOL | Claims Operations – Auto

Tel: 8001206556 | Ext: 1002298
Yinrui.Hor@aig.com | www.aig.sg

From: motorclaims [mailto:motorclaims@abwinm9.com]
Sent: Wednesday, October 09, 2019 5:11 PM
To: AIG SGP, Claims-Survey
Subject: [EXTERNAL] FW: ACCIDENT INVOLVING SFG 618K AND SMK7158X ALONG MARINE PARADE ROAD ON 05/10/2019 AT ABOUT 1840 HOURS

This message is from an external sender; be cautious with links and attachments.

Hi

We refer to the above accident.

We have been appointed by the owner, LEE TZE BOON the registered owner of vehicle no. SFG 618K.

Kindly arrange your surveyor to attend the Pre-repair inspection within 2 working days.

The said vehicle can be inspected at: No. 8 Kaki Bukit Avenue 4, #07-48 Premier @ Kaki Bukit Gate 2 Singapore 415875

Please note that if you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday and/or Public Holiday, the said workshop will commence repairs thereafter without any further notice or reference to you.

From: motorclaims [mailto:motorclaims@abwinm9.com]
Sent: Wednesday, 9 October, 2019 5:10 PM
To: 'AIGSGP_claimssurvey@aig.com' <AIGSGP_claimssurvey@aig.com>
Subject: ACCIDENT INVOLVING SFG 618K AND SMK7158X ALONG MARINE PARADE ROAD ON 05/10/2019 AT ABOUT 1840 HOURS

Hi

We refer to the above accident.

We have been appointed by the owner, LEE TZE BOON the registered owner of vehicle no. SFG 618K.

Kindly arrange your surveyor to attend the Pre-repair inspection within 2 working days.

The said vehicle can be inspected at: No. 8 Kaki Bukit Avenue 4, #07-48 Premier @ Kaki Bukit Gate 2 Singapore 415875

Please note that if you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday and/or Public Holiday, the said workshop will commence repairs thereafter without any further notice or reference to you.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

View Received Message

This mail is associated with :

*SFG618K (8177161573SG)
[SMK7158X]
TP
LEE TZE BOON (LI ZHIWEN)
Oct 5 2019 12:00AM
[BIS MOTORING PTE LTD]
Abwin Service Pte Ltd

Reply Reply All Mark as Unread Print Message Delete Message Forward

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 24/02/2020 08:28 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$5374.45) - SFG618K - Claim Handler: Loh, Chee-Heng

Approved:5374.45.

DOCUMENTS SUMMARY
There are no documents.

...CLAIM SUBFOLDER...(Pending for Survey Report)
Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Oct 2019 Edit Reg		10 Oct 2019 00:00 Edit Adj Rpt	S\$4,100.00 Edit Estimates	S\$4,100.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS			[Created by adjuster]
Insured:	BIS MOTORING PTE LTD, Co. Reg. No.: 201735055D, Tel: +6599999999		
Main Claimant:	LEE TZE BOON (LI ZHIWEN)		
Vehicle Reg. No.:	SFG618K	Date of Loss:	05/10/2019 00:00 - :59 [36 Months and 26 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 8177161573SG	Policy/Cover Note No.:	999994322 (Comprehensive)
Vehicle Reg. No. (Insured):	SMK7158X	Policy No. (Claimant):	5083534502-03
		Excess:	
Repairer:	Abwin Service Pte Ltd (HQ) No. 8 Kaki Bukit Avenue 4, #07-48 Premier@Kaki Bukit Gate 2, 415875 Kaki Bukit - Tel: 6713 9400		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 21/10/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG_EXPRESS (24/02/2020): Alert - Adj Mandate Approved (S\$5374.45) - SFG618K - Claim Handler: Loh, Chee-He...
- AIG_SG (11/10/2019): TP GIA report

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SFG618K (8177161573SG)
[SMK7158X]
TP
LEE TZE BOON (LI ZHIWEN)
Oct 5 2019 12:00AM
[BIS MOTORING PTE LTD]
Abwin Service Pte Ltd

Upload Documents

Upload Photos

Compose New Letter

Upload Video

Upload Audio

View

View in Browser

Video

1 per page

No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	11/10/19 14:29	OI VIDEO	Load AVI	

Letters/Correspondences

1 per page

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown	Edit	

Assessment Reports

1 per page

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/02/20 10:49	Adjuster Immediate Advice	Load HTM	

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/01/20 09:01	General View	Load JPG	
2	24/01/20 09:02	General View	Load JPG	
3	24/01/20 09:02	General View	Load JPG	
4	24/01/20 09:02	General View	Load JPG	
5	24/01/20 09:02	General View	Load JPG	
6	24/01/20 09:02	General View	Load JPG	
7	24/01/20 09:02	General View	Load JPG	
8	24/01/20 09:02	General View	Load JPG	
9	24/01/20 09:02	General View	Load JPG	
10	24/01/20 09:02	General View	Load JPG	
11	24/01/20 09:02	General View	Load JPG	
12	24/01/20 09:02	General View	Load JPG	
13	24/01/20 09:02	General View	Load JPG	
14	24/01/20 09:02	General View	Load JPG	
15	24/01/20 09:02	General View	Load JPG	
16	24/01/20 09:02	General View	Load JPG	
17	24/01/20 09:02	General View	Load JPG	
18	24/01/20 09:02	General View	Load JPG	
19	24/01/20 09:02	General View	Load JPG	
20	24/01/20 09:02	General View	Load JPG	
21	24/01/20 09:02	General View	Load JPG	
22	24/01/20 09:02	General View	Load JPG	
23	24/01/20 09:02	General View	Load JPG	
24	24/01/20 09:02	General View	Load JPG	
25	24/01/20 09:02	General View	Load JPG	
26	24/01/20 09:02	General View	Load JPG	
27	24/01/20 09:02	General View	Load JPG	
28	24/01/20 09:02	General View	Load JPG	
29	24/01/20 09:02	General View	Load JPG	
30	24/01/20 09:02	General View	Load JPG	
31	24/01/20 09:02	General View	Load JPG	
32	24/01/20 09:02	General View	Load JPG	
33	24/01/20 09:02	General View	Load JPG	

Video			1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
34	24/01/20 09:02	General View	 Load JPG	☒
35	24/01/20 09:02	General View	 Load JPG	☒
36	24/01/20 09:02	General View	 Load JPG	☒
37	24/01/20 09:02	General View	 Load JPG	☒
38	24/01/20 09:02	General View	 Load JPG	☒
39	24/01/20 09:02	General View	 Load JPG	☒
40	24/01/20 09:02	General View	 Load JPG	☒
41	24/01/20 09:02	General View	 Load JPG	☒
42	24/01/20 09:02	General View	 Load JPG	☒
43	24/01/20 09:02	General View	 Load JPG	☒
44	24/01/20 09:02	General View	 Load JPG	☒
45	24/01/20 09:02	General View	 Load JPG	☒
46	24/01/20 09:02	General View	 Load JPG	☒
47	24/01/20 09:02	General View	 Load JPG	☒
48	24/01/20 09:02	General View	 Load JPG	☒
49	24/01/20 09:03	Odometer Reading	 Load JPG	☒
50	24/01/20 09:03	Chassis Number	 Load JPG	☒
51	24/01/20 09:04	Dismantled Parts	 Load JPG	☒
52	24/01/20 09:04	Dismantled Parts	 Load JPG	☒
53	24/01/20 09:04	Dismantled Parts	 Load JPG	☒
54	24/01/20 09:04	Dismantled Parts	 Load JPG	☒
55	24/01/20 09:04	Dismantled Parts	 Load JPG	☒
56	24/01/20 09:04	Dismantled Parts	 Load JPG	☒
57	24/01/20 09:04	Dismantled Parts	 Load JPG	☒
58	24/01/20 09:04	Dismantled Parts	 Load JPG	☒
59	24/01/20 09:04	Dismantled Parts	 Load JPG	☒
60	24/01/20 09:04	Dismantled Parts	 Load JPG	☒
61	24/01/20 09:04	Dismantled Parts	 Load JPG	☒
62	24/01/20 09:04	Dismantled Parts	 Load JPG	☒
63	24/01/20 09:04	Dismantled Parts	 Load JPG	☒
64	24/01/20 09:04	Dismantled Parts	 Load JPG	☒
65	24/01/20 09:04	Dismantled Parts	 Load JPG	☒
66	24/01/20 09:04	Dismantled Parts	 Load JPG	☒
67	24/01/20 09:04	Dismantled Parts	 Load JPG	☒
68	24/01/20 09:04	Dismantled Parts	 Load JPG	☒
69	24/01/20 09:04	Dismantled Parts	 Load JPG	☒
70	24/01/20 09:04	Dismantled Parts	 Load JPG	☒
71	24/01/20 09:04	Dismantled Parts	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	10/10/19 15:01	ACKNOWLEDGEMENT EMAIL TO AIG DD 10.10.19	 Load PDF	
2	10/10/19 15:01	EMAIL FROM AIG DD 10.10.19	 Load PDF	
3	14/10/19 11:32	TP ESTIMATE - MARKED	 Load PDF	
4	14/10/19 11:32	TP GIA REPORT	 Load PDF	
5	18/02/20 10:28	TP ESTIMATE - MARKED (FINAL)	 Load PDF	
6	18/02/20 10:33	LOD	 Load PDF	
7	18/02/20 10:33	RENTAL RECEIPT	 Load PDF	
8	18/02/20 10:33	LTA SEARCH FEE	 Load PDF	
9	13/03/20 14:21	WORKSHOP INVOICE	 Load PDF	
10	13/03/20 14:21	AUTHORISATION TO ACT FORM	 Load PDF	
11	13/03/20 14:21	Release Voucher	 Load PDF	
12	13/03/20 14:21	LETTER TO OI	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	11/10/19 14:29	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer			
Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SMK7158X (Insd veh)	Model:	TOYOTA HARRIER 2.0
	SFG618K (TP veh)		PREMIUM (A)
Date of Accident:	05/10/2019		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	15,014.10
Final Repair Cost	:	\$	4,387.00
Loss of Use	:	\$	_____ days at \$0.00 per day
Rental (if any)	:	\$	980.00 7 days
LTA / GIA Search Fee	:	\$	7.45
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	5,374.45
Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)			
A) For Non GIA Registered Workshop:		Agreed Liability _____ 100 _____ (%)	
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Abwin Service Pte Ltd	:	\$ 5,374.45
2)		:	\$
3)		:	\$
4)		:	\$

JOANNE LEE KHANG MIN

13 Mar
2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any)

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19017882/GDA3Q2

Date: 13/03/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 999994322
 Claimant SFG618K Insured Vehicle No : SMK7158X
 Vehicle No : SFG618K
 Date of Loss: 05/10/2019 Nature of Claim: TP Claim No: 8177161573SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SFG618K
 Make & Model: TOYOTA HARRIER, 2.0 Premium (A) Engine No: 3ZRB755323
 Reg. Date: 09/09/2016 (Man. Year: 2016) Chassis No: ZSU600074935
 Colour: White Odometer: 60859 km
 Engine Capacity: 1986 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55 R18 Rear Tyre Size: 235/55 R18
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,621.87	3,451.30	7,170.57	67.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,410.00	1,690.00	1,720.00	50.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,031.87	5,141.30	8,890.57	63.36
Approved Total (Overridden) (S\$)		4,100.00		
(S\$)	14,031.87	4,100.00	9,931.87	70.78
+ GST 7.00/7.00% (S\$)	982.23	287.00	695.23	70.78
Nett Amount (S\$)	15,014.10	4,387.00	10,627.10	70.78
+ Car Rental (7.0 x S\$140.00/day) (S\$)		980.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,374.45		

INSPECTION

Date of Assignment: 10/10/2019
 Date Inspected: 10/10/2019 Inspected At: Abwin Service Pte Ltd (HQ)
 No. 8 Kaki Bukit Avenue 4, #07-48
 Premier@Kaki Bukit Gate 2
 Singapore 415875
 Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG**Manager:** CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,495.30 F	*1,349.00 FL
2	1		*REAR BUMPER BRACKET R/H	Not Necessary	95.80 F	*- FL
3	1		*REAR BUMPER BRACKET L/H	Not Necessary	95.80 F	*- FL
4	1		*REAR BUMPER SIDE RETAINER	Deformed	65.70 F	*65.70 FL
5	1		*REAR END PANEL	Buckled	801.30 F	*597.10 FL
6	1		*REAR END PANEL TOP GARNISH	Deformed	387.90 F	*387.90 FL
7	1		*REAR BUMPER SPONGE	Cracked	127.80 F	*127.80 FL
8	1		*REAR BUMPER LOWER GARNISH	Cut	396.10 F	*396.10 FL
9	1		*REFLECTOR	Not Necessary	56.70 F	*- FL
10	1		*TAILGATE	Buckled	1,621.50 F	*1,224.80 FL
11	1		*TAILGATE LOCK	Not Necessary	991.40 F	*- FL
12	1		*TAILGATE LAMP R/H	Not Necessary	422.80 F	*- FL
13	1		*TAILGATE LAMP L/H	Not Necessary	422.80 F	*- FL
14	1		*TAIL LAMP R/H	Not Necessary	451.60 F	*- FL
15	1		*SPARE TYRE PANEL	Repair	896.30 F	*- FL
16	1		*WEATHER STRIP	Not Necessary	443.07 F	*- FL
17	2		*REVERSE SENSOR	Damaged	760.00 FS	*200.00 FS
18	1		*REVERSE CAMERA	Not Necessary	680.00 FS	*- FS
19	10		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
20	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*20.00 FS
21	1		*TAILGATE SEALANT	Not Necessary	50.00 FS	*- FS
22	1		*TOYOTA LOGO	Not Necessary	80.00 FS	*- FS
23	1		*EMBLEM HARRIER	Necessary	80.00 FS	*50.00 FS
24	1		*NUMBER PLATE	Scratched	50.00 FS	*40.00 FS
25	1		*NUMBER PLATE BRACKET	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	10,621.87	4,488.40
- List Item Discount on L Items 0.00/25.00% (S\$)	0.00	1,037.10
Total Parts (S\$)	10,621.87	3,451.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CONDUCT PANEL BEATING AND STRAIGHTEN PARTS ON DAMAGED AREAS	New	1,200.00	800.00
2	TO SPRAY PAINT ON AFFECTED AREAS	New	1,200.00	600.00
3	TO APPLY TUFF COAT ON AFFECTED AREAS	New	100.00	60.00
4	TO DISMANTLE ,REPLACE AND/OR REPAIR REVERSE SENSOR & TESTING	New	180.00	40.00
5	TO DISMANTLE ,REPLACE AND /OR REPAIR CAMERA & TESTING	New	200.00	40.00
6	TO CHECK WIRING	New	100.00	30.00
7	TO DISMANTLE ,REPLACE AND /OR REPAIR TAILGATE COMPONENTS	New	250.00	60.00
8	TO DISMANTLE & REFIX INTERIOR UPHOLSTERY	New	180.00	60.00
Gross Labour Cost (S\$)			3,410.00	1,690.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >