

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

8-Oct-19

ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHD 1214 C

2 pcs	Rear bumper n/s & o/s side bracket @ \$52.20	X sc	\$	104.40
1 pc	Rear bumper o/s reflector @\$107.50	X sc	\$	107.50
1 pc	Rear bumper	X Rep sc	\$	811.11
1 pc	Rear o/s mud flap guard	X sc	\$	47.45
				\$ 1,070.46
Less 20%				\$ 214.09
				\$ 856.37

S/NETT

1 set	Rear bumper clips	X an	\$	48.00
1 set	Reverse sensor	X sc	\$	280.00
1 pc	Rear o/s fender sticker	X an	\$	60.00

Sundry

To dismantle and replace reverse sensor and test system

To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.

To labour charge for dismantle and renew the accident damaged parts. Including to knock-out, straighten, repair, reshape of the rear o/s fender, rear bumper, etc.

To putty and spray painting on the rear bumper, rear o/s rim, rear o/s fender

To apply rustproofing on the repaired and replaced panels

\$	50.00	X an
\$	80.00	X an
\$	180.00	X an
\$	180.00	
\$	750.00	
\$	600.00	180
\$	150.00	X an
Total	\$ 3,054.37	

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey damaged part(s) during resurvey
• To display damaged part(s) during confirmation
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal work (etc) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
Acknowledged by Repairer
Signature:
Date:

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)
THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.