

**ZOOM AUTOWERKS PTE LTD**

130 Bedok Reservoir Road, Eunos Spring

#08-1339 Singapore 470130

Tel: 9450 7920

zoomautowerks@gmail.com

Car Number: SLC965H

Model: AUDI A3 1.4 TFSI

Damaged Area: (Rear Portion Damaged)

Repairer Estimation Cost of Repair :

Supplementary may be included during the cost of repair :

not Attached
Date: 14/10/20191/5 @ 1350
3 day
10/10/19**Parts / Material :**

	Quantity		
1 Rear Bumper	1	\$	1,614.00
2 Rear Bumper Reinforcement Beam	1	\$	486.00
3 Rear Bumper Reinforcement Beam Bracket	1	\$	160.00
4 Rear Bumper Bracket	\$156.00 X 2pcs	\$	312.00
5 Rear Bumper Clips	\$6.00 X 10pcs	\$	60.00
6 Rear Bumper Reflector LH	1	\$	225.00
7 BootLid	1	\$	2,136.00
8 Bootlid Badge	1	\$	103.00
9 Bootlid Emblem A3	1	\$	96.00
10 Bootlid Emblem TFSI	1	\$	98.00
11 Bootlid Lamp LH	1	\$	492.00
12 Bootlid Inner lock	1	\$	395.00
13 Bootlid weather Strip	1	\$	265.00
14 Rear Taillamp LH	1	\$	758.00
15 Rear End Panel	1	\$	815.20
16 Rear End Panel Top Garnish	1	\$	245.00
17 Rear Fender Inner Shield LH	1	\$	270.00
18 Rear Fender Inner Shield Clips	\$6.00 X 10pcs	\$	60.00
19 Rear Ultra sound Sensor	\$225.00 X 2pcs	\$	450.00
20 Rear Ultra sound Sensor O-Ring	\$14.00 X 4pcs	\$	56.00

Parts : \$ 9,096.20

Less Parts 5% : \$ 454.81

Total Parts : \$ 8,641.39

Special Net Items :

Rear Number Plate With Garnish

Rear End Panel Sealant

1	\$	55.00
1	\$	80.00
Total S/N Parts : \$		135.00

Labour :

To Remove & Renew Rear Affected Accident Areas
To Putty, Spray Paint on Rear Affected Accident Areas
To Check & Re-Connect all electrical wiring
To Remove & Install Rear Bootlid Compartment Trims
To Remove & Install Rear Bootlid Panel Trims
To Re-position & Install Reverse Sensor
To Re-Programme & Reset Diagnostic
To Rust Proof Affected Areas

\$	1,200.00	200
\$	1,200.00	200
\$	50.00	20
\$	11	150.00 X
\$	11	150.00 X
\$	11	150.00 X
\$	11	250.00 X
\$	11	150.00 X

Total Labour : \$ 3,300.00

TOTAL PARTS :	\$	8,641.39
TOTAL SPECIAL NET ITEM :	\$	135.00
TOTAL LABOUR :	\$	3,300.00
TOTAL REPAIR COST :	\$	12,076.39

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

DATE OF SURVEY / INSPECTED:

RECOMMENDED PART BY PART / LUMP SUM :

RECOMMENDED NUMBER OF DAYS :

SURVEY BY / SURVEYOR FIRM :

RE-SURVEY DISMANTLE PARTS / BEFORE PAINT / AFTER PAINT :

FINALISED AMOUNT :

P- 1417-60

10%

P- 1275.84

L- 420.00

1695.84

202

1358.67