

ASS. REC. BY:

REF: CS/FCI 19017895/KVf3

Special Instruction:

SUNVAPOR: Kenneth

ASSIGNMENT (Office)

From (Person): Jason Tea chu vat of FCI Date/Time: 10.10.19 3.11p.m

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHD 3394 Insured: SHC 80191

nt Workshop m/s Trans-rab Tel: 6287 6666

of NO 2 Ann Street 63

Policy No: Claim No: D19006475MFSH

Sum Insured: Excess:

Make of Veh: D.O.A. 6.10.2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 10.10.19 3.17p.m

Person Contacted:

Zhe Wei

H.O.D. Endorsement:

Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SHD 3394 - NBA / MSG 1901654 / 11 P.O.A - 04/09/2019
	SHC 80191 - CS / FCI 18003605 / Kvd 302 DoA - 23/02/2018
11/10/19	Email preli revised to FCI

ASS. REC. BY:

REF: 1021

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHD 33 PH

Yr Regn:

03 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Renault Latitude cc

1995

Colour:

White / Red

A/C: Insured / Std / NI / NA

Sp. Reading

368500

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

VF1ABL15AUC 282743

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Giti

Front

R/Bal.

8 mm

Rear

R/Bal.

8 mm

L/Bal.

8 mm

L/Bal.

8 mm

D.O.A.

6/10/19

D.O.I.

10/10/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

N/S body

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 File pass to
Car injury

14/10/19 11:25 AM 2250h (Red 35,171.88, 949) confirmed by email

RECEIVED OCT 2019

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

14/10 - typst

Report Format :

CWS

Lump Sum / I.B.I: (\$

2250h

Days Of Repair:

3

Resurvey No. of Trip:

-

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation

) \$ - RS. \$

) Fuel

) Others

TOTAL

350

Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	08-10-2019	Our Ref No. D19006475MFSH
Accident Date	06-10-2019	Claim Type. Third Party
Insured Vehicle	SHC8019J	Third Party Vehicle. SHD339H
Survey Location	NO. 2 ANG MO KIO STREET 63	
Contact Person.	KEK ZHEWEI	
Contact No.	62876666/ 0	Fax No. 62571330
Survey Type	WITHOUT PREJUDICE: LIABILITY NOT CLEAR	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TRANS-CAB AUTO SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JASON TEA CHEE KIAT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 11 October 2019 11:26 AM
To: 'CWS Motor Claims'; SUR
Cc: 'Jason Tea'
Subject: RE: SURVEY ASSESSMENT - D19006475MFSH/1-SHD 339H
Attachments: SHD 339H PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SHD 339H
Date of survey: 10/10/2019
Number of days (estimated) : 3 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Thursday, 10 October 2019 3:18 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Jason Tea' <JasonTea@msfirstcapital.com.sg>
Subject: RE: SURVEY ASSESSMENT - D19006475MFSH/1

Dear Sir/Madam,

Thank you for your assignment.

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>
Sent: Thursday, 10 October, 2019 3:11 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Jason Tea <JasonTea@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19006475MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

Veron Chen (LKKAUTO)

From: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Sent: Monday, 14 October 2019 2:44 PM
To: Veron Chen (LKKAUTO)
Subject: FW: SHD 339H-DOA: 6/10/2019 -- AAD1910-058
Attachments: MARKING.pdf

From: Ng Wai Yin [mailto:waiyin.ng@transcab.com.sg]
Sent: Friday, 11 October, 2019 2:30 PM
To: 'Veron Chen (LKKAUTO)' <veronchen@lkkauto.com>
Cc: 'jasminetan@transcab.com.sg' <jasminetan@transcab.com.sg>; 'SUR' <sur@lkkauto.com>
Subject: FW: SHD 339H-DOA: 6/10/2019 -- AAD1910-058

Hi Veron

Amount confirmed \$ 2,250 (before GST).

Thank You
Best Regards,
Ng Wai Yin
Finance Department
TEL: 6603 1265 Ext.308

***** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg**



TRANS-CAB SERVICES PTE LTD
No. 2 Ang Mo Kio Street 63, Singapore 569111
Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764
Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From: Veron Chen (LKKAUTO) [mailto:veronchen@lkkauto.com]
Sent: Friday, 11 October, 2019 11:38 AM
To: Ng Wai Yin <waiyin.ng@transcab.com.sg>; SUR <sur@lkkauto.com>
Cc: jasminetan@transcab.com.sg
Subject: SHD 339H-DOA: 6/10/2019

Dear Wai Yin,

WITHOUT PREJUDICE

Lump Sum \$2250 @ 3 working days.

Best Regards,
Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 11 October 2019 11:38 AM
To: Ng Wai Yin; SUR
Cc: jasminetan@transcab.com.sg
Subject: SHD 339H-DOA: 6/10/2019
Attachments: MARKING.pdf

Dear Wai Yin,

WITHOUT PREJUDICE

Lump Sum \$2250 @ 3 working days.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	878K
Vehicle Details	
Vehicle No.:	SHD339H
Vehicle to be Exported:	Yes
Intended Deregistration Date:	07 Oct 2019
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2015
Engine No.:	M9R8839C002938
Chassis No.:	VF1ABL15AUC282743
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	22 Mar 2016
First Registration Date:	22 Mar 2016
Transfer Count:	0
Actual ARF Paid:	\$19,998.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Mar 2024
PARF Rebate Amount:	\$14,998.00
Intended COE Rebate Details	
COE Expiry Date:	21 Mar 2024
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$39,633.00
COE Rebate Amount:	\$22,067.00
Total Rebate Amount:	\$37,065.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 07 Oct 2019

OK

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 339H**AAD1910-058**

Not Withheld
11 Sep @ 2250h

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident:

Third Party Insurer:

Date of Registration:

SHD 339H

VF1ABL15AUC282743

RENAULT

LATITUDE

6.10.19

FCIL

22/3/2016

PART		LIST	
1	DOOR PANEL REAR LH	\$	758.70 ✓
1	DOOR GUIDE REAR LH	\$	136.40 X
1	DOOR HINGE UPPER LH	\$	180.70 X
1	DOOR HINGE LOWER LH	\$	169.90 X
1	DOOR CHECK REAR LH/RH L70Y	\$	114.90 X
1	DOOR LOCK REAR LH	\$	468.20 X
1	DOOR REGULATOR REAR LH	\$	657.10 X
1	DOOR REGULATOR MOTOR REAR LH	\$	450.60 X
1	DOOR WHEATHESTRIIP REAR LH	\$	240.50 X
1	DOOR SEAL REAR LH	\$	119.40
1	DOOR GLASS RUNNER SEAL REAR LH	\$	116.10
1	DOOR WAIST SEAL OUTER REAR LH	\$	169.60
1	DOOR BLIND REAR LH	\$	506.90
1	DOOR CATCH REAR LH	\$	73.70
1	DOOR MOULDING REAR LH	\$	100.50
1	DOOR FINISHER REAR LH	\$	230.30
1	DOOR HANDLE OUTER REAR LH L70Y	\$	42.10
1	DOOR HANDLE CAP REAR LH L70Y	\$	57.90
1	DOOR HANDLE SEAL REAR LH L70Y	\$	1.60
1	DOOR HANDLE COVER REAR LH L70Y	\$	6.10
1	DOOR HANDLE MODULE REAR LH L70Y	\$	133.40
1	DOOR HARNESS WIRE LH	\$	2,670.00
1	DOOR PANEL FRT LH	\$	2,844.66
1	ROCKER PANEL INNER GARNISH LH	\$	466.51
1	ROCKER PANEL INNER LH	\$	1,024.79
1	ROCKER PANEL OUTER LH	\$	1,184.99
1	ROCKER PANEL CENTER LH	\$	990.25
1	DOOR MIRROR ASSY LH	\$	727.90
1	FENDER PANEL REAR LH	\$	1,933.20
1	FENDER PANEL INNER TRIM REAR LH	\$	671.45

Trans-cab Auto Services Pte Ltd

AAD1910-058

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 339H

1	WHEELARCH REAR LH	\$	181.60	}	X
1	TAILLAMP LH	\$	401.40		
1	BUMPER COVER REAR	\$	561.70		
1	BUMPER LOWER REAR	\$	411.90		
1	BUMPER BRACKET CTR REAR	\$	98.10		
1	BUMPER BRACKET SIDE LH REAR	\$	80.80		
1	BUMPER RETAINER LH REAR	\$	54.20		
1	BUMPER REFLECTOR LH	\$	16.60		
1	BUMPER BEAM REAR	\$	547.80		
1	BUMPER BEAM BRACKET LH REAR	\$	114.50		
TOTAL		\$	19,716.95		
10%		\$	1,971.69		
		\$	17,745.25		

Special Nett

Special Nett			
1	REAR DOOR STICKER '6555-3333'	\$	100.00 60sn
1	FRONT DOOR STICKER 'Trans-Cab'	\$	80.00 60sn
1	FRONT DOOR STICKER 'Classic'	\$	80.00 15sn
1	DOOR CHECK BOLT	\$	22.69
1	DOOR GUIDE SCREW	\$	10.85
1	DOOR HINGE BOLT	\$	10.85
1	DOOR HINGE NUT LH	\$	14.60
1	DOOR CHECK BOLT	\$	22.69
1	DOOR CHECK NUT	\$	3.75
1	DOOR LOCK SCREW L70Y	\$	6.12
1	DOOR CATCH SCREW L70Y	\$	10.06
1	REAR LEFT TYRE	\$	300.00
1	REAR LEFT TYRE RIM	\$	380.00
1	FENDER INNER TRIM CLIP LH	\$	28.00 X
1SET	FENDER WHEELARCH REAR LH CLIP	\$	35.00 X
1	TAILLAMP CLIP	\$	5.00 X
1SET	REAR BUMPER CLIP	\$	66.00
1SET	BUMPER BRACKET CTR CLIP	\$	33.00
1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	10.00
1SET	BUMPER RETAINER CLIP LH RR	\$	20.00
1SET	BUMPER LOWER REAR RIVET	\$	22.00
1SET	BUMPER LOWER REAR CLIP	\$	66.00
TOTAL		\$	1,326.63

TOTAL PARTS \$ 19,071.88

Trans-cab Auto Services Pte Ltd**AAD1910-058**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 339H**LABOUR**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	7,500.00	500l
Putty and spray painting of the affected portion.	\$	7,500.00	880l
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	n 380.00	60l
To check steering geometry and computer wheel alignment	\$	220.00	80l
To rust-proofing of the affected areas.	\$	170.00	30l
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	nr 170.00	X
To transfer of tire, rim and on wheel balancing.	\$	170.00	20l
To Check Electrical Lighting Concerned.	\$	170.00	20l
To transfer of Rear fender fittings, attachment and perform water seepage test.	\$	nr 380.00	X
To transfer of Rear door fittings, attachment and perform water seepage test.	\$	380.00	60l
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	nr 380.00	X
To transfer of Front door fittings, attachment and perform water seepage test.	\$	4 380.00	X
To transfer of Rear bumper fittings, attachment and perform water seepage test.	\$	4 380.00	X
Towing Fees	\$	4 170.00	X
TOTAL	\$	18,350.00	

Over All Total \$ 37,421.88**LUMP SUM (REPAIR DAY)****25 DAYS 3 days.**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19017895/Kvf3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 15-10-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHC 8019J	Veh. Inspected	SHD 339H
	Policy No.		Coverage (\$)	0.00
	Claim No.	D19006475MFSH	Excess (\$)	0.00
	Assign From	JASON TEA CHEE KIAT	Assign Date	10/10/2019
2. Vehicle Particulars & Condition				
	Make & Model	RENAULT LATITUDE (A)	c.c	1995
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	VF1ABL15AUC282743	Colour	METALLIC WHITE / RED
	Odometer	368500	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/60 R16	GITI	8 mm
	L/H Front Tyre	215/60 R16	GITI	8 mm
	R/H Rear Tyre	215/60 R16	GITI	8 mm
	L/H Rear Tyre	215/60 R16	GITI	8 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	06/10/2019	Inspection Date	10/10/2019
	Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		
5a. Remarks				
	A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 339H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	DOOR PANEL REAR LH	BENT	758.70	758.70
1	DOOR GUIDE REAR LH	SERVICEABLE	136.40	-
1	DOOR HINGE UPPER LH	TO REPAIR SEE LABOUR	180.70	-
1	DOOR HINGE LOWER LH	TO REPAIR SEE LABOUR	169.90	-
1	DOOR CHECK REAR LH/RH L70Y	SERVICEABLE	114.90	-
1	DOOR LOCK REAR LH	TO REPAIR SEE LABOUR	468.20	-
1	DOOR REGULATOR REAR LH	TO REPAIR SEE LABOUR	657.10	-
1	DOOR REGULATOR MOTOR REAR LH	SERVICEABLE	450.60	-
1	DOOR WEATHERSTRIP REAR LH	SERVICEABLE	240.50	-
1	DOOR SEAL REAR LH	SERVICEABLE	119.40	-
1	DOOR GLASS RUNNER SEAL REAR LH	SERVICEABLE	116.10	-
1	DOOR WAIST SEAL OUTER REAR LH	SERVICEABLE	169.60	-
1	DOOR BLIND REAR LH	SERVICEABLE	506.90	-
1	DOOR CATCH REAR LH	SERVICEABLE	73.70	-
1	DOOR MOULDING REAR LH	SERVICEABLE	100.50	-
1	DOOR FINISHER REAR LH	SERVICEABLE	230.30	-
1	DOOR HANDLE OUTER REAR LH L70Y	SERVICEABLE	42.10	-
1	DOOR HANDLE CAP REAR LH L70Y	SERVICEABLE	57.90	-
1	DOOR HANDLE SEAL REAR LH L70Y	SERVICEABLE	1.60	-
1	DOOR HANDLE COVER REAR LH L70Y	SERVICEABLE	6.10	-
1	DOOR HANDLE MODULE REAR LH L70Y	SERVICEABLE	133.40	-
1	DOOR HARNESS WIRE LH	SERVICEABLE	2,670.00	-
1	DOOR PANEL FRT LH	TO REPAIR SEE LABOUR	2,844.66	-
1	ROCKER PANEL INNER GARNISH LH	SERVICEABLE	466.51	-
1	ROCKER PANEL INNER LH	TO REPAIR SEE LABOUR	1,024.79	-
1	ROCKER PANEL OUTER LH	TO REPAIR SEE LABOUR	1,184.99	-

Report Ref No. CS/FCI19017895/Kvf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	ROCKER PANEL CENTER LH	TO REPAIR SEE LABOUR	990.25	-
1	DOOR MIRROR ASSY LH	SERVICEABLE	727.90	-
1	FENDER PANEL REAR LH	TO REPAIR SEE LABOUR	1,933.20	-
1	FENDER PANEL INNER TRIM REAR LH	SERVICEABLE	671.45	-
1	WHEELARCH REAR LH	SERVICEABLE	181.60	-
1	TAILLAMP LH	SERVICEABLE	401.40	-
1	BUMPER COVER REAR	TO REPAIR SEE LABOUR	561.70	-
1	BUMPER LOWER REAR	SERVICEABLE	411.90	-
1	BUMPER BRACKET CTR REAR	SERVICEABLE	98.10	-
1	BUMPER BRACKET SIDE LH REAR	SERVICEABLE	80.80	-
1	BUMPER RETAINER LH REAR	SERVICEABLE	54.20	-
1	BUMPER REFLECTOR LH	SERVICEABLE	16.60	-
1	BUMPER BEAM REAR	TO REPAIR SEE LABOUR	547.80	-
1	BUMPER BEAM BRACKET LH REAR	TO REPAIR SEE LABOUR	114.50	-
	LESS 10% DISCOUNT		-1,971.70	-75.87
			17,745.25	682.83
	SPECIAL NETT ITEMS			
1	REAR DOOR STICKER "6555-3333" (SN)	NECESSARY	100.00	60.00
1	FRONT DOOR STICKER "TRANS-CAB" (SN)	NECESSARY	80.00	60.00
1	FRONT DOOR STICKER "CLASSIC" (SN)	NECESSARY	80.00	15.00
1	DOOR CHECK BOLT (SN)	SERVICEABLE	22.69	-
1	DOOR GUIDE SCREW (SN)	SERVICEABLE	10.85	-
1	DOOR HINGE BOLT (SN)	SERVICEABLE	10.85	-
1	DOOR HINGE NUT LH (SN)	SERVICEABLE	14.60	-
1	DOOR CHECK BOLT (SN)	SERVICEABLE	22.69	-
1	DOOR CHECK NUT (SN)	SERVICEABLE	3.75	-
1	DOOR LOCK SCREW L70Y (SN)	SERVICEABLE	6.12	-
1	DOOR CATCH SCREW L70Y (SN)	SERVICEABLE	10.06	-
1	REAR LEFT TYRE (SN)	SERVICEABLE	300.00	-

Report Ref No. CS/FCI19017895/Kvf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR LEFT TYRE RIM (SN)	DENTED	380.00	380.00
1	FENDER INNER TRIM CLIP LH (SN)	NOT NECESSARY	28.00	-
1	SET FENDER WHEELARCH REAR LH CLIP (SN)	NOT NECESSARY	35.00	-
1	TAILLAMP CLIP (SN)	NOT NECESSARY	5.00	-
1	SET REAR BUMPER CLIP (SN)	NOT NECESSARY	66.00	-
1	SET BUMPER BRACKET CTR CLIP (SN)	NOT NECESSARY	33.00	-
1	SET BUMPER BRACKET SIDE CLIP LH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER CLIP LH RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER LOWER REAR RIVET (SN)	NOT NECESSARY	22.00	-
1	SET BUMPER LOWER REAR CLIP (SN)	NOT NECESSARY	66.00	-
			1,326.61	515.00
	LABOUR			
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF DOOR HINGE UPPER LH,DOOR HINGE LOWER LH,DOOR LOCK REAR LH,DOOR REGULATOR REAR LH,DOOR PANEL FRT LH,ROCKER PANEL INNER LH,ROCKER PANEL OUTER LH,ROCKER PANEL CENTER LH,FENDER PANEL REAR LH,BUMPER COVER REAR,BUMPER BEAM REAR AND BUMPER BEAM BRACKET LH REAR.		7,500.00	500.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		7,500.00	880.00
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR.		380.00	60.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.		220.00	60.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	30.00
	TO TRANSFER OF REAR WINDSCREEN GLASS TO FACILITATE BODYWORK REPAIR.	NOT NECESSARY	170.00	-
	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING.		170.00	20.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	TO TRANSFER OF REAR FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-

Report Ref No. CS/FCI19017895/Kvf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TRANSFER OF REAR DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.		380.00	60.00
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR.	NOT NECESSARY	380.00	-
	TO TRANSFER OF FRONT DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR BUMPER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TOWING FEES.	NOT NECESSARY	170.00	-
			18,350.00	1,630.00
GRAND TOTAL			37,421.86	2,827.83
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,250.00

Report Ref No. CS/FCI19017895/Kvf3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part does so at his or her own risk.