



MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z

Address: 60 JALAN LAM HUAT, CARROS CENTRE #05-68 S737896

HP: 98888885

Estimation

Date: 8/10/2019

Vehicle: SLB5759J

Make / Model: TOYOTA NOAH

INSURANCE: SOMPO

No.	Description	Unit	Unit Price	Amount
	Parts Replacement:			
1	FRONT BUMPER	1	\$ 1,985.00	\$ 1,985.00
2	FRONT BUMPER LOWER GARNISH	1	\$ 512.00	\$ 512.00
3	FRONT BUMPER SPONGE	1	\$ 298.00	\$ 298.00
4	FRONT BUMPER BRACKET RH	1	\$ 144.00	\$ 144.00
5	FRONT BUMPER SIDE RETAINER RH	1	\$ 112.00	\$ 112.00
6	FRONT BUMPER SIDE COVER RH	1	\$ 160.00	\$ 160.00
7	HEADLAMP LED RH	1	\$ 3,824.20	\$ 3,824.20
8	HEADLAMP GARNISH RH	1	\$ 112.00	\$ 112.00
9	FRONT HEADLAMP LOWER BRACKET	1	\$ 122.00	\$ 112.00
10	WIPER WASHER TANK C/W MOTOR	1	\$ 459.00	\$ 459.00
11	FRONT FENDER RH	1	\$ 987.00	\$ 987.00
12	FRONT FENDER COWLING RH	1	\$ 321.20	\$ 321.20
13	FRONT FENDER EMBLEM HYBRID RH	1	\$ 96.00	\$ 96.00
				\$ 9,122.40
			Less 25%	\$ 2,280.60
			Total	\$ 6,841.80

	S/Nett items:			
1	FRONT BUMPER CLIPS	1	\$ 80.00	\$ 80.00
2	FRONT FENDER COWLING CLIPS SET	1	\$ 50.00	\$ 50.00
3	FRONT FENDER SEALANT	1	\$ 80.00	\$ 80.00
				\$ 210.00
	Labour to:			
1	TO CHECK ELECTRICAL WIRING	1	\$ 200.00	\$ 200.00
2	REALIGN HEADLAMP	1	\$ 300.00	\$ 300.00
3	CHECK AND RESET FAULT CODE LIGHT ON	1	\$ 500.00	\$ 500.00
4	APPLY ANTI RUST ON AFFECTED AREAS	1	\$ 300.00	\$ 300.00
5	SPRAY PAINTING ON AFFECTED AREAS	1	\$ 600.00	\$ 600.00
6	PANEL BEATING ON AFFECTED AREAS	1	\$ 600.00	\$ 600.00
				\$ 2,500.00
		Parts Replacement Amount		\$ 7,051.80
		Total Amount for Labour		\$ 2,500.00
		Total Amount		\$ 9,551.80