

ASS. REC. BY:

REF: 08/SMO19017847/Asd3/1

Special Instructions:

Inspector: Adrian

ASSIGNMENT (Office)

Meimer

From (Person): Thelma Choo

of SMO

Date/Time: 10/10/19 @ 7:49

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SLE 650SC

Insured: PC 7220E

at Workshop n/s Green Forest Automobile

Tel: 63846383

of 8 Leaki Bukit Ave # 05-25 Premier

Policy No: DIAMTSCBU000328

Claim No: CM1D1904735

Sum Insured:

Excess:

Make of Veh:

D.O.A. 3/10/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endowment:

Date/Time: 11/7am @ 10/10/19

Person Contacted: chris

Vehicle IN/OUT

Date/Time	Action/Instruction
	1-11/10/19
	SLE 650SC - CC+ / ASM / 4007502 / Apha
	PC 7220E - X

20A: 27/4/2019

1

The U/C / Chassis frame / Body Structure affected due to collision

RECEIVED 15 JAN 2020

Survey Fee:	
Transportation:	350
T-PE:	11
Phone:	
Other:	
Total:	361

Long Term (L.P.E.): \$ 1,200/- 45

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Oct 2019		10 Oct 2019 07:49 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	DEM LIMO SERVICES, Co. Reg. No.: 53382490K		
Main Claimant:	SLE6505C, Co. Reg. No.: 201825832G		
Vehicle Reg. No.:	SLE6505C	Date of Loss:	03/10/2019 06:00 - :59
Claim Type:	TP / CMTD1904735	Policy/Cover Note No.:	D19MTSCBU000328 (Comprehensive)
Vehicle Reg. No. (Insured):	PC7220E	Policy No. (Claimant):	
		Excess:	
Repairer:	Green Forest Automobile Pte Ltd (Kaki Bukit) 8 Kaki Bukit Avenue 4, #05-25,, Premier@Kaki Bukit, 415875 Kaki Bukit - Tel: 63846383		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Thelma Choo - 6322 4681]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 21/10/2019]		
Driver/Custodian (Insured):	AZHAR BIN AHMAD (), NRIC: S8532487Z, Tel: +6587994090 Email: -		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

View Sent Message

This mail is associated with :

***SLE6505C (CMTD1904735)
[PC7220E]**

TP
SLE6505C
Oct 3 2019 6:00AM
[DEM LIMO SERVICES]
Green Forest Automobile Pte Ltd

[Resend](#) [View Recipients](#) [Print Message](#) [Delete Message](#) [Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on **11/10/2019 16:20 PM**.
To thelma.choo@sompo.com.sg
CC sur@lkkauto.com
Subject **SLE6505C (CMTD1904735) [PC7220E] TP**

Dear Thelma,

Please be informed that we have inspected the vehicle SLE 6505C on 03/10/2019.

We are pending estimate from repairer.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

DOCUMENTS SUMMARY

There are no documents.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/10/2019 11:15
Date Of Accident	03/10/2019 07:00
Exact Location Of Accident	PASIR RIS INDUSTRIAL DR 1 TOWARDS PUNGGOL CTRL
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLE6505C
Insured/Policyholder	
Name Of Registered Owner	CARRO LEASING PTE. LTD.
Co Reg No	201825832G
Email Address	KEANE@CARRO.CO
Mobile Phone No	
Alternative Phone No	OFFICE-67146652

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL 1.5X CVT

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5111909119-000029 CLASSIC
Cover Note Number	

Driver

Name of Driver	ANG DIXON
NRIC No	S8020386A
Date Of Birth	15/07/1980
Occupation	OUTDOOR
Date Of Driving Pass	24/02/2005
Driving Experience	14 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98791047
Fax Number	
Contact Number	
Email Address	DIXON6886@GMAIL.COM

Address	BLK 487C TAMPINES STREET 45 #03-115
Postcode	522487
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : GOJEK PASSENGER
	GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	PC7220E
Vehicle Make/Model/Colour	TOYOTA / HIACE COMMUTER GL 2.8 AUTO
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	ANG DIXON
Approximate Age	
Injuries Sustain	NECK & SHOULDERS
Injured person in which vehicle?	SLE6505C
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	NO
Address	BLK 487C TAMPINES STREET 45 #03-115
Postcode	522487

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)

Date & Time: - 4 OCT 2019

IDAC KAKI BUKIT (VAC)
23 Kaki Bukit Ave 4 #02-02
Singapore 415933
Tel: 67416697 Fax: 67492305

Email: workshop-form@idac.com.sg
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:


Sketch Plan #2

SKETCH PLAN

PUNGGOL
EAST

VEHICLE A - SLE 6505C

VEHICLE B - PC 7200E



PASIR RIS INDUSTRIAL DRIVE 1
(TOWARDS PUNGGOL CENTRAL)

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON 03/OCT/2019 @ 0700HRS, I WAS WAITING AT THE TRAFFIC JUNCTION OF PASIR RIS INDUSTRIAL DRIVE 1 & PUNGGOL EAST. ALL OF A SUDDEN, I FELT AN IMPACT TO THE REAR MY CAR (VEHICLE A). I GOT DOWN TO CHECK AND FOUND OUT A PRIVATE BUS (VEHICLE B) HAD HIT THE REAR OF MY CAR (VEHICLE A). I FELT PAIN IN MY NECK & SHOULDERS.

DECLARATION

I/We declare that the above particulars are true in every respect.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)

Date & Time: - 4 OCT 2019

IDAC KAKI BUKIT (VAC)
23 Kaki Bukit Ave 4 #02-02
Singapore 415933

Reporting Centre Personnel's Signature
Name: vackb@vicom.com.sg
NRIC/FIN No.:

GREEN FOREST AUTOMOBILE PTE LTD

8 Kaki Bukit Avenue 4, #05-25 Premier @ Kaki Bukit Singapore 415875

CARRO LEASING PTE LTD
8 KAKI BUKIT AVE 4
05-25 PREMIER @ KB
Singapore 415875

TP Sampo
Shirley

10th Oct 2019

Accident date: 03rd OCT 2019

Estimated repair cost for vehicle no: SLE6505C Honda Vezel 1.5 '2016

S/n	Qty	Items	U/price	Amount
				\$821.40
1	1	Rear Boot Lid		\$276.00
2	2	Rear Boot Lid Hinges	\$138.00	\$55.00
3	1	Rear boot lid emble logo		\$38.10
4	1	Rear boot lid Vezel logo		\$776.20
5	2	Rear Boot Lid side reflector	\$388.10	\$237.00
6	1	Rear boot lid inner rubber		\$284.20
7	1	Rear Boot Lid Inner Lock		\$50.00
8	1	Rear Boot Lid Number Plate		\$122.20
9	2	Rear Boot Lid Number Plate Lamp	\$61.10	\$285.00
10	1	Rear Boot Lid center moulding		\$50.00
11	10	Rear Boot Lid Inner Trim board clips	\$5.00	\$385.60
12	1	Rear Boot Lid Inner Trim board		\$840.20
13	2	Rear tail lamp	\$420.10	\$420.00
14	1	Rear end panel		\$188.00
15	1	Rear End Panel Top Garnish		\$745.30
16	1	Rear Bumper		\$176.40
17	2	Rear Bumper Side Bracket	\$88.20	\$300.00
18	1	Rear Bumper reverse sensor		\$400.00
19	2	Rear Bumper reverse camera	\$225.00	\$450.00
20	2	Rear side Bumper	\$5.00	\$40.00
21	8	Rear bumper clips		\$386.20
22	1	Rear fender inner trim board -RH		\$825.10
23	1	Rear Exhaust		\$112.00
24	1	Rear Exhaust aluminium cover		\$158.00
25	1	Rear windscreen moulding		\$428.00
26	1	Rear spare tire panel lower cover		\$580.00
27	2	Rear spare tire panel lower pump		\$200.00
28	1	Rear spare tire panel sealant		

Subtotal :- \$9,629.90

84030 SN: 200

67224

Labour charges

To Remove & refix cushion

~~\$120.00~~ 40

To Remove & refix rear windscreen

~~\$120.00~~ +

Gum

~~\$50.00~~ +

To Remove & refix rear exhaust

~~\$280.00~~ +

To Remove & refix reverse Sensor

~~\$120.00~~ 50

To Remove & refix reverse camera

~~\$120.00~~ +

Tuff kote

~~\$150.00~~ 40

To Check Wiring System

7/0 ~~\$120.00~~ 30

Panel beating

~~\$800.00~~ 300

Spray painting

~~\$800.00~~ 250

Subtotal :- \$2,680.00

Total:- \$12,309.90

total: 1582.24

A/S: 12K
038mg

L&K Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Oct 2019		10 Oct 2019 07:49 Edit Adj Rpt	S\$1,200.00 Edit Estimates	S\$1,200.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	DEM LIMO SERVICES , Co. Reg. No.: 53382490K								
Main Claimant:	SLE6505C , Co. Reg. No.: 201825832G								
Vehicle Reg. No.:	SLE6505C	Date of Loss:	03/10/2019 06:00 - :59 [38 Months and 5 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / CMTD1904735	Policy/Cover Note No.:	D19MTSCBU000328 (Comprehensive)						
Vehicle Reg. No. (Insured):	PC7220E	Policy No. (Claimant):							
		Excess:							
Repairer:	Green Forest Automobile Pte Ltd (Kaki Bukit) 8 Kaki Bukit Avenue 4, #05-25,, Premier@Kaki Bukit, 415875 Kaki Bukit - Tel: 63846383								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Thelma Choo - 6322 4681]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 21/10/2019]								
Driver/Custodian (Insured):	AZHAR BIN AHMAD () , NRIC: S8532487Z, Tel: +6587994090 Email:								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLE6505C (CMTD1904735)
[PC7220E]
TP
SLE6505C
Oct 3 2019 6:00AM
[DEM LIMO SERVICES]
Green Forest Automobile Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	14/01/20 17:10	General View	 Load JPG	☒
2	14/01/20 17:10	General View	 Load JPG	☒
3	14/01/20 17:10	General View	 Load JPG	☒
4	14/01/20 17:10	General View	 Load JPG	☒
5	14/01/20 17:10	General View	 Load JPG	☒
6	14/01/20 17:10	General View	 Load JPG	☒
7	14/01/20 17:10	General View	 Load JPG	☒
8	14/01/20 17:10	General View	 Load JPG	☒
9	14/01/20 17:10	General View	 Load JPG	☒
10	14/01/20 17:10	General View	 Load JPG	☒
11	14/01/20 17:10	General View	 Load JPG	☒
12	14/01/20 17:10	Reinspection Photo	 Load JPG	☒
13	14/01/20 17:10	Reinspection Photo	 Load JPG	☒
14	14/01/20 17:10	Reinspection Photo	 Load JPG	☒
15	14/01/20 17:10	Reinspection Photo	 Load JPG	☒
16	14/01/20 17:10	Reinspection Photo	 Load JPG	☒
17	14/01/20 17:10	Reinspection Photo	 Load JPG	☒
18	14/01/20 17:10	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	10/10/19 07:52	Pre-Repair Survey-GREE FOREST ACK/AGREE LKK	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST Reset Save Print
There are no document checklists configured.
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19017897/ASD3Q2

Date: 16/01/2020

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D19MTSCBU000328
Claimant Vehicle No :	SLE6505C	Insured Vehicle No :	PC7220E
Date of Loss:	03/10/2019	Nature of Claim:	TP
		Claim No:	CMTD1904735

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLE6505C	Engine No:	L15B4037832
Make & Model:	HONDA VEZEL, 1.5 X CVT (A)	Chassis No:	RU11117827
Reg. Date:	28/07/2016 (Man. Year: 2016)	Odometer:	233691 km
Colour:	White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Firenza 6 mm	Rear Left Side:	Firenza 6 mm
Front Right Side:	Firenza 6 mm	Rear Right Side:	Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,629.90	872.24	8,757.66	90.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,680.00	710.00	1,970.00	73.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,309.90	1,582.24	10,727.66	87.15
Approved Total (Overridden) (S\$)		1,200.00		
(S\$)	12,309.90	1,200.00	11,109.90	90.25
+ GST 7.00/7.00% (S\$)	861.69	84.00	777.69	90.25
Nett Amount (S\$)	13,171.59	1,284.00	11,887.59	90.25

INSPECTION

Date of Assignment:	10/10/2019	
Date Inspected:	10/10/2019 Inspected At:	Green Forest Automobile Pte Ltd (Kaki Bukit) 8 Kaki Bukit Avenue 4, #05-25., Premier@Kaki Bukit Singapore 415875
Estimated Period of Repair:	3.0 days	

Adjuster: ADRIAN LING

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 Jan 2020)
Parts:	M1-SUV	HONDA VEZEL 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLE6505C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Not Necessary	821.40 F	*- FL
2	2		*REAR BOOT LID HINGES	Not Necessary	276.00 F	*- FL
3	1		*REAR BOOT LID EMBLE LOGO	Not Necessary	55.00 F	*- FL
4	1		*REAR BOOT LID VEZEL LOGO	Not Necessary	38.10 F	*- FL
5	2		*REAR BOOT LID SIDE REFLECTOR	Not Necessary	776.20 F	*- FL
6	1		*REAR BOOT LID INNER RUBBER	Not Necessary	237.00 F	*- FL
7	1		*REAR BOOT LID INNER LOCK	Not Necessary	284.20 F	*- FL
8	1		*REAR BOOT LID NUMBER PLATE	Not Necessary	50.00 F	*- FL
9	2		*REAR BOOT LID NUMBER PLATE LAMP	Not Necessary	122.20 F	*- FL
10	1		*REAR BOOT LID CENTER MOULDING	Not Necessary	285.00 F	*- FL
11	10		*REAR BOOT LID INNER TRIM BOARD CLIPS	Not Necessary	50.00 F	*- FL
12	1		*REAR BOOT LID INNER TRIM BOARD	Not Necessary	385.60 F	*- FL
13	2		*REAR TAIL LAMP	Not Necessary	840.20 F	*- FL
14	1		*REAR END PANEL	Repair	420.00 F	*- FL
15	1		*REAR END PANEL TOP GARNISH	Not Necessary	188.00 F	*- FL
16	1		*REAR BUMPER	Deformed	745.30 F	*745.30 FL
17	2		*REAR BUMPER SIDE BRACKET	Necessary	176.40 F	*65.00 FL
18	1		*REAR BUMPER REVERSE SENSOR	Damaged	300.00 FS	*200.00 FS
19	2		*REAR BUMPER REVERSE CAMERA	Not Necessary	400.00 F	*- FL
20	2		*REAR SIDE BUMPER	Not Necessary	450.00 F	*- FL
21	8		*REAR BUMPER CLIPS	Necessary	40.00 F	*30.00 FL
22	1		*REAR FENDER INNER TRIM BOARD -RH	Not Necessary	386.20 F	*- FL
23	1		*REAR EXHAUST	Not Necessary	825.10 F	*- FL
24	1		*REAR EXHAUST ALUMINIUM COVER	Not Necessary	112.00 F	*- FL
25	1		*REAR WINDSCREEN MOULDING	Not Necessary	158.00 F	*- FL
26	1		*REAR SPARE TIRE PANEL LOWER COVER	Not Necessary	428.00 F	*- FL
27	2		*REAR SPARE TIRE PANEL LOWER PUMP	Not Necessary	580.00 F	*- FL
28	1		*REAR SPARE TIRE PANEL SEALANT	Not Necessary	200.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,629.90	1,040.30
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	168.06
Total Parts (\$\$)	9,629.90	872.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIX CUSHION	New	120.00	40.00
2	TO REMOVE & REFIX REAR WINDSCREEN	New	120.00	0.00
3	GUM	New	50.00	0.00
4	TO REMOVE & REFIX REAR EXHAUST	New	280.00	0.00
5	TO REMOVE & REFIX REVERSE SENSOR	New	120.00	50.00
6	TO REMOVE & REFIX REVERSE CAMERA	New	120.00	0.00
7	TUFF KOTE	New	150.00	40.00
8	TO CHECK WIRING SYSTEM	New	120.00	30.00
9	PANEL BEATING	New	800.00	300.00
10	SPRAY PAINTING	New	800.00	250.00
Gross Labour Cost (S\$)			2,680.00	710.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >