

MAXIMUS RACING PTE LTD

MR Performance Centre. No.7 Soon Lee Street, #05-05, iSpace, Singapore 627608.

Enquiry Hotline : +65 6250 1198 / Fax : +65 6250 1081

Company Registration No. : 200507694R

ESTIMATION FOR SMK7153J

Requested By: AXA Insurance Singapore Pte Ltd

Address: 143 Cecil Street #01-01 GB Building

Singapore 069542

Tel: 1800 880 4888

Reference No: Q-19-103

Date: 11/10/2019

Terms: Cash



Item	Description	Qty	Unit Price	Disc %	Total Price
	Policy No // Accident Date: MT/00620631 // 10/10/2019				
	Drive In: 9/10/2019				
	Vehicle Make/Model: Honda Vezel 1.5X CVT				
	Vehicle Number: SMK7153J				
	Manufacturing Year: 2017				
	Engine: Chassis No:RU1-1314840				
	Rear Bonnet	1	\$ 1,460.00	20%	\$ 1,168.00
	Bonnet Hinge	2	\$ 55.00	20%	\$ 88.00
	Rear Bonnet Weather Seal	3	\$ 130.00	20%	\$ 104.00
	Rear Bonnet hinge	4	\$ 100.00	20%	\$ 80.00
	Rear Bonnet bracket	5	\$ 165.00	20%	\$ 132.00
	rear Bonnet hinge	6	\$ 50.00	20%	\$ 40.00
	Rear bonnet absorber left	7	\$ 145.00	20%	\$ 116.00
	Rear Bonnet stopper	8	\$ 15.00	20%	\$ 24.00
	rear Bonnet hinge	9	\$ 15.00	20%	\$ 24.00
	Rear bonnet Absorber Right	10	\$ 165.00	20%	\$ 132.00
	Rear Bonnet Button	11	\$ 130.00	20%	\$ 104.00
	Rear Spoiler	12	\$ 900.00	20%	\$ 720.00
	Bonnet absorber Nuts	21	\$ 30.00	20%	\$ 96.00
	Rear Windscreen	1	\$ 1,765.00	20%	\$ 1,412.00
	Rear Windscreen molding	1	\$ 40.00	20%	\$ 32.00
	Rear Windscreen molding	1	\$ 40.00	20%	\$ 32.00
	Rear Gutter Compartment	19	\$ 160.00	20%	\$ 128.00
	Rear Gutter Compartment	26	\$ 160.00	20%	\$ 128.00
	Rear Panel Compartment	28	\$ 740.00	20%	\$ 592.00
	Rear Bumper Reflector	1	\$ 105.00	20%	\$ 84.00
	Rear Bumper Reflector	2	\$ 105.00	20%	\$ 84.00
	Rear Bumper	3	\$ 705.00	20%	\$ 564.00
	Rear Bumper Side	4	\$ 325.00	20%	\$ 260.00
	Rear Lower Panel	5	\$ 325.00	20%	\$ 260.00
	Rear Spacer Bumper	6	\$ 25.00	20%	\$ 20.00
	Rear Spacer Bumper	7	\$ 40.00	20%	\$ 32.00
	Rear Bumper Cover	1	\$ 200.00	20%	\$ 160.00
	Rear top cover left	2	\$ 120.00	20%	\$ 96.00
	rear hinge	3	\$ 50.00	20%	\$ 40.00
	Rear top Cover right	7	\$ 50.00	20%	\$ 40.00
	Wiring Connection	2	\$ 105.00	20%	\$ 84.00
	Rear Tail Lamp Unit Right	3	\$ 540.00	20%	\$ 432.00
	Rear Tail Lamp Unit Left	7	\$ 540.00	20%	\$ 432.00
	Rear Side Tail Light Right	9	\$ 355.00	20%	\$ 284.00
	Rear Side Tail Light Left	12	\$ 355.00	20%	\$ 284.00
	Rear 'Vezel' Emblem	1	\$ 55.00	20%	\$ 44.00
	Honda Rear logo Assy	5	\$ 285.00	20%	\$ 228.00
	Rear Licence Light	2	\$ 70.00	20%	\$ 112.00
	Rear Licence Bracket	1	\$ 70.00	20%	\$ 56.00
	Rear Wiper Motor Assy	1	\$ 210.00	20%	\$ 168.00
	Rear Wiper Blade	1	\$ 70.00	20%	\$ 56.00
	Rear Fender Cover Left	1	\$ 250.00	20%	\$ 200.00
	Rear Fender Cover Right	1	\$ 250.00	20%	\$ 200.00

Bonnet Cover bottom Inside	1	\$ 75.00	20%	\$ 60.00	X
Reverse Sensor Aftermarket	2	\$ 120.00	S.NETT	\$ 240.00	200nw
Rear Reverse camera	1	\$ 250.00	S.NETT	\$ 250.00	X
Car plate	1	\$ 40.00	S.NETT	\$ 40.00	45
Car plate Frame	1	\$ 40.00	S.NETT	\$ 40.00	
Remove and renew damaged parts, straighten and realign affected areas	1			\$ 1,600.00	600
Respray affected areas.	1			\$ 1,600.00	700
Remove and refit rear upholstery and trims to assist workload	1			\$ 500.00	60
To apply cavity wax coating on affected areas	1			\$ 150.00	40
To check rear lights, reverse sensor and water leakages	1			\$ 120.00	60
Install new rear windscreen	1			\$ 200.00	120
Rewiring of Rear Electronic boot motor	1			\$ 150.00	60
General diagnosis and checking	1			\$ 300.00	120
Wiring for Reversing Camera & Sensors	1			\$ 200.00	50
PRICE BEFORE GST				\$ 14,822.00	
ADD GST 7%				\$ 1,037.54	
Grand Total:				\$ 15,859.54	

Tauplin 97445719 / 67418431
'wp'

11/10/19 @ 2:15 pm

5 days

Reversing before paint.

sur @ lkkauto.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: