

MAXIMUS RACING PTE LTD

MR Performance Centre. No.7 Soon Lee Street, #06-05, iSpace, Singapore 627608.

Enquiry Hotline : +65 6250 1198 / Fax : +65 6250 1081

Company Registration No. : 200507694R

ESTIMATION FOR SMK7153J

Requested By: AXA Insurance Singapore Pte Ltd

Address: 143 Cecil Street #01-01 GB Building

Singapore 069542

Tel: 1800 880 4888

Reference No: Q-19-103

Date: 11/10/2019

Terms: Cash



Item	Description	Qty	Unit Price	Disc %	Total Price
	Policy No // Accident Date: MT/00620631 // 10/10/2019				
	Drive In: 9/10/2019				
	Vehicle Make/Model: Honda Vezel 1.5X CVT				
	Vehicle Number: SMK7153J				
	Manufacturing Year: 2017				
	Engine: Chassis No:RU1-1314840				
	Rear Bonnet	1	\$ 1,480.00	20%	\$ 1,188.00
	Bonnet Hinge	2	\$ 55.00	20%	\$ 88.00
	Rear Bonnet Weather Seal	3	\$ 130.00	20%	\$ 104.00
	Rear Bonnet hinge	4	\$ 100.00	20%	\$ 80.00
	Rear Bonnet bracket	5	\$ 165.00	20%	\$ 132.00
	rear Bonnet hinge	6	\$ 50.00	20%	\$ 40.00
	Rear bonnet absorber left	7	\$ 145.00	20%	\$ 116.00
	Rear Bonnet stopper	8	\$ 18.00	20%	\$ 24.00
	rear Bonnet hinge	9	\$ 15.00	20%	\$ 24.00
	Rear bonnet Absorber Right	10	\$ 165.00	20%	\$ 132.00
	Rear Bonnet Button	11	\$ 130.00	20%	\$ 104.00
	Rear Spoiler	12	\$ 900.00	20%	\$ 720.00
	Bonnet absorber Nuts	21	\$ 30.00	20%	\$ 96.00
	Rear Windscreen	1	\$ 1,765.00	20%	\$ 1,412.00
	Rear Windscreen molding	1	\$ 40.00	20%	\$ 32.00
	Rear Windscreen molding	1	\$ 40.00	20%	\$ 32.00
	Rear Gutter Compartment	19	\$ 160.00	20%	\$ 128.00
	Rear Gutter Compartment	26	\$ 160.00	20%	\$ 128.00
	Rear Panel Compartment	28	\$ 740.00	20%	\$ 592.00
	Rear Bumper Reflector	1	\$ 105.00	20%	\$ 84.00
	Rear Bumper Reflector	2	\$ 105.00	20%	\$ 84.00
	Rear Bumper	3	\$ 705.00	20%	\$ 564.00
	Rear Bumper Side	4	\$ 325.00	20%	\$ 260.00
	Rear Lower Panel	5	\$ 325.00	20%	\$ 260.00
	Rear Spacer Bumper	6	\$ 25.00	20%	\$ 20.00
	Rear Spacer Bumper	7	\$ 40.00	20%	\$ 32.00
	Rear Bumper Cover	1	\$ 200.00	20%	\$ 160.00
	Rear top cover left	2	\$ 120.00	20%	\$ 96.00
	rear hinge	3	\$ 50.00	20%	\$ 40.00
	Rear top Cover right	7	\$ 50.00	20%	\$ 40.00
	Wiring Connection	2	\$ 105.00	20%	\$ 84.00
	Rear Tail Lamp Unit Right	3	\$ 540.00	20%	\$ 432.00
	Rear Tail Lamp Unit Left	7	\$ 540.00	20%	\$ 432.00
	Rear Side Tail Light Right	9	\$ 355.00	20%	\$ 284.00
	Rear Side Tail Light Left	12	\$ 355.00	20%	\$ 284.00
	Rear 'Vezel' Emblem	1	\$ 55.00	20%	\$ 44.00
	Honda Rear logo Assy	5	\$ 285.00	20%	\$ 228.00
	Rear Licence Light	2	\$ 70.00	20%	\$ 112.00
	Rear Licence Bracket	1	\$ 70.00	20%	\$ 56.00
	Rear Wiper Motor Assy	1	\$ 210.00	20%	\$ 168.00
	Rear Wiper Blade	1	\$ 70.00	20%	\$ 56.00
	Rear Fender Cover Left	1	\$ 250.00	20%	\$ 200.00
	Rear Fender Cover Right	1	\$ 250.00	20%	\$ 200.00

h2 de ✓

MAXIMUS RACING PTE LTD

MR Performance Centre. No.7 Soon Lee Street, #05-05, Singapore 627608.

Enquiry Hotline : +65 62501198 / Fax : +65 62501081

Company Registration No. : 200507694R

**FINALIZATION FOR SMK7153J**

Requested By: AXA Insurance Singapore Pte Ltd

Address: 143 Cecil Street #01-01 GB Building

Singapore 069542

Tel: 1800 880 4888

Reference No: Q-19-103

Date: 18/10/2019

Terms: Cash

Item	Description	Qty	Unit Price	Total Price
	Policy No // Accident Date: MT/00620631 // 10/10/2019 Drive In: 9/10/2019 Vehicle Make/Model: Honda Vezel 1.5X CVT Vehicle Number: SMK7153J Manufacturing Year: 2017 Engine: L15B4405906 Chassis No:RU1-1314840			
1	Rear Bonnet	1 unit	\$	1,168.00
2	Rear Windscreen molding	1 unit	\$	32.00
3	Rear Windscreen molding	1 unit	\$	32.00
4	Rear Bumper	1 unit	\$	564.00
5	Rear Spacer Bumper	1 unit	\$	20.00
6	Rear Spacer Bumper	1 unit	\$	32.00
7	Rear Tail Lamp Unit Right	1 unit	\$	432.00
8	Rear Side Tail Light Right	1 unit	\$	284.00
9	Rear Side Tail Light Left	1 unit	\$	284.00
10	Rear 'Vezel' Emblem	1 unit	\$	44.00
11	Honda Rear logo Assy	1 unit	\$	228.00
12	Rear Fender Cover Right	1 unit	\$	200.00
13	Reverse Sensor Aftermarket	2 units	\$	200.00
14	Car plate & Car plate Cover	1 unit	\$	45.00
15	Remove and renew damaged parts, straighten and realign affected areas	1 unit	\$	600.00
16	Respray affected areas.	1 unit	\$	700.00
17	Remove and refit rear upholstery and trims to assist workload	1 unit	\$	60.00
18	To apply cavity wax coating on affected areas	1 unit	\$	40.00
19	To check rear lights, reverse sensor and water leakages	1 unit	\$	60.00
20	Install new rear windscreen	1 unit	\$	120.00
21	Rewiring of Rear Electronic boot motor	1 unit	\$	60.00
22	General diagnosis and checking	1 unit	\$	120.00
23	Wiring for Reversing Camera & Sensors	1 unit	\$	50.00
E. & O.E.				
Sub-Total				\$ 5,375.00
ADD GST 7%				\$ 376.25
Grand Total:				\$ 5,751.25

Please visit our website @ www.MaximusRacing.com**TERMS & CONDITIONS:**

Some products are made exclusively for off-road use, we do not accept any claims/liabilities from their usage.

Do not use the product except in specified car types. We reserve the right to dispose of goods/parts unclaimed after 3 months.

Maximus Racing Pte Ltd will not accept any claims and/or responsibility arising therefrom.

Any Deposit paid are strictly non-refundable!!

Payment by CHEQUES should be crossed and made payable to MAXIMUS RACING PTE LTD

Goods or Parts sold are not returnable nor refundable!

We reserve the rights to charge 1.5% interest per month on all overdue accounts.

Received and agreed to all above charges and sales terms.

Authorised By:

Receiver's Signature