

SIH5750A.

Toyota Allion 1496

NZT2603032428

TPMS16.

Denise.

Front Bumper Repairs

791.40 x

Front Bumper Clips. new

30 x

Front Bumper Side Holder LH. new

38 x

Front LH Fender new

645.20 x

Front Grille cranked

349.10 ✓

1212.20

Front Grille Clips. new

20 ✓

lens 909.15

Front Grille Logo new

78 ✓

Headlamp LH. cranked

765.10. ✓

Panel Bending

~~500~~ 200.

Spray Painting

~~500~~ 200

430

Wiring.

~~50~~ 30.

3739.80

total : 1339.15

n/s : 1050 62 Days

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

PBC