



TRANS EUROKARS PTE LTD



ESTIMATE COST OF REPAIRS

EQ INSURANCE COMPANY LTD 5 Maxwell Road #17-00 Tower Block MND Complex, Singapore 069110 ATTN.: MOTOR CLAIMS FAX:		NAME: Mr Bao Hongman ADDRESS: 19 Sembawang Crscent #09-36 SKYPARK RESIDENCES Singapore 757052 TEL: 85181093		WIP: 52869 EXCESS: DATE: 5-Oct-19	
VEH NO:	SMF217G	DATE IN:		CONTACT PERSON:	Eva 63310683
CHASSIS NO:	JM6BN22A8K0251238	MILEAGE:		TYPE OF CLAIM:	THIRD PARTY CLAIM
MODEL:	MAZDA3	DATE REG.:	25-Oct-18	POLICY NO.:	
NATURE OF WORKS					
Parts Description					
NO	QTY			REVISED	PRICES
1	REAR BUMPER	1	MBHN1-50-221ABB	de	\$ 1,128.60
2	BRACKET CENTER	1	MKD53-50-251	?	\$ 5.40
3	REAR REINFORCEMENT	1	MB45A-50-260	?	\$ 564.20
4	GROMMET, REAR BUMPER	4	MBHN1-50-021A	we	\$ 10.80
5	GROMMET, REAR BUMPER	2	M9991-00-501	we	\$ 6.00
6	FASTENER, REAR BUMPER	4	MB45A-56-146A	we	\$ 12.00
7	RIVET, REAR BUMPER	4	MBBM4-50-355	we	\$ 18.00
8	REAR END PANEL	1	MB4YA-70-75Z	?	\$ 530.40
9	TRIM, END PANEL	1	MBHN1-68-89XA	?	\$ 89.40
10	FASTENER, TRIM	10	MGJ21-68-885B02	?	\$ 30.00
11	BOOTLID	1	MBHY2-52-61XB	bt	\$ 1,005.30
12	WEATHERSTRIP, BOOTLID	1	MBHN1-56-951A	X	\$ 113.10
13	LOCK, BOOTLID	1	MGHK1-56-820A	?	\$ 160.70
14	STRIKER, BOOTLID	1	MGG2A-56-840	?	\$ 35.10
15	FASTENER, BOOTLID	2	MEG21-51-146	we	\$ 12.40
16	GROMMET, BOOTLID	2	MGA7B-51-146	we	\$ 6.60
17	GASKET LHS, BOOTLID	1	MB45A-51-3J8	we	\$ 22.00
18	GASKET RHS, BOOTLID	1	MB45A-51-3H8	we	\$ 22.00
19	GASKET LHS, TAILLAMP	1	MBHN1-51-163	we	\$ 22.00
20	GASKET RHS, TAILLAMP	1	MBHN1-51-153	we	\$ 22.00
21	ORNAMENT, MAZDA	1	MBHN1-51-721	we	\$ 56.10
22	MASCOT, REAR	1	MBHN1-51-730	we	\$ 78.20
23	ORNAMENT, SKYACTIVE	1	MBHN1-51-771	we	\$ 66.80
TOTAL PARTS					\$ 4,017.10
LESS 10%					\$ 401.71
TOTAL PARTS COST					\$ 3,615.39
Labour Description					

1	MZ-BR-REAR05	TO REPLACE REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL AND BOOT LID. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	1320.	\$	3,630.00
2	MZ-SP-SREAR5	TO RESPRAY REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL AND BOOT LID.	1260.	\$	2,520.00
3	MZ-BR-REVSEN	TO TRANSFER REVERSE SENSORS. (WITH REVERSE SENSOR)	330.	NETT	\$ 660.00
4	MZ-BR-CAMERA	TO TRANSFER REVERSE CAMERA.	X	NETT	\$ 330.00
5	MZ-BR-PLATE1	TO SUPPLY NUMBER PLATE.	X	NETT	\$ 70.00
6	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	150.	\$	250.00
7	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150.	\$	250.00
8	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180.	\$	350.00
9		TO SUPPLY BODY COATING.	✓	NETT	\$ 250.00
10	MZ-BR-SUNDRI	SUNDRIES.	20	NETT	\$ 100.00
TOTAL LABOUR			\$ -	\$	8,410.00
TOTAL PARTS			\$ -	\$	3,615.39
TOTAL			\$ -	\$	12,025.39
LESS EXCESS			\$ -	\$	-
TOTAL AFTER EXCESS			\$ -		
GST 7%			\$ -	\$	-
GRAND TOTAL			\$ -	\$	-

REMARKS:
THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD

Authorised Signature

Tayfun 9749 5749
WP
11/10/19 E 4349
5 days
Resurvey before paint
sure/through.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: