

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 15027

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1203/2019/NS
Date : 7-Oct-19

Vehicle IN workshop. Kindly arrange for survey.

Your insured vehicle no. :

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Rengaraj Ranganathan
Address : 103 Hillview Rise
#09-18
Singapore 667982
Telephone : HP +65 81574100
Type of Claim : Own Damage Claim
Policy No. : 1700018472-02
Vehicle No : **SLP 8208 P**
Model Code : Audi Q2 1.0 TFSI S tronic
Model / Year : Jun-17
Engine No : CHZ 401661
Chassis No : WAUZZZGA3HA052306
Mileage : 412930
Date In : 7-Oct-19
Estimated By : Johnny Boo / Allan Wu
Accident Date : 5-Oct-19
Place of Accident : Along PIE Towards Airport Before Exit 11A

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLP 8208 P

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To tow and recover vehicle from scene of accident.	S/N \$ 280.00	X
2	To carry out first measurement test on car o-liner	S/N \$ 800.00	? photo. ✓
3	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00	✓ ✓
4	To remove and transfer rear parking aid. Check function and renew according to damage.	S/N \$ 280.00	✓ ✓
5	To remove and reinstall rear lid's convenience lock system, wire harness for tail lights and rear wiper assy.	S/N \$ 480.00	✓ ✓
SUB TOTAL LABOUR CHARGES		: \$ 2,200.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLP 8208 P

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
6	To renew rear windscreen	S/N \$ 480.00 ✓	✓
7	To install rear windscreen solar film.	S/N \$ 400.00 ✓	✓
8	To remove and renew aircon condenser, additional radiator, radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$ 1,400.00 ✓ <i>check price</i>	✓
9	To dismantle and reinstall centre console. Renew airbag control unit and both front seatbelt.	S/N \$ 1,800.00 ✓	✓
10	To remove and reinstall engine assy with gearbox assy to facilitate car o-liner repairs.	S/N \$ 2,800.00 ? <i>plus to X</i>	
SUB TOTAL LABOUR CHARGES		: <u>\$ 6,880.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLP 8208 P

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
11	To remove and reinstall front suspension assy with subframe to facilitate car o-liner repairs. Inspect for damages and renew if necessary.	S/N \$ 2,400.00	? photo x
12	To remove and reinstall exhaust system and rear suspension assembly. Renew accordingly.	S/N \$ 2,400.00	? photo ✓
13	To remove and reinstall fuel tank assy.	S/N \$ 600.00	? photo ✓
14	To place vehicle on car o-liner. <i>celette bench</i>	S/N \$ 2,400.00	? photo 1200
15	To dismantle and renew front bumper, bonnet, both headlights, rear bumper and rear lid. Cut out and reweld end panelling and spare wheel housing. To repair both front fenders and both rear fenders. Renew front lock carrier and align to position. Re-organise crash management components. reinstall all parts removed.	\$ 12,000.00	7000 8000
SUB TOTAL LABOUR CHARGES		: <u>\$ 26,680.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLP 8208 P

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
16	To carry out stone chip primer work on rear end panelling and spare wheel housing.	S/N \$ 780.00	✓ ✓
17	To respray front bumper, both front fenders, bonnet, engine compartment, rear bumper, rear lid, both rear fenders, hinges, end panelling and spare wheel housing. To carry out joint sealer works and stone chip treatment.	\$ 10,100.00	5500 6000
18	To carry out wheel alignment.	S/N \$ 240.00	? photo ✓
19	To carry out diagnostic checks.	S/N \$ 384.00	✓ ✓
TOTAL LABOUR CHARGES		: <u>\$ 47,264.00</u>	40,384

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLP 8208 P

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	Remarks
1	FRONT BUMPER	\$ 1,704.00	de ✓ 1364
2	FRONT BUMPER FIXING PARTS	\$ 314.00	? X
3	FRONT BUMPER GRILLE - CENTRE	\$ 179.00	de ✓ 143.20
4	FRONT BUMPER AIR GUIDE GRILLE - LH / RH	2 \$ 308.00	mis ✓ 245.60
5	FRONT BUMPER END CAP - LH / RH	2 \$ 62.00	mis ✓ 48.80
6	FRONT BUMPER SPOILER	\$ 273.00	de ✓ 218
7	FRONT BUMPER CLOSING ELEMENT	\$ 142.00	cm ✓ 113.20
8	FRONT WHEEL SPOILER - LH / RH	2 \$ 62.00	RH - cm - , LH - ? 31 49.12
9	FRONT BUMPER ADAPTER - LH / RH	2 \$ 70.00	ney ✓ 55.92
10	RADIATOR GRILLE	\$ 1,301.00	cm ✓ 1046.80
11	RADIATOR GRILLE STRIKER PLATE	\$ 114.00	? 91.20
12	FRONT BUMPER CARRIER	\$ 625.00	bt ✓ 499.60
13	FRONT BUMPER FOAM FILLER PIECE	\$ 71.00	cm ✓ 56.08
14	FRONT BUMPER COVER	\$ 91.00	de ✓ 72.56
15	FRONT BUMPER GUIDE SECTION - LH / RH	2 \$ 64.00	? 51.20
16	FRONT BUMPER DISTANCE PIECE	\$ 12.00	? X
17	HORN - LH LOW TONE	\$ 262.00	cm ✓ 209.20
18	SIGNAL HORN - RH HIGH TONE	\$ 180.00	de ✓ 143.60
19	HORN SPRING SHACKLE - LH / RH	2 \$ 58.00	bt ✓ 45.44
20	EXTERNAL TEMPERATURE SENSOR	\$ 54.00	? 42.96
SUB TOTAL SPARE PARTS		\$ 5,946.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLP 8208 P

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	Remarks
21	BONNET	\$ 2,549.00	bt - 2039.20
22	BONNET ATTACHMENT PARTS	\$ 149.00	? x
23	BONNET LID HINGE - LH / RH	2 \$ 108.00	? x
24	BONNET GAS FILLED STRUT	\$ 93.00	? x
25	BONNET STRIKER - LH / RH	2 \$ 200.00	? 159.04
26	BONNET SOUND ABSORBER	\$ 201.00	X un
27	BONNET IMPACT PROTECTION - LH / RH / CENTRE	3 \$ 82.00	un - 64.40
28	BONNET LOWER COVER - LH / RH	2 \$ 74.00	X
29	BONNET UPPER COVER - LH / RH	2 \$ 28.00	X } un
30	PLENUM CHAMBER COVER FRONT	\$ 144.00	X
31	WATER BOX	\$ 124.00	X
32	BONNET BOWDEN CABLE - CENTRE	\$ 53.00	? 41.68
33	BONNET LID LOCK CABLE	\$ 67.00	? x
34	BONNET RELEASE ELEMENT	\$ 53.00	? 41.68
35	BONNET BOWDEN CABLE - LH / RH	2 \$ 106.00	X un 83.36
36	BONNET RELEASE LEVER	\$ 12.00	X un 9.60
37	CAUTION SIGN STICKER	NEC \$ 13.00	un 9.76
38	AIRCON STICKER	NEC \$ 7.00	un 5.12
39	HEADLIGHT MOUNTING - LH / RH	2 \$ 214.00	? 171.20
40	LED HEADLIGHT - LH / RH	2 \$ 8,982.00	RH un 7185.60
SUB TOTAL SPARE PARTS		\$ 13,259.00	P LH - ? 4491

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLP 8208 P

S/N	Parts Description	Damage Parts & Prices		Remarks
		S/NETT		
41	MAIN LIGHT ELECTRONICS POWER MODULE - LH / RH	2 \$	1,385.00	X } un
42	LIGHT CONTROL SYSTEM CONTROL UNIT - LH / RH	2 \$	1,015.00	X } un
43	LED WITH HEAT SINK - LH / RH	2 \$	1,332.00	X }
44	HEADLIGHT HOSE - LH / RH	2 \$	52.00	? X
45	LIFT CYLINDER - LH / RH	2 \$	256.00	? 136
46	HEADLIGHT HOSE	\$	170.00	? 21.76
47	HEADLIGHT DISTRIBUTOR	\$	27.00	? 65.28
48	HEADLIGHT ELBOW FITTING	3 \$	81.00	? X
49	HEADLIGHT PUMP	\$	147.00	? X
50	WINDSCREEN WASHER SYSTEM PUMP	\$	118.00	? X
51	WASH WATER RESERVOIR	\$	156.00	del - 124.80
52	HEADLIGHT WASHER STRAINER	\$	19.00	del X un
53	HEADLIGHT WASHER END CAP	\$	19.00	X un
54	LOCK CARRIER	\$	907.00	chg - 725.60
55	A/C CONDENSER	\$	503.00	bt - 402
56	REFRIGERANT LINE A/C CONDENSER - CUT - OFF POINT	\$	601.00	? 480.40
57	REFRIGERANT LINE A/C COMPRESSOR - CONDENSER	\$	461.00	? 368.80
58	RADIATOR	\$	878.00	? 718.80
59	ADDITIONAL RADIATOR	\$	837.00	? 686
60	RADIATOR BRACKET - UPPER	2 \$	77.00	? 61.28
SUB TOTAL SPARE PARTS		:	\$ 9,041.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLP 8208 P

S/N	Parts Description	Damage Parts & Prices		Remarks
		S/NETT		
61	RADIATOR BUSH - LOWER	2 \$	18.00	de ✓ 14.24
62	RADIATOR SEALING STRIP - LH / RH	2 \$	32.00	? 24.96
63	READY MIX COOLANT	4 \$	84.00	neu ✓ 67.20
64	RADIATOR FAN	\$	1,483.00	? X
65	RADIATOR AIR GUIDE - LH / RH	2 \$	54.00	? 42.72
66	RADIATOR AIR GUIDE - UPPER CENTRE	\$	19.00	? 15.20
67	AIR INLET	\$	53.00	? 41.84
68	AIR FILTER	\$	62.00	? X
69	INTER COOLER GASKET	\$	13.00	? X
70	WATER DRAINAGE HOSE	\$	31.00	? X
71	AIR FILTER	\$	252.00	? X
72	INTAKE MANIFOLD	\$	129.00	? X
73	ACTIVATED CHARCOAL CONTAINER	\$	294.00	? X
74	NOISE INSULATION - FRONT	\$	239.00	neu ✓ 191.20
75	FRONT WHEEL COVER - LH / RH	2 \$	588.00	RH - mis ✓ LH ✓ 294
76	REAR BUMPER	\$	1,074.00	de ✓ 859.20
77	REAR BUMPER FIXING PARTS	\$	70.00	? X
78	REAR BUMPER SPOILER	\$	259.00	neu ✓ 207.20
79	REAR BUMPER TOWING EYE COVER	\$	39.00	de ✓ 30.88
80	REAR LIGHT REFLECTOR - LH / RH	2 \$	54.00	mis ✓ 43.04
SUB TOTAL SPARE PARTS		:	\$ 4,847.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLP 8208 P

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	Remarks
81	REAR BUMPER CARRIER	\$ 501.00	bt - 400.40
82	REAR BUMPER HOLDING STRAP - LH / RH	2 \$ 24.00	one - 17.92
83	REAR BUMPER GUIDE SECTION - LH / RH	2 \$ 98.00	? 77.44
84	REAR PARKING AID SENSOR - LH / RH	4 \$ 924.00	? X
85	REAR PARKING AID SEAL RING	4 \$ 12.00	nei - 9.68
86	REAR BUMPER WIRING SET	\$ 472.00	? X
87	REAR LID	\$ 2,195.00	bt - 1756
88	REAR LID HINGE	2 \$ 275.00	X nm
89	REAR LID ATTACHMENT PARTS	\$ 109.00	? X
90	REAR LID LOCK STRIKER	\$ 265.00	? X
91	REAR LID FLAP GASKET	\$ 106.00	nei - 84.40
92	REAR LID LOCK STRIKER	\$ 196.00	? 156.40
93	BONNET LOCK COVER	\$ 11.00	? 8.64
94	REAR LID LOCK ACTUATOR PUSH BUTTON	\$ 167.00	? X
95	REAR LID GAS FILLED STRUT	2 \$ 217.00	? X
96	REAR LID GAS FILLED STRUT BRACKET - LH / RH	2 \$ 66.00	? X
97	REAR LID BRACKET - LH / RH	2 \$ 178.00	? X
98	LICENCE PLATE TRIM	\$ 213.00	cut - 170
99	REAR LID BALANCE WEIGHT	\$ 485.00	? X
100	AUDI EMBLEM	\$ 113.00	nei - 90
SUB TOTAL SPARE PARTS		\$ 6,627.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLP 8208 P

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	Remarks
101	Q2 INSCRIPTION	\$ 87.00	net ✓ 69.28
102	TFSI INSCRIPTION	\$ 87.00	net ✓ 69.28
103	REAR LID FOAM STRIPS	\$ 121.00	net ✓ 96.40
104	REAR LID SPOILER FIXING PARTS - photo	\$ 121.00	net ✓ 96.40
105	REAR WINDSCREEN	\$ 711.00	net ✓ 568.80
106	PRIMER	\$ 19.00	net ✓ 15.20
107	LED LICENCE PLATE LIGHT	2 \$ 92.00	? X 1931.20
108	TAIL LIGHT - LH / RH	2 \$ 2,414.00	14-01-12 RH ✓
109	TAIL LIGHT TRIM - LH / RH	2 \$ 54.00	? 43.04
110	CROSS PANEL REINFORCEMENT	\$ 669.00	bt ✓ 535.20
111	REAR CROSS PANEL	\$ 224.00	bt ✓ 178.80
112	REAR CROSS PANEL CONNECTING PIECE - LH	\$ 37.00	? 29.44
113	REAR CROSS PANEL BOOT FLOOR PLATE	\$ 1,687.00	buc ✓ 1349.60
114	REAR CROSS PANEL TRIM	\$ 141.00	de ✓ 112.40
115	REAR CROSS PANEL TRIM PLASTIC TRAY	\$ 210.00	? X
116	LUGGAGE COMPARTMENT FLOOR COVERING	\$ 646.00	X m
117	REAR LID TRIM PANEL - LOWER	\$ 447.00	? 357.20
118	REAR WHEEL COVER - LH / RH	2 \$ 312.00	? photo 248.80
119	REAR SILENCER	\$ 653.00	? photo 522
120	REAR SILENCER DUAL CLIP	\$ 55.00	? 43.52
TOTAL SPARE PARTS		: \$ 8,787.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLP 8208 P

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	Remarks
121	EXHAUST SYSTEM RETAINER	2 \$ 75.00	? X
122	THREE-POINT AUTOMATIC SEAT BELT	\$ 952.00	cut — 761.60
123	FELT STRIPS - LH	\$ 22.00	? X
124	THREE-POINT AUTOMATIC SEAT BELT	\$ 952.00	act — 761.60
125	FELT STRIPS - LH	\$ 22.00	? X
126	SEAT BELT HEIGHT ADJUSTER	2 \$ 322.00	? 257.60
127	AIRBAG CONTROL UNIT	\$ 1,578.00	net — 1262.40
128	FRONT NO PLATE	S/N \$ 40.00	bt — 40
129	REAR NO PLATE	S/N \$ 40.00	bt — 40
130	ACRYLIC SEALANT	S/N \$ 180.00	net — 180
131	CAVITY WAX	S/N \$ 140.00	net — 140
132	STONE CHIP	S/N \$ 180.00	net — 180
133	REAR WINDSCREEN SEALANT	S/N \$ 200.00	net — 200
134	METAL FILLER POWDER	S/N \$ 280.00	net — 280
135	SUNDRIES	\$ 1,000.00	? 243.60
TOTAL SPARE PARTS		: \$ 54,490.00	
TOTAL LABOUR CHARGES		: \$ 47,264.00	
GRAND TOTAL		: \$ 101,754.00	94,874

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

102418

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :


Tanjah 97495749
9/10/19 @ 1140
Not Authorise
Ex: to be advise
Resurvey before paint.
25 days
suu@kianta.com

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

RS 215/60K16

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLP 8208 P

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	Remarks
1	FRONT BUMPER	\$ 1,704.00	de ✓
2	FRONT BUMPER FIXING PARTS	\$ 314.00	?
3	FRONT BUMPER GRILLE - CENTRE	\$ 179.00	de ✓
4	FRONT BUMPER AIR GUIDE GRILLE - LH / RH	2 \$ 308.00	mis ✓
5	FRONT BUMPER END CAP LH/RH	2 \$ 62.00	mis ✓
6	FRONT BUMPER SPOILER	\$ 273.00	de ✓
7	FRONT BUMPER CLOSING ELEMENT	\$ 142.00	can ✓
8	FRONT WHEEL SPOILER LH/RH	2 \$ 62.00	RH - can - , LH - ?
9	FRONT BUMPER ADAPTER - LH / RH	2 \$ 70.00	mis ✓
10	RADIATOR GRILLE	\$ 1,301.00	can ✓
11	RADIATOR GRILLE STRIKER PLATE X	\$ 114.00	?
12	FRONT BUMPER CARRIER	\$ 625.00	bt ✓
13	FRONT BUMPER FOAM FILLER PIECE	\$ 71.00	can ✓
14	FRONT BUMPER COVER	\$ 91.00	de ✓
15	FRONT BUMPER GUIDE SECTION LH/RH ?	2 \$ 64.00	?
16	FRONT BUMPER DISTANCE PIECE	\$ 12.00	?
17	HORN - LH LOW TONE	\$ 262.00	can ✓
18	SIGNAL HORN - RH HIGH TONE	\$ 180.00	de ✓
19	HORN SPRING SHACKLE - LH / RH	2 \$ 58.00	bt ✓
20	EXTERNAL TEMPERATURE SENSOR	\$ 54.00	?
SUB TOTAL SPARE PARTS		\$ 5,946.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLP 8208 P

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	Remarks
21	BONNET	S 2,549.00	bt-
22	BONNET ATTACHMENT PARTS	S 149.00	?
23	BONNET LID HINGE - LH / RH	2 S 108.00	?
24	BONNET GAS FILLED STRUT	S 93.00	?
25	BONNET STRIKER - LH / RH	2 S 200.00	?
26	BONNET SOUND ABSORBER	S 201.00	X
27	BONNET IMPACT PROTECTION - LH / RH / CENTRE	3 S 82.00	na-
28	BONNET LOWER COVER - LH / RH	2 S 74.00	X
29	BONNET UPPER COVER - LH / RH	2 S 28.00	X
30	PLENUM CHAMBER COVER FRONT	S 144.00	X
31	WATER BOX	S 124.00	X
32	BONNET BOWDEN CABLE - CENTRE	S 53.00	?
33	BONNET LID LOCK CABLE	S 67.00	?
34	BONNET RELEASE ELEMENT	S 53.00	X un
35	BONNET BOWDEN CABLE - LH / RH	2 S 106.00	X
36	BONNET RELEASE LEVER	S 12.00	X un
37	CAUTION SIGN STICKER	NEC S 13.00	na-
38	AIRCON STICKER	NEC S 7.00	na-
39	HEADLIGHT MOUNTING - LH / RH	2 S 214.00	? cor
40	LED HEADLIGHT - LH / RH	2 S 8,982.00	RH-int ✓
SUB TOTAL SPARE PARTS		: S 13,259.00	P LH-?

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLP 8208 P

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	Remarks
41	MAIN LIGHT ELECTRONICS POWER MODULE - LH / RH	2 S 1,385.00	X } un
42	LIGHT CONTROL SYSTEM CONTROL UNIT - LH / RH	2 S 1,015.00	X } un
43	LED WITH HEAT SINK - LH / RH	2 S 1,332.00	X } un
44	HEADLIGHT HOSE - LH / RH	2 S 52.00	?
45	LIFT CYLINDER - LH / RH	2 S 256.00	?
46	HEADLIGHT HOSE X	S 170.00	X } un
47	HEADLIGHT DISTRIBUTOR X	S 27.00	X } un
48	HEADLIGHT ELBOW FITTING X	3 S 81.00	X } un
49	HEADLIGHT PUMP	S 147.00	?
50	WINDSCREEN WASHER SYSTEM PUMP	S 118.00	?
51	WASH WATER RESERVOIR	S 156.00	oil -
52	HEADLIGHT WASHER STRAINER	S 19.00	X un
53	HEADLIGHT WASHER END CAP	S 19.00	X un
54	LOCK CARRIER	S 907.00	eng -
55	A/C CONDENSER	S 503.00	bt -
56	REFRIGERANT LINE A/C CONDENSER - CUT - OFF POINT bt -	S 601.00	?
57	REFRIGERANT LINE A/C COMPRESSOR - CONDENSER bt -	S 461.00	?
58	RADIATOR bt -	S 878.00	?
59	ADDITIONAL RADIATOR bt -	S 837.00	?
60	RADIATOR BRACKET - UPPER cut -	2 S 77.00	?
SUB TOTAL SPARE PARTS		: \$ 9,041.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLP 8208 P

S/N	Parts Description	Damage Parts & Prices		Remarks
		S/NETT		
61	RADIATOR BUSH - LOWER	2	\$ 18.00	de ✓
62	RADIATOR SEALING STRIP LH / RH <i>cut</i>	2	\$ 32.00	?
63	READY MIX COOLANT	4	\$ 84.00	na ✓
64	RADIATOR FAN <i>X</i>		\$ 1,483.00	<i>Ken</i>
65	RADIATOR AIR GUIDE LH / RH <i>con</i>	2	\$ 54.00	?
66	RADIATOR AIR GUIDE - UPPER CENTRE <i>ca</i>		\$ 19.00	?
67	AIR INLET <i>ca</i>		\$ 53.00	?
68	AIR FILTER		\$ 62.00	?
69	INTER COOLER GASKET		\$ 13.00	?
70	WATER DRAINAGE HOSE		\$ 31.00	?
71	AIR FILTER		\$ 252.00	?
72	INTAKE MANIFOLD		\$ 129.00	?
73	ACTIVATED CHARCOAL CONTAINER		\$ 294.00	?
74	NOISE INSULATION - FRONT		\$ 239.00	<i>fine</i>
75	FRONT WHEEL COVER - LH / RH	2	\$ 588.00	<i>RH - mis, LH - ?</i>
76	REAR BUMPER		\$ 1,074.00	<i>de</i>
77	REAR BUMPER FIXING PARTS		\$ 70.00	?
78	REAR BUMPER SPOILER		\$ 259.00	<i>con</i>
79	REAR BUMPER TOWING EYE COVER		\$ 39.00	<i>de</i>
80	REAR LIGHT REFLECTOR - LH / RH	2	\$ 54.00	<i>mis</i>
SUB TOTAL SPARE PARTS			\$ 4,847.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLP 8208 P

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	Remarks
81	REAR BUMPER CARRIER	\$ 501.00	bt
82	REAR BUMPER HOLDING STRAP - LH / RH	2 \$ 24.00	cu
83	REAR BUMPER GUIDE SECTION - LH / RH	2 \$ 98.00	?
84	REAR PARKING AID SENSOR - LH / RH	4 \$ 924.00	?
85	REAR PARKING AID SEAL RING	4 \$ 12.00	ner
86	REAR BUMPER WIRING SET	\$ 472.00	?
87	REAR LID	\$ 2,195.00	bt
88	REAR LID HINGE	2 \$ 275.00	X
89	REAR LID ATTACHMENT PARTS	\$ 109.00	?
90	REAR LID LOCK STRIKER	\$ 265.00	?
91	REAR LID FLAP GASKET	\$ 106.00	ner
92	REAR LID LOCK STRIKER	\$ 196.00	JAM
93	BONNET LOCK COVER	\$ 11.00	X
94	REAR LID LOCK ACTUATOR PUSH BUTTON	\$ 167.00	?
95	REAR LID GAS FILLED STRUT	2 \$ 217.00	?
96	REAR LID GAS FILLED STRUT BRACKET - LH / RH	2 \$ 66.00	?
97	REAR LID BRACKET - LH / RH	2 \$ 178.00	?
98	LICENCE PLATE TRIM	\$ 213.00	cut
99	REAR LID BALANCE WEIGHT	\$ 485.00	?
100	AUDI EMBLEM	\$ 113.00	ner
SUB TOTAL SPARE PARTS		\$ 6,627.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLP 8208 P

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	Remarks
101	Q2 INSCRIPTION	\$ 87.00	ne ✓
102	TFSI INSCRIPTION	\$ 87.00	ne ✓
103	REAR LID FOAM STRIPS	\$ 121.00	ne ✓
104	REAR LID SPOILER FIXING PARTS - photo	\$ 121.00	ne ✓
105	REAR WINDSCREEN	\$ 711.00	ne ✓
106	PRIMER	\$ 19.00	ne ✓
107	LED LICENCE PLATE LIGHT	2 \$ 92.00	?
108	TAIL LIGHT - LH / RH	2 \$ 2,414.00	LH - ok - RH ✓
109	TAIL LIGHT TRIM - LH / RH	2 \$ 54.00	?
110	CROSS PANEL REINFORCEMENT	\$ 669.00	bt ✓
111	REAR CROSS PANEL	\$ 224.00	bt ✓
112	REAR CROSS PANEL CONNECTING PIECE - LH X	\$ 37.00	Run
113	REAR CROSS PANEL BOOT FLOOR PLATE	\$ 1,687.00	buc ✓
114	REAR CROSS PANEL TRIM	\$ 141.00	de ✓
115	REAR CROSS PANEL TRIM PLASTIC TRAY	\$ 210.00	-
116	LUGGAGE COMPARTMENT FLOOR COVERING	\$ 646.00	X
117	REAR LID TRIM PANEL - LOWER	\$ 447.00	?
118	REAR WHEEL COVER - LH / RH	2 \$ 312.00	? photo
119	REAR SILENCER bt ✓	\$ 653.00	? photo
120	REAR SILENCER DUAL CLIP	\$ 55.00	?
TOTAL SPARE PARTS		\$ 8,787.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLP 8208 P

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	Remarks
1	FRONT BUMPER	\$ 1,704.00	de ✓
2	FRONT BUMPER FIXING PARTS	\$ 314.00	?
3	FRONT BUMPER GRILLE - CENTRE	\$ 179.00	de ✓
4	FRONT BUMPER AIR GUIDE GPTILE - LH / RH	2 \$ 308.00	mis ✓
5	FRONT BUMPER END CAP LH/RH	2 \$ 62.00	mis ✓
6	FRONT BUMPER SPOILER	\$ 273.00	de ✓
7	FRONT BUMPER CLOSING ELEMENT	\$ 142.00	con ✓
8	FRONT WHEEL SPOILER LH/RH	2 \$ 62.00	RH - con - , LH - ?
9	FRONT BUMPER ADAPTER - LH / RH	2 \$ 70.00	mis ✓
10	RADIATOR GRILLE	\$ 1,301.00	con ✓
11	RADIATOR GRILLE STRIKER PLATE X de ✓	\$ 114.00	?
12	FRONT BUMPER CARRIER	\$ 625.00	bt ✓
13	FRONT BUMPER FOAM FILLER PIECE	\$ 71.00	con ✓
14	FRONT BUMPER COVER	\$ 91.00	de ✓
15	FRONT BUMPER GUIDE SECTION LH/RH X	2 \$ 64.00	mis ✓
16	FRONT BUMPER DISTANCE PIECE	\$ 12.00	?
17	HORN - LH LOW TONE	\$ 262.00	con ✓
18	SIGNAL HORN - RH HIGH TONE	\$ 180.00	de ✓
19	HORN SPRING SHACKLE - LH / RH	2 \$ 58.00	bt ✓
20	EXTERNAL TEMPERATURE SENSOR mis ✓	\$ 54.00	?
SUB TOTAL SPARE PARTS		\$ 5,946.00	

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Signature 10/1

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLP 8208 P

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	Remarks
21	BONNET	\$ 2,549.00	bt -
22	BONNET ATTACHMENT PARTS	\$ 149.00	?
23	BONNET LID HINGE - LH / RH	2 \$ 108.00	?
24	BONNET GAS FILLED STRUT	\$ 93.00	?
25	BONNET STRIKER - LH / RH	2 \$ 200.00	?
26	BONNET SOUND ABSORBER	\$ 201.00	X
27	BONNET IMPACT PROTECTION - LH / RH / CENTRE	3 \$ 82.00	na -
28	BONNET LOWER COVER - LH / RH	2 \$ 74.00	X
29	BONNET UPPER COVER - LH / RH	2 \$ 28.00	X
30	PLENUM CHAMBER COVER FRONT	\$ 144.00	X
31	WATER BOX	\$ 124.00	X
32	BONNET BOWDEN CABLE - CENTRE	\$ 53.00	dis ✓ <i>15/11</i>
33	BONNET LID LOCK CABLE	\$ 67.00	?
34	BONNET RELEASE ELEMENT	\$ 53.00	?
35	BONNET BOWDEN CABLE - LH / RH	2 \$ 106.00	X
36	BONNET RELEASE LEVER	\$ 12.00	X
37	CAUTION SIGN STICKER	NEC \$ 13.00	na
38	AIRCON STICKER	NEC \$ 7.00	na
39	HEADLIGHT MOUNTING - LH / RH	2 \$ 214.00	?
40	LED HEADLIGHT - LH / RH	2 \$ 8,982.00	RH - ✓
SUB TOTAL SPARE PARTS		\$ 13,259.00	P LH - ?

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

PA/OD/1203/2019/NS

Date

25-Oct-19

Service Advisor

Glory Tan

Pages

1 of 1

Regn No

SLP 8208 P

Model No

Audi Q2 1.0 TFSI S tronic

Quantity	Description	Unit Price	Amount
Parts			
1	Heat shield for rear silencer <i>bu</i>	\$ 153.00	122.40
2	Bonnet bungs <i>na</i>	\$ 110.00	87.36
3	Coolant hose with quick release coupling lower <i>cm</i>	\$ 126.00	100.40
4	Coolant hose with quick release coupling front <i>cm</i>	\$ 234.00	186.80
5	Mechatronic with software <i>bt</i>	\$ 3,690.00	2952.96
6	Transmission fluid <i>na</i>	\$ 120.00	96
7	Wheel housing liner LHS front <i>cut</i>	\$ 183.00	146
8	Wheel housing liner RHS front <i>cut</i>	\$ 183.00	146
9	Bonnet lid lock with micro switch <i>na</i>	\$ 367.00	293.60
10	Corrugated pipe for water reservoir <i>cut</i>	\$ 75.00	59.92
11	Water reservoir terminal <i>mu</i>	\$ 8.00	7.04
12	Radiator fan with fan ring <i>cm</i>	\$ 1,046.00	836.80
13	Air intake top cover <i>cm</i>	\$ 27.00	21.36
14	Air intake air guide <i>cut</i>	\$ 19.00	14.48
15	End panel connecting plate RHS <i>cm</i>	\$ 37.00	29.44

\$ 6,378.00

Labours

- 1 To renew mechatronic with software. To carry out calibration.

S/N \$ 980.00

Labours total \$ 6,378.00

Parts total \$ 980.00

GRAND TOTAL \$ 7,358.00

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

PA/OD/1203/2019/NS

Date

8-Nov-19

Service Advisor

Glory Tan

Pages

1 of 1

Regn No

SLP 8208 P

Model No

Audi Q2 1.0 TFSI S tronic

Quantity Description

Unit Price Amount

Parts

1	Rear wheel housing liner RHS <i>cm</i>	\$ 189.00	150.80
2	Bolt for spare wheel mounting <i>cm</i>	\$ 24.00	19.20

GRAND TOTAL \$ 213.00

For Premium Automobiles Pte Ltd



Authorised Signature

11/11/19 @ 1530hrs

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

PA/OD/1203/2019/NS

Date

18-Nov-19

Service Advisor

Glory Tan

Pages

1 of 1

Regn No

SLP 8208 P

Model No

Audi Q2 1.0 TFSI S tronic

Quantity	Description	Unit Price	Amount
----------	-------------	------------	--------

Parts

1	Support floor luggage boot lining LHS lower	\$ 73.00	de / 58
---	---	----------	---------

GRAND TOTAL

\$ 73.00

For Premium Automobiles Pte Ltd

Signature 18/11

Signature

Authorised Signature

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/1203/2019/NS 18-Nov-19 Glory Tan 1 of 1 SLP 8208 P Audi Q2 1.0 TFSI S tronic
Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	Seat frame with height adjustment	\$ 2,110.00	\$ 1,688.00
		\$ 2,110.00	\$ 1,688.00
<u>Labours</u>			
1	To remove and reinstall driver seat.	s/n \$ 180.00	\$ 180.00
2	To dismantle and reinstall driver seat backrest, driver leather seat. To renew seat frame.	s/n \$ 300.00	\$ 300.00
	Labours total	\$ 480.00	\$ 480.00
	Part total		
	GRAND TOTAL	\$ 480.00	\$2,168.00

For Premium Automobiles Pte Ltd

Authorised Signature