



# ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

## Repair Estimates

SLX 7346 M

*Not Authorised  
Rebody B6paim*

Parts	(a) Cost / List Price Items	\$	8,515.10
	Plus/Less 20%	\$	1,703.02
	<b>Total of Cost / List</b>	<b>\$</b>	<b>6,812.08</b>
	(b) Nett Price Items		
	Less		
	<b>Total of Nett Item</b>		
	(c) <b>Special Nett Items</b>	<b>\$</b>	<b>295.00</b>
<b>Total Parts Cost</b>		<b>\$</b>	<b>7,107.08</b>
<b>Labour</b>		<b>\$</b>	<b>2,690.00</b>
<b>Total</b>		<b>\$</b>	<b>9,797.08</b>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth  
Company : LKK  
Survey conducted on : 10/10/19 at 14:00

### Remarks By Surveyor

- (a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.
- (b) Recommended Days of Repair : 4-5 day(s)
- (c) Resurvey : Required / ~~Not Required~~
- (d) Excess : \$
- (e) Signature of surveyor : *LK* Date: 10/10/19



## ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

### Spare Parts

Vehicle No. : **SLX 7346 M**  
Make & Model : **HONDA SHUTTLE**  
Chassis No : **GP71104081**

Submit By : **SERENCE**  
Year Manufacture : **2016**  
Engine No. :

### Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Rear windscreen moulding <i>Me</i>	1	\$120.00		✓
2	Rear windscreen sealant <i>Me</i>	1	\$50.00	S.N	405N
3	Reverse sensor <i>shot</i>	2	\$200.00	S.N	✓
4	Rear number plate <i>Red</i>	1	\$45.00	S.N	✓
5	Rear No.plate lamp LH <i>Sn</i>	1	\$38.50		X
6	Rear No.plate lamp RH <i>Sn</i>	1	\$38.50		X
7	Rear bumper <i>By</i>	1	\$1,150.60		✓
8	Rear bumper clip <i>Me</i>	10	\$35.00		✓
9	Rear bumper side retainer LH <i>Sn</i>	1	\$26.50		X
10	Rear bumper side retainer RH <i>Sn</i>	1	\$26.50		X
11	Rear bumper bracket LH <i>By</i>	1	\$48.70		X
12	Rear bumper bracket RH <i>By</i>	1	\$48.70		X
13	Rear bumper sponge	2	\$179.00		7
14	Rear bumper reflector LH <i>Sn</i>	1	\$45.00		X
15	Rear bumper reflector RH <i>Sn</i>	1	\$45.00		X
16	Rear bumper reflector garnish LH <i>Sn</i>	1	\$45.00		X
17	Rear bumper reflector garnish RH <i>Sn</i>	1	\$45.00		X
18	Tail door <i>By</i>	1	\$1,193.00		✓
19	Tail door lock <i>Red</i>	1	\$157.10		✓
20	Tail door emblem <i>Me</i>	1	\$38.00		✓
21	Wording "SHUTTLE" <i>Me</i>	1	\$55.00		✓
22	Wording "HYBRID" <i>Me</i>	1	\$80.10		✓
23	Tail door chrome <i>CM</i>	1	\$383.10		✓

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts

Vehicle No. :	SLX 7346 M	Submit By :	SERENCE
Make & Model :	HONDA SHUTTLE	Year Manufacture :	2016
Chassis No. :	GP71104081	Engine No. :	0

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	Tail door trim	1	\$320.00		?
25	Tail door trim clip	10	\$35.00		?
26	Taildoor reflector LH	1	\$395.00		?
27	Taildoor reflector RH	1	\$395.00		?
28	Tail end panel	1	\$560.80		?
29	Tail end panel garnish	1	\$155.50		?
30	Tail end panel garnish clip	10	\$35.00		?
31	Boot weatherstrip	1	\$168.50		X
32	Tail lamp LH	1	\$520.50		X
33	Tail lamp RH	1	\$520.50		X
34	Spare tyre well panel	1	\$956.00		X
35	Spare tyre board	1	\$655.00		X
36					
37					
38					
39					
40					
41					
42					
43					
44					
45					
46					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.





## ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

### Labour

Vehicle No. : **SLX 7346 M** Submit By : **SERENCE**  
Make & Model : **TOYOTA PRIUS** Year of Manufacture : **2017**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER, END PANEL, TAILDOOR, SPARE TYRE COMPARTMENT)	\$1,000.00	400-600
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER, END PANEL, TAILDOOR, SPARE TYRE COMPARTMENT)	\$1,000.00	800
3	To tuff coat.	\$100.00	?
4	TO Check wiring	\$50.00	20
5	To transfer boot mechanism to new boot	\$120.00	60
6	To conduct water leakage tests to ensure proper air and sealing	\$120.00	20
7	To remove & refit reverse sensor	\$150.00	50
8	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load.	\$150.00	?

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.