

KK



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLX 7346 M

Finalized

Parts (a) Cost / List Price Items	\$ 3711.90	8,515.10
Plus/Less 20%	\$ 642.38	1,703.02
Total of Cost / List	\$ 2569.52	6,812.08
(b) Nett Price Items		
Less		
Total of Nett Item		
(c) Special Nett Items	\$ 285	295.00
Total Parts Cost	\$ 2854.52	7,107.08
Labour	\$ 1240	2,690.00
Total	\$ 4094.52	9,797.08

Not to be used
Murray B. G. paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No legal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth
Company : LKK
Survey conducted on : 10/10/19 at 14:00

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 4-5 day(s)

(c) Resurvey : Required / ~~Not Required~~

(d) Excess : \$

(e) Signature of surveyor : Pe Date: 10/10/19



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemparf.com.sg

Spare Parts

Vehicle No. : **SLX 7346 M**
Make & Model : **HONDA SHUTTLE**
Chassis No : **GP71104081**

Submit By : **SERENCE**
Year Manufacture : **2016**
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Rear windscreen moulding	1	\$120.00	✓	✓
2	Rear windscreen sealant	1	\$50.00	S.N	405m
3	Reverse sensor	2	\$200.00	✓ S.N	✓
4	Rear number plate	1	\$45.00	✓ S.N	✓
5	Rear No.plate lamp LH	1	\$38.50		X
6	Rear No.plate lamp RH	1	\$38.50		X
7	Rear bumper	1	\$1,150.60	✓	✓
8	Rear bumper clip	10	\$35.00	✓	✓
9	Rear bumper side retainer LH	1	\$26.50		X
10	Rear bumper side retainer RH	1	\$26.50		X
11	Rear bumper bracket LH	1	\$48.70		X
12	Rear bumper bracket RH	1	\$48.70		X
13	Rear bumper sponge	2	\$179.00		X
14	Rear bumper reflector LH	1	\$45.00		X
15	Rear bumper reflector RH	1	\$45.00		X
16	Rear bumper reflector garnish LH	1	\$45.00		X
17	Rear bumper reflector garnish RH	1	\$45.00		X
18	Tail door	1	\$1,193.00	✓	✓
19	Tail door lock	1	\$157.10	✓	✓
20	Tail door emblem	1	\$38.00	✓	✓
21	Wording "SHUTTLE"	1	\$55.00	✓	✓
22	Wording "HYBRID"	1	\$80.10	✓	✓
23	Tail door chrome	1	\$383.10	✓	✓

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

3211.90

SN: 785

Spare Parts

Vehicle No. : **SLX 7346 M**
 Make & Model : **HONDA SHUTTLE**
 Chassis No. : **GP71104081**

Submit By : **SERENCE**
 Year Manufacture : **2016**
 Engine No. : **0**

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	Tail door trim <i>SL</i>	1	\$320.00		<i>7</i>
25	Tail door trim clip <i>nn</i>	10	\$35.00		<i>7</i>
26	Taildoor reflector LH <i>SL</i>	1	\$395.00		<i>7</i>
27	Taildoor reflector RH <i>SL</i>	1	\$395.00		<i>7</i>
28	Tail end panel <i>R</i>	1	\$560.80		<i>7</i>
29	Tail end panel garnish <i>SL</i>	1	\$155.50		<i>7</i>
30	Tail end panel garnish clip <i>nn</i>	10	\$35.00		<i>7</i>
31	Boot weatherstrip <i>SL</i>	1	\$168.50		<i>X</i>
32	Tail lamp LH <i>SL</i>	1	\$520.50		<i>X</i>
33	Tail lamp RH <i>SL</i>	1	\$520.50		<i>X</i>
34	Spare tyre well panel <i>R</i>	1	\$956.00		<i>X</i>
35	Spare tyre board <i>SL</i>	1	\$655.00		<i>X</i>
36					
37					
38					
39					
40					
41					
42					
43					
44					
45					
46					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : **SLX 7346 M** Submit By : **SERENCE**
Make & Model : **TOYOTA PRIUS** Year of Manufacture : **2017**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER, END PANEL, TAILDOOR, SPARE TYRE COMPARTMENT)	\$1,000.00	400-600
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER, END PANEL, TAILDOOR, SPARE TYRE COMPARTMENT)	\$1,000.00	880
3	To tuff coat.	\$100.00	30/40
4	TO Check wiring	\$50.00	20
5	To transfer boot mechanism to new boot	\$120.00	60
6	To conduct water leakage tests to ensure proper air and sealing	\$120.00	20
7	To remove & refit reverse sensor	\$150.00	50
8	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load.	\$150.00	X

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

1740