

ESTIMATE

DATE OF ACCIDENT : 06/10/2019
VEHICLE : SLN3069S
MAKE & MODEL : HONDA VEZEL
INSURANCE : MSIG INSURANCE
SURVEYOR : MSIG INSURANCE

Cost price.

	PARTS	CONDITION	AMOUNT
1.	FRONT BONNET <i>X Repair.</i>		\$ 890
2.	FRONT BONNET HINGE - LEFT <i>X Repair.</i>		\$ 55
3.	FRONT BUMPER <i>/ Re.</i>		\$ 420
4.	FRONT BUMPER GARNISH <i>?</i>		\$ 260
5.	FRONT BUMPER LOWER GRILLE <i>X NA</i>		\$ 180
6.	FRONT BUMPER LOWER LIPS <i>/ Re.</i>		\$ 110
7.	FRONT BUMPER CENTRE BRACKET <i>?</i>		\$ 95
8.	FRONT BUMPER GRILLE <i>X ?</i>		\$ 310
9.	FRONT BUMPER BRACKET - LEFT <i>?</i>		\$ 55
10.	FRONT BUMPER TOP COVER <i>?</i>		\$ 180
11.	HEADLAMP - LEFT <i>/ CRP</i>		\$ 1950
12.	HEADLAMP UPPER BRACKET - LEFT <i>?</i>		\$ 95
13.	HEADLAMP LOWER BRACKET - LEFT <i>?</i>		\$ 95
14.	FOG LAMP COVER - LEFT <i>/ Re.</i>		\$ 75



JACK CARS

15.	FENDER - LEFT X repair		\$ 430
16.	WHEELARCH - LEFT / ll.		\$ 95
17.	FRONT SUPPORT BEAM ?		\$ 680
		20	
	SPECIAL NETT 20%		
1.	CLIPS / ll.		\$ 100
2.	NUMBER PLATE COVER X NN		\$ 35
	LABOUR		
1.	TO PUTTY & SPRAY PAINT OF AFFECTED AREA	600	\$ 1200
2.	TO PANEL BEAT & RENEWAL OF ALL NECESSARY DAMAGED BODY PARTS	400	\$ 2000
3.	TO CHECK LIGHTING SYSTEM , WIRING & REWIRE	20	\$ 150
4.	PROGRAMMING OF HEADLAMP	X	\$ 300
5.	ANTI RUST TREATMENT	60	\$ 120
		PARTS + 10% :	\$ 6,572.50
		SPECIAL NETT :	\$ 135
		LABOUR :	\$ 3,770
		TOTAL :	\$ 10,477.50
		7% GST :	\$ 733.42
		GRAND TOTAL :	\$ 11,210.92

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

4 Days.
 P/P ~~imp~~ repair.
 before/After repair photos.
 Gino Riano - 82880282
 11/10/19.

Excess \$ 500
 Not Authorised.