



CHENG TAI LING
NO. 370E #14-02
ALEXANDRA ROAD
SINGAPORE 159958

File No :
Date : 09-October-2019

Estimated cost of repair for vehicle no: SKR1992E MERCEDES C180
Accident involving vehicle no: SKR1992E & GBD201S on 01-October-2019

Description	Quantity		List Price
LH rear door	1	\$	1,100.00
LH rear door outer handle	1	\$	390.00
LH rear door inner lock	1	\$	240.00
LH rear fender	1	\$	1,250.00
Rear bumper	1	\$	980.00
LH rear wheel rim	1	\$	580.00
LH rear knuckle arm (to check)	1	\$	850.00
LH rear knuckle arm bearing (to check)	1	\$	190.00
		\$	5,580.00
	Add 15%	\$	837.00
		\$	6,417.00
To supply rear silicon gum	1	SN \$	80.00
To supply rear rubber seal	1	SN \$	28.00
To remove and reinstall rear windscreen and conduct water leak test.	1	\$	120.00
To spray paint rear RH fender, rear bumper, RH rear door and accident repair areas.	1	\$	800.00
To remove damaged parts, to jack out LH rear door , LH rear fender, rear bumper , to reinstall RH rear door quarter glass , ECU diagnostic, and adjust body alignment	1	\$	850.00
To perform computerised wheel alignment	1	\$	80.00
		\$	8,375.00

T/Party: LONPAC INSURANCE BHD