



CARZ AUTO SERVICES PTE LTD

UEN/ GST 201409457D

61 WOODLANDS IND PARK E9 (E9 PREMIUM) #04-04 Singapore 757047

Email: alex@carzauto.com.sg

Tel: 65 6493 1924

Fax: 65 6493 1928

Insurance Company: INDIA INTERNATIONAL INSURANCE SINGAPORE

Address: 64 Cecil Street #04, #05 IOB Building Singapore 049711

Telephone: 6347 6100

Fax: 6224 4174

Email:

Make/ Model : NISSAN URVAN

Date: 10/9/2019

Chassis No : JN1MG4E25Z0793972

Vehicle No: GBB 9476 S

Date/Time of Accident 10/6/19 20:20

Materials Cost/ Spare Parts Cost

TO BE COMPLETED BY SERVICE ADVISOR

ITEMS	PARTS DESCRIPTION	QTY	LIST PRICE \$	PARTS DISCOUNT	FINAL PRICE \$
1	FRONT BUMPER / <i>BR</i>	1	\$ 629.10	10%	\$ 566.19
2	FRONT BUMPER SIDE RETAINER / <i>BR</i>	2	\$ 245.00	10%	\$ 220.50
3	FRONT BUMPER REINFORCEMENT ?	1	\$ 228.70	10%	\$ 205.83
4	FRONT BUMPER FOG LAMP LH ?	1	\$ 321.60	10%	\$ 289.44
5	FRONT BUMPER FOG LAMP COVER LH / <i>CNT</i>	1	\$ 120.70	10%	\$ 108.63
6	FRONT RADIATOR GRILLE / <i>BR</i>	1	\$ 492.20	10%	\$ 442.98
7	FRONT RADIATOR GRILLE LOGO / <i>MC</i>	1	\$ 87.90	10%	\$ 79.11
8	FRONT HEAD LAMP LH / <i>BR</i>	1	\$ 561.20	10%	\$ 505.08
9	FRONT HEAD LAMP PANEL LH ?	1	\$ 387.80	10%	\$ 349.02
10	FRONT CORNER PANEL LH / <i>DD</i>	1	\$ 588.00	10%	\$ 529.20
11	FRONT SIDE LAMP LH / <i>BR</i>	1	\$ 219.00	10%	\$ 197.10
12	FRONT WINDSCREEN GLASS / <i>BR</i>	1	\$ 1,086.30	10%	\$ 977.67
13	FRONT WINDSCREEN GLASS MOULDING / <i>MC</i>	1	\$ 110.60	10%	\$ 99.54
14	FRONT DOOR LH / <i>DD</i>	1	\$ 1,296.30	10%	\$ 1,166.67
15	FRONT DOOR HINGE LH / <i>BT</i>	2	\$ 129.60	10%	\$ 116.64
16	FRONT DOOR CHECK PIN LH X	1	\$ 60.00	10%	\$ 54.00
17	FRONT DOOR OUTER MOULDING LH X	1	\$ 173.60	10%	\$ 156.24
18	FRONT DOOR INNER LOCK / <i>BT</i>	2	\$ 344.60	10%	\$ 310.14
19	FRONT DOOR TRIM BOARD / <i>CRV</i>	2	\$ 1,435.80	10%	\$ 1,292.22
20	FRONT DOOR GLASS RUN CHANNEL LH X	1	\$ 113.90	10%	\$ 102.51
21	FRONT DOOR PILLAR LH ?	1	\$ 1,271.80	10%	\$ 1,144.62
22	FRONT DOOR LOWER SEAL LH ?	1	\$ 36.00	10%	\$ 32.40
23	FRONT DOOR WEATHERSTRIP LH ?	1	\$ 141.50	10%	\$ 127.35
24	FRONT DOOR PILLAR WEATHERSTRIP LH / <i>TN</i>	1	\$ 107.70	10%	\$ 96.93
25	FRONT STEP PANEL LH / <i>DD</i>	1	\$ 129.30	10%	\$ 116.37
26	FRONT STEP PANEL GARNISH LH / <i>MIS</i>	1	\$ 329.30	10%	\$ 296.37
27	FRONT WASHER TANK LH ?	1	\$ 279.90	10%	\$ 251.91
28	FRONT A/C COOLING COIL ASSY ?	1	\$ 1,376.10	10%	\$ 1,238.49
29	FRONT A/C BLOWER MOTOR ASSY ?	1	\$ 2,216.20	10%	\$ 1,994.58
30	FRONT DASHBOARD ?	1	\$ 1,562.00	10%	\$ 1,405.80
31	FRONT DASHBOARD CONSOLE BOX COVER LH ?	1	\$ 282.30	10%	\$ 254.07
32	FRONT TURBO CHARGER X	1	\$ 3,382.00	10%	\$ 3,043.80
33	FRONT TURBO CHARGER HOSE ?	1	\$ 258.60	10%	\$ 232.74
34	FRONT TURBO CHARGE PIPE ?	1	\$ 863.40	10%	\$ 777.06

