

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : SXXX6574Z

MANAMOHAN S/O SIVASAMY
BLK 33 SIMEI STREET 4
05-21
SINGAPORE 529878
TEL : FAX :
PH : 98166704
ATTN :

ESTIMATE BILL

Number : EB00005296
Date : 11/10/2019
Case No : AD00010723
Vehicle No : SKD5702Z
Chassis : WBAFP32040C867224
Year of Mfr : 2011
Policy No :
Model : BMW 523I

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	REAR BUMPER	1.0	1,396.60	0	1,396.60
2	REAR BUMPER RETAINER RH	1.0	137.75	0	137.75
3	REAR BUMPER RETAINER LH	1.0	137.75	0	137.75
4	REAR BUMPER REINFORCEMENT	1.0	772.05	0	772.05
5	REAR BUMPER BRACKET RH	1.0	137.75	0	137.75
6	REAR BUMPER BRACKET LH	1.0	137.75	0	137.75
7	REAR BUMPER TOWING COVER	1.0	47.60	0	47.60
8	REVERSE SENSOR	4.0	236.85	0	947.40
9	REAR BUMPER LOWER CENTER GARNISH	1.0	58.25	0	58.25
10	REAR BUMPER REFLECTOR RH	1.0	38.50	0	38.50
11	REAR BUMPER REFLECTOR LH	1.0	38.50	0	38.50
List Price - Parts Sub Total					3,849.90
12	END PANEL - REPAIR	1.0			
13	BOOTLID - REPAIR	1.0			
Special Nett Price - Parts Sub Total					0.00
Parts Total					3,849.90
14	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	800.00	0	800.00
15	SPRAY PAINT ON THE AFFECTED AREAS	1.0	800.00	0	800.00
16	ANTI-RUST COATING	1.0	250.00	0	250.00
17	TO REMOVE & REFIT REVERSE SENSOR	1.0	150.00	0	150.00
Labour 1 Sub Total					2,000.00
SINGAPORE DOLLARS : SIX THOUSAND TWO HUNDRED FIFTY-NINE AND CENTS THIRTY-NINE ONLY					
Less Excess					0.00
SUBTOTAL					5,849.90
GST 7.00%					409.49
TOTAL					6,259.39

Date of accident : 09/10/2019 07:30 AM Place: AIRPORT ROAD

E. & O. E.

CUSTOMER SIGNATURE

Acknowledged by Repairer

Signature:

Date:

HOCK WAH MOTOR WORKSHOP PTE LTD

AUTHORISED SIGNATURE

* N = Item not subjected to GST