

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 15335

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1218/2019/NS
Date : 09-Oct-19

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mdm Goh Bee Kheng
Address : 993 Bukit Timah Road
#10-08
Singapore 589631
Telephone : HP +65 96775514
Type of Claim : Own Damage Claims
Policy No. : 2100237329-08
Vehicle No : **SJZ 3783 Z**
Model Code : A3 CAB 1.8 TFSI
Model / Year : 19-11-10
Engine No : cda 157279
Chassis No : truzzz8p5b1003420
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 08-Oct-19
Place of Accident : Steven Road Towards Scott

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SJZ 3783 Z

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 ✓	
2	To remove and renew aircond condenser, radiator and additional radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$ 1,200.00 ? X 111	
3	To dismantle and renew front bumper, rhs front fender, bonnet and rhs headlight. Renew front lock carrier and align to position. Re-organise crash management components reinstall all parts removed.	\$ 5,250.00 1500 1750	
4	To respray front bumper, bonnet, rhs front fender and hinges.	\$ 3,200.00 1650 1650	
5	To renew rhs front rim and carry out wheel alignment	S/N \$ 280.00 X 111	
6	To carry out diagnostic check.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: <u>\$ 10,482.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJZ 3783 Z

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER <i>de</i>	\$ 1,236.00	988.80 -
2	FRONT BUMPER FIXING PARTS <i>? xsv</i>	\$ 164.00	X
3	FRONT BUMPER CARRIER <i>? xsv</i>	\$ 611.00	X
4	FRONT SHOCK ABSORBER- RH <i>? xsv</i>	\$ 200.00	X
5	FRONT BUMPER GUIDE SECTION- RH <i>? cm</i>	\$ 35.00	88 ✓ 27.52 -
6	FRONT BUMPER AIR GUIDE GRILLE - RH <i>MU</i>	\$ 233.00	✓ 186.40 -
7	FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE <i>? xsv</i>	\$ 177.00	X
8	FRONT BUMPER FOAM FILLER PIECE <i>? wt</i>	\$ 118.00	✓ 94 -
9	SPRING SHACKLE <i>? xsv</i>	\$ 47.00	X
10	SIGNAL HORN - LOW TONE / HIGH TONE <i>SCA</i>	2 \$ 412.00	✓ 329.60 -
11	FRONT FENDER - RH <i>bt</i>	\$ 692.00	✓ 553.60 -
12	FRONT FENDER ATTACHMENT PARTS <i>? xsv</i>	\$ 44.00	X
13	FRONT FENDER - FRONT / REAR / CENTRE <i>? bt</i>	3 \$ 135.00	✓ 106.80 -
14	FRONT FENDER BRACE - RH <i>? bt</i>	\$ 49.00	✓ 39.12 -
15	WHEEL HOUSING LINER - RH <i>cm</i>	\$ 158.00	✓ 126.00 -
16	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS <i>? xsv</i>	\$ 66.00	X
17	FRONT WHEEL HOUSING LINER - RH <i>? de</i>	\$ 121.00	✓ 96.80 -
18	WHEEL HOUSING LINER SPOILER - RH <i>? xsv</i>	\$ 51.00	X
19	BONNET <i>bt</i>	\$ 2,189.00	✓ 1751.20 -
20	BONNET ATTACHMENT PARTS <i>? xsv</i>	\$ 88.00	X
SUB-TOTAL SPARE PARTS CHARGES		\$ 6,826.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJZ 3783 Z

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
21	BONNET LID HINGE - LH / RH <i>X</i>	2 \$	106.00
22	BONNET GAS FILLED STRUT <i>X</i>	\$	109.00
23	BONNET CATCH HOOK <i>X</i>	\$	85.00
24	GAS FILLED STRUT BRACKET - RH <i>X</i>	\$	38.00
25	BONNET LID LOCK <i>X</i>	\$	196.00
26	MICRO SWITCH <i>X</i>	\$	99.00
27	BONNET LOCK COVER - UPPER FRONT <i>X</i>	\$	46.00
28	HEADLIGHT MOUNTING - RH <i>? cr</i>	\$	107.00 <i>✓ 85.60 -</i>
29	HALOGEN TWIN HEADLIGHTS - RH <i>cr</i>	\$	1,859.00 <i>✓ 1487.20 -</i>
30	GAS DISCHARGE LAMP CONTROL UNIT <i>? cr</i>	\$	1,051.00 <i>✓ 840.80 -</i>
31	GAS DISCHARGE LAMP <i>? cr</i>	\$	398.00 <i>✓ 318.40 -</i>
32	COMPENSATION PIECE <i>? X su</i>	2 \$	80.00 <i>X</i>
33	HEADLAMP HOUSING REPAIRING KIT - RH <i>? X su</i>	\$	65.00 <i>X</i>
34	LIFT CYLINDER - RH <i>? cr</i>	\$	192.00 <i>✓ 153.20 -</i>
35	HEADLIGHT HOSE <i>? X su</i>	5 \$	179.00 <i>X</i>
36	HEADLIGHT ELBOW FITTING <i>? X su</i>	3 \$	81.00 <i>X</i>
37	HEADLIGHT SPRING CLIP <i>? X su</i>	\$	12.00 <i>X</i>
38	HALOGEN FOG LAMP - RH <i>cr</i>	2 \$	237.00 <i>✓ 189.60 -</i>
39	LOCK CARRIER <i>? X su</i>	\$	898.00 <i>X</i>
40	READY MIX COOLANT <i>? X su</i>	4 \$	84.00 <i>X</i>
41	RADIATOR AIR GUIDE - RH <i>? X su</i>	\$	35.00 <i>X</i>
42	FRONT ALUMINIUM RIM - RH <i>X su</i>	\$	1,128.00 <i>X</i>
43	ALUMINIUM RIM RUBBER VALVE <i>X su</i>	4 \$	13.00 <i>X</i>
44	SUNDRIES <i>? cr</i>	\$	400.00 <i>✓ 51.04 -</i>
TOTAL SPARE PARTS CHARGES		\$	14,324.00
TOTAL LABOUR CHARGES		\$	10,482.00
GRAND TOTAL		\$	24,806.00

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax



Name : *RASUL - HP 90010068*
Surveyed Date : *10/10/19 @ 0950*
Authorised Date :
Excess Cost : *7 days*
Liability : *EXCESS: TBA*
Remarks : *REVERT*
Resurvey before paint

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be rectified and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/1218/2019/NS 23-Oct-19 Glory Tan 1 of 1 SJZ 3783 Z A3 CAB 1.8 TFSI
Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	Water reservoir <i>de</i>	\$ 155.00	\$ 124.00
2	Water reservoir end cap <i>X inconsistent not given</i>	\$ 19.00	\$ 15.60
3	Windscreen washer system pump <i>ru</i>	\$ 118.00	\$ 94.00
4	Water level switch <i>ca</i>	\$ 43.00	\$ 34.16
5	Radiator grille <i>sub</i>	\$ 1,359.00	\$ 1,087.20
6	Flat contact housing wuth contact <i>ca</i> locking mechanism	\$ 29.00	\$ 22.72
7	No Plate <i>new</i>	\$ 40.00	\$ 40.00
TOTAL		\$ 1,723.00	\$ 1,417.68

MIS

For Premium Automobiles Pte Ltd

Authorised Signature

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: