

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 15 Oct 2019

Preliminary Advice

Vehicle No	: SJZ3783Z	Accident Date	: 08/10/2019
Make	: AUDI A3	Policy No.	: 2100237329-08
Assignment Date	: 11/10/2019	Excess	: S\$0.00
Date of Inspection	: 10/10/2019	Est. Duration of Repair	: 7 days
Inspection At	: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	24,806.00
Revised Amount	:S\$	10,718.00
Check Items (Estimated)	:S\$	6,638.00
Total	:S\$	17,356.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	40,000.00
COE / PARF Rebate	:S\$	28,278.00
Salvage Value	:S\$	
Margin for Repair	:S\$	11,722.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Repairer able to undertake the repair cost not exceeding \$ 11,000.00. Margin for repair is \$ 11,722.00.