

FASTECT AUTO PTE LTD
BLK1 KAKI BUKIT AVE 6
#01-46,48,50 AUTOBAY
SINGAPORE 417883

VEHICLE NO: SLD 81683

QTY	PARTICULAR	
1 PCS	BOOTLID	1562.00
1 PCS	BOOTLID REAR LOGO	75.00
1 PCS	BOOTLID '528' EMBLEM	
1 PCS	BOOTLID INNER LOCK	299.08
2 PCS	BOOTLID REFLECTORS @ \$685.00	
1 PCS	BOOTLID WEATHERSTRIP	293.66
1 PCS	BOOTLID INNER TRIM	
1 SET	BOOTLID INNER TRIM CLIPS	
2 PCS	TAILLAMPS @ \$750.00	590.00
1 PCS	REAR BUMPER (M)	1615.00
1 PCS	REAR BUMPER LOWER SPOILER	
1 PCS	REAR BUMPER TOW COVER	
4 PCS	REAR BUMPER PDC SENSORS @ \$313.0	215 x 2 = 430
1 PCS	REAR BUMPER PDC SENSOR WINE	
1 PCS	REAR BUMPER REINFORCEMENT	640.93
2 PCS	REAR BUMPER REINFORCEMENT STAY BRACKETS @ \$140.00	
1 PCS	REAR BUMPER LOWER GUIDE	
2 PCS	REAR BUMPER SIDE RETAINERS @ \$195.00	
1 SET	REAR BUMPER CLIPS	
2 PCS	REAR BUMPER REFLECTORS @ \$115.00	
1 PCS	REAR BUMPER INNER PAD	
1 PCS	REAR BUMPER INNER FRAME GARNISH	266.00
1 PCS	REAR END PANEL	
1 PCS	REAR END PANEL TOP GARNISH	
1 PCS	REAR EXHAUST	
1 PCS	REAR EXHAUST HEAT SHIELD	
2 PCS	REAR EXHAUST MOUNTING @ \$60.00	
1 PCS	REAR FLOOR PANEL	
1 PCS	REAR FLOOR PANEL TOP BOARD	
2 PCS	REAR FENDER INNER TRIMS @ \$397.00	

S.NETT

1 PCS	REAR END PANEL SEALANT
1 PCS	REAR EXHAUST CHROME
1 PCS	REAR LICENCE PLATE WHOLDER

LABOUR CHARGES:

TO CHECK WIRING	
TO DISMANTLE & REPLACING REVERSE SENSOR	
TO TRANSFER BOOTLID MECHANISM	
TO DISMANTLE & REFIX REAR EXHAUST	
TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTERY	
TO SPRAY RUST PROOFING	
LABOUR FOR PANEL BEATING & REPLACING PARTS	
TO PUTTY & SPRAY PAINTING	

Bar/merged	\$1,866.10	✓
nu	\$85.00	✓
NT	\$57.00	X
Shuttl/Twi	\$315.00	✓
11	\$1,370.00	X
11	\$366.00	✓
11	\$365.00	X
11	\$50.00	X
0/Score	\$1,500.00	12c
11/12	\$1,658.00	
de/merged	\$423.65	✓
11	\$36.00	X
Shuttl	\$1,252.00	2pc
11	\$386.00	X
311	\$685.00	✓
11	\$280.00	X
NT	\$185.00	X
11	\$390.00	X
nu	\$60.00	✓
11	\$230.00	X
NT	\$268.00	X
11	\$335.00	✓
311	\$1,018.50	✓
11	\$388.00	✓
11	\$1,980.00	X
11	\$245.00	X
11	\$120.00	X
11	\$1,495.00	X
11	\$485.00	X
11	\$794.00	X
	\$18,688.25	

nu	\$50.00	✓
11	\$200.00	X
11	\$50.00	X

	\$80.00	30
	\$80.00	50
	\$80.00	60
11	\$150.00	X
	\$120.00	80
	\$100.00	60
	\$1,080.00	800

LKK Auto Consultants hence notify the Repairer of the following:

to be done by before/after spray painting

to be done by damaged part(s) during resurvey

to be done by subject to confirmation

to be done by is on a "Without Prejudice" basis

to be done by is allowed

to be done by Supplementary item(s) must be resurveyed and

to be done by is subject to final approval from Insurance Company

Acknowledged by Repairer

Signed by:

22178.25

266.82

684.83

9074.63

7120.