

ASS. REC. BY:

REF: CS/CTI/19017955/Rlyd362

Special Instruction:

Summary: Rasu

ASSIGNMENT (Office)

From (Person):

Elaine Cheong

of

CTI

Date/Time:

10/10/2019 @ 4:50pm

Estimated Cost:

Bill to:

①

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMH 3997H

Insured:

at Workshop m/s

Borneo Motor

Tel:

66311857.

of

2 parden Crescent

Policy No:

60014287

Claim No:

SNM19D204699C01

Sum Insured:

Excess:

\$1,000.00

Make of Veh:

(Client's Record)

D.O.A

7/10/2019

CA / REV /

REP. / REV 24 HRS

14/10/2019

H.O.D. Endorsement

Date/Time:

10:04am 11/10/2019

Person Contacted:

Wally

Vehicle IN/OUT

Date/Time

Action/Instruction

Schedule ✓

SMH 3997H: CS/CTI/19017955/Ktd3 DOA: 7/10/2019

14/10/19

Revert via merimen

15/10/19

Rece approved from Alfred by merimen

15/10/19

Informed Wally c/A ex \$1000 by email

Photo 0.12

ASS. REC. BY: Paxu

REF: C11 CS / C11 1907955 / R11 d 3

172H

ASSIGNMENT

From: _____ Date: 14.10.2019
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SMH 3997H
 at Workshop m/s: Borneo Motor
 of 2 Pandan Crescent
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: \$1000.00
 (Client's Record)
 Make of Veh: 10.00am Owner waiting

Veh No: SMH 3997H Yr Regn: 2019 / JAN
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: TOYOTA LEXUS ES 300H c.c. 2487
 Colour: Gold A/C: Insured / Std / NI / NA
 Sp. Reading: 14237 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JTH B21B180 2019526
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 235/45R18
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____

Front	Rear
R/Bal. <u>6</u> mm	R/Bal. <u>6</u> mm
L/Bal. <u>6</u> mm	L/Bal. <u>6</u> mm
D.O.A. <u>07/10/19</u>	D.O.I. <u>14/10/19</u>
Survey held at <u>Borneo Motor</u>	
Des. of Damages: <u>Fit</u> Rear / O/S / N/S / U/C / Rooftop or +.	

The U/C / Chassis frame / Body Structure affected due to collision.

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

 Bal. or Market Value: 195K
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV REP. / 24 HRS amp
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Date / Time	Action / Instruction
15/11/19	P/P \$14,318-10 @ 6 days (Red \$14,623-90, 50%)

RECEIVED 15 NOV 2019

Date/Time, File Pass to? ☐ : Prell. Report

1) ☐ : Final Report

Date/Time, File Return to?

2) 15/11/19 Typist

Rep. Format: _____

Lump Sum / LD: _____

P/P \$14,318-10

Days Of Repair: 6

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$ _____) ☐ : S + RS \$ _____
☐ : Interview (\$ _____) ☐ : Photos
☐ : Tech. Invs (\$ _____) ☐ : Others
☐ : Weekend (\$ _____)

Survey Fee: 220

Transportation: _____

TOTAL

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	09 Oct 2019		10 Oct 2019 16:50 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured: NG ENG TECK , ID: S0122172H, Tel: +6596511111, Email: NOEMAIL	
Vehicle Reg. No.: SMH3997H	Date of Loss: 07/10/2019 15:00 - :59
Claim Type: OD / SNM19D204699C01	Policy/Cover Note No.: 60014287 (Comprehensive)
	Excess: S\$1,000.00
Repairer: Borneo Motors (S) Pte Ltd (Pandan) 2 Pandan Crescent, 128462 West Coast - Tel: 66311857	
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]	
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 21/10/2019]	
Driver/Custodian: NG ENG TECK (66 / Male) , NRIC: S0122172H, Tel: +6596511111 Email: NOEMAIL	

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Tuesday, 15 October 2019 10:47 AM
To: SUR; 'Wally Tan TCBC'
Subject: SMH 3997H-DOA: 7/10/2019 (CHINA TAIPING OD)

Dear Wally,

As instructed by our client , please proceed to repair the insured vehicle **SMH 3997H** ,**According to surveyor's marking or whichever lower, (Excess \$1000/-).**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler on behalf of Yvonne

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

***SMH3997H (SNM19D204699C01)**

OD

Oct 7 2019 3:00PM

[NG ENG TECK]

Borneo Motors (S) Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA_TAIPING), sent on **15/10/2019 10:13 AM.**

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$27675.00) - SMH3997H - Claim Handler: Elaine Cheong

Approved:27675.00:Please proceed to authorize repairs UP TO \$27,675.00 BEFORE Excess of \$1,000.00

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:	China Taiping Insurance (Singapore) Pte. Ltd. 3 Anson Road #16-00 Springleaf Tower Singapore 079909	From:	LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
-----	--	-------	---

Attn:	Elaine Cheong	Date:	14 Oct 2019
-------	---------------	-------	-------------

Preliminary Advice

Vehicle No	: SMH3997H	Accident Date	: 07/10/2019
Make	: LEXUS ES300	Policy No.	: 60014287
Assignment Date	: 10/10/2019	Excess	: S\$1,000.00
Date of Inspection	: 14/10/2019	Est. Duration of Repair	: 6
Inspection At	: BORNEO MOTORS (SINGAPORE) PTE LTD		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	28,942.00
Revised Amount	:S\$	11,994.00
Check Items (Estimated)	:S\$	15,681.00
Total	:S\$	27,675.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	195,000.00
COE / PARF Rebate	:S\$	70,608.00
Salvage Value	:S\$	
Margin for Repair	:S\$	124,392.00

Remarks

(X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

() Other comments :

Nivitha (LKK Auto)

From: Elaine Cheong <elaine.cheong@sg.cntaiping.com>
Sent: Thursday, 10 October 2019 4:45 PM
To: 'wally.tan@borneomotors.com.sg'; assignments
Subject: FW: OUR REF: SNM19D204699C01-SMH3997H-CML- Own damage claim for SMH3997H
Attachments: 08102019165439-0001.pdf
Importance: High

Dear Wally,

We refer to your email of 09.10.19.

Please be informed that we have assigned M/s LKK Auto Consultants Pte Ltd.

Kindly liaise with them.

Aside to LKK,

Please assist to contact Mr Wally Tan on the arrangement of survey.

Thank you.

Regards,

Elaine Cheong
Executive (Motor Claims)
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower
Singapore 079909
Co. Reg. No. 200208384E
DID: 6389 6530
Fax: 6224 7478 / 6224 7175
Email:
Website: www.sg.cntaiping.com

-----Original Message-----

From: Lim Shu Min
Sent: Wednesday, 9 October, 2019 4:23 PM
To: Elaine Cheong <elaine.cheong@sg.cntaiping.com>
Subject: FW: OUR REF: SNM19D204699-SMH3997H-CML- Own damage claim for SMH3997H

Dear Elaine,

Please assist OD claim.

Note : officer in charge - Elaine Cheong 63896530.

Regards,

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
T: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

-----Original Message-----

From: Wally Tan PTCBC [mailto:wally.tan@borneomotors.com.sg]
Sent: Tuesday, 8 October, 2019 5:06 PM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Cc: Dion Wang <Dion.Wang@inchcape.com.sg>
Subject: RE: Own damage claim for SMH3997H

Dear Sir/Madam,

Reference to the above-mentioned.

Please find attached herein a copy of our client's Estimation and relevant documents for your kind perusal.

Your kind attention into the above is greatly appreciated.

Thank you and Best Regards

Wally Tan TCBC

This e-mail (and any attachment) is intended for the addressee(s) only and contains information that is legally privileged and confidential. If you are not the intended recipient, please be advised that you have received this e-mail in error and that any use, dissemination, distribution, printing or copying of this communication is unauthorized and strictly prohibited. Kindly notify us by replying to the sender's e-mail address and delete this e-mail immediately. E-mail transmissions cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, delayed or incomplete, or could contain viruses. We therefore do not accept liability for any errors or omissions in the contents of this e-mail which arise as a result of e-mail transmission, and you are advised to carry out your own virus checks and confirm the accuracy of the contents of this e-mail before relying on it for any purpose.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	172H
Vehicle Details	
Vehicle No.:	SMH3997H
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Oct 2019
Vehicle Make:	TOYOTA
Vehicle Model:	LEXUS ES300H 4DR SEDAN (AUTO) EXECUTIVE
Primary Colour:	Gold
Manufacturing Year:	2018
Engine No.:	A25A5098998
Chassis No.:	JTHB21B1802019526
Maximum Power Output:	160.0 kW (214 bhp)
Open Market Value:	\$45,594.00
Original Registration Date:	22 Jan 2019
First Registration Date:	22 Jan 2019
Transfer Count:	0
Actual ARF Paid:	\$55,832.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Jan 2029
PARF Rebate Amount:	\$41,874.00
Intended COE Rebate Details	
COE Expiry Date:	21 Jan 2029
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$31,809.00
COE Rebate Amount:	\$28,734.00
Total Rebate Amount:	\$70,608.00

The information contained herein is correct as at 14 Oct 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/10/2019 13:22
Date Of Accident	07/10/2019 15:05
Exact Location Of Accident	EN TONG SEN STREET TWDS OUTRAM ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMH3997H
Insured/Policyholder	
Name Of Registered Owner	NG ENG TECK
NRIC No	S0122172H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96511111
Alternative Phone No	OTHERS-96511111

Vehicle Particulars

Manufacturer	LEXUS
Model	ES300-3.0 (A)
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	60014287
Cover Note Number	

Driver

Name of Driver	NG ENG TECK
NRIC No	S0122172H
Date Of Birth	17/08/1953
Occupation	INDOOR
Date Of Driving Pass	03/05/1972
Driving Experience	47 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96511111
Fax Number	
Contact Number	OTHERS-96511111
Email Address	NOEMAIL

Address	370H ALEXANDRA ROAD #06-07
Postcode	159961
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO THE ATTACHED SKETCH PLAN & VIDEO FOOTAGE FOR THE CIRCUMSTANCE OF ACCIDENT.


Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLR8620X
Vehicle Make/Model/Colour	TOYOTA VIOS
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

The vehicle SLR 8620X brake and I couldn't stop in time and hit the rear portion of SLR 8620X.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

黃榮(古)

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver.**
3. Information provided must be as **truthful and accurate as possible.** Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability.**
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "**Purposes**")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



中国太平保险(新加坡)有限公司
CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

CERTIFICATE OF INSURANCE

Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189)
Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960
Road Transport Act, 1987 (Malaysia)
Motor Vehicles (Third-Party Risks) Rules, 1955 (Malaysia)

I/We hereby Certify

I/We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).
Please see reverse.

For CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.



Countersigned By

Authorized Signatory

3 Anson Road #16-00 Springleaf Tower Singapore 079908 Tel: 6389 6111 Fax: 6225 3592 Website: www.sg-entailing.com



TAX INVOICE

Borneo Motors (Singapore) Pte Ltd

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

www.lexus.com.sg

Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388

ESTIMATE

Account Detail	Account No	Customer Detail
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICCI1	Mr Ng Eng Teck 370H Alexandra Road #06-07 The Anchorage Singapore 159961
	Document No 0	Mobile: 96511111
	Document Date 08/10/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
18	AEXGB	S1	AXZH10R	22/01/2019	SMH3997H	0	17782 :40D/SMH3997H/07101!
Chassis No	Engine No	Terms	Lexus Consultant	Vehicle In	Collected On		
JTHB21B1802019526	A25A5098998	60	Wally Tan G H	08/10/2019	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES POLICY NO.:DMPCSN1903571900 ACC DATE:07.10.19 TOW/DRIVE IN: EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:		Rasul Hp 90010068 6 days 14/10/19 @ 1010		50 80.00
2	B	BP-LAB3 CHECK WIRING SYSTEM AND FOCUS HEADLAMP. (ETT)				216.50
3	B	BP-LAB3 REMOVE/REFIX FRONT PARKING SENSORS. (NETT)				216.50
4	B	BP-MECH3 REMOVE/REFIX AIR-CON CONDENSER, RECEIVER DRYER, GAS PIPES TO ENABLE REPAIRING AND FIT NEW PARTS. (NETT)		EXCESS: 1000 Xma?		866.00
5	B	BP-LAB3 REMOVE ALL NECESSARY PARTS, TO ENABLE REPAIRING AND STRAIGHTEN FRONT SUPPORT PANEL, R/H AND L/H HEADLAMP PANELS AND FIT NEW PARTS.		Repair before paint		2598 3464.00
6	B	BP-RES3 SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR.				2226 2597.00
Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.						
For & on behalf of Borneo Motors		Customer's Signature	Change Summary		Total	
		Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others		Less	
					Amount Due	

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

Third party survey is on a "Without Prejudice" basis

No illegal modification(s) is allowed

Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD Acknowledged by Repairer

Signature:

DATE 08/10/2019

PLEASE ALLOW THE UNDERMENTIONED

TIME 16:49

VEHICLE TO LEAVE THE COMPANY PREMISES.

VEHICLE NO

SMH3997H

CUSTOMER

SIGNATURE

FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

Inchcape



TAX INVOICE

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

www.lexus.com.sg

Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388

Account Detail	Account No	Customer Detail
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICCI1	Mr Ng Eng Teck 370H Alexandra Road #06-07 The Anchorage Singapore 159961 Mobile: 96511111
	Document No 0	
	Document Date 08/10/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
18	AEXGB	S1	AXZH10R	22/01/2019	SMH3997H	0	17782 40D/SMH3997H/07101
Chassis No	Engine No	Terms	Lexus Consultant	Vehicle In	Collected On		
JTHB21B1802019526	A25A5098998	60	Wally Tan G H	08/10/2019	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
7	Z	BP-SLANT SUPPLY SEALANT (NETT)				100.00
8	B	BP-ECU3 TO RESET ECU & REPROGRAMME. (NETT)				216.50
9	L	BP-LPO SUPPLY REGN PLATE (PO#)				96.00
		FRONT (NETT)				
10	1	L81145-33F21 UNIT, HEADLAMP	1.00	3702.20		3702.20
11	2	L81185-33F21 UNIT, HEADLAMP	1.00	3702.20		3702.20
12	3	L81136-33J00 RIM, HEADLAMP	1.00	17.50		17.50
13	4	L81176-33J00 RIM, HEADLAMP	1.00	17.50		17.50
14	5	L81137-33J00 RIM, HEADLAMP	1.00	46.50		46.50
15	6	L81177-33J00 RIM, HEADLAMP	1.00	28.80		28.80
16	7	L53301-33260 HOOD SUB-ASSY	1.00	2962.10		2962.10
17	8	T90467-09050 CLIP	9.00	2.90		26.10
18	9	T88723-33170 LABEL, COOLER	1.00	4.20		4.20
19	0	T11293-36070 LABEL, ENGINE	1.00	7.30		7.30
20	1	TG9275-12010 LABEL, BATTERY	1.00	9.20		9.20
21	2	L53101-33670 GRILLE SUB-ASSY	1.00	1660.70		1660.70
22	3	L53112-33390 GRILLE, RADIATOR	1.00	223.40		223.40
23	4	L53141-33180 GARNISH, RADIATOR	1.00	2100.70		2100.70
24	5	L88210-33120 SENSOR ASSY	1.00	2125.80		2125.80
25	6	L52115-33110 SUPPORT, FR BUMPER	1.00	43.00		43.00
Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.						

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 08/10/2019
TIME 16:49

VEHICLE NO SMH3997H

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

**TAX INVOICE****Borneo Motors (Singapore) Pte Ltd**Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

www.lexus.com.sg

Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388**ESTIMATE**

Account Detail	Account No	Customer Detail
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICCI1	Mr Ng Eng Teck 370H Alexandra Road #06-07 The Anchorage Singapore 159961
	Document No 0	Mobile: 96511111
	Document Date 08/10/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
18	AEXGB	S1	AXZH10R	22/01/2019	SMH3997H	0	17782 40D/SMH3997H/07101

Chassis No	Engine No	Terms	Lexus Consultant	Vehicle In	Collected On
JTHB21B1802019526	A25A5098998	60	Wally Tan G H	08/10/2019	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
26	7	L52116-33100 SUPPORT, FR BUMPER <i>new</i>	1.00	43.00		43.00
27	8	L52021-33240 REINFORCEMENT <i>? x 50c</i>	1.00	909.60	X	909.60
28	9	L52148-33040 BRACKET, FR BUMPER <i>? x 50c</i>	1.00	503.30	X	503.30
29	0	L52611-33330 ABSORBER, FR BUMPER <i>? x 50c</i>	1.00	112.40	X	112.40
30	1	L52620-50010 CHAMBER ASSY, <i>? x 50c</i>	1.00	790.30	X	790.30
31	2	L53114-33050 GRILLE, RADIATOR, <i>? x 50c</i>	1.00	199.30	X	199.30
32	3	L52521-33100 RETAINER, FR BUMPER, <i>new</i>	2.00	19.20		38.40
33	4	L52542-33010 SEAL, FR BUMPER, CTR <i>new</i>	1.00	92.50		92.50
34	5	L52119-3T943 COVER, FR BUMPER <i>new</i>	1.00	1046.20		1046.20
35	6	L52127-33905 COVER, FR BUMPER <i>? x 50c</i>	1.00	54.20	X	54.20
36	7	L52114-33520 BRACKET, FR BUMPER <i>new</i>	1.00	161.10		161.10
37	8	L52618-33090 ABSORBER, FR BUMPER, <i>? x 50c</i>	1.00	281.30	X	281.30
38	9	T53879-33030 RETAINER, FR FENDER <i>new</i>	6.00	12.20		73.20
39	0	T47749-33030 CLIP, PIN HOLD <i>new</i>	6.00	8.60		51.60
40	1	L89348-50130 RETAINER, ULTRASONIC <i>new</i>	2.00	19.20		38.40
41	2	T90467-07217 CLIP <i>new</i>	7.00	2.50		17.50

Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total	28,942.00
<i>Signature</i>	Please acknowledge receipt of vehicle	Parts 21,089.50	GST 7.00%	2,025.94
		Labour 7,756.50		
		Materials 96.00	Less	0.00
		Lubrication/Fluid 0.00		
		Others 0.00		
			Amount Due	30,967.94

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 08/10/2019
TIME 16:49

VEHICLE NO SMH3997H

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD**Borneo Motors**

Inchcape



Attn: Rasul
Final Bill

TAX INVOICE

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

www.lexus.com.sg

Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no. 6631 1388

Account Detail	Account No	Customer Detail
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICCI1	Mr Ng Eng Teck 370H Alexandra Road #06-07 The Anchorage Singapore 159961 Mobile: 96511111
	Document No 0	
	Document Date 12/11/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
18	AEXGB	S1	AXZH10R	22/01/2019	SMH3997H	14415	17782 40D/SMH3997H/07101:
Chassis No	Engine No	Terms	Lexus Consultant	Vehicle In	Collected On		
JTHB21B1802019526	A25A5098998	60	Wally Tan G H	08/10/2019	0.00	12/11/2019	18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES POLICY NO.:DMPCSN1903571900 ACC DATE:07.10.19 TOW/DRIVE IN: EXCESS:\$1000/- DATE-IN:16.10.19 DATE SURVEY:14.10.19 NO OF REPAIR DAYS: BY:RASUL (LKK) AUTHORIZED ON:15.10.19				50.00 ✓
2	B	BP-LAB3 CHECK WIRING SYSTEM AND FOCUS HEADLAMP. (ETT)	08			216.50 ✓
3	B	BP-LAB3 REMOVE/REFIX FRONT PARKING SENSORS. (NETT)	08			216.50 ✓
4	B	BP-LAB3 REMOVE ALL NECESSARY PARTS, TO ENABLE REPAIRING AND STRAIGHTEN FRONT SUPPORT PANEL, R/H AND L/H HEADLAMP PANELS AND FIT NEW PARTS.	08			2598.00 ✓
5	B	BP-RES3 SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR.	*			2226.00 ✓
6	Z	BP-SLANT SUPPLY SEALANT (NETT)				100.00 ✓
7	B	BP-ECU3 TO RESET ECU & REPROGRAMME. (NETT)	18			216.50 ✓
8	L	BP-LPO SUPPLY REGN PLATE (PO#4584) FRONT (NETT)	E33			96.00 ✓
Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.						

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 12/11/2019
TIME 16:06

VEHICLE NO SMH3997H

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

Inchape

**TAX INVOICE****Borneo Motors (Singapore) Pte Ltd**Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

www.lexus.com.sg

Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388**ESTIMATE**

Account Detail	Account No	Customer Detail
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICCI1	Mr Ng Eng Teck 370H Alexandra Road #06-07 The Anchorage Singapore 159961
	Document No 0	Mobile: 96511111
	Document Date 12/11/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
18	AEXGB	S1	AXZH10R	22/01/2019	SMH3997H	14415	17782 40D/SMH3997H/07101
Chassis No	Engine No	Terms	Lexus Consultant	Vehicle In	Collected On		
JTHB21B1802019526	A25A5098998	60	Wally Tan G H	08/10/2019	0.00	12/11/2019	18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
9	V	EXC Excess element of insurance repair to be 88				-1000.00
		paidby the insured party				
10	1	T88723-33170 LABEL, COOLER	1.00	4.20		4.20
11	2	TG9275-12010 LABEL, BATTERY	1.00	9.20		9.20
12	3	L53301-33260 HOOD SUB-ASSY	1.00	2962.10		2962.10
13	4	T90467-09050 CLIP	9.00	2.90		26.10
14	5	T11293-36070 LABEL, ENGINE	1.00	7.30		7.30
15	6	L53101-33670 GRILLE SUB-ASSY,	1.00	1660.70		1660.70
16	7	L52115-33110 SUPPORT, FR BUMPER	1.00	43.00		43.00
17	8	L52116-33100 SUPPORT, FR BUMPER	1.00	43.00		43.00
18	9	L52521-33100 RETAINER, FR BUMPER,	2.00	19.20		38.40
19	0	L52542-33010 SEAL, FR BUMPER, CTR	1.00	92.50		92.50
20	1	L52119-3T943 COVER, FR BUMPER	1.00	1046.20		1046.20
21	2	L52114-33520 BRACKET, FR BUMPER	1.00	161.10		161.10
22	3	T53879-33030 RETAINER, FR FENDER	6.00	12.20		73.20
23	4	T47749-33030 CLIP, PIN HOLD	6.00	8.60		51.60
24	5	L89348-50130 RETAINER, ULTRASONIC	2.00	19.20		38.40
25	6	T90467-07217 CLIP	7.00	2.50		17.50
26	7	L53112-33390 GRILLE, RADIATOR,	1.00	223.40		223.40
27	8	L53141-33180 GARNISH, RADIATOR	1.00	2100.70		2100.70
Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.						

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total	13,318.10
	Please acknowledge receipt of vehicle	Parts 8,598.60	GST 7.00%	932.27
		Labour 5,623.50	Less	0.00
		Materials 96.00		
		Lubrication/Fluid 0.00		
		Others 0.00		
			Amount Due	14,250.37

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 12/11/2019
TIME 16:06

VEHICLE NO SMH3997H

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD**Borneo Motors**

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 Oct 2019		10 Oct 2019 16:50 Edit Adj Rpt	S\$14,318.10 Edit Estimates	S\$14,318.10 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	NG ENG TECK, ID: S0122172H, Tel: +6596511111, Email: NOEMAIL		
Vehicle Reg. No.:	SMH3997H	Date of Loss:	07/10/2019 15:00 - :59 [8 Months and 15 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / SNM19D204699C01	Policy/Cover Note No.:	60014287 (Comprehensive)
		Excess:	S\$1,000.00
Repairer:	Borneo Motors (S) Pte Ltd (Pandan) 2 Pandan Crescent, 128462 West Coast - Tel: 66311857		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 21/10/2019]		
Driver/Custodian:	NG ENG TECK (66 / Male) , NRIC: S0122172H, Tel: +6596511111 Email: NOEMAIL		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- CHINA_TAIPING (15/10/2019): Alert - Adj Mandate Approved (S\$27675.00) - SMH3997H - Claim Handler: Elaine Che...

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SMH3997H (SNM19D204699C01)



















































OD

Oct 7 2019 3:00PM

[NG ENG TECK]

Borneo Motors (S) Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View View in Browser	
Video				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Borneo Motors (S) Pte Ltd (Leng Kee)		Thumbnail	Print
1	08/10/19 13:39	Video - Accident [Linked Accident Report Documents]		Load MP4	
2	08/10/19 13:39	Video - Accident [Linked Accident Report Documents]		Load MP4	
Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Borneo Motors (S) Pte Ltd (Leng Kee)		Thumbnail	Print
1	08/10/19 13:42	Accident Statement		Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	14/10/19 12:16	Adjuster Immediate Advice		Load HTM	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Borneo Motors (S) Pte Ltd (Leng Kee)		Thumbnail	Print
1	08/10/19 13:37	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
2	08/10/19 13:37	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
3	08/10/19 13:37	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
4	08/10/19 13:37	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
5	08/10/19 13:37	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
6	08/10/19 13:37	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
7	08/10/19 13:37	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
8	08/10/19 13:37	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
9	08/10/19 13:37	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
10	08/10/19 13:37	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
11	08/10/19 13:37	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
12	08/10/19 13:37	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
13	08/10/19 13:37	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
14	08/10/19 13:37	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
15	08/10/19 13:37	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
16	08/10/19 13:37	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
17	08/10/19 13:37	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
18	08/10/19 13:37	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
19	08/10/19 13:37	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	15/11/19 10:01	General View		Load JPG	<input checked="" type="checkbox"/>
2	15/11/19 10:01	General View		Load JPG	<input checked="" type="checkbox"/>
3	15/11/19 10:01	General View		Load JPG	<input checked="" type="checkbox"/>
4	15/11/19 10:01	General View		Load JPG	<input checked="" type="checkbox"/>
5	15/11/19 10:01	General View		Load JPG	<input checked="" type="checkbox"/>
6	15/11/19 10:01	General View		Load JPG	<input checked="" type="checkbox"/>
7	15/11/19 10:01	General View		Load JPG	<input checked="" type="checkbox"/>
8	15/11/19 10:01	General View		Load JPG	<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Borneo Motors (S) Pte Ltd (Leng Kee)	Thumbnail	Print
9	15/11/19 10:01	General View	 Load JPG	<input checked="" type="checkbox"/>
10	15/11/19 10:01	General View	 Load JPG	<input checked="" type="checkbox"/>
11	15/11/19 10:01	General View	 Load JPG	<input checked="" type="checkbox"/>
12	15/11/19 10:01	General View	 Load JPG	<input checked="" type="checkbox"/>
13	15/11/19 10:01	General View	 Load JPG	<input checked="" type="checkbox"/>
14	15/11/19 10:01	General View	 Load JPG	<input checked="" type="checkbox"/>
15	15/11/19 10:01	General View	 Load JPG	<input checked="" type="checkbox"/>
16	15/11/19 10:01	General View	 Load JPG	<input checked="" type="checkbox"/>
17	15/11/19 10:01	General View	 Load JPG	<input checked="" type="checkbox"/>
18	15/11/19 10:01	General View	 Load JPG	<input checked="" type="checkbox"/>
19	15/11/19 10:01	General View	 Load JPG	<input checked="" type="checkbox"/>
20	15/11/19 10:01	General View	 Load JPG	<input checked="" type="checkbox"/>
21	15/11/19 10:01	General View	 Load JPG	<input checked="" type="checkbox"/>
22	15/11/19 10:01	General View	 Load JPG	<input checked="" type="checkbox"/>
23	15/11/19 10:01	General View	 Load JPG	<input checked="" type="checkbox"/>
24	15/11/19 10:01	General View	 Load JPG	<input checked="" type="checkbox"/>
25	15/11/19 10:01	General View	 Load JPG	<input checked="" type="checkbox"/>
26	15/11/19 10:01	General View	 Load JPG	<input checked="" type="checkbox"/>
27	15/11/19 10:01	General View	 Load JPG	<input checked="" type="checkbox"/>
28	15/11/19 10:01	General View	 Load JPG	<input checked="" type="checkbox"/>
29	15/11/19 10:01	General View	 Load JPG	<input checked="" type="checkbox"/>
30	15/11/19 10:01	General View	 Load JPG	<input checked="" type="checkbox"/>
31	15/11/19 10:01	General View	 Load JPG	<input checked="" type="checkbox"/>
32	15/11/19 10:01	General View	 Load JPG	<input checked="" type="checkbox"/>
33	15/11/19 10:01	General View	 Load JPG	<input checked="" type="checkbox"/>
34	15/11/19 10:01	General View	 Load JPG	<input checked="" type="checkbox"/>
35	15/11/19 10:01	General View	 Load JPG	<input checked="" type="checkbox"/>
36	15/11/19 10:01	General View	 Load JPG	<input checked="" type="checkbox"/>
37	15/11/19 10:01	General View	 Load JPG	<input checked="" type="checkbox"/>
38	15/11/19 10:01	General View	 Load JPG	<input checked="" type="checkbox"/>
39	15/11/19 10:01	General View	 Load JPG	<input checked="" type="checkbox"/>
40	15/11/19 10:01	General View	 Load JPG	<input checked="" type="checkbox"/>
41	15/11/19 10:01	General View	 Load JPG	<input checked="" type="checkbox"/>
42	15/11/19 10:01	General View	 Load JPG	<input checked="" type="checkbox"/>
43	15/11/19 10:01	General View	 Load JPG	<input checked="" type="checkbox"/>
44	15/11/19 10:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	15/11/19 10:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	15/11/19 10:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	15/11/19 10:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	15/11/19 10:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	15/11/19 10:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	15/11/19 10:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	10/10/19 16:51	OD SURVEY - SMH3997H	 Load PDF	
2	10/10/19 16:51	OD REPAIR ESTIMATE - SMH3997H	 Load PDF	
No	Finalized On	Borneo Motors (S) Pte Ltd (Leng Kee)	Thumbnail	Print
1	08/10/19 13:42	Accident Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	08/10/19 13:42	Accident Sketch Plan [Linked Accident Report Documents]	 Load TIF	
3	08/10/19 13:42	CI [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
4	08/10/19 13:42	CI [Linked Accident Report Documents]	 Load TIF	
5	08/10/19 13:42	Driving License & NRIC [Linked Accident Report Documents]	 Load TIF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	14/10/19 12:16	MARK ESTIMATE	 Load PDF	

Linked Accident Report Documents

View View in Browser

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Borneo Motors (S) Pte Ltd (Leng Kee)	Thumbnail	Print
1	08/10/19 13:39	Video - Accident	Load MP4	
2	08/10/19 13:39	Video - Accident	Load MP4	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Borneo Motors (S) Pte Ltd (Leng Kee)	Thumbnail	Print
1	08/10/19 13:42	Accident Statement	Load HTM	
2	02/11/19 10:21	Addendum Sheet	Load JPG	<input checked="" type="checkbox"/>
3	02/11/19 10:24	Accident Statement Addm. #1	Load HTM	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Borneo Motors (S) Pte Ltd (Leng Kee)	Thumbnail	Print
1	08/10/19 13:37	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	08/10/19 13:37	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	08/10/19 13:37	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	08/10/19 13:37	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	08/10/19 13:37	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	08/10/19 13:37	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
7	08/10/19 13:37	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
8	08/10/19 13:37	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
9	08/10/19 13:37	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
10	08/10/19 13:37	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
11	08/10/19 13:37	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
12	08/10/19 13:37	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
13	08/10/19 13:37	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
14	08/10/19 13:37	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
15	08/10/19 13:37	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
16	08/10/19 13:37	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
17	08/10/19 13:37	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
18	08/10/19 13:37	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
19	08/10/19 13:37	Accident Photo	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Borneo Motors (S) Pte Ltd (Leng Kee)	Thumbnail	Print
1	08/10/19 13:42	Accident Sketch Plan	Load JPG	<input checked="" type="checkbox"/>
2	08/10/19 13:42	Accident Sketch Plan	Load TIF	
3	08/10/19 13:42	CI	Load JPG	<input checked="" type="checkbox"/>
4	08/10/19 13:42	CI	Load TIF	
5	08/10/19 13:42	Driving License & NRIC	Load TIF	
6	02/11/19 10:22	Police Report	Load JPG	<input checked="" type="checkbox"/>
7	02/11/19 10:22	Police Report	Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI19017955/R1YD3E2

Date: 27/11/2019

REFERENCE

Insured/Claimant: NG ENG TECK Policy No: 60014287
Date of Loss: 07/10/2019 Nature of Claim: OD Claim No: SNM19D204699C01

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMH3997H**
Make & Model: LEXUS ES300, 3.0 (A) Engine No: A25A5098998
Reg. Date: 22/01/2019 (Man. Year: 2018) Chassis No: JTHB21B1802019526
Colour: Gold Odometer: 14237 km
Engine Capacity: 2487 cc
Market Value/New Car Price: S\$195,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/45 R18 Rear Tyre Size: 235/45 R18
Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,365.50	8,844.60	12,520.90	58.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,576.50	5,473.50	2,103.00	27.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	28,942.00	14,318.10	14,623.90	50.53
- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
(S\$)	27,942.00	13,318.10	14,623.90	52.34
+ GST 7.00/7.00% (S\$)	1,955.94	932.27	1,023.67	52.34
Nett Amount (S\$)	29,897.94	14,250.37	15,647.57	52.34

INSPECTION

Date of Assignment: 10/10/2019

Date Inspected: 14/10/2019 Inspected At:

Borneo Motors (S) Pte Ltd (Pandan)
2 Pandan Crescent
Singapore 128462

Estimated Period of Repair: 6.0 days

Adjuster: MOHD RASUL

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Nov 2019)
Parts:	143	LEXUS ES300 3.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMH3997H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	80.00 FS	*50.00 FS
2	1		*SEALANT	Necessary	100.00 FS	*100.00 FS
3	1		*REGN PLATE (PO#)	Bent	96.00 FS	*96.00 FS
4	1		*UNIT, HEADLAMP	Serviceable	3,702.20 FS	*- FS
5	1		*UNIT, HEADLAMP	Serviceable	3,702.20 FS	*- FS
6	1		*RIM, HEADLAMP	Serviceable	17.50 FS	*- FS
7	1		*RIM, HEADLAMP	Serviceable	17.50 FS	*- FS
8	1		*RIM, HEADLAMP	Serviceable	46.50 FS	*- FS
9	1		*RIM, HEADLAMP	Serviceable	28.80 FS	*- FS
10	1		*HOOD SUB-ASSY	Bent	2,962.10 FS	*2,962.10 FS
11	9		*CLIP	Necessary	26.10 FS	*26.10 FS
12	1		*LABEL, COOLER	Necessary	4.20 FS	*4.20 FS
13	1		*LABEL, ENGINE	Necessary	7.30 FS	*7.30 FS
14	1		*LABEL, BATTERY	Necessary	9.20 FS	*9.20 FS
15	1		*GRILLE SUB-ASSY	Cracked	1,660.70 FS	*1,660.70 FS
16	1		*GRILLE, RADIATOR	Cracked	223.40 FS	*223.40 FS
17	1		*GARNISH, RADIATOR	Cracked	2,100.70 FS	*2,100.70 FS
18	1		*SENSOR ASSY	Serviceable	2,125.80 FS	*- FS
19	1		*SUPPORT, FR BUMPER	Necessary	43.00 FS	*43.00 FS
20	1		*SUPPORT, FR BUMPER	Necessary	43.00 FS	*43.00 FS
21	1		*REINFORCEMENT	Serviceable	909.60 FS	*- FS
22	1		*BRACKET, FR BUMPER	Serviceable	503.30 FS	*- FS
23	1		*ABSORBER, FR BUMPER	Serviceable	112.40 FS	*- FS
24	1		*CHAMBER ASSY	Serviceable	790.30 FS	*- FS
25	1		*GRILLE, RADIATOR	Serviceable	199.30 FS	*- FS
26	2		*RETAINER, FR BUMPER	Necessary	38.40 FS	*38.40 FS
27	1		*SEAL, FR BUMPER, CTR	Necessary	92.50 FS	*92.50 FS
28	1		*COVER, FR BUMPER	Deformed	1,046.20 FS	*1,046.20 FS
29	1		*COVER, FR BUMPER	Serviceable	54.20 FS	*- FS
30	1		*BRACKET, FR BUMPER	Necessary	161.10 FS	*161.10 FS
31	1		*ABSORBER, FR BUMPER	Serviceable	281.30 FS	*- FS
32	6		*RETAINER, FR FENDER	Necessary	73.20 FS	*73.20 FS
33	6		*CLIP, PIN HOLD	Necessary	51.60 FS	*51.60 FS
34	2		*RETAINER, ULTRASONIC	Necessary	38.40 FS	*38.40 FS
35	7		*CLIP	Necessary	17.50 FS	*17.50 FS
Total Parts (\$\$)					21,365.50	8,844.60

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK WIRING SYSTEM AND FOCUS HEADLAMP	New	216.50	216.50
2	REMOVE / REFIX FRONT PARKING SENSORS	New	216.50	216.50
3	REMOVE / REFIX AIR-CON CONDENSER, RECEIVER DRYER, GAS PIPES TO ENABLE REPAIRING AND FIT NEW PARTS	New	866.00	0.00
4	REMOVE ALL NECESSARY PARTS, TO ENABLE REPAIRING AND STRAIGHTEN FRONT SUPPORT PANEL, R/H AND L/H HEADLAMP PANELS AND FIT NEW PARTS	New	3,464.00	2,598.00
5	SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR	New	2,597.00	2,226.00
6	TO RESET ECU & REPROGRAMME	New	216.50	216.50
Gross Labour Cost (\$\$)			7,576.50	5,473.50

Report was unsubmitted during this print-out.

< END OF ESTIMATES >