

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
AXA	NSURANCE PTE	LTD	Ref : CC4/ASM19017959/Kgb3q2		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:PETER			Date: 09-04-2020 Code: ASM		
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SJU 1081E	Veh. Inspected	SMC 8351P	
	Policy No.	GA498576/1	Coverage (\$)	0.00	
	Claim No.	S9M0231U	Excess (\$)	0.00	
	Assign From		Assign Date	11/10/2019	
2. Vehicle Particulars & Condition					
	Make & Model	MERCEDES BENZ GLA180 (A)	c.c	1595	
	Engine No.	HIDDEN	Year of Reg.	2018	
	Chassis No.	WDC1569422J527711	Colour	METALLIC BLACK	
	Odometer	21739	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	235/50 R18	YOKOHAMA	8 mm	
	L/H Front Tyre	235/50 R18	YOKOHAMA	8 mm	
	R/H Rear Tyre	235/50 R18	YOKOHAMA	8 mm	
	L/H Rear Tyre	235/50 R18	YOKOHAMA	8 mm	
4.	·				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	07/10/2019	Inspection Date	11/10/2019	
	Survey held at	TONG LUCK AUTO PL			
		160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY SINGAPORE 575722			
5a.	Remarks				
		A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b.	Estimate Days of Repair				
	ESTIMATED NOR	STIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days			