

ASSIGNMENT

Surveyor:

MARCUS

DOI: 11/10/2019

Date / Time: 11/10/2019

Registered in Merimen: 11/10/2019

Pre-assign / CCU / FTE



Insured Vehicle No.: SDB 1089E

Claim No.: 18563038316G

Name of Insured: TEO AH CHEO @ KHERNG GEOK YEN

Policy No.: 1800006570

Insured Tel No.: HP:

Make / Model: MERCEDES-BENZ C180

Excess Sec II :S\$ D.O.A: 07/10/2019 20:45

Place of Accident: SENGKANG EAST DRIVE

Is driver the owner? (YES / NO) Nature of Accident:

If NO, Driver Name / Age: DAN HUA CHIN

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.: +65-98756494

(V/L: YES / NO)

Insured Liability: % Final ? Yes / No

SLT 7762R

INSRS:
WSP: FASTECH
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time		STAGE	DATE / PIC
	SDB 1089E - X	Non-Reporting ltr (1st):	
	SLT 7762R - CC6/AIG18006411/Uha3q2; DOA: 03/04/18	Non-Reporting ltr (2nd):	
	- NA/CTI18006212/h4; DOA: 03/04/18	Non-Reporting ltr (Final):	
21/10/19	- PLUS REVIEWED. OLD REPAIR - ENDED TP.	Notification ltr (if non-pickup):	
	- SEND LETTER TO OI.	Call OI:	
	- OI VIDEO UPLOADED BY AIG IN MERIMEN	After call ltr to OI:	21/10/19 - VIC
	- FINALIZED	Documentation Check List:	Handler Typist
18/01/2020	- ORIGINAL TP LOD IN.	Notification ltr (if non-pickup):	☐
	- UPLOADED MANIFEST LA IN OC	After call ltr to OI:	☒
22/01/2020	- AIG APPROVED WARRANT	Authorisation To Act:	☒
01/02/2020	- SEND 1ST OFFER TO TP.	Release Voucher:	☒
03/02/2020	- TP ACCEPTED OFFER.	Final Repair Bill:	☒
	- ALL DOCS IN ORDER.	Car Rental Invoice:	☐
	- TO CLOSE.	Towing Invoice:	☐
		LTA / GIA:	☒
		Medical Bill:	☐
		PIR:	☐
		Mandate/Reject Instruction:	☒
		LOD:	☒
		Payment Breakdown Form:	☐
PRELIMINARY ADVICE	Date/Time:	Post-Repair Photos:	☐
	Sent By:	Others:	☐
FINALIZATION	Date/Time:	Confirm by:	
Repair Cost: US	S\$ 6,400.00 (6 days) Reduction: 66 %	Email ☐ Call ☐	
FINAL SETTLEMENT	Date/Time: 03/02/20 Confirm with JASON	Email ☒ Call ☐	
Final Liability:	% 100 (Agreed / Assessed) BOLA S/N No.: 24	If NO or B 28, Ass. Lia:	
Repair Cost: (w/1000)	S\$ 6,848.00	COLD REPAIR - ENDED TP	
Loss of Rental (LOR):	S\$ - (days)	COPY SENT	
Loss of Use (LOU):	S\$ 480.00 x 8 days	6/2/2020	
Loss of Income (LOI):	S\$ - (5 x days)		
LOR only ☐ LOU only ☒	LOR + LOU ☐ LOR + LOI ☐ (Tick only one)		
GIA/LTA Search	S\$ 200	1) Claim status: Normal/Reject/Private Settle	
Medical:	S\$ -	2) Report Format:	
Disbursement:	S\$ - (e.g. Tow/ Independent)	3) Survey fee:	\$320.00
Legal Cost	S\$ -		
Total:	S\$ 7,330.00 Global Sum S\$: 7,330.00		
FINAL PAYMENT	Date/Time:	Confirm by:	
Payee 1:	S\$ 7,330.00 Name 1: FASTECH AUTO PTE LTD	Email ☐ Call ☐	
Payee 2: (Strike if N.A.)	S\$ - Name 2: -		
Payee 3: (Strike if N.A.)	S\$ - Name 3: -		

ASS. REC. BY Marcus

REF:

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To inspect Vehicle No: **SLY7762R**
at Workshop m/s **LI**
of _____
Insured: _____
Policy No: _____
Claims No: _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: **75**
IDAC Accident Report: _____ Consistent? : Yes or No
GIA / PR Seen: **2** Consistent? : Yes or No
Est. Repairs: **6** days Res: Yes or No
Lump Sum: **20** % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: **SLY7762R** Yr Regn: **11 17**
Type: **2** M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or **CA**
Make: **Honda** Verel / Hybrid 1496
Colour: **Black** A/C: Insured / Std / Nil / NA
Sp. Reading: **5-1559** T/Radio: Insured / Std / Nil / NA
Eng/No: _____
C/No: **RU31263732**
Gen. Cond: **2** Good / Fair / Poor / Burnt
Steering: **2** Wonder / Jammed / Leaked / Burnt or
Brake: **2** Wonder / Jammed / Leaked / Burnt or
Mod: Nil / S/Rim / STD A/Rim or
Tyre Size: F: _____ R: **215/60R16**
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or
Front: _____ Rear: _____
R/Bal: **7** mm R/Bal: **7** mm
L/Bal: **7** mm L/Bal: **7** mm
D.O.A: **7/10/19** D.O.I: **11/10/19**
Survey held at: _____
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear
The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction
25/10/19 14:15 have G.A. **27A44140**
45400 confirmed with Alan
(exp: \$12,916.00 / 60%)

Date/Time, File Pass to: ☐ : Prel. Report
☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$ _____) ☐ : S + RS (\$ _____)
☐ : Interview (\$ _____) ☐ : Photo
☐ : Tech. Invs (\$ _____) ☐ : Other (\$ _____)
☐ : Weekend (\$ _____)

Report Format :

Lump Sum / I.B.I: (\$ _____)

TOTAL

ASS. REC. BY: Marcus

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Est. or Market Value:

IDAC Accident Report:

GLP / PR Seen:

Est. Repairs:

days

Res.:

Yes or No

Lump Sum:

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Judder / Jammed / Leaked / Burnt or

Brake: Judder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Rear

R/Bal.

L/Bal.

D.O.A.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to:

☐

: Preli. Report

☐

: Final Report

Date/Time, File Return to:

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

US + RS: \$

Photo:

Other:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

TOTAL

FASTECH AUTO PTE LTD

VEHICLE NO: SLT7762R

Qty Particular

Amount S\$

List Item:

1 PCS	REAR WINDSCREEN MOULDING	
1 PCS	TAILGATE	953.00
1 PCS	TAILGATE OUTER HANDLE GARNISH	
1 PCS	TAILGATE 'H' LOGO	
2 PCS	TAILGATE REFLECTORS @\$280	
1 PCS	TAILGATE 'VEZEL' EMBLEM	
1 PCS	TAILGATE INNER LOCK	
1 PCS	TAILGATE LOCK STRIKER	
1 PCS	TAILGATE INNER TRIM BOARD	
1 SET	TAILGATE INNER TRIM BOARD CLIPS	
1 PCS	TAILGATE WEATHERSTRIP	
1 PCS	TAILGATE KEYLESS SENSOR	
1 PCS	REAR BUMPER CENTRE	
2 PCS	REAR BUMPER SIDES @\$235.10	
2 PCS	REAR BUMPER SIDE RETAINERS @\$35.20	
2 PCS	REAR BUMPER SCREW SPACERS @\$12	
2 PCS	REAR BUMPER REFLECTORS @\$151.20	
2 PCS	TAILLAMPS @\$460.60	
2 PCS	TAILLAMP HOUSING PANELS @\$195	
1 PCS	REAR END PANEL	
1 PCS	REAR END PANEL TOP GARNISH	
1 PCS	REAR BUMPER LOWER DIFFUSER	
1 SET	REAR BUMPER LOWER DIFFUSER CLIPS	
1 PCS	REAR EXHAUST	
2 PCS	REAR EXHAUST MOUNTINGS @\$45	
1 PCS	REAR EXHAUST HEAT SHIELD	
2 PCS	REAR FENDER INNER TRIMS @\$295.30	
1 SET	REAR FENDER INNER TRIM CLIPS	
2 PCS	REAR FENDER OUTER GARNISH @\$195.80	
1 PCS	REAR FLOOR PANEL	
1 PCS	REAR FLOOR PANEL Top board	415.00
1 PCS	REAR floor panel Top tray	488.20
List Item Total:		

rec	\$	121.30	/
305500	\$	1,100.90	/
crn	\$	285.30	/
neu	\$	35.80	/
o/sca7	\$	560.00	1PC
neu	\$	56.20	/
twi	\$	198.50	/
11	\$	25.50	X
de/cne	\$	321.70	/
neu	\$	50.00	/
twi	\$	135.70	/
11	\$	180.00	X
Dis	\$	762.70	/
o/sborn	\$	470.20	1PC
11	\$	70.40	X
11	\$	24.00	X
o/sca	\$	302.40	1PC
o/sca9	\$	921.20	1PC
n	\$	390.00	X
body	\$	514.00	/
twi	\$	125.00	/
Dis	\$	348.20	/
neu	\$	50.00	/
n	\$	899.20	X
11	\$	90.00	X
11	\$	98.30	X
o/sene	\$	590.60	1PC
11	\$	50.00	X
o/sborn	\$	391.60	1PC
n	\$	912.30	X
Torn	\$	685.00	/
era	\$	2,200.00	/
		\$ 12,966.00	

6478.60
518288

Special Nett Item:

1 SET	REAR BUMPER REVERSER SENSOR	
1 PCS	REAR REVERSE CAMERA	
1 PCS	REAR WINDSCREEN SEALANT	
1 PCS	REAR END PANEL SEALANT	
1 PCS	REAR FLOOR PANEL INSULATOR	
Special Nett Total:		

shob	\$	280.00	200
shob	\$	500.00	350
neu	\$	50.00	40
neu	\$	50.00	/
11	\$	180.00	X
		\$ 1,060.00	

Labour Charge:

TO CHECK WIRING

\$ 80.00 30

Not Allocated
1/10/19
6400
11/10/19
6400

TO DISMANTLE & REPLACE REVERSE SENSOR	\$ 80.00	50
TO TRANSFER TAILGATE MECHANISM	\$ 100.00	60
TO DISMANTLE & REFIX REAR WINDSCREEN	\$ 150.00	120
TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTERY	\$ 150.00	80
TO DISMANTLE & REPLACE REAR EXHAUST	11 \$ 100.00	X
TO SPRAY RUST PROOFING	\$ 150.00	60
TO MOUNT VEHICLE ON CAR O-LINER	11 \$ 380.00	X
TO DISMANTLE & REFIX PETROL TANK	11 \$ 100.00	X
LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS	\$ 2,000.00	700
TO PUTTY & SPRAY PAINTING	\$ 2,000.00	1080
Labour Charge Total:	\$ 5,290.00	


ESTIMATE PARTS AND LABOUR GRAND TOTAL

\$ 19,316.00 5002-88
6402.

and shall immediately hence notify the "Insurer" of the following:

- estimate spray painting
- replacement parts during resurvey
- subject to confirmation
- on a "Without Prejudice" basis
- a further inspection(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Reposer:
Signature:
Date:



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

Toyota Wish 1.8A X (New 5-yr COE).



Low Depreciation Yet Spacious!
That Suits Big Family! Well
Maintain.
Direct Owner StarAd

HIN LUNG AUTO
HoBee Group
One Stop Car!
Finance, Insurance, We
New and Used Cars

Browse by Category « Back (1 2 3) Next » Sort by Date Posted

50 vehicles honda vezel Advanced Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh T
Search Selection	honda vezel	Any	Any	2017	Any	Any	
	Honda Vezel 1.5A X Honda Sensing Elegant Silver SUV, Comes With Honda Sensing, This Is Not A Rental/Limousine Unit, Low Mileage Done, One Owner Only, Low Maintenance Cost, Very Well Maintained, Easy Financing, Flexible In-House Loan Packages Available., Prime Motor & Leasing Posted: 13-Oct-2019 Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda	\$72,500	\$8,540 /yr	30-Jun-2017	1,496 cc	-	5
	Honda Vezel Hybrid 1.5A X Honda Sensing Fuel Type: Petrol-Electric Attractive Loan Packages, Enquirer To Know More! Very Beautiful Purplish Black Vezel Hybrid! Powerful Yet Low Petrol Consumption! Safety Honda Sensing Functions With Auto Lane Departure Warning! Well Taken Care By Previous Owner! STA Evaluation Highly Recom... Posted: 13-Oct-2019 Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda	\$77,800	\$9,750 /yr	04-Jul-2017	1,496 cc	23,000 km	5
	Honda Vezel 1.5A X One Owner Only! 6-12 Months Warranty On Engine And Gearbox. Free 1x Normal Servicing Upon Purchased. Fuel Efficient! Very Well Maintained, Original Paint! Serviced Records Available. Owner Upgraded! 100% Loan Approval Rate! Come Down Now To View This Bea... Posted: 12-Oct-2019 Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda	\$67,888	\$8,360 /yr	07-Apr-2017	1,496 cc	51,000 km	5
	Honda Vezel 1.5A RS Rare "RS Edition" Vezel 1.5A With Honda Sensing! Priced Same Depreciation As Normal, No Gimmicks! Genuine Low Mileage Done 46546km! Like New, See To Certify. 1 Owner. New Paintwork. 100% Accident Free. In House Loan Available. Price Negotiable. Call Now! Lake View Credit Pte Ltd Posted: 12-Oct-2019 Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda	\$73,800	\$8,400 /yr	03-May-2017	1,496 cc	46,546 km	5
	Style Vezel With Quality Leather Upholstery Quality Half-Leather Upholstery For Honda Vezel Car Seat. Comes with an 15-month warranty & Life-Time Cleaning Service More info about this product						
Compare	1a Vezel 1.5A X Honda	\$69,800	\$8,410 /yr	15-May-2017	1,496 cc	33,000 km	5

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 272A

Vehicle Details

Vehicle No.: SLT7762R
Vehicle to be Exported: No
Intended Deregistration Date: 11 Oct 2019
Vehicle Make: HONDA
Vehicle Model: VEZEL HYBRID 1.5X AUTO
Primary Colour: Black
Manufacturing Year: 2017
Engine No.: LEB5963752
Chassis No.: RU31263732
Maximum Power Output: 112.0 kW (150 bhp)
Open Market Value: \$27,871.00
Original Registration Date: 10 Nov 2017
First Registration Date: 10 Nov 2017
Transfer Count: 0
Actual ARF Paid: \$5,000.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 09 Nov 2027
PARF Rebate Amount: \$3,750.00

Intended COE Rebate Details

COE Expiry Date: 09 Nov 2027
COE Category: B - Car above 1600cc or 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$49,996.00
COE Rebate Amount: \$40,390.00
Total Rebate Amount: \$44,140.00

The information contained herein is correct as at 11 Oct 2019

OK

Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number: 5104774982

Cover : drive CLASSIC

- | | |
|---|----------------------|
| 1. Index mark and Registration Number of Vehicle | : SLT7762R |
| Chassis Number | : RU31263732 |
| 2. Name of Policyholder | : SARAVANAN S/O RAMU |
| 3. Effective Date of Insurance | : 10 Nov 2018 |
| 4. Expiry Date of Insurance | : 09 Nov 2019 |
| 5. Persons or Classes of Persons entitled to drive# | |
| (a) The Policyholder. | |
| (b) Any other person who is driving on the Policyholder's order or with his/her permission. | |
| Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle. | |
| 6. Limitations as to Use# | |
| (a) Use for social domestic and pleasure purposes and in connection with the Policyholder's business or profession. | |

This Policy does not cover

- (a) Use for hire or reward.
- (b) Use for racing, pace-making, reliability trial or speed-testing.
- (c) Use for the carriage of goods (other than samples) in connection with any trade or business.
- (d) Use for any purpose in connection with the Motor Trade.

Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION 1)	: S\$600
EXCESS (SECTION 2)	: N/A
WINDSCREEN EXCESS	: S\$100
ADDITIONAL EXCESS	: N/A
UNNAMED DRIVER EXCESS	: PLEASE REFER OVERLEAF
REPAIR AT OWNER'S PREFERRED WORKSHOP	: NO
INSURE WITH COE	: YES
NCD PROTECTION	: NO
TRANSPORT ALLOWANCE	: NO
EXCESS WAIVER	: NO
PRIMARY DRIVER	: SARAVANAN S/O RAMU
NAMED DRIVER (1)	: N/A
NAMED DRIVER (2)	: N/A
HIRE PURCHASE COMPANY	: UNITED OVERSEAS BANK LIMITED
SUM INSURED	: MARKET VALUE OF INSURED VEHICLE AT TIME OF LOSS

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : VICOM LTD (00000614946)
Date of Issue : 19 Oct 2018 11:28 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED



Countersigned By:

Authorised Officer



Chief Executive

Vic (LKKAUTO)

From: Jason <Jason@fastechauto.com.sg>
Sent: Monday, 3 February, 2020 11:09 AM
To: Vic (LKKAUTO); Ong Shiyong
Cc: Lina Pang; Admin A
Subject: RE: Your Ref : SDB 1089E DOA : 08.10.2019 Our Ref : SLT 7762R *** LKK REF: CC6/AIG19017967/Uha3

Without Prejudice

Dear Vic,

We are pleased to accept your offer of global sum of \$7,330.00 for my client's vehicle property claim.

Thank you.

Best Regards

Jason Tang
Fastech Auto Pte Ltd
1 Kaki Bukit Ave 6
#01-46/48/50 AutoBay
Singapore 417883
Tel: 67465405
Hp: 98218445
jason@fastechauto.com.sg

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/claimant.

From: Vic (LKKAUTO) [mailto:vicalpeh@lkkauto.com]
Sent: Saturday, February 1, 2020 1:36 PM
To: Ong Shiyong <shiyong.ong@fastechauto.com.sg>
Cc: Jason <Jason@fastechauto.com.sg>; Lina Pang <Lina.pang@fastechauto.com.sg>; Admin A <admin-a@lkkauto.com>; Vic (LKKAUTO) <vicalpeh@lkkauto.com>
Subject: RE: Your Ref : SDB 1089E DOA : 08.10.2019 Our Ref : SLT 7762R *** LKK REF: CC6/AIG19017967/Uha3

WITHOUT PREJUDICE

Dear Shiyong,

We refer further to our below email.

On a without prejudice basis and purely for an amicable settlement on a without admission of liability to our Insured's part, we have our principal's mandate and we offer a global sum of \$7,330.00 (all in).

For your acceptance please.

The above amount is to be made payable to **FASTECH AUTO PTE LTD.**

Thank you.



"Please note that our above offer and any settlement arising from the above offer are made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our Insured Driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters.

"Wishing you a Happy and Prosperous Lunar New Year"

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

From: Mei Kwan (LKKAuto)

Sent: Monday, 20 January, 2020 3:01 PM

To: Ong Shiyong; Vic (LKKAuto)

Cc: Jason; Lina Pang; Admin A

Subject: RE: Your Ref : SDB 1089E DOA : 08.10.2019 Our Ref : SLT 7762R *** LKK REF: CC6/AIG19017967/Uha3

Dear Sir / Madam,

Thank you for your email.

Our respective case handler will look into the matter and get back to you in due course.

Hi Vic,

Kindly assist.

To check availability of the case handler, you may contact the undersigned.

"Wishing you a Happy and Prosperous Lunar New Year"



Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ong Shiying <shiyong.ong@fastechauto.com.sg>

Sent: Monday, 20 January, 2020 2:59 PM

To: Admin A <admin-a@lkkauto.com>

Cc: Jason <jason@fastechauto.com.sg>; Lina Pang <Lina.pang@fastechauto.com.sg>

Subject: Your Ref : SDB 1089E DOA : 08.10.2019 Our Ref : SLT 7762R

Without Prejudice

Dear Sir / Madam,

Kindly refer to our Letter of Demand dated 26/12/2019.

Please provide us with the name of OIC.

Thank you.

Best Regards,

Shiying

Fastech Auto Pte Ltd

1 Kaki Bukit Avenue 6 #01-46/48/50

Autobay Singapore 417883

Tel: 6746 5405

Fax: 6745 8520

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Oct 2019 Edit Reg		11 Oct 2019 00:00 Edit Adj Rpt	S\$6,400.00 Edit Estimates	S\$6,400.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	TEO AH CHEO @ KHERNG GEOK YEN, ID: -								
Main Claimant:	SARAVANAN S/O RAMU								
Vehicle Reg. No.:	SLT7762R	Date of Loss:	07/10/2019 00:00 - :59 [22 Months and 27 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 1856303831SG	Policy/Cover Note No.:	(Comprehensive) Coverage: 23/01/2019 - 22/01/2020						
Vehicle Reg. No. (Insured):	SDB1089E	Policy No. (Claimant):	5104774982						
		Excess:							
Repairer:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay, 417883 Kaki Bukit - Tel: 67465405								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 22/10/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG_EXPRESS (22/01/2020): Alert - Adj Mandate Approved (S\$7330.00) - SLT7762R - Claim Handler: Syed-Yusoff... - AIG_SG (14/10/2019): TP GIA REPORT									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLT7762R (1856303831SG)
[SDB1089E]
TP
SARAVANAN S/O RAMU
Oct 7 2019 12:00AM
[TEO AH CHEO @ KHERNG GEOK YEN]
Fastech Auto Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Video															1 per page		☒			
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)												Thumbnail		Print				
1	14/10/19 11:41	OI VIDEO												1 Load MP4						
Letters/Correspondences															1 per page		☒			
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print				
1	(Draft)	Third Party Express Settlement – Payment Breakdown												1 Edit						
Assessment Reports															1 per page		☒			
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print				
1	18/01/20 14:47	Adjuster Immediate Advice												1 Load HTM						
Photos/Images															3 per page		☒			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print				
1	11/10/19 18:00	Odometer Reading												1 Load JPG		☒				
2	11/10/19 18:01	Chassis Number												1 Load JPG		☒				
3	11/10/19 18:01	General View												1 Load JPG		☒				
4	11/10/19 18:01	General View												1 Load JPG		☒				
5	11/10/19 18:01	General View												1 Load JPG		☒				
6	11/10/19 18:01	General View												1 Load JPG		☒				
7	11/10/19 18:01	General View												1 Load JPG		☒				
8	11/10/19 18:01	General View												1 Load JPG		☒				
9	11/10/19 18:01	General View												1 Load JPG		☒				
10	11/10/19 18:01	General View												1 Load JPG		☒				
11	11/10/19 18:01	General View												1 Load JPG		☒				
12	11/10/19 18:01	General View												1 Load JPG		☒				
13	11/10/19 18:01	General View												1 Load JPG		☒				
14	11/10/19 18:01	General View												1 Load JPG		☒				
15	11/10/19 18:01	General View												1 Load JPG		☒				
16	11/10/19 18:01	General View												1 Load JPG		☒				
17	11/10/19 18:01	General View												1 Load JPG		☒				
18	11/10/19 18:01	General View												1 Load JPG		☒				
19	11/10/19 18:01	General View												1 Load JPG		☒				
20	11/10/19 18:01	General View												1 Load JPG		☒				
21	11/10/19 18:01	General View												1 Load JPG		☒				
22	11/10/19 18:01	General View												1 Load JPG		☒				
23	11/10/19 18:01	General View												1 Load JPG		☒				
24	11/10/19 18:01	General View												1 Load JPG		☒				
25	11/10/19 18:01	General View												1 Load JPG		☒				
26	11/10/19 18:01	General View												1 Load JPG		☒				
27	11/10/19 18:01	General View												1 Load JPG		☒				
28	11/10/19 18:01	General View												1 Load JPG		☒				
29	11/10/19 18:01	General View												1 Load JPG		☒				
30	11/10/19 18:01	General View												1 Load JPG		☒				
31	11/10/19 18:01	General View												1 Load JPG		☒				
32	11/10/19 18:01	General View												1 Load JPG		☒				
33	11/10/19 18:01	General View												1 Load JPG		☒				

Video				1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print	
34	11/10/19 18:01	General View	 Load JPG	☒	
35	11/10/19 18:01	General View	 Load JPG	☒	
36	11/10/19 18:01	General View	 Load JPG	☒	
37	11/10/19 18:01	General View	 Load JPG	☒	
38	11/10/19 18:01	General View	 Load JPG	☒	
39	11/10/19 18:01	General View	 Load JPG	☒	
40	11/10/19 18:03	Reinspection Photo	 Load JPG	☒	
41	11/10/19 18:03	Reinspection Photo	 Load JPG	☒	
42	11/10/19 18:03	Reinspection Photo	 Load JPG	☒	
43	11/10/19 18:03	Reinspection Photo	 Load JPG	☒	
44	11/10/19 18:03	Reinspection Photo	 Load JPG	☒	
45	11/10/19 18:03	Reinspection Photo	 Load JPG	☒	
46	11/10/19 18:03	Reinspection Photo	 Load JPG	☒	
47	11/10/19 18:03	Reinspection Photo	 Load JPG	☒	
48	11/10/19 18:03	Reinspection Photo	 Load JPG	☒	
49	11/10/19 18:03	Reinspection Photo	 Load JPG	☒	
50	11/10/19 18:03	Reinspection Photo	 Load JPG	☒	
51	11/10/19 18:03	Reinspection Photo	 Load JPG	☒	
52	11/10/19 18:03	Reinspection Photo	 Load JPG	☒	
53	11/10/19 18:03	Reinspection Photo	 Load JPG	☒	
54	11/10/19 18:03	Reinspection Photo	 Load JPG	☒	
55	11/10/19 18:03	Reinspection Photo	 Load JPG	☒	
56	11/10/19 18:03	Reinspection Photo	 Load JPG	☒	
57	11/10/19 18:03	Reinspection Photo	 Load JPG	☒	
58	11/10/19 18:03	Reinspection Photo	 Load JPG	☒	
59	11/10/19 18:03	Reinspection Photo	 Load JPG	☒	
60	11/10/19 18:03	Reinspection Photo	 Load JPG	☒	
61	11/10/19 18:03	Reinspection Photo	 Load JPG	☒	
62	11/10/19 18:03	Reinspection Photo	 Load JPG	☒	
63	11/10/19 18:03	Reinspection Photo	 Load JPG	☒	
64	11/10/19 18:03	Reinspection Photo	 Load JPG	☒	
65	11/10/19 18:03	Reinspection Photo	 Load JPG	☒	
66	11/10/19 18:03	Reinspection Photo	 Load JPG	☒	
67	11/10/19 18:03	Reinspection Photo	 Load JPG	☒	
68	11/10/19 18:03	Reinspection Photo	 Load JPG	☒	
69	11/10/19 18:03	Reinspection Photo	 Load JPG	☒	
70	11/10/19 18:03	Reinspection Photo	 Load JPG	☒	
71	11/10/19 18:03	Reinspection Photo	 Load JPG	☒	
72	11/10/19 18:03	Reinspection Photo	 Load JPG	☒	
73	11/10/19 18:03	Reinspection Photo	 Load JPG	☒	
74	11/10/19 18:03	Reinspection Photo	 Load JPG	☒	
75	11/10/19 18:03	Reinspection Photo	 Load JPG	☒	
76	11/10/19 18:03	Reinspection Photo	 Load JPG	☒	
77	11/10/19 18:03	Reinspection Photo	 Load JPG	☒	
78	11/10/19 18:03	Reinspection Photo	 Load JPG	☒	
79	11/10/19 18:03	Reinspection Photo	 Load JPG	☒	
80	11/10/19 18:03	Reinspection Photo	Load JPG	☒	
81	11/10/19 18:03	Reinspection Photo	Load JPG	☒	
82	11/10/19 18:03	Reinspection Photo	Load JPG	☒	
83	11/10/19 18:03	Reinspection Photo	Load JPG	☒	
84	11/10/19 18:03	Reinspection Photo	Load JPG	☒	
85	11/10/19 18:03	Reinspection Photo	Load JPG	☒	
86	11/10/19 18:03	Reinspection Photo	Load JPG	☒	
87	11/10/19 18:03	Reinspection Photo	Load JPG	☒	
88	11/10/19 18:03	Reinspection Photo	Load JPG	☒	
89	11/10/19 18:03	Reinspection Photo	Load JPG	☒	

Video			1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
90	11/10/19 18:03	Reinspection Photo	 Load JPG	☒
91	11/10/19 18:03	Reinspection Photo	 Load JPG	☒
92	11/10/19 18:03	Reinspection Photo	 Load JPG	☒
93	11/10/19 18:03	Reinspection Photo	 Load JPG	☒
94	11/10/19 18:03	Reinspection Photo	 Load JPG	☒
95	11/10/19 18:03	Reinspection Photo	 Load JPG	☒
96	11/10/19 18:03	Reinspection Photo	 Load JPG	☒
97	11/10/19 18:03	Reinspection Photo	 Load JPG	☒
98	11/10/19 18:03	Reinspection Photo	 Load JPG	☒
99	11/10/19 18:03	Reinspection Photo	 Load JPG	☒
100	11/10/19 18:03	Reinspection Photo	 Load JPG	☒
101	17/10/19 18:08	After Repair Photo	 Load JPG	☒
102	17/10/19 18:08	After Repair Photo	 Load JPG	☒
103	17/10/19 18:08	After Repair Photo	 Load JPG	☒
104	17/10/19 18:08	After Repair Photo	 Load JPG	☒
105	17/10/19 18:08	After Repair Photo	 Load JPG	☒
106	17/10/19 18:08	After Repair Photo	 Load JPG	☒
107	17/10/19 18:08	After Repair Photo	 Load JPG	☒
108	17/10/19 18:08	After Repair Photo	 Load JPG	☒
109	17/10/19 18:08	After Repair Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	15/10/19 16:17	TP GIA REPORT	 Load PDF	
2	31/10/19 13:48	LETTER TO OI	 Load PDF	
3	18/01/20 14:33	TP ESTIMATE - FINALIZED	 Load PDF	
4	18/01/20 14:37	TP LOD	 Load PDF	
5	07/02/20 11:37	WORKSHOP INVOICE	 Load PDF	
6	07/02/20 11:37	AUTHORISATION TO ACT FORM	 Load PDF	
7	07/02/20 11:37	Release Voucher	 Load PDF	
8	07/02/20 11:37	LOD	 Load PDF	
9	07/02/20 11:37	GIA SEARCH	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	14/10/19 11:19	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SDB1089E (Insd veh)	Model:	HONDA VEZEL 1.5 HYBRID
	SLT7762R (TP veh)		X (A)
Date of Accident:	07/10/2019		

Global Sum Settlement :	☒ [X]	Yes	☐ []	No	
Repair Estimate	:	\$	20,668.12		
Final Repair Cost	:	\$	7,330.00		
Loss of Use	:	\$			8.00 days at \$60.00 per day
Rental (if any)	:	\$			days
LTA / GIA Search Fee	:	\$			
Others:	:	\$			
	:	\$			
Final Settlement Sum (Global Sum)	:	\$	7,330.00		

Is Third Party Workshop GIA Registered? ☐ [] YES ☒ [X] NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____ 100 ____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Fastech Auto Pte Ltd	:	7,330.00
2)		:	
3)		:	

JOANNE LEE KHANG MIN

07 Feb

2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19017967/UHA3Q2

Date: 07/02/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant

Vehicle No : SLT7762R

Insured Vehicle No : SDB1089E

Date of Loss: 07/10/2019

Nature of Claim: TP

Claim No: 1856303831SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLT7762R

Make & Model: HONDA VEZEL, 1.5 HYBRID X (A)

Engine No: LEB5963752

Reg. Date: 10/11/2017 (Man. Year: 2017)

Chassis No: RU31263732

Colour: Black

Odometer: 51559 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size:

215/60 R16

Front Left Side: Dunlop 7 mm

Rear Left Side:

Dunlop 7 mm

Front Right Side: Dunlop 7 mm

Rear Right Side:

Dunlop 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,026.00	5,822.88	8,203.12	58.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,290.00	2,180.00	3,110.00	58.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,316.00	8,002.88	11,313.12	58.57
Approved Total (Overridden) (S\$)		6,400.00		
(S\$)	19,316.00	6,400.00	12,916.00	66.87
+ GST 7.00/7.00% (S\$)	1,352.12	448.00	904.12	66.87
Nett Amount (S\$)	20,668.12	6,848.00	13,820.12	66.87
+ Loss of Use (8.0 x S\$60.00/day) (S\$)		480.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		7,330.00		
Global Sum Settlement (S\$)		7,330.00		

INSPECTION

Date of Assignment: 11/10/2019

Date Inspected: 11/10/2019 Inspected At:

Fastech Auto Pte Ltd (HQ)

1 Kaki Bukit Ave 6, #01-46/48/50

Autobay

Singapore 417883

Estimated Period of Repair: 6.0 days

Adjuster: MARCUS CHUA**Manager:** VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Necessary	121.30 F	*121.30 FL
2	1		*TAILGATE	Badly Dented	1,100.90 F	*953.00 FL
3	1		*TAILGATE OUTER HANDLE GARNISH	Cracked	285.30 F	*285.30 FL
4	1		*TAILGATE H LOGO	Necessary	35.80 F	*35.80 FL
5	1		*TAILGATE REFLECTORS	O/S Cut	560.00 F	*280.00 FL
6	1		*TAILGATE VEZEL EMBLEM	Necessary	56.20 F	*56.20 FL
7	1		*TAILGATE INNER LOCK	Twisted	198.50 F	*198.50 FL
8	1		*TAILGATE LOCK STRIKER	Not Necessary	25.50 F	*- FL
9	1		*TAILGATE INNER TRIM BOARD	Deformed / Cracked	321.70 F	*321.70 FL
10	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 F	*50.00 FL
11	1		*TAILGATE WEATHERSTRIP	Twisted	135.70 F	*135.70 FL
12	1		*TAILGATE KEYLESS SENSOR	Not Necessary	180.00 F	*- FL
13	1		*REAR BUMPER CENTRE	Distorted	762.70 F	*762.70 FL
14	1		*REAR BUMPER SIDES	O/S Torn	470.20 F	*235.10 FL
15	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	70.40 F	*- FL
16	2		*REAR BUMPER SCREW SPACERS	Not Necessary	24.00 F	*- FL
17	1		*REAR BUMPER REFLECTORS	O/S Cracked	302.40 F	*151.20 FL
18	1		*TAILLAMPS	O/S Cracked	921.20 F	*460.60 FL
19	2		*TAILLAMP HOUSING PANELS	Repair	390.00 F	*- FL
20	1		*REAR END PANEL	Badly Dented	514.00 F	*514.00 FL
21	1		*REAR END PANEL TOP GARNISH	Twisted	125.00 F	*125.00 FL
22	1		*REAR BUMPER LOWER DIFFUSER	Distorted	348.20 F	*348.20 FL
23	1		*SET REAR BUMPER LOWER DIFFUSER CLIPS	Necessary	50.00 F	*50.00 FL
24	1		*REAR EXHAUST	Repair	899.20 F	*- FL
25	2		*REAR EXHAUST MOUNTINGS	Not Necessary	90.00 F	*- FL
26	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	98.30 F	*- FL
27	1		*REAR FENDER INNER TRIMS	O/S Cracked	590.60 F	*295.30 FL
28	1		*SET REAR FENDER INNER TRIM CLIPS	Not Necessary	50.00 F	*- FL
29	1		*REAR FENDER OUTER GARNISH	O/S Torn	391.60 F	*195.80 FL
30	1		*REAR FLOOR PANEL	Repair	912.30 F	*- FL
31	1		*REAR FLOOR PANEL TOP BOARD	Torn	685.00 F	*415.00 FL
32	1		*REAR FLOOR PANEL TOP TRAY	Cracked	2,200.00 F	*488.20 FL
33	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
34	1		*REAR REVERSE CAMERA	Shorted	500.00 FS	*350.00 FS
35	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
36	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
37	1		*REAR FLOOR PANEL INSULATOR	Not Necessary	180.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	14,026.00	7,118.60
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	1,295.72

Total Parts (\$\$)	14,026.00	5,822.88
--------------------	-----------	----------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	80.00	30.00
2	TO DISMANTLE & REPLACE REVERSE SENSOR	New	80.00	50.00
3	TO TRANSFER TAILGATE MECHANISM	New	100.00	60.00
4	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	120.00
5	TO DISMANTLE & REFIX SEAT ,CUSHION UPHOLSTERY	New	150.00	80.00
6	TO DISMANTLE & REPLACE REAR EXHAUST	New	100.00	0.00
7	TO SPRAY RUST PROOFING	New	150.00	60.00
8	TO MOUNT VEHICLE ON CAR O-LINER	New	380.00	0.00
9	TO DISMANTLE & REFIX PETROL TANK	New	100.00	0.00
10	LABOUR FOR PANEL BEATING ,CUT ,WELD ,STRAIGHTEN & REPLACING PARTS	New	2,000.00	700.00
11	TO PUTTY & SPRAY PAINTING	New	2,000.00	1,080.00
Gross Labour Cost (\$\$)			5,290.00	2,180.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >