

INS. CASE OWNER:

MingYao.Lee

CC6/AIG19017972/Uda3

LKK:

IDAC:

ASSIGNMENT

Surveyor:

MARCUS

DOI: 11/10/2019

Date / Time: 11/10/2019

Registered in Merimen: 11/10/2019

Pre-assign / CCU / FTE



Insured Vehicle No. SLA 318L

Name of Insured CHUA LAY TIN

Insured Tel No. HP:

Excess Sec II :SS D.O.A: 10/10/2019

Is driver the owner? (YES / ☒ NO) Nature of Accident:

If NO, Driver Name / Age: SEAH YIEN CHIONG

Driver Tel No.: +65-96470108 (V/L: ☒ YES / NO)

Claim No.:

Policy No. 2100449854

Make / Model: MERCEDES-BENZ GLE 400

Place of Accident: RAFFLES AVE

OI GIA REPORT: ☒ YES NO ; TP GIA REPORT: ☒ YES NO

Insured Liability: % Final ? Yes / No

SLV 1580C



INSRS:
WSP: SPECIALISTS
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time	SLV 1580C - X	SLA 318L - X	STAGE	DATE / PIC
14/10/2019	Kindly confirm correct DOA as OI confirm DOA as 10/10/2019 but TP stated DOA as 9/10/2019.		Non-Reporting ltr (1st):	
			Non-Reporting ltr (2nd):	
			Non-Reporting ltr (Final):	
			Notification ltr (if non-pickup):	
			Call OI	
			After call ltr to OI	
			Documentation Check List: Handler	Typist
			Notification ltr (if non-pickup)	☐
			After call ltr to OI	☒
			Authorisation To Act:	☒
			Release Voucher:	☒
			Final Repair Bill:	☒
			Car Rental Invoice:	☒
			Towing Invoice	☐
			LTA / GIA:	☒
			Medical Bill:	☐
			PDR:	☐
			Mandate/Reject Instruction:	☐
			LOD	☒
			Payment Breakdown Form:	☐
			Post-Repair Photos:	☐
			Others:	☐

PRELIMINARY ADVICE	Date/Time:	Sent By:
--------------------	------------	----------

FINALIZATION	Date/Time:	Confirm with:	Confirm by:
--------------	------------	---------------	-------------

Repair Cost:	SS	(days) Reduction:	%	Email ☐	Call ☐
--------------	----	--------------------	---	--------------------------------	-------------------------------

FINAL SETTLEMENT	Date/Time: 2/12/19	Confirm with: Karen Ong	Email ☒	Call ☐
------------------	--------------------	-------------------------	---	-------------------------------

Final Liability:	% 100	(Agreed / Assessed) BOLA S/N No.: 27	If NO or B 28, Ass. Lia:		
------------------	-------	--------------------------------------	--------------------------	--	--

Repair Cost: (w/6h)	SS 5153.76				
---------------------	------------	--	--	--	--

Loss of Rental (LOR): (w/6h)	SS 1048.60	(7 days) x \$140			
------------------------------	------------	-------------------	--	--	--

Loss of Use (LOU):	SS -	(\$ x days)			
--------------------	------	-------------	--	--	--

Loss of Income (LOI):	SS -	(\$ x days)			
-----------------------	------	-------------	--	--	--

LOR only ☒	LOU only ☐	LOR + LOU ☐	LOR + LOI ☐	[Tick only one]	
--	-----------------------------------	------------------------------------	------------------------------------	-----------------	--

GIA/LTA Search:	SS 2.00				
-----------------	---------	--	--	--	--

Medical:	SS -				
----------	------	--	--	--	--

Disbursement:	SS -	(e.g. Tow/ Independent)			
---------------	------	--------------------------	--	--	--

Legal Cost	SS -				
------------	------	--	--	--	--

Total:	SS 6204.36	Global Sum SS: 6200.00			
--------	------------	------------------------	--	--	--

FINAL PAYMENT	Date/Time:	Confirm with:	Email ☐	Call ☐
---------------	------------	---------------	--------------------------------	-------------------------------

Payee 1:	SS 6200.00	Name 1: Specialists Motor Pte Ltd			
----------	------------	-----------------------------------	--	--	--

Payee 2: (Strike if N.A.)	SS	Name 2:			
---------------------------	----	---------	--	--	--

Payee 3: (Strike if N.A.)	SS	Name 3:			
---------------------------	----	---------	--	--	--

COPY SENT
2/12/19

- 1) Claim status: Normal/Reject/Private Settle
- 2) Report Format: TP
- 3) Survey fee: \$320

A14
ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MVTo inspect Vehicle No: SLV 1580Cat Workshop m/s Splint.

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$110k.

IDAC Accident Report: _____ Consistent? : Yes or No

G/A / PR Seen: 2 Consistent? : Yes or NoEst. Repairs: 5 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS LTA 60490

Date: _____ Person Contacted: _____

Date / Time Action / Instruction Rep 12P/P - \$4816.60 (Red \$6197.10 / 567.)Veh No: SLV 1580C Yr Regn: 12 17

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CAMake: Toyota harrier C.C. 1988Colour: Black A/C: Insured / Std / NI / NASp. Reading: 35963 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 25U 60 00 85 310

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Good / Jammed / Leaked / Burnt orBrake: Good / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: 225/55-R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: _____ Rear: _____

R/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 9/10/19 D.O.L. 11/10/19

Survey held at: _____

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Data/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

Days Of Repair:

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

1) _____
Date/Time, File Return to?

2) _____

Add Fee: ☐ : Site Insp (\$ _____) ☐ : S + R6 (\$ _____)☐ : Interview (\$ _____) Photos☐ : Tech. Invs (\$ _____) Others☐ : Weekend (\$ _____)

Report Format: _____

Lump Sum / I.B.I: (\$ _____)

TOTAL

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SLV1580C/1910136

11th October 2019

The Manager
Motor Claim Dept.
AIG Asia Pacific Insurance Pte Ltd
CHARTIS Building
78 Shenton Way #07-16
Singapore 079120

2/7 \$ 4816.60

Not Attached
The, 6 set up
11/10/19
54.

Date of Accident : 09th October 2019
Location : Infront Esplanade Drive Traffic Junction
Third Party Claim Vehicle No : SLA 318 L
Repair Cost For Vehicle No : SLV 1580 C (Toyota Harrier)

Estimate Supply of Parts & Labours

No.	Particulars	Qty	Price	Amounts
1	Rear boot cover <i>Body</i>	1	1,380.40	\$ 1,380.40 ✓
2	Rear boot cover weather strip <i>Tw</i>	1	269.70	\$ 269.70 ✓
3	Rear boot cover emblem (logo) <i>Rec</i>	1	85.60	\$ 85.60 ✓
4	Rear boot cover emblem (harrier) <i>Rec</i>	1	98.40	\$ 98.40 ✓
5	Rear boot cover lock <i>su</i>	1	360.50	\$ 360.50 ✗
6	Rear boot cover lamp LH & RH <i>17</i>	2	350.60	\$ 701.20 ✗
7	Rear windscreen glass <i>17</i>	1	1,190.50	\$ 1,190.50 ✗
8	Rear windscreen moulding (low) <i>rec</i>	1	120.00	\$ 120.00 ✓
9	Rear windscreen moulding (side) LH & RH <i>rec</i>	2	110.50	\$ 221.00 ✓
10	Rear bumper fascia <i>to be</i>	1	1,088.50	\$ 1,088.50 ✓
11	Rear bumper clips <i>rec</i>	1 set	85.00	\$ 85.00 ✓
12	Rear bumper retainer LH & RH <i>17</i>	2	108.60	\$ 217.20 ✗
13	Rear bumper sponge <i>su</i>	1	149.70	\$ 149.70 ✗
14	Rear bumper lower lip <i>re</i>	1	219.70	\$ 219.70 ✓
15	Rear bumper sensor <i>su</i>	1	228.50	\$ 228.50 ✗
16	Rear end panel <i>2</i>	1	519.30	\$ 519.30 ✗
17	Rear end panel garnish <i>tw</i>	1	200.50	\$ 200.50 ✓
18	Rear end panel garnish clips <i>17</i>	1 set	88.00	\$ 88.00 ✗
				\$ 7,223.70
19	Rear windscreen sealant (s/net) <i>rec</i>	1	60.00	\$ 60.00 40
20	Rear end panel sensor (s/net) <i>17</i>	1	80.00	\$ 80.00 ✗
21	Rear number plate (s/net) <i>scr</i>	1	50.00	\$ 50.00 40
				\$ 7,413.70

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SLV1580C/1910136

11th October 2019

Balance b/f

\$ 7,413.70

Labour Charges :-

Cut out, renew, knocking & welding rear boot cover, rear bumper fascia, rear end panel, remove & install all damage parts, straighten & re-align body

Amounts
\$ 1,700.00 *510*

To dismantle & install rear windscreen glass

\$ 140.00 *120*

Remove & install rear bumper sensor

\$ 80.00 *50*

Spray painting on damage parts

\$ 1,300.00 *1000*

Tuff-kote on damage parts

\$ 80.00 *50*

Remove & re-fix tail gate board, rear boot garnish, rear wiper motor, trimming, furnisher, carpets & etc

\$ 140.00 *80*

Remove & re-fix rear boot wiring, check lighting after repair

\$ 160.00 *60*

Labour Charge

\$ 3,600.00

Total Amount

\$ 7,413.70

GST will be reflected in the final bills.

Notes : -Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs of repairs, loss of use and storage.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Signed by Repairer

P - 3768.80
252
P - 2826.60
S.W - 80.00
L - 1910.00
4816.60

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	348K
Vehicle Details	
Vehicle No.:	SLV1580C
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Oct 2019
Vehicle Make:	TOYOTA
Vehicle Model:	HARRIER ELEGANCE 2.0 A
Primary Colour:	Black
Manufacturing Year:	2016
Engine No.:	3ZRB845705
Chassis No.:	ZSU600085310
Maximum Power Output:	111.0 kW (148 bhp)
Open Market Value:	\$30,254.00
Original Registration Date:	22 Dec 2017
First Registration Date:	22 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$29,356.00 14678
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Dec 2027
PARF Rebate Amount:	\$22,017.00
Intended COE Rebate Details	
COE Expiry Date:	21 Dec 2027
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$48,011.00
COE Rebate Amount:	\$38,473.00
Total Rebate Amount:	\$60,490.00

The information contained herein is correct as at 14 Oct 2019

OK



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Jun 2015 Volvo S60 T5 Drive-E (2.0L)



Low Mileage Well Maintained
Full Specification Sport Sedan
For The Family.
Direct Owner StarAd



Post an Ad Advertiser Login Ways of Selling

Browse by Category ▼

« Back (1 2 3) Next »

Sort by Date Posted

46 vehicles

harrier

Advanced Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh T
Search Selection	harrier	Any	Any	2017	Any	Any	
	Toyota Harrier 2.0A Elegance	\$101,188	\$11,710 /yr	17-Feb-2017	1,986 cc	64,000 km	
Good Fuel Consumption. Regular Services By Reputable Workshop. 90% Parked Indoor. Looking For A New Owner For My Beloved SUV. To Dealer : Call Only If You Have Buyer Or Willing To Offer Near My Asking. Thanks.							
Posted: 14-Oct-2019	Tags: 2017 Toyota Harrier, 2017 toyota harrier, Toyota Harrier, toyota harrier, Toyota, Harrier, harrier, Used Toyota						
	Toyota Harrier 2.0A Premium Panoramic	\$107,999	\$12,050 /yr	17-Apr-2017	1,986 cc	71,888 km	
Popular Toyota Luxurious SUV, Huge And Spacious, Comfortable Drive, Safe And Reliability. 1 Owner, Excellent Condition, Well Maintained Interior And Exterior, Flexible Bank/In House Loan Available,Buy With A Peace Of Mind. Trade In Welcome, Come View To Believe, View...							
Posted: 13-Oct-2019	Tags: 2017 Toyota Harrier, 2017 toyota harrier, Toyota Harrier, toyota harrier, Toyota, Harrier, harrier, Used Toyota						
	Toyota Harrier 2.0A M-Grade Turbo	\$114,800	\$12,170 /yr	10-Oct-2017	1,998 cc	31,500 km	
1 Owner! Agent Unit With 5 Years Borneo Warranty! Excellent Condition. Accident Free. Bank Loan In-house Loan Available. Trade In Welcome.							
Posted: 13-Oct-2019	Tags: 2017 Toyota Harrier, 2017 toyota harrier, Toyota Harrier, toyota harrier, Toyota, Harrier, harrier, Used Toyota						
	Toyota Harrier 2.0A G-Grade Turbo	\$122,800	\$12,630 /yr	22-Dec-2017	1,998 cc	20,700 km	
Genuine Low Mileage. 1 Careful Owner. Borneo Unit With Warranty. Not To Be Missed. Buy With An Added Peace Of Mind From Vantage Pre-Owned, A Member Of The Sime Darby Group. Complete With A Comprehensive 72 Points Check. Call Now For An Exclusive Viewing!							
Vantage Pre-Owned							
Posted: 13-Oct-2019	Tags: 2017 Toyota Harrier, 2017 toyota harrier, Toyota Harrier, toyota harrier, Toyota, Harrier, harrier, Used Toyota						



Why Toyota Harrier is the best SUV choice

SUVs are the common choice for practicality. If you are looking for one, you don't need to look further than the Harrier. Here's five reasons so.

[Read this article](#)

Compare

ta Harrier 2.0A Premium \$108,000 \$12,010 /yr 05-Apr-2017 1,986 cc 56,000 km

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SLV1580C/1910136

11th October 2019

The Manager
Motor Claim Dept.
AIG Asia Pacific Insurance Pte Ltd
CHARTIS Building
78 Shenton Way #07-16
Singapore 079120

Not Authorised
The 1st set up
11/10/19
S.H.

Date of Accident : 09th October 2019
Location : Infront Esplanade Drive Traffic Junction
Third Party Claim Vehicle No : SLA 318 L
Repair Cost For Vehicle No : SLV 1580 C (Toyota Harrier)

Estimate Supply of Parts & Labours

No.	Particulars	Qty	Price	Amounts
1	Rear boot cover <i>Body</i>	1	1,380.40	\$ 1,380.40 ✓
2	Rear boot cover weather strip <i>Trim</i>	1	269.70	\$ 269.70 ✓
3	Rear boot cover emblem (logo) <i>Rec</i>	1	85.60	\$ 85.60 ✓
4	Rear boot cover emblem (harrier) <i>Rec</i>	1	98.40	\$ 98.40 ✓
5	Rear boot cover lock	1	360.50	\$ 360.50 ?
6	Rear boot cover lamp LH & RH <i>1 1</i>	2	350.60	\$ 701.20 X
7	Rear windscreen glass <i>1 1</i>	1	1,190.50	\$ 1,190.50 X
8	Rear windscreen moulding (low) <i>Rec</i>	1	120.00	\$ 120.00 ✓
9	Rear windscreen moulding (side) LH & RH <i>Rec</i>	2	110.50	\$ 221.00 ✓
10	Rear bumper fascia <i>to Rec</i>	1	1,088.50	\$ 1,088.50 ✓
11	Rear bumper clips <i>Rec</i>	1 set	85.00	\$ 85.00 ✓
12	Rear bumper retainer LH & RH <i>1 1</i>	2	108.60	\$ 217.20 X
13	Rear bumper sponge	1	149.70	\$ 149.70 ?
14	Rear bumper lower lip <i>Rec</i>	1	219.70	\$ 219.70 ✓
15	Rear bumper sensor	1	228.50	\$ 228.50 ?
16	Rear end panel	1	519.30	\$ 519.30 ?
17	Rear end panel garnish	1	200.50	\$ 200.50 ?
18	Rear end panel garnish clips <i>1 1</i>	1 set	88.00	\$ 88.00 X
				\$ 7,223.70
19	Rear windscreen sealant (s/net) <i>Rec</i>	1	60.00	\$ 60.00 40
20	Rear end panel sensor (s/net)	1	80.00	\$ 80.00 ?
21	Rear number plate (s/net) <i>Scr</i>	1	50.00	\$ 50.00 40
				\$ 7,413.70

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SLV1580C/1910136

11th October 2019

Balance b/f

\$ 7,413.70

Labour Charges :-

Amounts

Cut out, renew, knocking & welding rear boot cover, rear bumper fascia, rear end panel, remove & install all damage parts, straighten & re-align body

\$ 1,700.00 ?

To dismantle & install rear windscreen glass

\$ 140.00 120

Remove & install rear bumper sensor

\$ 80.00 50

Spray painting on damage parts

\$ 1,300.00 1000

Tuff-kote on damage parts

\$ 80.00 50

Remove & re-fix tail gate board, rear boot garnish, rear wiper motor, trimming, furnisher, carpets & etc

\$ 140.00 80

Remove & re-fix rear boot wiring, check lighting after repair

\$ 160.00 60

Labour Charge

\$ 3,600.00

Total Amount

\$ 7,413.70

GST will be reflected in the final bills.

Notes : -Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs of repairs, loss of use and storage.

LKK Auto Consultants hence notify the Repairer of the following:

- To remedy before/after spray painting
- To display damaged part(s) during recovery
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be recognised and subject to final approval from Insurance Company

Consent by Repairer:

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Oct 2019 Edit Reg		11 Oct 2019 00:00 Edit Adj Rpt	S\$4,816.60 Edit Estimates	S\$4,816.60 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	Chua Lay Tin, ID: -		
Main Claimant:	ACE DRIVE PTE LTD, Co. Reg. No.: 201004348K		
Vehicle Reg. No.:	SLV1580C	Date of Loss:	10/10/2019 11:00 - :59 [21 Months and 18 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 4747088226SG	Policy/Cover Note No.:	2100449854 (Comprehensive) Coverage: 01/02/2019 - 31/01/2020
Vehicle Reg. No. (Insured):	SLA318L	Policy No. (Claimant):	VFX/P1861952
	Excess:		
Repairer:	Specialists Motor Pte Ltd (HQ) Blk 3018A Ubi Road 1, #01-24/25/26, 408711 Ubi - Tel: 6747 2112		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@aig.com		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 22/10/2019]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AIG_SG_EXPRESS (29/11/2019): Alert - Adj Mandate Approved (S\$6204.36) - SLV1580C - Claim Handler: Lee, Ming-Y...
- AIG_SG (14/10/2019): confirm DOA

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLV1580C (4747088226SG)
[SLA318L]
TP
ACE DRIVE PTE LTD
Oct 10 2019 11:00AM
[Chua Lay Tin]
Specialists Motor Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Letters/Correspondences															1 per page		☒			
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print			
1	(Draft)		Third Party Express Settlement – Payment Breakdown													Edit				
Assessment Reports															1 per page		☒			
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print			
1	13/11/19 12:32		Adjuster Immediate Advice													Load HTM				
Photos/Images															3 per page		☒			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print				
1	11/10/19 17:43	Chassis Number													Load JPG	☒				
2	11/10/19 17:43	Odometer Reading													Load JPG	☒				
3	11/10/19 17:43	General View													Load JPG	☒				
4	11/10/19 17:43	General View													Load JPG	☒				
5	11/10/19 17:43	General View													Load JPG	☒				
6	11/10/19 17:43	General View													Load JPG	☒				
7	11/10/19 17:43	General View													Load JPG	☒				
8	11/10/19 17:43	General View													Load JPG	☒				
9	11/10/19 17:43	General View													Load JPG	☒				
10	11/10/19 17:43	General View													Load JPG	☒				
11	11/10/19 17:43	General View													Load JPG	☒				
12	11/10/19 17:43	General View													Load JPG	☒				
13	11/10/19 17:43	General View													Load JPG	☒				
14	11/10/19 17:43	General View													Load JPG	☒				
15	11/10/19 17:43	General View													Load JPG	☒				
16	11/10/19 17:43	General View													Load JPG	☒				
17	11/10/19 17:43	General View													Load JPG	☒				
18	11/10/19 17:43	General View													Load JPG	☒				
19	11/10/19 17:43	General View													Load JPG	☒				
20	11/10/19 17:43	General View													Load JPG	☒				
21	11/10/19 17:43	General View													Load JPG	☒				
22	11/10/19 17:43	General View													Load JPG	☒				
23	11/10/19 17:43	General View													Load JPG	☒				
24	11/10/19 17:43	General View													Load JPG	☒				
25	11/10/19 17:43	General View													Load JPG	☒				
26	11/10/19 17:43	General View													Load JPG	☒				
27	11/10/19 17:43	General View													Load JPG	☒				
28	11/10/19 17:43	General View													Load JPG	☒				
29	11/10/19 17:43	General View													Load JPG	☒				
30	11/10/19 17:43	General View													Load JPG	☒				
31	11/10/19 17:43	General View													Load JPG	☒				
32	11/10/19 17:43	General View													Load JPG	☒				
33	11/10/19 17:43	General View													Load JPG	☒				
34	11/10/19 17:43	General View													Load JPG	☒				
35	11/10/19 17:43	General View													Load JPG	☒				
36	11/10/19 17:43	General View													Load JPG	☒				

Letters/Correspondences				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
37	11/10/19 17:43	General View		Load JPG	☒
38	11/10/19 17:43	General View		Load JPG	☒
39	11/10/19 17:43	General View		Load JPG	☒
40	11/10/19 17:43	General View		Load JPG	☒
41	11/10/19 17:43	General View		Load JPG	☒
42	11/10/19 17:43	General View		Load JPG	☒
43	11/10/19 17:43	General View		Load JPG	☒
44	24/10/19 09:25	Reinspection Photo		Load JPG	☒
45	24/10/19 09:25	Reinspection Photo		Load JPG	☒
46	24/10/19 09:25	Reinspection Photo		Load JPG	☒
47	29/10/19 17:32	General View		Load JPG	☒
48	29/10/19 17:32	General View		Load JPG	☒
49	29/10/19 17:32	General View		Load JPG	☒
50	29/10/19 17:33	General View		Load JPG	☒
51	29/10/19 17:33	General View		Load JPG	☒
52	29/10/19 17:33	General View		Load JPG	☒
53	29/10/19 17:33	General View		Load JPG	☒
54	29/10/19 17:33	General View		Load JPG	☒
Documentation				1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	11/10/19 16:19	TP GIA REPORT		Load PDF	
2	14/10/19 17:47	TP GIA REPORT (AMENDED)		Load PDF	
3	15/10/19 16:16	TP ESTIMATE - MARKED		Load PDF	
4	13/11/19 11:46	LOD		Load PDF	
5	13/11/19 11:46	RENTAL		Load PDF	
6	13/11/19 11:46	GIA SEARCH FEE		Load PDF	
7	10/12/19 09:00	WORKSHOP INVOICE		Load PDF	
8	10/12/19 09:00	AUTHORISATION TO ACT FORM		Load PDF	
9	10/12/19 09:00	Release Voucher		Load PDF	
10	10/12/19 09:01	LETTER TO OI		Load PDF	
No	Finalized On	ATG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	14/10/19 10:59	OI GIA REPORT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLA318L (Insd veh)	Model:	TOYOTA HARRIER 2.0
	SLV1580C (TP veh)		ELEGANCE (A)
Date of Accident:	10/10/2019		

Global Sum Settlement	:	☒ Yes	☐ No
Repair Estimate	:	\$	11,784.66
Final Repair Cost	:	\$	6,200.00
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	7 days
LTA / GIA Search Fee	:	\$	
Others:	:	\$	
	:	\$	
Final Settlement Sum (Global Sum)	:	\$	6,200.00

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____ 100 ____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Specialists Motor Pte Ltd	:	\$ 6,200.00
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

10 Dec
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19017972/UDA3Q2

Date: 10/12/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100449854
Claimant
Vehicle No : SLV1580C **Insured Vehicle No :** SLA318L
Date of Loss: 10/10/2019 **Nature of Claim:** TP **Claim No:** 4747088226SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLV1580C**
 Make & Model: TOYOTA HARRIER, 2.0 Elegance (A) Engine No: 3ZRB845705
 Reg. Date: 22/12/2017 (Man. Year: 2016) Chassis No: ZSU600085310
 Colour: Black Odometer: 35963 km
 Engine Capacity: 1986 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 R17 Rear Tyre Size: 225/55 R17
 Front Left Side: Dunlop 7 mm Rear Left Side: Dunlop 7 mm
 Front Right Side: Dunlop 7 mm Rear Right Side: Dunlop 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,413.70	2,908.60	4,507.10	60.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,600.00	1,910.00	1,690.00	46.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	11,013.70	4,816.60	6,197.10	56.27
+ GST 7.00/7.00% (S\$)	770.96	337.16	433.80	56.27
Nett Amount (S\$)	11,784.66	5,153.76	6,630.90	56.27
+ Car Rental (7.0 x S\$140.00/day + 7.00% GST) (S\$)		1,048.60		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		6,204.36		
Global Sum Settlement (S\$)		6,200.00		

INSPECTION

Date of Assignment: 11/10/2019
 Date Inspected: 11/10/2019 Inspected At: Specialists Motor Pte Ltd (HQ)
 Blk 3018A Ubi Road 1, #01-24/25/26
 Singapore 408711
 Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT COVER	Badly Dented	1,380.40 F	*1,380.40 FL
2	1		*REAR BOOT COVER WEATHER STRIP	Twisted	269.70 F	*269.70 FL
3	1		*REAR BOOT COVER EMBLEM (LOGO)	Necessary	85.60 F	*85.60 FL
4	1		*REAR BOOT COVER EMBLEM (HARRIER)	Necessary	98.40 F	*98.40 FL
5	1		*REAR BOOT COVER LOCK	Serviceable	360.50 F	*- FL
6	2		*REAR BOOT COVER LAMP LH & RH	Not Necessary	701.20 F	*- FL
7	1		*REAR WINDSCREEN GLASS	Not Necessary	1,190.50 F	*- FL
8	1		*REAR WINDSCREEN MOULDING (LOW)	Necessary	120.00 F	*120.00 FL
9	2		*REAR WINDSCREEN MOULDING (SIDE) LH & RH	Necessary	221.00 F	*221.00 FL
10	1		*REAR BUMPER FASCIA	Dented / Deformed	1,088.50 F	*1,088.50 FL
11	1		*SET REAR BUMPER CLIPS	Necessary	85.00 F	*85.00 FL
12	2		*REAR BUMPER RETAINER LH & RH	Not Necessary	217.20 F	*- FL
13	1		*REAR BUMPER SPONGE	Serviceable	149.70 F	*- FL
14	1		*REAR BUMPER LOWER LIP	Deformed	219.70 F	*219.70 FL
15	1		*REAR BUMPER SENSOR	Serviceable	228.50 F	*- FL
16	1		*REAR END PANEL	Repair	519.30 F	*- FL
17	1		*REAR END PANEL GARNISH	Twisted	200.50 F	*200.50 FL
18	1		*SET REAR END PANEL GARNISH CLIPS	Not Necessary	88.00 F	*- FL
19	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*40.00 FS
20	1		*REAR END PANEL SENSOR	Not Necessary	80.00 FS	*- FS
21	1		*REAR NUMBER PLATE	Scratched	50.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,413.70	3,848.80
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	942.20

Total Parts (\$\$)	7,413.70	2,906.60
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CUT OUT ,RENEW ,KNOCKING & WELDING REAR BOOT COVER,REAR BUMPER FASCIA ,REAR END PANEL,REMOVE & INSTALL ALL DAMAGE PARTS ,STRAIGHTEN & RE-ALIGN BODY	New	1,700.00	550.00
2	TO DISMANTLE & INSTALL REAR WINDSCREEN GLASS	New	140.00	120.00
3	REMOVE & INSTALL REAR BUMPER SENSOR	New	80.00	50.00
4	SPRAY PAINTING ON DAMAGE PARTS	New	1,300.00	1,000.00
5	TUFF-KOTE ON DAMAGE PARTS	New	80.00	50.00
6	REMOVE & RE-FIX TAIL GATE BOARD ,REAR BOOT GARNISH ,REAR WIPER MOTOR ,TRIMMING ,FURNISHER ,CARPETS & ETC	New	140.00	80.00
7	REMOVE & REFIX REAR BOOT WIRING ,CHECK LIGHTING AFTER REPAIR	New	160.00	60.00
Gross Labour Cost (S\$)			3,600.00	1,910.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >