

# SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SLV1580C/1910136

11<sup>th</sup> October 2019

The Manager  
Motor Claim Dept.  
AIG Asia Pacific Insurance Pte Ltd  
CHARTIS Building  
78 Shenton Way #07-16  
Singapore 079120

Not Attached  
dla  
The 1st set up only  
11/10/19  
Sdy.

Date of Accident : 09<sup>th</sup> October 2019  
Location : Infront Esplanade Drive Traffic Junction  
Third Party Claim Vehicle No : SLA 318 L  
Repair Cost For Vehicle No : SLV 1580 C (Toyota Harrier)

## Estimate Supply of Parts & Labours

No.	Particulars	Qty	Price	Amounts
1	Rear boot cover <i>300</i>	1	1,380.40	\$ 1,380.40 ✓
2	Rear boot cover weather strip <i>7m</i>	1	269.70	\$ 269.70 ✓
3	Rear boot cover emblem (logo) <i>new</i>	1	85.60	\$ 85.60 ✓
4	Rear boot cover emblem (harrier) <i>new</i>	1	98.40	\$ 98.40 ✓
5	Rear boot cover lock	1	360.50	\$ 360.50 ?
6	Rear boot cover lamp LH & RH <i>1 1</i>	2	350.60	\$ 701.20 X
7	Rear windscreen glass <i>1 1</i>	1	1,190.50	\$ 1,190.50 X
8	Rear windscreen moulding (low) <i>new</i>	1	120.00	\$ 120.00 ✓
9	Rear windscreen moulding (side) LH & RH <i>new</i>	2	110.50	\$ 221.00 ✓
10	Rear bumper fascia <i>new</i>	1	1,088.50	\$ 1,088.50 ✓
11	Rear bumper clips <i>new</i>	1 set	85.00	\$ 85.00 ✓
12	Rear bumper retainer LH & RH <i>1 1</i>	2	108.60	\$ 217.20 X
13	Rear bumper sponge	1	149.70	\$ 149.70 ?
14	Rear bumper lower lip <i>new</i>	1	219.70	\$ 219.70 ✓
15	Rear bumper sensor	1	228.50	\$ 228.50 ?
16	Rear end panel	1	519.30	\$ 519.30 ?
17	Rear end panel garnish	1	200.50	\$ 200.50 ?
18	Rear end panel garnish clips <i>1 1</i>	1 set	88.00	\$ 88.00 X
				\$ 7,223.70
19	Rear windscreen sealant (s/net) <i>new</i>	1	60.00	\$ 60.00 40
20	Rear end panel sensor (s/net)	1	80.00	\$ 80.00 ?
21	Rear number plate (s/net) <i>new</i>	1	50.00	\$ 50.00 40
				\$ 7,413.70

# SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SLV1580C/1910136

11<sup>th</sup> October 2019

Balance b/f

\$ 7,413.70

## Labour Charges :-

## Amounts

Cut out, renew, knocking & welding rear boot cover, rear bumper fascia, rear end panel, remove & install all damage parts, straighten & re-align body

\$ 1,700.00 ?

To dismantle & install rear windscreen glass

\$ 140.00 120

Remove & install rear bumper sensor

\$ 80.00 50

Spray painting on damage parts

\$ 1,300.00 1000

Tuff-kote on damage parts

\$ 80.00 50

Remove & re-fix tail gate board, rear boot garnish, rear wiper motor, trimming, furnisher, carpets & etc

\$ 140.00 80

Remove & re-fix rear boot wiring, check lighting after repair

\$ 160.00 60

Labour Charge

\$ 3,600.00

Total Amount

\$ 7,413.70

GST will be reflected in the final bills.

Notes : -Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs of repairs, loss of use and storage.

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Knownledged by Repairer