

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Elaine Cheong

Date: 14 Oct 2019

Preliminary Advice

Vehicle No	: SGK9789H	Accident Date	: 07/10/2019
Make	: BMW M140I	Policy No.	: DMPCSN1817531901
Assignment Date	: 11/10/2019	Excess	: S\$1,500.00
Date of Inspection	: 11/10/2019	Est. Duration of Repair	: 8.00
Inspection At	: BIS AUTOMOBILES PTE LTD (HQ) 30 TEBAN GARDENS CRESCENT SINGAPORE 608927		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	22,529.02
Revised Amount	:S\$	15,704.51
Check Items (Estimated)	:S\$	4,675.20
Total	:S\$	20,379.71
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	124,000.00
COE / PARF Rebate	:S\$	67,226.00
Salvage Value	:S\$	
Margin for Repair	:S\$	56,774.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :