



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

DESMOND KWANG

10/10/2019

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP ALG

Vic

Accident date: 09/10/2019

Estimated repair cost for vehicle no: SLG3712E HONDA CIVIC 1.5 TURBO '16

CHASSIS: MRHFC1660GT000107

S/n	Qty	Items	U/price	Amount
1	1	Front Bumper		\$579.50 +
2	10	Front Bumper Clip		\$65.00 +
3	1	Front R/H Bumper Side Retainer		\$22.00 +
5	1	Front R/H Headlamp		\$1,155.10 +
6	1	Front R/H Headlamp Lower Bracket		\$25.90 +
7	1	Front R/H Fender <i>Repair</i>		\$356.90 +
8	1	Front R/H Fender Cowling		\$62.00 +
9	8	Front R/H Fender Cowling Clip		\$52.00 +
10	1	Front R/H Fender Signal Lamp		\$38.50
12	1	Front R/H Rim <i>lt</i>		\$852.70 590 (sw)
13	1	Front R/H Tyre <i>Not New</i>		\$380.00 +
14	1	Front R/H Lower Arm <i>Best</i>		\$291.40 ✓
15	1	Front R/H Knuckle Arm <i>Best</i>		\$241.40 ✓
16	1	Front R/H Knuckle Arm Bearing <i>New</i>		\$190.60 ✓
17	1	Front R/H Shock Absorber <i>Best</i>		\$328.80 ✓
18	1	Front R/H Drive Shaft <i>New</i>		\$1,027.50 +
19	1	Front Steering Rack <i>New</i>		\$2,598.80 +
20	1	Front R/H Side Mirror Assembly <i>Damaged</i>		\$807.50 ✓
21	1	Front R/H Door <i>Dented</i>		\$1,024.70 ✓
22	2	Front R/H Door Hinge <i>New</i>	\$40.10	\$80.20 +
23	1	Front R/H Door Lock <i>Damaged</i>		\$272.30 ✓
24	1	Front R/H Door Weather Strip <i>New</i>		\$89.10 +
26	1	Front R/H Door Inner Trim Board <i>Cracked</i>		\$388.50 ✓
27	1	Front R/H Door Power Window Motor Assy <i>Damaged</i>		\$485.00 ✓
29	1	R/H Center Door Pillar <i>Repair</i>		\$711.60 +
30	1	R/H Rocker Panel <i>Repair</i>		\$502.70 +
31	1	R/H Rocker Panel Side Skirt <i>Cracked</i>		\$221.80 ✓

32	12	R/H Rocker Panel Side Skirt Clip	new	\$6.50	\$78.00	30
33	1	Rear R/H Door	Dented.		\$1,024.70	✓
34	2	Rear R/H Door Hinge	new	\$40.10	\$80.20	+
35	1	Rear R/H Door Lock	new		\$272.30	+
36	1	Rear R/H Door Weather Strip	new		\$89.10	+
37	2	Rear R/H Door Frame Sticker	new	\$38.30	\$76.60	✓
38	1	Rear R/H Door Inner Trim Board	new		\$411.00	+
39	1	Rear R/H Door Power Window Motor	new		\$455.00	+
41	1	Rear R/H Fender	new		\$961.00	+
42	1	Rear R/H Fender Glass Assy	new		\$233.60	+
44	1	Rear R/H Taillamp	new		\$323.10	+
45	1	Rear R/H Rim	new		\$852.70	50 (sn)
46	1	Rear R/H Tyre	new		\$380.00	+
47	1	Rear R/H Lower Arm	new		\$209.10	✓
48	1	Rear R/H Knuckle Arm	new		\$283.00	✓
49	1	Rear R/H Knuckle Arm Bearing	new		\$280.60	✓
50	1	Rear R/H Trailing Arm	new		\$221.90	✓
51	1	Rear R/H Shock Absorber	new		\$328.80	✓
52	1	Rear Bumper	new		\$657.50	+
53	10	Rear Bumper Clip	new	\$6.50	\$65.00	+


Subtotal :- \$20,134.70

6706.70

5365.36 sn 1100

Labour charges

To remove & refit cushion & trim board	\$380.00 *
To remove & refit front R/H door, lock, rubber, glass, regulator window motor & trim board	\$280.00 80
To remove & refit rear R/H door, lock, rubber, glass, regulator window motor & trim board	\$280.00 80
To remove & refit reverse sensor	\$100.00 *
To remove & refit front R/H undercarriage	\$380.00 220
To remove & refit drive shaft & steering rack	\$380.00 *
To remove & refit rear R/H undercarriage	\$380.00 220
To check whee alignment	\$380.00 80
To check wiring	2060 \$100.00 30
Tuff kote	\$150.00 50
Towing fee	\$100.00 *
Panel beating	\$1,800.00 700
Spray painting	\$2,000.00 1200



Subtotal :- \$6,710.00

Total:- \$26,844.70

total: 9125.36

L/S: 7.31c

08 Days

7.31c