

KCN

# COMFORTDELGRO ENGINEERING

Our Job Ref No 305340317  
Date : 12/10/19

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508989  
Fax: 6546 8156

## FINALIZATION FORM

To : LKK  
Attn : KALVIN  
: SHC 626J

Fax :

305333809 09/10/19

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: CHINA --- SLJ5150Y  
###
2. The finalized amount shall be:
 

|  |     |                             |
|--|-----|-----------------------------|
| (a) Spare Parts after List discount                  | ### | <u>\$0.00</u>               |
| (b) Labour Charges                                   | ### | <u>\$440.00</u>             |
| <b>Total for Part-By-Part Repair Cost</b>            |     | <u>\$440.00</u>             |
|  | ### |                             |
| (c) Lumpsum Repair (if applicable)                   |     |                             |
| Total for Lumpsum repair cost after Less: <u>20%</u> |     | <u>                    </u> |
| <b>Final Lumpsum Repair cost</b>                     |     | <u>                    </u> |


3. Estimated normal period for repairs: 2 working days


J

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature :   
Name : JUMANI  
Tel : 6214 8315  
Fax : 65468156

Signature :   
Name : Kalvin  
Date : 14/10/19

## For Official Use Only

| Item   | Amount | Document Attached Yes or No | Confirm By (Signature) | Remarks |
|--|--------|-----------------------------|------------------------|---------|
| 1. Rental Rate P/Day                                 |        | YES                         |                        |         |
| 2. Loss of Income Paid                               |        | N                           |                        |         |
| 3. Survey Fees                                       |        |                             |                        |         |
| 4. LTA Search Fee                                    | \$7.49 |                             |                        |         |
| 5. Medical Fees (on behalf of driver, if applicable) |        |                             |                        |         |
| 6. Overrun   |        |                             |                        |         |

Remarks:

\_\_\_\_\_  
\_\_\_\_\_

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 11.10.2019

Time: 17:36:54

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010070  
ADDRESS : CITYCAB PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65551188

JOB NO : 305340317  
REGN NO : SHC 626J  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : SONATA  
DATE OF REGN : 25.10.2012  
DATE/TIME IN : 10.10.2019 10:35  
ACCIDENT DATE : 09.10.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

SUB-TOTAL : 0.00

JOB NATURE

0000 PB PANEL BEATING 240.00

0001 SP SPRAYPAINT CHARGE 200.00

SUB-TOTAL : 440.00

TOTAL : 440.00

MVA NAME & SIGNATURE

DATE :

AUTHORISED : YES / NO

SURVEYOR NAME & SIGNATURE

DATE :

DATE 10/10/2019 11:33

China - 54  
19 11:33  
LDM

| Qty  | Parts Description/ Labour                     | Type | Unit Price | Amount        |
|--|---|------|------------|---------------|
|  | Rear Bumper X <del>As per repair</del> repair |      |            | \$ 578.40     |
|  | Rear Bumper Clip X m                          |      |            | \$ 22.00      |
|  | Rear Bumper Protector (RH) X Repair           |      |            | \$ 38.00      |
|  | SUB TOTAL                                     |      |            | \$ 638.40     |
|  | LESS 20%                                      |      |            | \$ 127.68     |
|  | DISCOUNTED TOTAL                              |      |            | \$ 510.72     |
|  | Rear Bumper Rubber Mat X m                    |      |            | \$ 50.00      |
|  |   |      |            | \$ 50.00      |
|  | Labour Charge                                 |      |            | 2%o           |
|  | Panel Beating                                 |      |            | \$ 300.00     |
|  | Spray Painting Charge                         |      |            | \$ 200.00 200 |
|  | Wiring Charge                                 |      |            | \$ 50.00 X m  |
|  | Remove/Refix Reverse Sensor                   |      |            | \$ 120.00 X m |
|  | TOTAL LABOUR                                  |      |            | \$ 670.00     |
|  | ESTIMATE TOTAL                                |      |            | \$ 1,230.72   |
| <p>Kalin LKKK</p> <p>10/10/19 1345 hr</p> <p>2 Days.</p> <p>V/S</p> <p>After Repair photo</p> <div style="border: 1px solid blue; padding: 5px;"> <p>LKK Auto Consultants hence notify the Rep-Owner of the following:</p> <ul style="list-style-type: none"> <li>To resurvey if there was spray painting</li> <li>To dis-assemble damaged parts during resurvey</li> <li>Third party survey is on a "Without Prejudice" basis</li> <li>No illegal modification(s) is allowed</li> <li>Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</li> </ul> <p>Acknowledged by Repairer</p> <p>Signature:</p> <p>Date:</p> </div> |   |      |            |               |
| This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.   |   |      |            |               |