

ASS. REC. BY:

REF: CS/FCI 19018053/Bqd382

Special Instruction:

Survey: Mr. Kim
CWS

ASSIGNMENT (Office)

From (Person): Karen Tan

of FCI

Date/Time: 12:27pm @ 14/10/19

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: 8ML 9642X

Insured: SHA 7846E

at Workshop w/ Teamwork Garage

Tel: 6844 2475

of 53 Ubi Ave 1 #01-24

Policy No:

Claim No: D19006536 MFSH

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A. 10/10/19

CA / REV / REP. / REV 24 HRS DS)

H.O.D. Endorsement:

Date/Time: 12:37pm @ 14/10/19

Person Contacted: Darren

Vehicle IN/OUT

Date/Time	Action/Instruction
	Johnnie ✓
	SHA 7846E X
	8ML 9642X X
25/10/19 @ 2:42pm	revised to Karen Tan by email.
4/11/19 @ 12:18pm	air line confirmed with Darren US \$12450, 7 days.
	Used \$20283.95, 62/10

ISS. REG. BY:

REF: FCI

ASSIGNMENT

From: _____ Date: 14/10/2019

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SML 9642X

at Workshop with: Deannick Garage

of 53 ubi Ave 1 #01-24

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 103,000/-

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 7-8 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SML 9642X yr Regn: 13/6/2019

Type: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or _____

Make: Mitsubishi Outlander cc 1998

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 7234 T/Radio: Insured / Std / NI / NA

Eng/No: 4J11AR9706

C/No: GF7W0601287

Gen. Cond: Good / ☒ Fair / ☐ Poor / ☐ BurntSteering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orMod: Nil / ☒ S/Rim / ☐ STD A/Rim or

Tyre Size: F: 225/55/18

R: 225/55/18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal. 7 mm R/Bal. 7 mm

L/Bal. 7 mm L/Bal. 7 mm

D.O.A. 10/10/19 D.O.L. 14/10/19

Survey held at: Deannick Garage

Des. of Damages: ☒ Frt / ☒ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

4/5 12,450/- 14/10/19 with 8 days repair

MV 103,000/-

PV 56,031/-

NV 46,969/-

RECEIVED 14 NOV 2019

Tee Lim Kue
17/10/19

Date/Time, File Pass to?



Preli. Report

1) 14/11 transfer



Final Report

Date/Time, File Return to?

2)

Days Of Repair: 7

Resurvey No. of Trip: 3

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Wheel end (\$)

Survey Fee:

Transportation:

S + RS \$1

Photo: 580

Other: 638

14/11/19

22X15 = 330

170 + 330

50

50 + 50 + 50

145

845

Rep. Form: 7P

Lump Sum / Fee: 12450

MOTOR SURVEY ASSIGNMENT

Date	11-10-2019	Our Ref No. D19006536MFSH
Accident Date	10-10-2019	Claim Type. Third Party
Insured Vehicle	SHA7846E	Third Party Vehicle. SML9642X
Survey Location	BLK 53 UBI AVE 1 #01-24 PAYA UBI INDUSTRIAL PARK	
Contact Person.	SHU SHAN	
Contact No.	68442475/ 0	Fax No. 68442474
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TEAMWORK GARAGE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

Shiau Chan (LKKAuto)

From: Darren <claims@teamworkgarage.com>
Sent: Monday, 11 November 2019 12:18 PM
To: TG Lim (LKK Auto)
Cc: Shiau Chan (LKKAuto)
Subject: RE: VEHICLE SML 9642X

Hi Mr Lim,

We confirmed COR @ \$12450 and DOR @ 7 Days

Darren
Teamwork Garage Pte Ltd
53 Ubi Avenue 1
#01-24 Paya Ubi Industrial Park
Singapore 408934
Tel: 68442475
Fax: 68442474

From: TG Lim (LKK Auto)
Sent: Thursday, 31 October 2019 9:22 AM
To: Darren
Cc: Shiau Chan (LKKAuto)
Subject: VEHICLE SML 9642X

WITHOUT PREJUDICE

Hi Darren,

We have changed the repair duration from 7 days to 8 days after much consideration.
In view of that, can we finalise this case at lump sum \$12,450.00 with 8 days for repair.

We hope you are agreeable with our offer.

Best Regards,
TG Lim | Automotive Assessor
LKK Auto Consultants
Phone: 6256 3561 | Email: TeowGuan@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Friday, 25 October 2019 2:42 PM
To: 'CWS Motor Claims'; assignments
Cc: 'Karen Tan'; SUR
Subject: RE: SURVEY ASSESSMENT - D19006536MFSH/1
Attachments: CSFC119018053Bqd3.pdf

Dear Karen,

Enclosed herewith preliminary advice of SML 9642X.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sjewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Monday, 14 October 2019 12:34 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Karen Tan' <karentan@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19006536MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Monday, 14 October 2019 12:27 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Karen Tan <karentan@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19006536MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19006535MFSH

Date: 25 October 2019

Our Ref: CS/FCI19018053/Bqd3

The Motor Claims Department
MS First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SML 9642X

Please be informed that we had conducted the inspection of the abovementioned vehicle on 14/10/2019 at the premises of M/s TEAMWORK GARAGE, and have the following to report:-

Workshop Estimate Amount	: S\$ 32,733.95
Revised Estimate Amount	: S\$ 15,591.20
"Check" Items Amount	: S\$ -
Market Value	: S\$ -
LTA Reimbursement Value	: S\$ -
Nett Value	: S\$ -

Description of Damage:
The vehicle sustained damages
at the front and rear portion.



Yours faithfully

Lim T.G.
Automotive Assessor

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	681D
Vehicle Details	
Vehicle No.:	SML9642X
Vehicle to be Exported:	No
Intended Deregistration Date:	17 Oct 2019
Vehicle Make:	MITSUBISHI
Vehicle Model:	OUTLANDER 2.0 CVT
Primary Colour:	Blue
Manufacturing Year:	2019
Engine No.:	4J11AR9706
Chassis No.:	GF7W0601287
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$19,919.00
Original Registration Date:	13 Jun 2019
First Registration Date:	13 Jun 2019
Transfer Count:	0
Actual ARF Paid:	\$19,919.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Jun 2029
PARF Rebate Amount:	\$14,939.00
Intended COE Rebate Details	
COE Expiry Date:	12 Jun 2029
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$42,564.00
COE Rebate Amount:	\$41,092.00
Total Rebate Amount:	\$56,031.00

The information contained herein is correct as at 17 Oct 2019

OK

Dep 9810/4R
818/mth

MV 103,000/2
PV 56,031/2
NV 46,969/2

Tam
17/10/19

Posted: 06-Oct-2019 Tags: 2018 Mitsubishi Outlander, 2018 mitsubishi outlander, Mitsubishi Outlander, mitsubishi outlander, Mitsubishi, Outlander, outlander, Used Mitsubishi



Mitsubishi Outlander 2.0A \$98,600 \$9,810 /yr 07-Nov-2018 1,998 cc 14,000 km SUV Available

5 Years Warranty From C&C. Recently Serviced. Special Model With Neatly Attached Accessory To Give The Outlander A Better Ride. Up To 90% Loan Of The Car Price With Interest Rates Starting From 2.28% Possible. Trade-In Welcome. Call Now To Book An Appointment...

COMING SOON

Posted: 03-Oct-2019 Tags: 2018 Mitsubishi Outlander, 2018 mitsubishi outlander, Mitsubishi Outlander, mitsubishi outlander, Mitsubishi, Outlander, outlander, Used Mitsubishi



Mitsubishi Outlander 2.0A Sunroof \$96,200 \$9,910 /yr 19-Apr-2018 1,998 cc 30,700 km SUV Available

Comes With 5 Years Agent Warranty For Peace Of Mind! Beautiful Grey Unit And Very Well Maintained. Stylish And Practical 7 Seater SUV Equipped With A 2.0L Engine. High Loan With Lowest Interest Rates From 2.28%. Trade-In Welcome. Call Now To Book An Appointment...

COMING SOON

Posted: 03-Oct-2019 Tags: 2018 Mitsubishi Outlander, 2018 mitsubishi outlander, Mitsubishi Outlander, mitsubishi outlander, Mitsubishi, Outlander, outlander, Used Mitsubishi



Mitsubishi Outlander 2.0A Sunroof - N.A 03-Aug-2018 1,998 cc - SUV SOLD

Comes With Agent Warranty Till Aug 2023 For Peace Of Mind! Stylish And Practical 7 Seater SUV Equipped With A 2.0L Engine Mated To A CVT Gearbox Ensuring You Sufficient Power For Your Daily Drive, Yet With Surefooted Stability Thanks To Selective 4WD! Split Fold R...

PREMIUM AD

Select By Performance Premium Selection

Posted: 29-Sep-2019 Tags: 2018 Mitsubishi Outlander, 2018 mitsubishi outlander, Mitsubishi Outlander, mitsubishi outlander, Mitsubishi, Outlander, outlander, Used Mitsubishi



Save on petrol with DBS Esso card!

Enjoy huge petrol savings of up to 21%, interest-free 0% Instalment Payment Plan for Motor Insurance and Road Tax, and 1-year annual fee waiver. Find out more

Find out more!



Mitsubishi Outlander 2.0A - N.A 21-May-2018 1,998 cc - SUV SOLD

Sporty Red Responsive 2.0 SUV, One Careful Owner, Agent Serviced, Under Agent Warranty, Excellent Condition, Do Not Miss, Viewing By Appointment, Call Now.

Posted: 25-Sep-2019 Tags: 2018 Mitsubishi Outlander, 2018 mitsubishi outlander, Mitsubishi Outlander, mitsubishi outlander, Mitsubishi, Outlander, outlander, Used Mitsubishi



Mitsubishi Outlander 2.0A Sunroof - N.A 23-Feb-2018 1,998 cc - SUV SOLD

1 Owner, C&C Unit, Warranty Till Feb 2023, 10 Yrs Engine Warranty. Luxury 7 Seater SUV, Low Mileage, Nice No.5777! Higher Spec Model Come With Original Body- Kit, Sun-Roof, Key-less Entry, Auto Start/Stop, Cruise Control, DVD Player, GPS, Bluetooth, 18" S/Rim, Ex...

Posted: 23-Sep-2019 Tags: 2018 Mitsubishi Outlander, 2018 mitsubishi outlander, Mitsubishi Outlander, mitsubishi outlander, Mitsubishi, Outlander, outlander, Used Mitsubishi



Mitsubishi Outlander 2.0A - N.A 06-Jun-2018 1,998 cc - SUV SOLD

Drive With Assurance! Fully Serviced By Agent, Still Under Warranty! 10 Years Engine Warranty! Genuine And Transparent! Flexible Bank/In House Up To 90% Loan \$85k All Our Quality Consignment Cars Are Selling At The Most Reasonable Price With A Peace Of Mind...

CarQuartz Singapore

Posted: 21-Sep-2019 Tags: 2018 Mitsubishi Outlander, 2018 mitsubishi outlander, Mitsubishi Outlander, mitsubishi outlander, Mitsubishi, Outlander, outlander, Used Mitsubishi



Mitsubishi Outlander 2.0A - N.A 10-Sep-2018 1,998 cc - SUV SOLD

1 Owner! 10 Years Engine And 5 Years Car Warranty From C&C. Just Serviced On 20th August At Agent. Stylish And Practical 7 Seater SUV Equipped With A 2.0L Engine Mated To A CVT Gearbox Ensuring You Sufficient Power For Your Daily Drive, Yet With Surefooted St...

PREMIUM AD

Roadlink Auto Pte Ltd

Posted: 20-Aug-2019 Tags: 2018 Mitsubishi Outlander, 2018 mitsubishi outlander, Mitsubishi Outlander, mitsubishi outlander, Mitsubishi, Outlander, outlander, Used Mitsubishi



Mitsubishi Outlander 2.0A - N.A 29-Mar-2018 1,998 cc - SUV SOLD

Special Offer 1.5% Interest Rate, 1 Owner, Luxury 7 Seaters 4WD SUV, Low Mileage Vehicle Warranty By C&C, Excellent Condition, Beautiful Red Exterior. Call/SMS/WhatsApp For Enquiries And Viewing Appointment.

Republic Auto

Posted: 11-Aug-2019 Tags: 2018 Mitsubishi Outlander, 2018 mitsubishi outlander, Mitsubishi Outlander, mitsubishi outlander, Mitsubishi, Outlander, outlander, Used Mitsubishi

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Cost Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

20 results/page

Home New Cars Used Cars Sell My Car Directory Products Insurance Article Forum Resources

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sports cars or stationwagons, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy us Compare nter Singapore, used outlander Singapore, used outlander, used vehicles Singapore or even buy used outlander Singapore. We have new car dealers comprising parallel

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	11/10/2019 11:17
Date Of Accident	10/10/2019 17:10
Exact Location Of Accident	BUANGKOK GREEN AFTER HOUGANG STREET 51
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SML9642X
Insured/Policyholder	
Name Of Registered Owner	BENJAMIN YOW THIAM HUI
NRIC No	S8935681D
Email Address	BYOW89@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97490014
Alternative Phone No	OTHERS-97490014

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	OUTLANDER-2.0 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MT/00640353
Cover Note Number	

Driver

Name of Driver	BENJAMIN YOW THIAM HUI
NRIC No	S8935681D
Date Of Birth	08/10/1989
Occupation	INDOOR
Date Of Driving Pass	18/01/2011
Driving Experience	8 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	+65-97490014
Fax Number	
Contact Number	OTHERS-97490014
Email Address	BYOW89@GMAIL.COM

Address	BLK 315A PUNGGOL WAY #06-643 SINGAPORE
Postcode	821315
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	4
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO THE ATTACH STATEMENT RECORDED BY PEI WEN - PROGRESSIVE CAR CARE PTE LTD TEL 6741 5336

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHA7846E
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SLQ7471X
-----------------------------	----------

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

BENJAMIN YOW THIAM HUI

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SML9642X

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

11/10/19

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NIC/PIN No.:

permen

Sketch Plan #2

SKETCH PLAN

	Vehicle A - SML9642X B - SHA 7846 E C - SLQ7A71X
	Legend

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along Bangkok Green on the middle lane. As I was approaching the junction after Hongkong street SI, the vehicle in front of me suddenly stop. I manage to stop in time however after a few seconds I felt an huge impact from my vehicle rear portion. The impact caused my vehicle to thrust forward and hit onto the front car.

DECLARATION

I/We declare the foregoing particulars are true in every respect.
 Please be advised that your insurer may have a fourteen (14) days clause whereby the claim against own policy must be made within the stipulated timeframe from the day of occurrence. Kindly check your policy for more details.

Policyholder's Signature
 Date & Time:

11/10/19

Driver's Signature
 (if driver is not the policyholder)
 Date & Time:

Reporting Centre Person's Signature
 Name:
 NRIC/FIN No.:

11/10/19

POLICE REPORT PAGE 1



**SINGAPORE
POLICE FORCE**



T/20191010/7025

1 of 3

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20191010/7025

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 10/10/2019 19:18		Vide Report No.:		Station Diary No.:	
Informant's Particulars					
Name of Informant: BENJAMIN YOW THIAM HUI			Address: APT BLK 315A PUNGGOL WAY #06-643 SINGAPORE 821315		
ID Type / ID No.: NRIC NO / S8935681D			Contact No.: Home/Office:		Mobile: 97490014
Nationality: SINGAPORE CITIZEN			Email: byow68@gmail.com		
Sex: Male	Age: 30	Date of Birth: 08/10/1989	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Technical/Engineering services manager (eg shipyard manager)			Driving Licence Information: Class:		Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 10/10/2019 17:10	Type of Location: Straight Road
Location: BUANGKOK GREEN				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Traffic Light - Working	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHA7846E	Car				Slightly Damaged	0
SLQ7471X	Car				Slightly Damaged	0
SML9642X	Car	MITSUBISHI	OUTLANDE R 2.0 CVT	Blue	Seriously Damaged	0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
-------------	-------------------	--------------	-----------	-------------

POLICE REPORT PAGE 2



**SINGAPORE
POLICE FORCE**



T/20191010/7025

2 of 3

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20191010/7025

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SML9642X	DIRECT ASIA INSURANCE (SINGAPORE) PTE. LTD.	MT/00640353	13/06/2019	12/06/2020

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	BENJAMIN YOW THIAM HUI	ID No.	S8935681D
Related Vehicle	SML9642X (Car)	Contact No.	97490014
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	04	Degree of Injury	Slight

Brief Details.

On stated time and date, I was the driver of vehicle bearing car plate number SML9642X at buangkok green. I was driving at lane 2.

The vehicle bearing carplate number SLQ7471X in front slow down and came to a complete stop and I follow suit.

Suddenly, the vehicle behind bearing carplate number SHA7846E collided into my rear vehicle, thus my vehicle collided into the front vehicle which is SLQ7471X.

I got down my vehicle and exchanged particulars and left. Due to the accident, I suffered injuries and consult a doctor and get a 4 days MC.

POLICE REPORT PAGE 3



**SINGAPORE
POLICE FORCE**



T/20191010/7025

3 of 3

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20191010/7025

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / TPHQ /
JUREMAH BINTE AHMAD
Contact No.: 65476219

Authentication Stamp
NP166

Signature Of Informant:
The identity of the person making this report has
been authenticated by SingPass. No signature is
required.

Date/Time:
10/10/2019 19:18

Classification Of Case:

FIRST CAPITAL

Vehicle number	SML9642X
Make / Model	MITSUBISHI OUTLANDER
Chassis number	GF7W0601287
Accident date	10/10/2019
Reference	1910-08

Qty Particulars

Unit Price - SGD \$

<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	FRONT BUMPER	980.00 1380.00 BRV ✓
2	FRONT BUMPER SIDE RETAINER	✓ 55.20 NECV
1	FRONT BUMPER REINFORCEMENT	559.00 771.65 DDV
2	FRONT FOG LAMP	483.00 NDX
2	FRONT FOG LAMP COVER @ 45.00	90.00 133.40 CRAV ✓
2	FRONT BUMPER CHROME MOULDING (UPPER) @ 217.80	435.60 455.40 CRAV ✓
2	FRONT BUMPER CHROME MOULDING (LOWER)	✓ 232.30 CRAV
1	FRONT BUMPER LOWER LIP	402.50
2	FRONT BUMPER LOWER LIP CHROME	418.60 } NDX
1	FRONT GRILLE WITH MOULDING	✓ 656.65 BRV
1	FRONT GRILLE EMBLEM	✓ 61.50 NECV
2	FRONT HEADLAMP	3340.00 4406.80 BRV ✓
1	FRONT SUPPORT PANEL	✓ 560.20 DDV
1	FRONT SUPPORT PANEL BRACKET	56.00 RA
1	BONNET	1146.55
2	BONNET HINGE	149.50 } NDX
1	BONNET LOCK	84.00
1	BONNET LOCK STRIKER	25.00
1	REAR BUMPER	✓ 1003.95 DDV
2	REAR BUMPER SIDE RETAINER	✓ 163.30 NECV
1	REAR BUMPER REINFORCEMENT BRACKET	85.20 85.20 BT ✓
2	REAR BUMPER REFLECTOR @ 114.00	144.00 228.00 BRV
1	REAR BUMPER LOWER GARNISH	✓ 420.00 BRV
2	TAILLAMP	675.60 1351.20 CKV ✓
1	END PANEL	✓ 348.00 DDV
1	END PANEL TOP GARNISH	✓ 156.00 CRAV
1	TAILGATE	1014.80 1068.00 DDV
2	TAILGATE LAMP	238.20 476.40 CRA
1	TAILGATE INNER TRIM	312.00 NDX
1	TAILGATE LOCK	513.60 } NDX
1	TAILGATE LOCK STRIKER	21.60
1	TAILGATE WEATHERSTRIP	230.40 } NDX
1	TAILGATE OUTER CHROME GARNISH	559.20

11218.00

1	TAILGATE EMBLEM - LOGO	✓ 46.80	
1	TAILGATE EMBLEM - OUTLANDER	86.00 103.20	NEC ✓
1	TAILGATE EMBLEM - MIVEC	50.00 89.60	
2	REAR FENDER LH	1125.00 2796.00	NEC ✓ BAC
2	REAR FENDER INNER SHIELD	264.00	NDX
2	REAR FENDER ARC GARNISH	✓ 132.00	CUTV
1	REAR LH AIR VENT	100.00 120.00	CRAV
2	REAR QUARTER GLASS W MOULDING photo	456.00 912.00	NEC ✓
1	SPARE TYRE COMPARTMENT	324.00	NSX
1	FLOOR PANEL	856.80	NDX
1	KEYLESS SENSOR	✓ 102.00	BRV
1	KEYLESS SENSOR HOLDER	38.50 108.00	BTV
1	EXHAUST SILENCER	684.00	
2	EXHAUST MOUNTING	84.00	NDX
1	EXHAUST HEATSHIELD	114.00	
1	FRONT NUMBER PLATE GARNISH	40.00 64.00	CRA ✓
		25215.50	13394.00
Less 10%		2521.55	1339.40
Subtotal		22693.95	12054.6
Balance C/F		22693.95	
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>			
Balance B/F		22693.95	
1	FRONT NUMBER PLATE	30.00 80.00	BT ✓
1 SET	FRONT BUMPER CLIP	30.00 50.00	NEC ✓
1 SET	FRONT GRILLE CLIP	30.00 60.00	NEC ✓
1 SET	FRONT SUPPORT PANEL TOP GARNISH CLIP	30.00 60.00	NEC ✓
1	REVERSE CAMERA	400.00	NDX
1 SET	REVERSE SENSOR	200.00 800.00	DLV
1 SET	REAR BUMPER CLIP	30.00 50.00	NEC ✓
1 SET	END PANEL TOP GARNISH CLIP	30.00 60.00	NEC ✓
1 SET	TAILLAMP CLIP	60.00	SVCX
1 SET	BOOTLID INNER TRIM CLIP (TAIL GATE)	30.00 60.00	NEC ✓
2 SET	FENDER INNER TRIM CLIP	60.00	SVCX
1 SET	REAR WINDSCREEN MOULDING	156.60 250.00	NEC ✓
1	REAR NUMBER PLATE	80.00	SVCX
1	WINDSCREEN SEALANT	50.00 150.00	
1	QUARTER GLASS SEALANT	50.00 150.00	NEC ✓
Subtotal		666.60 2370.00	
Balance C/F		25063.95	

S/No	<u>LABOUR AND MISCELLANEOUS CHARGES</u>	
	Balance B/F	25063.95
1	CHECK FRONT & REAR WIRING AND LIGHTING SYSTEM	50.00 120.00
2	REMOVE AND REFIT GARNISH ,LINING AND TRIM FOR REPAIR	80.00 200.00
3	REMOVE AND REFIT FUEL TANK	80.00 200.00
4	REMOVE AND RENEW FLOOR INSULATOR	150.00
5	REMOVE AND RENEW EXHAUST ASSY	300.00
6	REMOVE AND REFIT REAR WINDSCREEN	120.00 200.00
7	TRANSFER PARTS, ATTACHMENT FROM OLD TAILGATE TO NEW	80.00 150.00
8	TRANSFER PARTS, ATTACHMENT FROM OLD BONNET TO NEW	150.00
9	PANEL BEATING ON AFFECTED AREAS	1200.00 3000.00
10	SPRAY PAINTING ON AFFECTED AREAS	1200.00 3000.00
11	APPLY ANTI-RUST ON AFFECTED AREAS	60.00 200.00
	Subtotal	7670.00
		2870.00
	Grand total	32733.95

Survey on 14/10/19

Part by Part repair

Repair days 7

1130 hrs

31/10/19 call hrs

[Signature]
25/10/19

Resurvey on 15/10/19

1130 hrs

Resurvey on Before Paint

on 21/10/19

1130 hrs

1130 hrs

After paint 23/10/19 (w3 photo)

1510 hrs

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Parts 12,054.60

SN 6,66.60

Labour 2870.00

15591.20

3118.24

12472.96

@ 20%

HS 12,450/-

TOTAL 1130 hrs

25/10/19

MOTORCAR (Rear)

Rear Portion

NAC	INC	Item	CON	ACQ	QTY
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	BR	✓	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower	BR	✓	
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips			
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer	NEC	✓	
1149	993045	Rear Bumper Reinforcement	DD	✓	
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor	DL	✓	
1159	993327	Rear End Panel	DD	✓	
1160	993339	Rear End Panel Top Garnish	DL	✓	
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate	DD	✓	
1182	991328	Tailgate Emblem	NEC	✓	
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant	NEC	✓	
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board	BR	✓	

Vehicle No. SML 9642X

NAC	INC	Item	CON	ACQ	QTY
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender	W/T	R	X
1219	993449	Rear LH Fender Protector	DL	✓	
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1255	990247	Sticker			
		Rear bumper lamp LH	DL	✓	
		Boot lock sensor	BR	✓	

No of Items: 15

Assessor: JCCM

line 24/10/13

(01)Skilled (02)Unskilled (03)Driver (04)Electrician (05)Mechanic (06)Welder (07)Defective
(08)Stuffed (09)Bushed (10)Broken (11)Exhaust (12)Missing (13)Tare
(14)Unconfirmed (15)Not Working

MOTOR CAR (Frt)

(1)Replace (✓) (2)Repair (X) (3)Check (M)
(4)Not Connected (N/C)

Front Portion

NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate	BT	✓	
1002	991887	Frt Number Plate Base			
1003	991889	Frt Number Plate Garnish			
1004	991300	Frt Bumper			
1005	992341	Frt Bumper Clips	NEC	✓	
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer	NEC	✓	
1008	991433	Frt Bumper Reinforcement	DD	✓	
1009	991318	Frt Bumper Beam			
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1012	991420	Frt Bumper Pad			
1013	991363	Frt Bumper Grille			
1014	991301	Frt Bumper Moulding	BR	✓	2
1015	991407	Frt Bumper Lower Spoiler			
1016	991438	Frt Bumper Sensor			
1017	995100	Frt LH Bumper Fog Lamp Cover			
1018	991355	Frt RH Bumper Fog Lamp Cover			
1019	995079	Frt LH Bumper Fog Lamp			
1020	995080	Frt RH Bumper Fog Lamp			
1021	991793	Frt Grille	BR	✓	
1022	991328	Frt Grille Emblem	NEC	✓	
1023	991799	Frt Grille Chrome Moulding			
1024	991222	Frt Apron Panel			
1025	992013	Frt Support Panel	DD	✓	
1026	992025	Frt Support Panel Top Garnish Cover			
1027	992416	Horn			
1028	991277	Frt Buce Panel	BT	✓	
1029	995153	Frt LH Headlamp Assy	BR	✓	
1030	991821	Frt RH Headlamp Assy	BR	✓	
1031	995088	Frt LH Side Lamp			
1032	995089	Frt RH Side Lamp			
1033	990248	Bonnet			
1034	991328	Bonnet Emblem			
1035	990287	Bonnet Lock			
1036	990285	Bonnet Insulator			
1037	990273	Bonnet Hinge			
1038	990261	Bonnet Damper			
1039	990305	Bonnet Rubber			
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy			
1044	990134	Air Con Suction Pipe (Low Pressure)			
1045	990118	Air Con Suction Hose			
1046	990133	Air Con Discharge Pipe (High Pressure)			
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	995294	Air Con Belt			
1052	995074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1055	992745	Radiator Fan Clutch			
1056	992758	Radiator Hose Top			
1057	992757	Radiator Hose Bottom			
1058	992741	Radiator Expansion Tank			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1061	990056	Air Cleaner Hose			
1062	990089	Air Cleaner Resonator			
1063	991712	Frt Exhaust Manifold			
1064	991713	Frt Exhaust Manifold Cover			
1065	991054	Frt Exhaust Manifold Sensor (Oxygen)			
1066	991714	Front Exhaust Pipe			
1067	990319	Battery			
1068	990224	Battery Cover			
1069	990223	Battery Bracket			
1070	990229	Battery Tray			

Vehicle No: SML 3642X

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank			
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
1096	995070	Frt LH Fender			
1097	995072	Frt LH Fender Inner Panel			
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector			
1100	991740	Frt LH Fender Inner Shield			
1101	995179	Frt LH Mudflap			
1102	995170	Frt LH Wheel Rim			
1103	994025	Frt LH Rim Cover			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender			
1106	991739	Frt RH Fender Inner Panel			
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			
1109	991740	Frt RH Fender Inner Shield			
1110	991884	Frt RH Mudflap			
1111	992087	Frt RH Wheel Rim			
1112	994025	Frt RH Rim Cover			
1113	995065	Frt RH Tyre			
1114	992093	Frt Windscreen Glass			
1115	992117	Frt Windscreen Rubber			
1116	992108	Frt Windscreen Moulding			
1117	992098	Frt Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag			
1128	994483	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Frt Driver Seat			
1133	991922	Frt RH Seat Belt Assy			
1134	991899	Frt Passenger Seat			
1135	995182	Frt LH Seat Belt Assy			
1136	990247	Sticker			

No of Items: 12

Astroport: TGU inc 24/10/13



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19018053/Bqd3e2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 25-11-2019	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
	Insured Veh.	SHA 7846E	Veh. Inspected
			SML 9642X
	Policy No.		Coverage (\$)
			0.00
	Claim No.	D19006536MFSH	Excess (\$)
			0.00
	Assign From	KAREN TAN	Assign Date
			14/10/2019
2. Vehicle Particulars & Condition			
	Make & Model	MITSUBISHI OUTLANDER	c.c
			1998
	Engine No.	HIDDEN	Year of Reg.
			2019
	Chassis No.	GF7W0601287	Colour
			BLUE
	Odometer	7234	Steering
			IN ORDER
	Brakes	IN ORDER	Modification
			SPORTS RIM
	General	FAIR	
3. Conditions of Tyres			
		Size	Make
			Balance
	R/H Front Tyre	225/55 R18	TOYO
			7 mm
	L/H Front Tyre	225/55 R18	TOYO
			7 mm
	R/H Rear Tyre	225/55 R18	TOYO
			7 mm
	L/H Rear Tyre	225/55 R18	TOYO
			7 mm
4. Description of Damages			
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.		
	DAMAGES SEE DETAILS.		
5. General Information			
	Accident Date	10/10/2019	Inspection Date
			14/10/2019
	Survey held at	TEAMWORK GARAGE PTE LTD	
		53 UBI AVENUE 1	
		#01-24	
		SINGAPORE 408934.	
5a. Remarks			
	A) DAMAGES CONSISTENT TO ACCIDENT REPORT.		
	B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.		
	C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.		
5b. Estimate Days of Repair			
	ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SML 9642X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	BROKEN	1,380.00	980.00
2	FRONT BUMPER SIDE RETAINER	NECESSARY	55.20	55.20
1	FRONT BUMPER REINFORCEMENT	DENTED	771.65	558.00
2	FRONT FOG LAMP	NO DAMAGED	483.00	-
2	FRONT FOG LAMP COVER	CRACKED	133.40	90.00
2	FRONT BUMPER CHROME MOULDING (UPPER)	CRACKED	455.40	435.60
2	FRONT BUMPER CHROME MOULDING (LOWER)	CRACKED	232.30	232.30
1	FRONT BUMPER LOWER LIP	NO DAMAGED	402.50	-
2	FRONT BUMPER LOWER LIP CHROME	NO DAMAGED	418.60	-
1	FRONT GRILLE WITH MOULDING	BROKEN	656.65	656.65
1	FRONT GRILLE EMBLEM	NECESSARY	61.50	61.50
2	FRONT HEADLAMP	BROKEN	4,406.80	3,340.00
1	FRONT SUPPORT PANEL	DENTED	560.20	560.20
1	FRONT SUPPORT PANEL BRACKET	TO REPAIR SEE LABOUR	56.00	-
1	BONNET	NO DAMAGED	1,146.55	-
2	BONNET HINGE	NO DAMAGED	149.50	-
1	BONNET LOCK	NO DAMAGED	84.00	-
1	BONNET LOCK STRIKER	NO DAMAGED	25.00	-
1	REAR BUMPER	DENTED	1,003.95	1,003.95
2	REAR BUMPER SIDE RETAINER	NECESSARY	163.30	163.30
1	REAR BUMPER REINFORCEMENT BRACKET	BENT	85.20	85.20
2	REAR BUMPER REFLECTOR	BROKEN (1PC ONLY)	228.00	114.00
1	REAR BUMPER LOWER GARNISH	BROKEN	420.00	420.00
2	TAILLAMP	CRACKED (1PC ONLY)	1,351.20	675.60
1	END PANEL	DENTED	348.00	348.00
1	END PANEL TOP GARNISH	CRACKED	156.00	156.00
1	TAILGATE	DENTED	1,068.00	1,014.00
2	TAILGATE LAMP	CRACKED (1PC ONLY)	476.40	238.20

Report Ref No. CS/FCI19018053/Bqd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	TAILGATE INNER TRIM	NO DAMAGED	312.00	-
1	TAILGATE LOCK	NO DAMAGED	513.60	-
1	TAILGATE LOCK STRIKER	NO DAMAGED	21.60	-
1	TAILGATE WEATHERSTRIP	NO DAMAGED	230.40	-
1	TAILGATE OUTER CHROME GARNISH	NO DAMAGED	559.20	-
1	TAILGATE EMBLEM - LOGO	NECESSARY	46.80	46.80
1	TAILGATE EMBLEM - OUTLANDER	NECESSARY	103.20	86.00
1	TAILGATE EMBLEM - MIVEC	NECESSARY	89.60	50.00
2	REAR FENDER	N/S BUCKLED	2,796.00	1,125.00
2	REAR FENDER INNER SHIELD	NO DAMAGED	264.00	-
2	REAR FENDER ARC GARNISH	CUT	132.00	132.00
1	REAR LH AIR VENT	CRACKED	120.00	100.00
2	REAR QUARTER GLASS W MOULDING	NECESSARY (1PC ONLY)	912.00	456.00
1	SPARE TYRE COMPARTMENT	NO SUCH PARTS	324.00	-
1	FLOOR PANEL	NO DAMAGED	856.80	-
1	KEYLESS SENSOR	BROKEN	102.00	102.00
1	KEYLESS SENSOR HOLDER	BENT	108.00	38.50
1	EXHAUST SILENCER	NO DAMAGED	684.00	-
2	EXHAUST MOUNTING	NO DAMAGED	84.00	-
1	EXHAUST HEATSHIELD	NO DAMAGED	114.00	-
1	FRONT NUMBER PLATE GARNISH	CRACKED	64.00	40.00
	LESS 10% DISCOUNT		-2,521.55	-1,336.40
			22,693.95	12,027.60
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT NUMBER PLATE (SN)	BENT	80.00	30.00
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	50.00	30.00
1	SET FRONT GRILLE CLIP (SN)	NECESSARY	60.00	30.00
1	SET FRONT SUPPORT PANEL TOP GARNISH CLIP (SN)	NECESSARY	60.00	30.00
1	REVERSE CAMERA (SN)	NO DAMAGED	400.00	-
1	SET REVERSE SENSOR (SN)	DISLODGE	800.00	200.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	50.00	30.00
1	SET END PANEL TOP GARNISH CLIP (SN)	NECESSARY	60.00	30.00

Report Ref No. CS/FCI19018053/Bqd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET TAILLAMP CLIP (SN)	SERVICEABLE	60.00	-
1	SET BOOTLID INNER TRIM CLIP (SN)	NECESSARY	60.00	30.00
2	SET FENDER INNER TRIM CLIP (SN)	SERVICEABLE	60.00	-
1	SET REAR WINDSCREEN MOULDING (SN)	NECESSARY	250.00	156.60
1	REAR NUMBER PLATE (SN)	SERVICEABLE	80.00	-
1	WINDSCREEN SEALANT (SN)	NECESSARY	150.00	50.00
1	QUARTER GLASS SEALANT (SN)	NECESSARY	150.00	50.00
			2,370.00	666.60
	LABOUR			
	CHECK FRONT & REAR WIRING AND LIGHTING SYSTEM.		120.00	50.00
	REMOVE AND REFIT GARNISH, LINING AND TRIM FOR REPAIR.		200.00	80.00
	REMOVE AND REFIT FUEL TANK.		200.00	80.00
	REMOVE AND RENEW FLOOR INSULATOR.	NOT NECESSARY	150.00	-
	REMOVE AND RENEW EXHAUST ASSY.	NOT NECESSARY	300.00	-
	REMOVE AND REFIT REAR WINDSCREEN.		200.00	120.00
	TRANSFER PARTS, ATTACHMENT FROM OLD TAILGATE TO NEW.		150.00	80.00
	TRANSFER PARTS, ATTACHMENT FROM OLD BONNET TO NEW.	NOT NECESSARY	150.00	-
	PANEL BEATING ON AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF FRONT SUPPORT PANEL BRACKET.		3,000.00	1,200.00
	SPRAY PAINTING ON AFFECTED AREAS.		3,000.00	1,200.00
	APPLY ANTI-RUST ON AFFECTED AREAS.		200.00	60.00
			7,670.00	2,870.00
GRAND TOTAL			32,733.95	15,564.20
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				12,450.00

Report Ref No. CS/FC119018053/Bqd3e2

LIM TEOW GUAN

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.