

INS. CASE OWNER:

CC3/CTI19018055/K1ea3

LKK:
IDAC:

Surveyor:

KALVIN

DOI: 11/10/2019

Date / Time: 11/10/2019

Registered in Meriton: —

Pre-assign / CCU / FTE



Insured Vehicle No.: PC 5720S

Claim No.: —

Name of Insured: RHR Conveyance

Policy No.: —

Insured Tel No.: — HP: —

Make / Model: —

Excess Sec II : S\$ — D.O.A: 10/10/19 02:20

Place of Accident: BOSS HOTEL

Is driver the owner? (YES ☒ NO) Nature of Accident: —

If NO, Driver Name / Age: —

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.: — (V/L: YES / NO)

Insured Liability: % Final ? Yes / No

SH 6650S

INSRS:
WSP: CDGE LOYANG
Tel: —
Liability: —
RMKS: —INSRS:
WSP: —
Tel: —
Liability: —
RMKS: —INSRS:
WSP: —
Tel: —
Liability: —
RMKS: —INSRS:
WSP: —
Tel: —
Liability: —
RMKS: —

Date/Time	STAGE	DATE / PIC
PC 5720S - X	Non-Reporting ltr (1st):	
SH 6650S - CC3/CTI19011673/K1ea3n2 : DOA: 28/6/19	Non-Reporting ltr (2nd):	
- CS/FCI19005832/K1td3n2: DOA: 30/3/19	Non-Reporting ltr (Final):	
- CS/FCI16011085/Avbm2: DOA: 5/6/16	Notification ltr (if non-pickup):	
	Call OI: RMHR 31.10.19	
	After call ltr to OI:	
	Documentation Check List: Handler Typist	
	Notification ltr (if non-pickup)	☐
	After call ltr to OI:	☒
	Authorisation To Act:	☒
	Release Voucher:	☒
	Final Repair Bill:	☒
	Car Rental Invoice:	☒
	Towing Invoice:	☐
	LTA / GIA:	☒
	Medical Bill:	☐
	PIR:	☐
	Mandate/Reject Instruction:	☐
	LOD:	☒
	Payment Breakdown Form:	☐
PRELIMINARY ADVICE Date/Time: — Sent By: —	Post-Repair Photos:	☒
	Others:	☐
FINALIZATION Date/Time: — Confirm with: —	Confirm by: AUC	
Repair Cost: 46 S\$ 1,500 (2 days) Reduction: 12 %	Email ☒ Call ☐	
FINAL SETTLEMENT Date/Time: 13.11.19 Confirm with: CHENG	Email ☒ Call ☐	
Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: 23	If NO or B 28, Ass. Lia:	
Repair Cost: 2/10/19 S\$ 1,465.00	DID HIT TP PARKED VEH.	
Loss of Rental (LOR): S\$ 330.92 (2 days) x \$ 165.46		
Loss of Use (LOU): S\$ — (\$ x days)		
Loss of Income (LOI): S\$ 100.00 (\$ 50 x 2 days)		
LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☒ [Tick only one]		
GIA/LTA Search: S\$ 144		
Medical: S\$ —		
Disbursement: S\$ — (e.g. Tow/ Independent)		
Legal Cost: S\$ —		
Total: S\$ 2,043.91	Global Sum S\$: 2,040.00	
FINAL PAYMENT Date/Time: 13.11.19 Confirm with: CHENG	Email ☒ Call ☐	
Payee 1: S\$ 2,040.00	Name 1: COMFORTDELTA ENGINEERING PTE LTD	
Payee 2: (Strike if N.A.) S\$	Name 2:	
Payee 3: (Strike if N.A.) S\$	Name 3:	

COPY SENT
21/11/191) Claim status: Normal/Reject/Private Settle
2) Report Format: TP
3) Survey fee: \$400

REPAIR ESTIMATE*

VEHICLE NO : SH 6650S

DATE 10/10/2019 14:57

MAKE :

MODEL : MERCEDES BENZ

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper <i>Detached</i>			\$ 1,510.00
	Rear Bumper Reinforcement <i>x sue</i>			\$ 1,150.00
	Rear Bumper Bracket Lower (LH/RH) <i>x sue</i>	\$	135.00	\$ 270.00
	Rear Bumper Bracket Top (LH/RH) <i>x sue</i>	\$	125.00	\$ 250.00
	Rear Bumper Retainer Mounting (LH/RH) <i>x sue</i>	\$	115.00	\$ 230.00
	Rear Bumper Lower Cover <i>x repair</i>			\$ 325.00
	Taillamp (LH) <i>x sue</i>			\$ 1,280.00
	SUB TOTAL			\$ 5,015.00
	LESS 20%			\$ 1,003.00
	DISCOUNTED TOTAL			\$ 4,012.00
	Rear Bumper Sensor <i>x sue</i>			\$ 388.00
	Rear Bumper Rubber Mat <i>x sue</i>			\$ 50.00
				\$ 438.00
	Labour Charge			360
	Panel Beating			\$ 400.00
	Spray Painting Charge			\$ 250.00
	Wiring Charge			\$ 50.00
	Remove/Refix Reverse Sensor			\$ 120.00
	TOTAL LABOUR			\$ 820.00
	ESTIMATE TOTAL			\$ 5,270.00

Nett

Nett

200

x, 1

70

Kalin 11/10/19

11/10/19 11:52
2 hrs

L/S

After Repair photo

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Our Job Ref No 305340530

Date 12/10/19

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To LKK

Fax :

Attn KALVIN

: SH 6650S

305333809 10/10/19

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: CHINA --- PC 5720C
###
2. The finalized amount shall be:
 - (a) Spare Parts after List discount
 - (b) Labour Charges ###
 - Total for Part-By-Part Repair Cost** ###
 - (c) Lumpsum Repair (if applicable) N
 - Total for Lumpsum repair cost after Less: 20% \$1,500.00
 - Final Lumpsum Repair cost**

3. Estimated normal period for repairs: 2 working days

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature :

Name : JUMANI

Tel : 6214 8315

Fax : 65468156

Signature :

Name :

Date :

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SH 6650S

DATE 10/10/2019 14:57

MAKE :

MODEL : MERCEDES BENZ

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper			\$ 1,510.00	
	Rear Bumper Reinforcement X			\$ 1,150.00	
	Rear Bumper Bracket Lower (LH/RH) X		\$ 135.00	\$ 270.00	
	Rear Bumper Bracket Top (LH/RH) X		\$ 125.00	\$ 250.00	
	Rear Bumper Retainer Mounting (LH/RH) X		\$ 115.00	\$ 230.00	
	Rear Bumper Lower Cover X repair			\$ 325.00	
	Taillamp (LH) X			\$ 1,280.00	
	SUB TOTAL			\$ 5,015.00	
	LESS 20%			\$ 1,003.00	
	DISCOUNTED TOTAL			\$ 4,012.00	
	Rear Bumper Sensor X			\$ 388.00	Nett
	Rear Bumper Rubber Mat /			\$ 50.00	Nett
				\$ 438.00	
	Labour Charge			360	
	Panel Beating			\$ 400.00	
	Spray Painting Charge			\$ 250.00	200
	Wiring Charge			\$ 50.00	X
	Remove/Refix Reverse Sensor			\$ 120.00	30
	TOTAL LABOUR			\$ 820.00	
	ESTIMATE TOTAL			\$ 5,270.00	
Kalin 1444 11/10/19 11:15L 2 lgs L/S After Repair photo					
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					

Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order:

JC NO: 305340530

OWNER

IS COMFORT TRANSPORTATION PTE LTD
7010045
OWNER NO. 383 SIN MING DRIVE
LESS Singapore SINGAPORE 575717
65508755

(R) (P) (Q)

UNIT CARD NO.

REGN NO.	SH 6650S	MILEAGE
MAKE	MERCEDES BENZ	FUEL E 1/2 F
MODEL	E220CDI (E5)	DATE/TIME IN 10.10.2019 13:40
YR OF MANUF	30.09.2013	TARGET DATE
CHASSIS CODE	WDD2120022A757675	COMPLETION DATE/TIME

JOB DESCRIPTION

Accident Date: 10.10.2019
NATURE: 3P 10.10.19

S/NO LABOR CODE DESCRIPTION



KEYED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Identification Slip

Exit Pass

Vehicle No: SH 6650S JU CHINA

Vehicle No: SH 6650S

Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC3/CTI19018055/K1ea3q2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 25-11-2019



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	PC 5720S	Veh. Inspected	SH 6650S
Policy No.	DMB1SN1919641900	Coverage (\$)	0.00
Claim No.	SNM19D204848	Excess (\$)	0.00
Assign From		Assign Date	11/10/2019

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ E 220	c.c	2143
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	WDD2120022A757675	Colour	WHITE
Odometer	976129	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	WEST LAKE	7 mm
L/H Front Tyre	205/60 R16	WEST LAKE	7 mm
R/H Rear Tyre	205/60 R16	WEST LAKE	7 mm
L/H Rear Tyre	205/60 R16	WEST LAKE	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	10/10/2019	Inspection Date	11/10/2019
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	-----------------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 6650S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DEFORMED	1,510.00	1,510.00
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	1,150.00	-
2	REAR BUMPER BRACKET LOWER (LH/RH) @\$135.00	SERVICEABLE	270.00	-
2	REAR BUMPER BRACKET TOP (LH/RH) @\$125.00	SERVICEABLE	250.00	-
2	REAR BUMPER RETAINER MOUNTING (LH/RH) @\$115.00	SERVICEABLE	230.00	-
1	REAR BUMPER LOWER COVER	TO REPAIR SEE LABOUR	325.00	-
1	TAILLAMP (LH)	SERVICEABLE	1,280.00	-
	LESS 20% DISCOUNT		-1,003.00	-302.00
			4,012.00	1,208.00
<u>SPECIAL NETT ITEMS</u>				
1	REAR BUMPER SENSOR (SN)	SERVICEABLE	388.00	-
1	REAR BUMPER RUBBER MAT (SN)	NECESSARY	50.00	50.00
			438.00	50.00
<u>LABOUR</u>				
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR BUMPER LOWER COVER.		400.00	360.00
	SPRAY PAINTING CHARGE.		250.00	200.00
	WIRING CHARGE.	NOT NECESSARY	50.00	-
	REMOVE/REFIX REVERSE SENSOR.		120.00	40.00
			820.00	600.00
GRAND TOTAL			5,270.00	1,858.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,500.00

Report Ref No. CC3/CTI19018055/K1ea3q2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.