

## REPAIR ESTIMATE\*

VEHICLE NO : SH 6650S

DATE 10/10/2019 14:57

MAKE :

MODEL : MERCEDES BENZ

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper <i>Detached</i>			\$ 1,510.00
	Rear Bumper Reinforcement <i>x sue</i>			\$ 1,150.00
	Rear Bumper Bracket Lower (LH/RH) <i>x sue</i>		\$ 135.00	\$ 270.00
	Rear Bumper Bracket Top (LH/RH) <i>x sue</i>		\$ 125.00	\$ 250.00
	Rear Bumper Retainer Mounting (LH/RH) <i>x sue</i>		\$ 115.00	\$ 230.00
	Rear Bumper Lower Cover <i>x repair</i>			\$ 325.00
	Taillamp (LH) <i>x sue</i>			\$ 1,280.00
	<b>SUB TOTAL</b>			<b>\$ 5,015.00</b>
	<b>LESS 20%</b>			<b>\$ 1,003.00</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$ 4,012.00</b>
	Rear Bumper Sensor <i>x sue</i>			\$ 388.00 <b>Nett</b>
	Rear Bumper Rubber Mat <i>/ sue</i>			\$ 50.00 <b>Nett</b>
				<b>\$ 438.00</b>
	<b>Labour Charge</b>			<b>360</b>
	Panel Beating			\$ 400.00
	Spray Painting Charge			\$ 250.00 <b>200</b>
	Wiring Charge			\$ 50.00 <b>x 1</b>
	Remove/Refix Reverse Sensor			\$ 120.00 <b>40</b>
	<b>TOTAL LABOUR</b>			<b>\$ 820.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$ 5,270.00</b>
<p><i>Kalvin 1404</i></p> <p><i>11/10/19 11:52</i></p> <p><i>2 bgs</i></p> <p><i>L/S</i></p> <p><i>After Repair photo</i></p>				
<p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p>				

Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: \_\_\_\_\_

Date: \_\_\_\_\_