

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

MR.CHUA ENG HUA
BLK 165 GANGSA ROAD #11-66
SINGAPORE 670165

Contact : 96206307

ESTIMATE

Repair Code : CLM14723

Date in : 11/10/2019

Vehicle Num. : SLV3310C

Model : TOYOTA SIENTA HYBRID 1.5G CVT

Chassis/Eng# : NPH1707105809/1NZ8348398

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER ✓ C/R	1	658.10	658.10 485.30
REAR BUMPER SIDE GARNISH LH ✓ S/R	1	155.00	155.00 ✓
REAR BUMPER SIDE RETAINER L/R L/H only ✓ nec	2/1	110.35	220.70 110.35
REAR LH TAILLAMP L/H ✓ C/R	1	404.10	404.10 330.00
REAR LH TAILLAMP LOWER BRACKET ✓ C/R	1	48.10	48.10 ✓
Subtotal before discount			1,486.00
Percentage discount 25%			371.50
Sub-total 1			1,114.50
REAR BUMPER CLIPS - SET ✓ nec	1	80.00	80.00 20.00
REAR BUMPER LOWER SPOILER X S/R R local rpr back = \$80	1	750.00	750.00
REAR BUMPER LOWER SPOILER SEAL X S/R	1	80.00	80.00
REAR BUMPER REFLECTOR LH ✓ C/R (have cap) 4H	1	280.00	280.00 150.00
REAR BUMPER REVERSE SENSOR - SET X S/R	1	350.00	350.00
REAR LH TAILAMP CLIPS - SET ✓ nec	1	25.00	25.00 15.00
Subtotal before discount			1,565.00
Percentage discount 0%			0.00
Sub-total 2			1,565.00
Parts-total			2,679.50

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

MR.CHUA ENG HUA
BLK 165 GANGSA ROAD #11-66
SINGAPORE 670165

Contact : 96206307

ESTIMATE

Repair Code : CLM14723

Date in : 11/10/2019

Vehicle Num. : SLV3310C

Model : TOYOTA SIENTA HYBRID 1.5G CVT

Chassis/Eng# : NPH1707105809/1NZ8348398

LABOUR

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident. *2 ps*

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident. *1.5*

To apply anti-rust chemical on repaired and replaced panel.

30 ~~100.00~~

X ~~100.00~~

400 ~~700.00~~

300 ~~400.00~~

X ~~80.00~~

Labour Total

1,380.00

Parts & Labour Total

4,059.50

*** This is a computer-generated document which requires no signature.

page 2

*3 day
h/s repair
without prejudice
Hock Ann
Hock Ann@lkk Auto.com
85311883
4.00pm
17/10/19
resurvey stop work*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: