

Date : 11/10/2019
 Vehicle No: SMN5843Z
 Model: BMW 218I M SPORT
 Chassis: WBA2D320405E76623 - 2017
 Reg.Year: 2017
 Policy No: DMPCSN3067141900
 Date of Accident: 04/10/2019

TO MOTOR CLAIM DEPT
 CHINA TAIPING INSURANCE (SINGAPORE)

RM
 12

NOT AUTHORIZED
 Repairing B&P
 Ex ?

3 days

Fax: 62564315

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BONNET ACTUATOR LH	1		Act \$375.00
2	FRONT BONNET ACTUATOR RH	1		Act \$375.00
3	FRONT BONNET HINGE LH	1		R \$138.00
4	FRONT BONNET HINGE RH	1		R \$138.00
5	FRONT HEADLIGHT LH	1		CM \$620.00
6	FRONT HEADLIGHT RH	1		CM \$620.00
7	FRONT HEADLIGHT BRACKET LH	1		R \$50.00
8	FRONT HEADLIGHT BRACKET RH	1		R \$50.00
9	FRONT BUMPER	1		Bu \$1,150.00
10	FRONT BUMPER SIDE RETAINER LH	1		Sm \$20.00
11	FRONT BUMPER SIDE RETAINER RH	1		Sm \$20.00
12	FRONT BUMPER SIDE RETAINER INSERT LH	1		Sm \$16.00
13	FRONT BUMPER SIDE RETAINER INSERT RH	1		Sm \$16.00
14	FRONT BUMPER FOG LAMP SUPPORT LH	1		Sm \$90.00
15	FRONT BUMPER BRAKE AIR CHANNEL COVER LH	1		Sm \$52.00
16	FRONT UNDERBONNET SCREEN PROTECTOR	1		CM Bu \$78.00
17	FRONT GRILLE RH	1		CM \$98.00
18	FRONT GRILLE LH	1		CM \$98.00
19	FRONT GRILLE BUMPER MIDDLE	1		CM \$156.00
20	FRONT GRILLE AIR DUCT	1		CM \$216.00
21	FRONT BUMPER REINFORCEMENT	1		Bu \$288.00
22	FRONT BUMPER TOP IMPACT ABSORBER	1		CM \$65.00
23	FRONT AIR-CON CONDENSER	1		Pr \$720.00
24	RADIATOR	1		Pr \$504.00
25	LOW TEMPERTURE RADIATOR	1		Bu \$528.00
26	LOW TEMPERTURE RADIATOR BRACKET	2	\$45.00	Sm \$90.00
27	RADIATOR FAN ASSY	1		Pr \$730.00
28	FRONT BONNET	1		Bu \$780.00
SUB TOTAL				\$8,081.00
COST + 15%				\$1,212.15
PARTS TOTAL				\$9,293.15

Head office

6 Kung Chong Road Singapore 159143
 Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
 Tel: (+65) 6484 9919 | Fax: (+65) 6481 1011

Branch

551 Upper Thomson Road Singapore 574415
 Tel: (+65) 6452 6868 | Fax: (+65) 6452 9223



Date : 11/10/2019
 Vehicle No: SMN5843Z
 Model: BMW 218i M SPORT
 Chassis: WBA2D320405E76623 - 2017
 Reg.Year: 2017
 Policy No: DMPCSN3067141900
 Date of Accident: 04/10/2019

TO MOTOR CLAIM DEPT
 CHINA TAIPING INSURANCE (SINGAPORE)

ESTIMATE

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT NUMBER PLATE WITH HOLDER	1		CM \$60.00
			S/N TOTAL	\$60.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REPAIR, RE-ADJUST FRONT
 ACCIDENT AREAS & ETC.

\$800.00 550

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING
 MATERIALS AT FRONT ACCIDENT AREAS & ETC.

\$800.00 500

TO CHECK WIRING & TO DIAGNOSIS FAULTY CODE & RESET MEMORY.

\$150.00 100

TO REFILL AIR CONDITIONER GAS & VACUUM.

\$100.00 ✓

TO TUFF KOTE & UNDERSEAL MATERIALS.

nn \$150.00 X

LABOUR TOTAL \$2,000.00

ONG \$11,353.15
 GST 7% \$794.72
 Total \$12,147.87

12401.95

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Head office

6 Kung Chong Road Singapore 159143
 Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
 Tel: (+65) 6484 9919 | Fax: (+65) 6481 1011

Branch

551 Upper Thomson Road Singapore 574415
 Tel: (+65) 6452 6868 | Fax: (+65) 6452 9223



Date : 23/10/2019
Vehicle No: SMN5843Z
Model: BMW 218i M SPORT
Chassis: WBA2D320405E76623 - 2017
Reg. Year: 2017
Policy No: DMPCSN3067141900
Date of Accident: 04/10/2019

TO MOTOR CLAIM DEPT
CHINA TAIPING INSURANCE (SINGAPORE)

Invoice missing

SUPPLEMENTARY

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT WIPER TANK	1		<i>Net</i> \$148.00
2	FRONT BUMPER FOG LAMP RH	1		<i>mgmt</i> \$230.00
SUB TOTAL				\$378.00
COST +15%				\$56.70
PARTS TOTAL				\$434.70

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1011

Branch

551 Upper Thomson Road Singapore 574415
Tel: (+65) 6452 6868 | Fax: (+65) 6452 9223



Date : 23/10/2019
Vehicle No: SMN5843Z
Model: BMW 218I M SPORT
Chassis: WBA2D320405E76623 - 2017
Reg.Year: 2017
Policy No: DMPCSN3067141900
Date of Accident: 04/10/2019

TO MOTOR CLAIM DEPT
CHINA TAIPING INSURANCE (SINGAPOR

SUPPLEMENTARY _ 2

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BONNET LOCK WITH ACTUATOR ASSY LH	1		Di 1 \$267.00 ✓
2	FRONT BONNET LOCK WITH ACTUATOR ASSY RH	1		Di 1 \$267.00 ✓
SUB TOTAL				\$534.00
COST +15%				\$80.10
PARTS TOTAL				\$614.10 ✓

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1011

Branch

551 Upper Thomson Road Singapore 574415
Tel: (+65) 6452 6868 | Fax: (+65) 6452 9223

