

Date: 11/10/2019  
Vehicle No: SMN5843Z  
Model: BMW 218I M SPORT  
Chassis: WBA2D320405E76623 - 2017  
Reg. Year: 2017  
Policy No: DMPCSN3067141900  
Date of Accident: 04/10/2019

TO MOTOR CLAIM DEPT  
CHINA TAIPING INSURANCE (SINGAPORE)

RM  
187

NOT Authorize  
Repair B & paint  
Ex ?

5 days

Fax: 62564315

## ESTIMATE

| NO.         | DESCRIPTION                             | QTY | UNIT S\$ | AMOUNT S\$     |
|-------------|-----------------------------------------|-----|----------|----------------|
| 1           | FRONT BONNET ACTUATOR LH                | 1   |          | Act \$375.00   |
| 2           | FRONT BONNET ACTUATOR RH                | 1   |          | Act \$375.00   |
| 3           | FRONT BONNET HINGE LH                   | 1   |          | R \$138.00     |
| 4           | FRONT BONNET HINGE RH                   | 1   |          | R \$138.00     |
| 5           | FRONT HEADLIGHT LH                      | 1   |          | CM \$620.00    |
| 6           | FRONT HEADLIGHT RH                      | 1   |          | CM \$620.00    |
| 7           | FRONT HEADLIGHT BRACKET LH              | 1   |          | R \$50.00      |
| 8           | FRONT HEADLIGHT BRACKET RH              | 1   |          | R \$50.00      |
| 9           | FRONT BUMPER                            | 1   |          | Per \$1,150.00 |
| 10          | FRONT BUMPER SIDE RETAINER LH           | 1   |          | Per \$20.00    |
| 11          | FRONT BUMPER SIDE RETAINER RH           | 1   |          | Per \$20.00    |
| 12          | FRONT BUMPER SIDE RETAINER INSERT LH    | 1   |          | Per \$16.00    |
| 13          | FRONT BUMPER SIDE RETAINER INSERT RH    | 1   |          | Per \$16.00    |
| 14          | FRONT BUMPER FOG LAMP SUPPORT LH        | 1   |          | Per \$90.00    |
| 15          | FRONT BUMPER FOG LAMP SUPPORT RH        | 1   |          | Per \$52.00    |
| 16          | FRONT BUMPER BRAKE AIR CHANNEL COVER LH | 1   |          | CM Per \$78.00 |
| 17          | FRONT UNDERBONNET SCREEN PROTECTOR      | 1   |          | CM \$98.00     |
| 18          | FRONT GRILLE RH                         | 1   |          | CM \$98.00     |
| 19          | FRONT GRILLE LH                         | 1   |          | CM \$156.00    |
| 20          | FRONT GRILLE BUMPER MIDDLE              | 1   |          | CM \$216.00    |
| 21          | FRONT GRILLE AIR DUCT                   | 1   |          | R \$288.00     |
| 22          | FRONT BUMPER REINFORCEMENT              | 1   |          | CM \$65.00     |
| 23          | FRONT BUMPER TOP IMPACT ABSORBER        | 1   |          | Per \$720.00   |
| 24          | FRONT AIR-CON CONDENSER                 | 1   |          | Per \$504.00   |
| 25          | RADIATOR                                | 1   |          | R \$528.00     |
| 26          | LOW TEMPERATURE RADIATOR                | 1   |          | Per \$90.00    |
| 27          | LOW TEMPERATURE RADIATOR BRACKET        | 2   | \$45.00  | Per \$730.00   |
| 28          | RADIATOR FAN ASSY                       | 1   |          | R \$780.00     |
| 28          | FRONT BONNET                            | 1   |          |                |
| SUB TOTAL   |                                         |     |          | \$8,081.00     |
| COST + 15%  |                                         |     |          | \$1,212.15     |
| PARTS TOTAL |                                         |     |          | \$9,293.15     |

### Head office

6 Kung Chong Road Singapore 159143  
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

### Branch

9A Serangoon North Ave S Singapore 554500  
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1011

### Branch

551 Upper Thomson Road Singapore 574415  
Tel: (+65) 6452 6868 | Fax: (+65) 6452 9223



Date: 11/10/2019  
Vehicle No: SMN5843Z  
Model: BMW 218i M SPORT  
Chassis: WBA2D320405E76623 - 2017  
Reg. Year: 2017  
Policy No: DMPCSN3067141900  
Date of Accident: 04/10/2019

TO MOTOR CLAIM DEPT  
CHINA TAIPING INSURANCE (SINGAPORE)

## ESTIMATE

| NO. | SPECIAL NETT                   | QTY | UNIT S\$  | AMOUNT S\$ |
|-----|--------------------------------|-----|-----------|------------|
| 1   | FRONT NUMBER PLATE WITH HOLDER | 1   |           | CM \$60.00 |
|     |                                |     |           |            |
|     |                                |     | S/N TOTAL | \$60.00    |

45.00

### LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REPAIR, RE-ADJUST FRONT ACCIDENT AREAS & ETC.

\$800.00 55.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT ACCIDENT AREAS & ETC.

\$800.00 50.00

TO CHECK WIRING & TO DIAGNOSIS FAULTY CODE & RESET MEMORY.

\$150.00 10.00

TO REFILL AIR CONDITIONER GAS & VACUUM.

\$100.00 ✓

TO TUFF KOTE & UNDERSEAL MATERIALS.

nn \$150.00 X

LABOUR TOTAL \$2,000.00

ONG \$11,353.15  
GST 7% \$794.72  
Total \$12,147.87

12401.95

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date : 23/10/2019  
Vehicle No: SMN5843Z  
Model: BMW 218I M SPORT  
Chassis: WBA2D320405E76623 - 2017  
Reg.Year: 2017  
Policy No: DMPCSN3067141900  
Date of Accident: 04/10/2019

TO MOTOR CLAIM DEPT  
CHINA TAIPING INSURANCE (SINGAPORE)

*Invoice missing*

## SUPPLEMENTARY

| NO.         | DESCRIPTION              | QTY | UNIT S\$   | AMOUNT S\$              |
|-------------|--------------------------|-----|------------|-------------------------|
| 1           | FRONT WIPER TANK         | 1   |            | <i>nd</i> \$148.00      |
| 2           | FRONT BUMPER FOG LAMP RH | 1   | <i>SVC</i> | <i>subject</i> \$230.00 |
| SUB TOTAL   |                          |     |            | \$378.00                |
| COST +15%   |                          |     |            | \$56.70                 |
| PARTS TOTAL |                          |     |            | \$434.70 ✓              |

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

### Head office

6 Kung Chong Road Singapore 159143  
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

### Branch

9A Serangoon North Ave 5 Singapore 554500  
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1011

### Branch

551 Upper Thomson Road Singapore 574415  
Tel: (+65) 6452 6868 | Fax: (+65) 6452 9223



Date : 23/10/2019  
Vehicle No: SMN5843Z  
Model: BMW 218i M SPORT  
Chassis: WBA2D320405E76623 - 2017  
Reg. Year: 2017  
Policy No: DMPCSN3067141900  
Date of Accident: 04/10/2019

TO MOTOR CLAIM DEPT  
CHINA TAIPING INSURANCE (SINGAPORE)

## SUPPLEMENTARY \_ 2

| NO.         | DESCRIPTION                             | QTY | UNIT S\$ | AMOUNT S\$                 |
|-------------|-----------------------------------------|-----|----------|----------------------------|
| 1           | FRONT BONNET LOCK WITH ACTUATOR ASSY LH | 1   |          | <del>Di 1</del> \$267.00 ✓ |
| 2           | FRONT BONNET LOCK WITH ACTUATOR ASSY RH | 1   |          | <del>Di 1</del> \$267.00 ✓ |
| SUB TOTAL   |                                         |     |          | \$534.00                   |
| COST +15%   |                                         |     |          | \$80.10                    |
| PARTS TOTAL |                                         |     |          | \$614.10 ✓                 |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

### Head office

6 Kung Chong Road Singapore 159143  
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

### Branch

9A Serangoon North Ave 5 Singapore 554500  
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1011

### Branch

551 Upper Thomson Road Singapore 574415  
Tel: (+65) 6452 6868 | Fax: (+65) 6452 9223

