

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chong Boon Sen

Date: 06 Apr 2020

Preliminary Advice

Vehicle No	: SMN5843Z	Accident Date	: 04/10/2019
Make	: BMW 218I	Policy No.	: DMPCSN3067141900
Assignment Date	: 15/10/2019	Excess	: S\$500.00
Date of Inspection	: 15/10/2019	Est. Duration of Repair	: 5 days
Inspection At	: Optima Werkz Pte Ltd (HQ) 9A Serangoon North Ave 5 Singapore 554500		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,401.95 (inclusive supp)
Revised Amount	:S\$	9,865.95 (inclusive supp)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	9,865.95

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	130,000.00
COE / PARF Rebate	:S\$	68,202.00
Salvage Value	:S\$	
Margin for Repair	:S\$	61,798.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Supplementary amount is \$ 1,048.80. Repairer informed the supplier invoice of the supplementary is missing.