

INS. CASE OWNER: Loh Chee Heng

CC4/AIG19018063/Bha3

LKK:  
IDAC:

ASSIGNMENT

Surveyor: LTG DOI: 14/10/2019 Date / Time: 14/10/2019  
Registered in Merimen: 14/10/2019

Pre-assign / CCU / FTE



Insured Vehicle No. : SJM 8971H Claim No. : 3615269933SG  
Name of Insured : AUTO TRUST LEASING PTE LTD Policy No. : 999994248  
Insured Tel No. : \_\_\_\_\_ HP: 64661009 Make / Model : TOYOTA WISH-1.8 (A)  
Excess Sec II :SS \_\_\_\_\_ D.O.A : 11/10/2019 12:25 Place of Accident : ALONG RACE COURSE ROAD  
Is driver the owner? ( YES / NO ) Nature of Accident : \_\_\_\_\_  
If NO, Driver Name / Age : CHITRAN S/O BALAKRISHNAN OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO  
Driver Tel No. : +65-91175455 (V/L: YES / NO ) Insured Liability : % Final ? Yes / No

SKT 7892K



INSRS:  
WSP: TEAM AUTOPRO  
Tel:  
Liability :  
RMKS:



INSRS:  
WSP:  
Tel:  
Liability :  
RMKS:



INSRS:  
WSP:  
Tel:  
Liability :  
RMKS:



INSRS:  
WSP:  
Tel:  
Liability :  
RMKS:

Date/Time	STAGE	DATE / PIC
SKT 7892K	Non-Reporting Itr (1st):	
SJM 8971H	Non-Reporting Itr (2nd):	
NBA/CTI19017991/Y; DOA: 11/10/2019	Non-Reporting Itr (Final):	
- CC3/LPC17020670/K1hb3n2; DOA: 27/10/17	Notification Itr (if non-pickup):	
- CS3/RSI14016663/T1bd1; DOA: 31/8/14	Call OI:	
	After call Itr to OI:	
	Documentation Check List:	Handler Typist
	Notification Itr (if non-pickup)	<input type="checkbox"/>
	After call Itr to OI:	<input checked="" type="checkbox"/>
	Authorisation To Act:	<input checked="" type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/>
	Car Rental Invoice:	<input checked="" type="checkbox"/>
	Towing Invoice:	<input type="checkbox"/>
	LTA / GIA :	<input checked="" type="checkbox"/>
	Medical Bill:	<input type="checkbox"/>
	PIR:	<input type="checkbox"/>
	Mandate/Reject Instruction:	<input checked="" type="checkbox"/>
	LOD	<input checked="" type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/>
	Others:	<input type="checkbox"/>
PRELIMINARY ADVICE Date/Time: _____ Sent By: _____	Confirm with: _____	Confirm by: _____
Repair Cost: <u>L16</u> SS <u>5,750.00</u> ( <u>5</u> days) Reduction: <u>67</u> %	Email <input type="checkbox"/> Call <input type="checkbox"/>	
FINAL SETTLEMENT Date/Time: <u>06/11/19</u> Confirm with: <u>ROEL</u>	Email <input checked="" type="checkbox"/> Call <input type="checkbox"/>	
Final Liability: % <u>100</u> (Assessed / Assessed) BOLA S/N No. : <u>26</u>	If NO or B 28, Ass. Lia :	
Repair Cost: SS <u>5,750.00</u>	(Old open book)	
Loss of Rental (LOR (w/Car)) SS <u>1,540.80</u> ( <u>8</u> days) X <u>190.00</u>		
Loss of Use (LOU): SS <u>-</u> ( <u>5</u> x days)		
Loss of Income (LOI): SS <u>-</u> ( <u>5</u> x days)		
LOR only <input checked="" type="checkbox"/> LOU only <input type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/> [Tick only one]		
GIA/LTA Search SS <u>7.45</u>		
Medical: SS <u>-</u>	1) Claim status: Normal/Reject/Private Settle	
Disbursement: SS <u>-</u> (e.g. Tow/ Independent )	2) Report Format:	
Legal Cost SS <u>-</u>	3) Survey fee: <u>4320.00</u>	
Total: SS <u>7,290.25</u> Global Sum SS: <u>7,290.00</u>		
FINAL PAYMENT Date/Time: _____ Confirm with: _____	Email <input type="checkbox"/> Call <input type="checkbox"/>	
Payee 1: SS <u>7,290.00</u> Name 1: <u>TEAM AUTOPRO PTE LTD</u>		
Payee 2: (Strike if N.A.) SS <u>-</u> Name 2: <u>-</u>		
Payee 3: (Strike if N.A.) SS <u>-</u> Name 3: <u>-</u>		



SJE : \_\_\_\_\_  
 Date of Survey : \_\_\_\_\_  
 Date of ReSurvey: \_\_\_\_\_ **After-Paint:** \_\_\_\_\_  
 Contacts : \_\_\_\_\_

Vehicle Nos : **SKT 7892 K**  
 Made : Volvo  
 Model : XC90  
 Chassis No : \_\_\_\_\_

**\* AGREED Cost Of Repair and Repair Day/s with SJE \***

Amount: \_\_\_\_\_ Working Day: \_\_\_\_\_

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Front fender	1	\$ 1,023.00	\$ ✓ 1,023.00
2	Front fender inner shield	1	\$ 294.00	\$ <del>294.00</del> 294.00
6	Front wheel arch moulding	1	\$ 465.00	\$ <del>325.00</del> 465.00
8	Front wheel arch garnish	1	\$ 68.00	\$ ✓ 68.00
9	Front shock absorber	1	\$ 672.00	\$ <del>672.00</del>
10	Front lower arm	1	\$ ✓ 391.00	\$ <del>391.00</del> 391.00
11	Front knuckle arm	1	\$ 564.00	\$ 564.00
12	Front knuckle arm bearing	1	\$ 216.00	\$ 216.00
14	Front door	1	\$ 1,218.00	\$ ✓ 1,218.00
15	Front door weatherstrip	1	\$ 192.00	\$ <del>192.00</del>
16	Front door checker	1	\$ 108.00	\$ 108.00
17	Front door hinge	2	\$ 86.00	\$ <del>172.00</del>
19	Rocker panel	1	\$ 946.00	\$ 946.00
21	Rocker panel garnish	1	\$ 368.00	\$ ✓ 368.00
22	Step panel	1	\$ 526.00	\$ <del>526.00</del>
23	Bonnet	1	\$ 2,990.00	\$ <del>2,990.00</del>
24	Headlamp LH	1	\$ 1,289.00	\$ <del>950.00</del> 1,289.00
28	Front bumper	1	\$ 986.00	\$ ✓ 986.00
30	Front bumper side retainer	1	\$ 90.00	\$ ✓ 90.00
Parts Sub Total :				\$ <del>5627.00</del> 12,578.00
5% Discount				\$ 281.35 628.90
<b>PARTS TOTAL :</b>				\$ <del>5345.65</del> 11,949.10

DD ✓  
 TN ✓  
 BR ✓  
 BR ✓  
 BT ✓  
 NDM X  
 NDM X  
 DD ✓  
 NDM X  
 NDM X  
 NDM X  
 NDM X  
 BR ✓  
 NDM X  
 RX  
 ? BR ✓  
 ? BR ✓  
 NEC ✓

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Front bumper clips	1	\$ 60.00	\$ 30.00 60.00
2	Front fender inner shield clips	1	\$ 60.00	\$ 30.00 60.00
3	Front alloy rim <i>SCR ✓ local repair</i>	1	\$ 800.00	\$ 200.00 800.00
4	Front tyre	1	\$ 325.00	\$ 325.00
5	Front bumper sensor	4	\$ 152.00	\$ 608.00
<b>SPECIAL NETT TOTAL :</b>				<b>\$ 260.00 1,853.00</b>

NEC ✓  
NEC ✓  
~~SCR~~  
ADAM ✓  
DMX ✓

Nos.	LABOUR	S\$
1	To R&R door component	\$ 50.00 150.00
2	To R&R front undercarriage	\$ 90.00 150.00
3	To R&R rim and tyre blanding	\$ 10.00 100.00
4	To do wheel alignment	\$ 60.00 120.00
5	To check wiring	\$ 50.00 120.00
6	To panel beat	\$ 700.00 1,800.00
7	To rust proof	\$ 10.00 120.00
8	To spray painting	\$ 600.00 1,500.00
<b>LABOUR TOTAL :</b>		<b>\$ 4,060.00</b>

PARTS TOTAL : \$ 11,949.10  
SPECIAL NETT TOTAL : \$ 1,853.00  
LABOUR TOTAL : \$ 4,060.00  
**GRAND TOTAL : \$ 17,862.10**

? photo  
Lump sum repair  
Repair days 5

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

TGGM  
lin  
14/10/19  
1615 hrs

Resurvey on 15/10/19  
1415 hrs  
TGGM lin

Parts 5345.65  
SN 260.00  
Labour 1640.00  
7245.65  
@ 20% 1449.13  
5796.52

L/S 5750/2

TGGM lin  
16/10/19

Used Cars ([//www.oneshift.com/used\\_cars/index.php](http://www.oneshift.com/used_cars/index.php)) › Volvo Listings ([listings.php?make=Volvo](http://www.oneshift.com/used_cars/listings.php?make=Volvo))  
› Volvo XC60 T5 Drive-E 2.0 (A)

[GO BACK](#)[SHOW FILTER](#)[ADVANCED SEARCH \(\[//www.oneshift.com/used\\\_cars/advanced\\\_search.php\]\(http://www.oneshift.com/used\_cars/advanced\_search.php\)\)](http://www.oneshift.com/used_cars/advanced_search.php)

Overview 



# Volvo XC60 T5 Drive-E 2.0 (A) ([listings.php?po\\_carname=Volvo XC60 T5 Drive-E 2.0](http://www.oneshift.com/used_cars/listings.php?po_carname=Volvo%20XC60%20T5%20Drive-E%202.0))

\$121,800

Be the first of your friends to like this.

 [Print Ad \(\[//www.oneshift.com/used\\\_cars/ads\\\_detail\\\_print.php?adid=239975&print=1\]\(http://www.oneshift.com/used\_cars/ads\_detail\_print.php?adid=239975&print=1\)\)](http://www.oneshift.com/used_cars/ads_detail_print.php?adid=239975&print=1)

Selling Price	\$121,800
Availability	Available
Reg Date	2 Nov 2015 6 yrs left
COE	 \$59,889

**MOTOR CAR (LH)**

**Left Partition**

NAC	INC	Item	CON	AC	Qty
1255	995326	Frt LH Door	DP	✓	
1256	995140	Frt LH Door Protector			
1257	995104	Frt LH Door Hinge			
1258	995142	Frt LH Door Wing Mirror			
1259	995102	Frt LH Door Garnish			
1260	991593	Frt LH Door Glass Outer Moulding			
1261	991588	Frt LH Door Glass Inner Moulding			
1262	995103	Frt LH Door Glass			
1263	991595	Frt LH Door Glass Regulator			
1264	991596	Frt LH Door Glass Regulator Motor			
1265	991662	Frt LH Door Rubber			
1266	991636	Frt LH Door Outer Handle			
1267	991607	Frt LH Door Inner Handle			
1268	991625	Frt LH Door Lock w/Key			
1269	991624	Frt LH Door Lock			
1270	991562	Frt LH Door Central Lock			
1271	991675	Frt LH Door Switch			
1272	991617	Frt LH Door Inner Trim Board			
1273	991568	Frt LH Door Checker			
1274	991575	Frt LH Door Felt			
1275	991688	Frt LH Door Wire Harness			
1276	991683	Frt LH Door Window Glass Pillar			
1277	991640	Frt LH Door Outer Pillar			
1278	991613	Frt LH Door Inner Pillar			
1279	991646	Frt LH Door Pillar Inner Garnish			
1280	990554	Centre Pillar LH			
1281	990542	Centre Inner Pillar LH			
1282	990517	Centre Pillar Upper Garnish LH			
1283	990564	Centre Pillar Lower Garnish LH			
1284	991670	Frt LH Door Step Garnish			
1285	994052	Rocker Panel LH			
1286	994049	Rocker Panel Inner Panel LH			
1287	994046	Rocker Panel Garnish LH	BR	✓	
1288	994055	Rocker Panel Outer Side Skirt LH			
1004	991300	Frt Bumper	BR	✓	
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer	NEG	✓	
1008	991433	Frt Bumper Reinforcement			
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1029	995153	Frt LH Headlamp Assy	BR	✓	
1031	995088	Frt LH Side Lamp			
1096	995070	Frt LH Fender	DP	✓	
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector			

Vehicle No: SKT 7892 R

NAC	INC	Item	CON	AC	Qty
1289	995156	Rear LH Door			
1290	993282	Rear LH Door Protector			
1291	995194	Rear LH Door Hinge			
1292	993228	Rear LH Door Garnish			
1293	993278	Rear LH Door Glass Outer Moulding			
1294	993231	Rear LH Door Glass Inner Moulding			
1295	995190	Rear LH Door Glass			
1296	993238	Rear LH Door Glass Regulator			
1297	995192	Rear LH Door Glass Regulator Motor			
1298	993294	Rear LH Door Rubber			
1299	993275	Rear LH Door Outer Handle			
1300	993250	Rear LH Door Inner Handle			
1301	993261	Rear LH Door Lock			
1302	993256	Rear LH Door Inner Trim Board			
1303	993218	Rear LH Door Checker			
1304	993230	Rear LH Door Glass Channel			
1305	993242	Rear LH Door Glass Triangle Garnish			
1306	993285	Rear LH Door 1/4 Glass			
1307	993288	Rear LH Door 1/4 Glass Rubber			
1308	993287	Rear LH Door 1/4 Glass Pillar			
1309	993305	Rear LH Door Step Garnish			
1310	993309	Rear LH Door Switch			
1311	994070	Roof Top Panel			
1312	994098	Roof Top Moulding			
1313	994085	Roof Top Air-bag			
1314	994084	Roof Top Air-bag Sensor			
1315	994083	Roof Top Air-bag Control Unit			
1141	992958	Rear Bumper			
1142	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
1151	993077	Rear Bumper Sponge			
1153	993040	Rear Bumper Protector			
1155	993026	Rear Bumper Moulding			
1157	993023	Rear Bumper Lower Spoiler			
1163	993851	Rear LH Taillamp			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1186	990247	Sticker			
		Frt Fender inner shield	TN	✓	
		Frt wheel arch moulding	BR	✓	
		Frt left shock absorber	BT	✓	
		Frt left alloy rim	R	X	

No of Items: 10

Assessor: JOTC/11

16/10/19



Volvo : XC90 : 2009-15 : All Wheel Drive  
 4-Wheel Total Alignment

Front : Left

Actual	Before	Specified Range
-2°21'	-2°21'	-0°45' 0°15'
5°14'	5°14'	4°42' 5°42'
-0°53'	-0°46'	0°02' 0°08'
15°36'	15°36'	
13°15'	13°15'	

Front : Right

Actual	Before	Specified Range
-0°11'	-0°11'	-0°45' 0°15'
5°10'	5°10'	4°42' 5°42'
-0°40'	-0°40'	0°02' 0°08'
13°39'	13°39'	
13°28'	13°28'	

Camber  
 Caster  
 Toe  
 SAI  
 Included Angle  
 Turning Angle Diff.

Front

Actual	Before	Specified Range
-2°09'	-2°10'	-0°30' 0°30'
0°04'	0°04'	-0°30' 0°30'
1°57'	1°57'	
-1°33'	-1°26'	-0°02' 0°22'

Cross Camber  
 Cross Caster  
 Cross SAI  
 Total Toe  
 Cross Turn Diff.

Rear : Left

Actual	Before	Specified Range
-1°31'	-1°31'	-1°06' 0°06'
0°11'	0°11'	0°06' 0°12'

Rear : Right

Actual	Before	Specified Range
-1°19'	-1°19'	-1°06' 0°06'
0°00'	-0°01'	0°06' 0°12'

Camber  
 Toe

Rear

Actual	Before	Specified Range
-0°12'	-0°13'	-0°36' 0°36'
0°11'	0°10'	0°06' 0°30'
0°06'	0°06'	-0°15' 0°15'

Cross Camber  
 Total Toe  
 Thrust Angle

-> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	616E
Vehicle Details	
Vehicle No.:	SKT7892K
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Oct 2019
Vehicle Make:	VOLVO
Vehicle Model:	XC90 T5
Primary Colour:	Brown
Manufacturing Year:	2014
Engine No.:	B5254T94738381
Chassis No.:	YV1CZ2457E1706402
Maximum Power Output:	154.0 kW (206 bhp)
Open Market Value:	\$45,803.00
Original Registration Date:	30 Apr 2015
First Registration Date:	30 Apr 2015
Transfer Count:	0
Actual ARF Paid:	\$56,125.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Apr 2025
PARF Rebate Amount:	\$42,093.00
Intended COE Rebate Details	
COE Expiry Date:	29 Apr 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$76,612.00
COE Rebate Amount:	\$42,455.00
Total Rebate Amount:	\$84,548.00

The information contained herein is correct as at 14 Oct 2019

OK

16,765 / yr  
1,397 / mth

MV 120,000 / =  
PV 84,548 / 2  
NV 35,452 / 2

Tedim  
14/10/19

## Print Received Message

This mail is associated with :

**\*SKT7892K (3615269933SG)**

**[SJM8971H]**

TP

GOLDEN LANDSCAPE & CONSTRUCTION PTE. LTD.

Oct 11 2019 12:00PM

[AUTO TRUST LEASING PTE LTD]

Team Autopro Pte Ltd - Sin Ming

**From** AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG\_SG\_EXPRESS), sent on 30/10/2019 11:22 AM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$7298.25) - SKT7892K - Claim Handler: Loh, Chee-Heng

Approved:7298.25:try to settle at best for rental rate.

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	12 Oct 2019 <a href="#">Edit Reg</a>		14 Oct 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$5,750.00</b> <a href="#">Edit Estimates</a>	<b>S\$5,750.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	AUTO TRUST LEASING PTE LTD, Co. Reg. No.: 201533654Z								
Main Claimant:	GOLDEN LANDSCAPE & CONSTRUCTION PTE. LTD., Co. Reg. No.: 201222616E								
Vehicle Reg. No.:	SKT7892K	Date of Loss:	11/10/2019 12:00 - :59 [53 Months and 11 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 3615269933SG	Policy/Cover Note No.:	(Third Party Only)						
Vehicle Reg. No. (Insured):	SJM8971H	Policy No. (Claimant):							
		Excess:							
Repairer:	Team Autopro Pte Ltd - Sin Ming (HQ) 160 SIN MING DRIVE #02-12 SIN MING AUTOCITY, 575722 Sin Ming - Tel: 9674 6635 / 9092 7279								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com								
Claimant's Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Lim Teow Guan] ... [Final Rpt due 23/10/2019]								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
• AIG_SG_EXPRESS (30/10/2019): Alert - Adj Mandate Approved (S\$7298.25) - SKT7892K - Claim Handler: Loh, Chee-H...									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SKT7892K (3615269933SG)  
[SJM8971H]

TP

GOLDEN LANDSCAPE & CONSTRUCTION PTE. LTD.

Oct 11 2019 12:00PM

[AUTO TRUST LEASING PTE LTD]

Team Autopro Pte Ltd - Sin Ming

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View <input type="button" value="View in Browser"/>	
<b>Letters/Correspondences</b>										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	(Draft)	Third Party Express Settlement - Payment Breakdown							Edit		
<b>Assessment Reports</b>										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	30/10/19 08:40	Adjuster Immediate Advice							Load HTM		
<b>Photos/Images</b>										3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	29/10/19 17:27	Odometer Reading							Load JPG	<input checked="" type="checkbox"/>	
2	29/10/19 17:27	Chassis Number							Load JPG	<input checked="" type="checkbox"/>	
3	29/10/19 17:27	General View							Load JPG	<input checked="" type="checkbox"/>	
4	29/10/19 17:27	General View							Load JPG	<input checked="" type="checkbox"/>	
5	29/10/19 17:27	General View							Load JPG	<input checked="" type="checkbox"/>	
6	29/10/19 17:27	General View							Load JPG	<input checked="" type="checkbox"/>	
7	29/10/19 17:27	General View							Load JPG	<input checked="" type="checkbox"/>	
8	29/10/19 17:27	General View							Load JPG	<input checked="" type="checkbox"/>	
9	29/10/19 17:27	General View							Load JPG	<input checked="" type="checkbox"/>	
10	29/10/19 17:27	General View							Load JPG	<input checked="" type="checkbox"/>	
11	29/10/19 17:27	General View							Load JPG	<input checked="" type="checkbox"/>	
12	29/10/19 17:27	General View							Load JPG	<input checked="" type="checkbox"/>	
13	29/10/19 17:27	General View							Load JPG	<input checked="" type="checkbox"/>	
14	29/10/19 17:27	General View							Load JPG	<input checked="" type="checkbox"/>	
15	29/10/19 17:27	General View							Load JPG	<input checked="" type="checkbox"/>	
16	29/10/19 17:27	General View							Load JPG	<input checked="" type="checkbox"/>	
17	29/10/19 17:27	General View							Load JPG	<input checked="" type="checkbox"/>	
18	29/10/19 17:27	General View							Load JPG	<input checked="" type="checkbox"/>	
19	29/10/19 17:27	General View							Load JPG	<input checked="" type="checkbox"/>	
20	29/10/19 17:27	General View							Load JPG	<input checked="" type="checkbox"/>	
21	29/10/19 17:27	General View							Load JPG	<input checked="" type="checkbox"/>	
22	29/10/19 17:27	General View							Load JPG	<input checked="" type="checkbox"/>	
23	29/10/19 17:27	General View							Load JPG	<input checked="" type="checkbox"/>	
24	29/10/19 17:27	General View							Load JPG	<input checked="" type="checkbox"/>	
25	29/10/19 17:27	General View							Load JPG	<input checked="" type="checkbox"/>	
26	29/10/19 17:27	General View							Load JPG	<input checked="" type="checkbox"/>	
27	29/10/19 17:27	General View							Load JPG	<input checked="" type="checkbox"/>	
28	29/10/19 17:27	General View							Load JPG	<input checked="" type="checkbox"/>	
29	29/10/19 17:27	General View							Load JPG	<input checked="" type="checkbox"/>	
30	29/10/19 17:27	General View							Load JPG	<input checked="" type="checkbox"/>	
31	29/10/19 17:27	General View							Load JPG	<input checked="" type="checkbox"/>	
32	29/10/19 17:27	General View							Load JPG	<input checked="" type="checkbox"/>	
33	29/10/19 17:27	General View							Load JPG	<input checked="" type="checkbox"/>	
34	29/10/19 17:27	General View							Load JPG	<input checked="" type="checkbox"/>	
35	29/10/19 17:27	General View							Load JPG	<input checked="" type="checkbox"/>	
36	29/10/19 17:27	General View							Load JPG	<input checked="" type="checkbox"/>	

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
37	29/10/19 17:27	General View		<input checked="" type="checkbox"/>
38	29/10/19 17:27	General View		<input checked="" type="checkbox"/>
39	29/10/19 17:27	General View		<input checked="" type="checkbox"/>
40	29/10/19 17:27	General View		<input checked="" type="checkbox"/>
41	29/10/19 17:27	General View		<input checked="" type="checkbox"/>
42	29/10/19 17:27	General View		<input checked="" type="checkbox"/>
43	29/10/19 17:27	Reinspection Photo		<input checked="" type="checkbox"/>
44	29/10/19 17:27	Reinspection Photo		<input checked="" type="checkbox"/>
45	29/10/19 17:27	Reinspection Photo		<input checked="" type="checkbox"/>
46	29/10/19 17:27	Reinspection Photo		<input checked="" type="checkbox"/>
47	29/10/19 17:27	Reinspection Photo		<input checked="" type="checkbox"/>
48	29/10/19 17:27	Reinspection Photo		<input checked="" type="checkbox"/>
49	29/10/19 17:27	Reinspection Photo		<input checked="" type="checkbox"/>
50	29/10/19 17:27	Reinspection Photo		<input checked="" type="checkbox"/>
51	29/10/19 17:27	Reinspection Photo		<input checked="" type="checkbox"/>
52	29/10/19 17:27	Reinspection Photo		<input checked="" type="checkbox"/>
53	29/10/19 17:27	Reinspection Photo		<input checked="" type="checkbox"/>
54	29/10/19 17:27	Reinspection Photo		<input checked="" type="checkbox"/>
55	29/10/19 17:28	After Repair Photo		<input checked="" type="checkbox"/>
56	29/10/19 17:28	After Repair Photo		<input checked="" type="checkbox"/>
57	29/10/19 17:28	After Repair Photo		<input checked="" type="checkbox"/>
58	29/10/19 17:28	After Repair Photo		<input checked="" type="checkbox"/>
59	29/10/19 17:28	After Repair Photo		<input checked="" type="checkbox"/>
60	29/10/19 17:28	After Repair Photo		<input checked="" type="checkbox"/>
61	29/10/19 17:28	After Repair Photo		<input checked="" type="checkbox"/>
62	29/10/19 17:28	After Repair Photo		<input checked="" type="checkbox"/>
63	29/10/19 17:28	After Repair Photo		<input checked="" type="checkbox"/>
64	29/10/19 17:28	After Repair Photo		<input checked="" type="checkbox"/>
65	29/10/19 17:28	After Repair Photo		<input checked="" type="checkbox"/>
66	29/10/19 17:28	After Repair Photo		<input checked="" type="checkbox"/>
67	29/10/19 17:28	After Repair Photo		<input checked="" type="checkbox"/>
68	29/10/19 17:28	After Repair Photo		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	14/10/19 16:30	ACKNOWLEDGEMENT EMAIL TO AIG DD 14.10.2019		<input type="checkbox"/>
2	14/10/19 16:30	EMAIL FROM AIG DD 14.10.19		<input type="checkbox"/>
3	14/10/19 16:30	NOTIFICATION FROM WORKSHOP + TP GIA REPORT		<input type="checkbox"/>
4	23/10/19 11:31	TP ESTIMATE - MARKED		<input type="checkbox"/>
5	23/10/19 11:31	WHEEL ALIGNMENT		<input type="checkbox"/>
6	25/10/19 11:05	EMAIL TO OI		<input type="checkbox"/>
7	25/10/19 11:05	LETTER TO OI		<input type="checkbox"/>
8	29/10/19 17:19	TP LOD		<input type="checkbox"/>
9	19/11/19 09:15	WORKSHOP INVOICE		<input type="checkbox"/>
10	19/11/19 09:15	AUTHORISATION TO ACT FORM		<input type="checkbox"/>
11	19/11/19 09:15	Release Voucher		<input type="checkbox"/>
12	19/11/19 09:15	RENTAL RECEIPT		<input type="checkbox"/>
13	19/11/19 09:15	LTA SEARCH		<input type="checkbox"/>
14	19/11/19 09:15	LOD		<input type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	15/10/19 14:12	OI GIA REPORT		<input type="checkbox"/>

### Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**

**Show Remarks To:**  Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

**THIRD PARTY EXPRESS SETTLEMENT  
(PAYMENT BREAKDOWN)**

Vehicle No:	SJM8971H (Insd veh)	Model:	VOLVO XC90 2.0 T5 (A)
	SKT7892K (TP veh)		
Date of Accident:	11/10/2019		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Repair Estimate	:	\$	17,862.10
Final Repair Cost	:	\$	7,290.00
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	8 days
LTA / GIA Search Fee	:	\$	
Others:	:	\$	
	:	\$	
Final Settlement Sum (Global Sum)	:	\$	7,290.00
Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO (Kindly indicate below)			
A) For <b>Non GIA Registered Workshop:</b>		Agreed Liability ___ 100 ___ (%)	
B) For <b>GIA Registered Workshop:</b>		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Team Autopro Pte Ltd	:	\$ 7,290.00
2)		:	\$
3)		:	\$
4)		:	\$

JOANNE LEE KHANG MIN

19 Nov  
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.  
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;  
Medical Report/ Bill (if any))

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199807198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19018063/BHA3Q2

Date: 19/11/2019

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:  
**Claimant**  
**Vehicle No :** SKT7892K **Insured Vehicle No :** SJM8971H  
**Date of Loss:** 11/10/2019 **Nature of Claim:** TP **Claim No:** 3615269933SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKT7892K**  
 Make & Model: VOLVO XC90, 2.0 T5 (A) Engine No: B5254T94738381  
 Reg. Date: 30/04/2015 (Man. Year: 2014) Chassis No: YV1CZ2457E1706402  
 Colour: Brown Odometer: 37655 km  
 Engine Capacity: 1969 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 235/65 R17 Rear Tyre Size: 235/65 R17  
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm  
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,802.10	5,605.65	8,196.45	59.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,060.00	1,640.00	2,420.00	59.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>17,862.10</b>	<b>7,245.65</b>	<b>10,616.45</b>	<b>59.44</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,750.00</b>		
<b>Nett Amount (S\$)</b>	<b>17,862.10</b>	<b>5,750.00</b>	<b>12,112.10</b>	<b>67.81</b>
+ Car Rental (8.0 x S\$180.00/day + 7.00% GST) (S\$)		1,540.80		
+ Doc/Search Fee (S\$)		7.45		
<b>Nett Liability (S\$)</b>		<b>7,298.25</b>		
<b>Global Sum Settlement (S\$)</b>		<b>7,290.00</b>		

### INSPECTION

Date of Assignment: 14/10/2019  
 Date Inspected: 14/10/2019 Inspected At: Team Autopro Pte Ltd - Sin Ming (HQ)  
 160 SIN MING DRIVE #02-12 SIN  
 MING AUTOCITY  
 Singapore 575722  
 Estimated Period of Repair: 5.0 days

**Adjuster:** Lim Teow Guan

**Manager:** VIC ALPEH

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER	Dented	1,023.00 FL	*1,023.00 FL
2	1		*FRONT FENDER INNER SHIELD	Torn	294.00 FL	*208.00 FL
3	1		*FRONT WHEEL ARCH MOULDING	Broken	465.00 FL	*325.00 FL
4	1		*FRONT WHEEL ARCH GARNISH	Broken	68.00 FL	*68.00 FL
5	1		*FRONT SHOCK ABSORBER	No Damaged	672.00 FL	*- FL
6	1		*FRONT LOWER ARM	Bent	391.00 FL	*391.00 FL
7	1		*FRONT KNUCKLE ARM	No Damaged	564.00 FL	*- FL
8	1		*FRONT KNUCKLE ARM BEARING	No Damaged	216.00 FL	*- FL
9	1		*FRONT DOOR	Dented	1,218.00 FL	*1,218.00 FL
10	1		*FRONT DOOR WEATHERSTRIP	No Damaged	192.00 FL	*- FL
11	1		*FRONT DOOR CHECKER	No Damaged	108.00 FL	*- FL
12	2		*FRONT DOOR HINGE	No Damaged	172.00 FL	*- FL
13	1		*ROCKER PANEL	No Damaged	946.00 FL	*- FL
14	1		*ROCKER PANEL GARNISH	Broken	368.00 FL	*368.00 FL
15	1		*STEP PANEL	No Damaged	526.00 FL	*- FL
16	1		*BONNET	Repair	2,990.00 FL	*- FL
17	1		*HEADLAMP LH	Broken	1,289.00 FL	*950.00 FL
18	1		*FRONT BUMPER	Broken	986.00 FL	*986.00 FL
19	1		*FRONT BUMPER SIDE RETAINER	Necessary	90.00 FL	*90.00 FL
20	1		*FRONT BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
21	1		*FRONT FENDER INNER SHIELD CLIPS	Necessary	60.00 FS	*30.00 FS
22	1		*FRONT ALLOY RIM (LOCAL REPAIR)	Scratched	800.00 FS	*200.00 FS
23	1		*FRONT TYRE	No Damaged	325.00 FS	*- FS
24	4		*FRONT BUMPER SENSOR	No Damaged	608.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>14,431.00</b>	<b>5,887.00</b>
- List Item Discount on L Items 5.00/5.00% (\$\$)	628.90	281.35
<b>Total Parts (\$\$)</b>	<b>13,802.10</b>	<b>5,605.65</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO R&R DOOR COMPONENT	New	150.00	50.00
2	TO R&R FRONT UNDERCARRIAGE	New	150.00	80.00
3	TO R&R RIM AND TYRE BALANCING	New	100.00	40.00
4	TO DO WHEEL ALIGNMENT	New	120.00	60.00
5	TO CHECK WIRING	New	120.00	50.00
6	TO PANEL BEAT	New	1,800.00	700.00
7	TO RUST PROOF	New	120.00	60.00
8	TO SPRAY PAINTING	New	1,500.00	600.00
<b>Gross Labour Cost (S\$)</b>			<b>4,060.00</b>	<b>1,640.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >