



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19018066/R1ga3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 14-05-2020



ATTN:KIAN CHUAN

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBE 1615U	Veh. Inspected	FBP 802U
Policy No.	CN056867	Coverage (\$)	0.00
Claim No.	S9M0226Z	Excess (\$)	0.00
Assign From		Assign Date	14/10/2019

2. Vehicle Particulars & Condition

Make & Model	YAMAHA MT-09 ABS TRACER	c.c	847
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	JYARN575000009335	Colour	BLUE
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	120/70Z R17	PIRELLI	4 mm
L/H Front Tyre			mm
R/H Rear Tyre	180/55Z R17	PIRELLI	4 mm
L/H Rear Tyre			mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S & O/S BODY. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	30/09/2019	Inspection Date	14/10/2019
Survey held at	SOUTHERN MOTOR BLOCK 1006 BUKIT MERAH LANE 2 #01-10 SINGAPORE 159762		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------